


Our Ref. EIR-17-1836 – Virginia Street
Your Ref. [REDACTED]
Contact Information Compliance Team
Email foienquiries@aberdeencity.gov.uk
Direct Dial 01224 522166



ABERDEEN CITY COUNCIL

11 January 2018



Information Compliance Team
Customer Services
Corporate Governance
Aberdeen City Council
Marischal College
3rd Floor North
Business Hub 17
ABERDEEN
AB10 1AQ

Tel 01224 522000
Minicom 01224 522381
DX 529451, Aberdeen 9
www.aberdeencity.gov.uk

Dear [REDACTED],

Environmental Information (Scotland) Regulations 2004 (EIRs)

EIR-17-1836 – Virginia Street

Thank you for your clarified information request of 13 December 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

We would be obliged if you could provide us with the following documents.

- **Inspection records for Virginia Street, Aberdeen from January 2016 until present.**
Please refer to the first enclosed document relating to 'Condition Survey'.
- **Reports or complaints received about the condition of the footway at Virginia Street, Aberdeen from January 2016 until present.**
Please refer to the second enclosed document relating to 'Customer Services'.

ACC has received no official complaints for this area within the given timescale. There are no complaints logged within ACC's Complaints system regarding the footway at Virginia Street, Aberdeen between 01 January 2016 and 05 January 2018.

ACC follows the Scottish Local Authority Complaints Handling Procedure. Under this procedure, a 'complaint' is defined as "an expression of dissatisfaction regarding our actions, or lack of action, or the standard of service provided by us or on our behalf". There are some topics that cannot be considered as a 'complaint', including first time requests for a service e.g. reporting a pothole, broken paving slab or the general condition of the footway.

For more information please visit www.aberdeencity.gov.uk/complaints and refer to the 'What is a complaint?' section.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Head of Service level have been redacted (blacked out) from the Customer Services

ANGELA SCOTT
CHIEF EXECUTIVE



Heritage 100% Recycled



Choose products with the FAIRTRADE Mark



document. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with Regulation 11(3)(a)(i) – Personal Information - of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals and the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as ACC considers that disclosure of this information would be a breach of the first Data Protection Principle (that personal information must be processed fairly and lawfully) and second Data Protection Principle (personal information must only be processed for a specific and lawful purpose).

Third parties named within the Customer Services document and ACC Officers below Head of Service level would not expect ACC to release this information about them into the public domain under the EIRs (or the Freedom of Information (Scotland) Act 2002 (FOISA)).

• Details of any works completed by independent contractors or Utility Companies on Virginia Street, Aberdeen from January 2016 until present.

The only works logged by a utility company on this section of carriageway were undertaken by BT between 3 and 4 August 2017 outside Grampian House. These works were on the footway. Having visited the site ACC can confirm that there are no trip hazards associated with the reinstatement. Please refer to the third enclosed document for a copy of the Works Log.

Please note that third party names and personal details have been redacted (blacked out) from the Works Log. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with Regulation 11(3)(a)(i) – Personal Information - of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals and the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as ACC considers that disclosure of this information would be a breach of the first Data Protection Principle (that personal information must be processed fairly and lawfully) and second Data Protection Principle (personal information must only be processed for a specific and lawful purpose).

Third parties named within the enclosed documents would not expect ACC to release this information about them into the public domain under the EIRs (or the Freedom of Information (Scotland) Act 2002 (FOISA)).

• **Records of any pedestrian accidents that have occurred at Virginia Street, Aberdeen from January 2016 until present.**

ACC has not received any other claims or intimations for Claims relating to Virginia Street aside from one personal injury claim for November 2017. There have also been no enquiries for accidents within the given timescale on the footway or carriageway.

We hope this helps with your request.

Yours sincerely,

Anna Buchan
Information Compliance Officer

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA. However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Effective: 01/01/2016 to 18/12/2017
 Site: VIRGINIA STREET (7601440)

Display Action Officer: No

Site: VIRGINIA STREET (7601440)

Locality: ABERDEEN, ABERDEEN CITY

Area: Aberdeen Central

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	S/30/2389 - VIRGINIA STREET	Feature Type:	RDS Road Section	Area:	Aberdeen Central	
Batch:	536600 - Inspection Batch			Route:	Week: 18 - Area: 18			Date: 27/07/2017
	No actionable defects found							
Batch:	534954 - Inspection Batch			Route:	Week: 14 - Area: 18			Date: 30/06/2017
	No actionable defects found							
Batch:	533737 - Inspection Batch			Route:	Week: 10 - Area: 18			Date: 09/06/2017
	No actionable defects found							
Batch:	531386 - Inspection Batch			Route:	Week: 06 - Area: 18			Date: 04/05/2017
	No actionable defects found							
Batch:	529466 - Inspection Batch			Route:	Week: 02 - Area: 18			Date: 07/04/2017
	No actionable defects found							
Batch:	527334 - Inspection Batch			Route:	Week: 46 - Area: 18			Date: 10/03/2017
	No actionable defects found							
Batch:	525886 - Inspection Batch			Route:	Week: 42 - Area: 18			Date: 14/02/2017
	No actionable defects found							
Batch:	524239 - Inspection Batch			Route:	Week: 38 - Area: 18			Date: 21/01/2017
	No actionable defects found							
Batch:	522188 - Inspection Batch			Route:	Week: 34 - Area: 18			Date: 15/12/2016
	No actionable defects found							
Batch:	520309 - Inspection Batch			Route:	Week: 30 - Area: 18			Date: 17/11/2016
	No actionable defects found							
Batch:	518305 - Inspection Batch			Route:	Week: 26 - Area: 18			Date: 27/10/2016
	No actionable defects found							
Batch:	515437 - Inspection Batch			Route:	Week: 22 - Area: 18			Date: 22/09/2016
	No actionable defects found							
Batch:	512621 - Inspection Batch			Route:	Week: 18 - Area: 18			Date: 31/08/2016
460440	Repair potholes around Scottish water manhole	31/08/2016	South bound just passed weigh-house square	Pot Hole	Internal		Archived	708212
Batch:	506703 - Inspection Batch			Route:	Week: 14 - Area: 18			Date: 25/07/2016
	No actionable defects found							
Batch:	505333 - Inspection Batch			Route:	Week: 10 - Area: 18			Date: 07/07/2016
	No actionable defects found							
Batch:	502432 - Inspection Batch			Route:	Week: 06 - Area: 18			Date: 02/06/2016
	No actionable defects found							
Batch:	499241 - Inspection Batch			Route:	Week: 02 - Area: 18			Date: 03/05/2016
	No actionable defects found							

Effective: 01/01/2016 to 18/12/2017
 Site: VIRGINIA STREET (7601440)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	S/30/2389 - VIRGINIA STREET	Feature Type:	RDS Road Section	Area:	Aberdeen Central	
Batch:	497488 - Inspection Batch			Route:	Week: 46 - Area: 18			Date: 11/04/2016
	No actionable defects found							
Batch:	493028 - Inspection Batch			Route:	Week: 38 - Area: 18			Date: 10/02/2016
	No actionable defects found							
Batch:	491251 - Inspection Batch			Route:	Week: 34 - Area: 18			Date: 18/01/2016
454655	approximately 2 square metres of pot holes carriageway depression and rutting repair as required to make safe	18/01/2016	East bound at junction with Commerce street	Pot Hole	Internal		Archived	700179
Asset:	1,001.00	Asset - Locn.:	1 - Grass verge	Feature Type:	RDS Verge	Area:	Aberdeen Central	
Batch:	536601 - Inspection Batch			Route:	Week: 18 - Area: 18			Date: 27/07/2017
	No actionable defects found							
Batch:	534955 - Inspection Batch			Route:	Week: 14 - Area: 18			Date: 30/06/2017
	No actionable defects found							
Batch:	533738 - Inspection Batch			Route:	Week: 10 - Area: 18			Date: 09/06/2017
	No actionable defects found							
Batch:	531387 - Inspection Batch			Route:	Week: 06 - Area: 18			Date: 04/05/2017
	No actionable defects found							
Batch:	529473 - Inspection Batch			Route:	Week: 02 - Area: 18			Date: 07/04/2017
	No actionable defects found							
Batch:	527335 - Inspection Batch			Route:	Week: 46 - Area: 18			Date: 10/03/2017
	No actionable defects found							
Batch:	525887 - Inspection Batch			Route:	Week: 42 - Area: 18			Date: 14/02/2017
	No actionable defects found							
Batch:	524240 - Inspection Batch			Route:	Week: 38 - Area: 18			Date: 21/01/2017
	No actionable defects found							
Batch:	522189 - Inspection Batch			Route:	Week: 34 - Area: 18			Date: 15/12/2016
	No actionable defects found							
Batch:	520310 - Inspection Batch			Route:	Week: 30 - Area: 18			Date: 17/11/2016
	No actionable defects found							
Batch:	518306 - Inspection Batch			Route:	Week: 26 - Area: 18			Date: 27/10/2016
	No actionable defects found							
Batch:	515438 - Inspection Batch			Route:	Week: 22 - Area: 18			Date: 22/09/2016
	No actionable defects found							
Batch:	512622 - Inspection Batch			Route:	Week: 18 - Area: 18			Date: 31/08/2016
	No actionable defects found							
Batch:	506704 - Inspection Batch			Route:	Week: 14 - Area: 18			Date: 25/07/2016
	No actionable defects found							

Effective: 01/01/2016 to 18/12/2017
 Site: VIRGINIA STREET (7601440)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,001.00	Asset - Locn.: 1 - Grass verge			Feature Type: RDS Verge			Area: Aberdeen Central	
Batch: 505334 - Inspection Batch	No actionable defects found			Route: Week: 10 - Area: 18			Date: 07/07/2016	
Batch: 502433 - Inspection Batch	No actionable defects found			Route: Week: 06 - Area: 18			Date: 02/06/2016	
Batch: 499240 - Inspection Batch	No actionable defects found			Route: Week: 02 - Area: 18			Date: 03/05/2016	
Batch: 497489 - Inspection Batch	No actionable defects found			Route: Week: 46 - Area: 18			Date: 11/04/2016	
Batch: 493029 - Inspection Batch	No actionable defects found			Route: Week: 38 - Area: 18			Date: 10/02/2016	
Batch: 491268 - Inspection Batch	No actionable defects found			Route: Week: 34 - Area: 18			Date: 18/01/2016	
Asset: 1,002.00	Asset - Locn.: 1 - Footway			Feature Type: RDS Footway			Area: Aberdeen Central	
Batch: 536603 - Inspection Batch	No actionable defects found			Route: Week: 18 - Area: 18			Date: 27/07/2017	
Batch: 534956 - Inspection Batch	No actionable defects found			Route: Week: 14 - Area: 18			Date: 30/06/2017	
Batch: 533739 - Inspection Batch	No actionable defects found			Route: Week: 10 - Area: 18			Date: 09/06/2017	
Batch: 531388 - Inspection Batch	No actionable defects found			Route: Week: 06 - Area: 18			Date: 04/05/2017	
Batch: 529474 - Inspection Batch	No actionable defects found			Route: Week: 02 - Area: 18			Date: 07/04/2017	
Batch: 527341 - Inspection Batch	No actionable defects found			Route: Week: 46 - Area: 18			Date: 10/03/2017	
Batch: 525888 - Inspection Batch	No actionable defects found			Route: Week: 42 - Area: 18			Date: 14/02/2017	
Batch: 524241 - Inspection Batch	No actionable defects found			Route: Week: 38 - Area: 18			Date: 21/01/2017	
Batch: 522190 - Inspection Batch	No actionable defects found			Route: Week: 34 - Area: 18			Date: 15/12/2016	
Batch: 520311 - Inspection Batch	No actionable defects found			Route: Week: 30 - Area: 18			Date: 17/11/2016	
Batch: 518307 - Inspection Batch	No actionable defects found			Route: Week: 26 - Area: 18			Date: 27/10/2016	
Batch: 515439 - Inspection Batch	No actionable defects found			Route: Week: 22 - Area: 18			Date: 22/09/2016	

Effective: 01/01/2016 to 18/12/2017
 Site: VIRGINIA STREET (7601440)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,002.00	Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen Central		
Batch: 512624	- Inspection Batch			Route: Week: 18	- Area: 18		Date: 31/08/2016	
No actionable defects found								
Batch: 506705	- Inspection Batch			Route: Week: 14	- Area: 18		Date: 25/07/2016	
No actionable defects found								
Batch: 505335	- Inspection Batch			Route: Week: 10	- Area: 18		Date: 07/07/2016	
No actionable defects found								
Batch: 502434	- Inspection Batch			Route: Week: 06	- Area: 18		Date: 02/06/2016	
No actionable defects found								
Batch: 499239	- Inspection Batch			Route: Week: 02	- Area: 18		Date: 03/05/2016	
No actionable defects found								
Batch: 497490	- Inspection Batch			Route: Week: 46	- Area: 18		Date: 11/04/2016	
No actionable defects found								
Batch: 493030	- Inspection Batch			Route: Week: 38	- Area: 18		Date: 10/02/2016	
No actionable defects found								
Batch: 491269	- Inspection Batch			Route: Week: 34	- Area: 18		Date: 18/01/2016	
No actionable defects found								
Asset:	1,006.00	Asset - Locn.: 1 - Central reservation (settled)		Feature Type: RDS Hard Landscaping		Area: Aberdeen Central		
Batch: 536602	- Inspection Batch			Route: Week: 18	- Area: 18		Date: 27/07/2017	
No actionable defects found								
Batch: 534957	- Inspection Batch			Route: Week: 14	- Area: 18		Date: 30/06/2017	
No actionable defects found								
Batch: 533740	- Inspection Batch			Route: Week: 10	- Area: 18		Date: 09/06/2017	
No actionable defects found								
Batch: 531389	- Inspection Batch			Route: Week: 06	- Area: 18		Date: 04/05/2017	
No actionable defects found								
Batch: 529475	- Inspection Batch			Route: Week: 02	- Area: 18		Date: 07/04/2017	
No actionable defects found								
Batch: 527336	- Inspection Batch			Route: Week: 46	- Area: 18		Date: 10/03/2017	
No actionable defects found								
Batch: 525889	- Inspection Batch			Route: Week: 42	- Area: 18		Date: 14/02/2017	
No actionable defects found								
Batch: 524242	- Inspection Batch			Route: Week: 38	- Area: 18		Date: 21/01/2017	
No actionable defects found								
Batch: 522195	- Inspection Batch			Route: Week: 34	- Area: 18		Date: 15/12/2016	
No actionable defects found								
Batch: 520312	- Inspection Batch			Route: Week: 30	- Area: 18		Date: 17/11/2016	
No actionable defects found								

Effective: 01/01/2016 to 18/12/2017
 Site: VIRGINIA STREET (7601440)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,006.00	Asset - Locn.: 1 - Central reservation (settled)		Feature Type: RDS Hard Landscaping		Area: Aberdeen Central		
Batch:	518308 - Inspection Batch			Route: Week: 26 - Area: 18		Date: 27/10/2016		
	No actionable defects found							
Batch:	515440 - Inspection Batch			Route: Week: 22 - Area: 18		Date: 22/09/2016		
	No actionable defects found							
Batch:	512623 - Inspection Batch			Route: Week: 18 - Area: 18		Date: 31/08/2016		
	No actionable defects found							
Batch:	506706 - Inspection Batch			Route: Week: 14 - Area: 18		Date: 25/07/2016		
	No actionable defects found							
Batch:	505336 - Inspection Batch			Route: Week: 10 - Area: 18		Date: 07/07/2016		
	No actionable defects found							
Batch:	502435 - Inspection Batch			Route: Week: 06 - Area: 18		Date: 02/06/2016		
	No actionable defects found							
Batch:	499238 - Inspection Batch			Route: Week: 02 - Area: 18		Date: 03/05/2016		
	No actionable defects found							
Batch:	497491 - Inspection Batch			Route: Week: 46 - Area: 18		Date: 11/04/2016		
	No actionable defects found							
Batch:	493031 - Inspection Batch			Route: Week: 38 - Area: 18		Date: 10/02/2016		
	No actionable defects found							
Batch:	491270 - Inspection Batch			Route: Week: 34 - Area: 18		Date: 18/01/2016		
	No actionable defects found							
Asset:	2,001.00	Asset - Locn.: 7601440/J/00001 - EB Opp LP23		Feature Type: RDS Gully		Area: Aberdeen Central		
Batch:	513825 - Inspection Batch			Route: Adhoc Inspection		Date: 09/09/2016		
	No actionable defects found							
Asset:	2,002.00	Asset - Locn.: 7601440/J/00002 - WB, LP 24		Feature Type: RDS Gully		Area: Aberdeen Central		
Batch:	513826 - Inspection Batch			Route: Adhoc Inspection		Date: 09/09/2016		
	No actionable defects found							
Asset:	2,003.00	Asset - Locn.: 7601440/J/00003 - EB, Opp LP21		Feature Type: RDS Gully		Area: Aberdeen Central		
Batch:	513827 - Inspection Batch			Route: Adhoc Inspection		Date: 09/09/2016		
	No actionable defects found							
Asset:	2,004.00	Asset - Locn.: 7601440/J/00004 - WB, LP 22		Feature Type: RDS Gully		Area: Aberdeen Central		
Batch:	513828 - Inspection Batch			Route: Adhoc Inspection		Date: 09/09/2016		
	No actionable defects found							
Asset:	2,005.00	Asset - Locn.: 7601440/J/00005 - EB opp LP19-21		Feature Type: RDS Gully		Area: Aberdeen Central		
Batch:	513829 - Inspection Batch			Route: Adhoc Inspection		Date: 09/09/2016		
	No actionable defects found							

Effective: 01/01/2016 to 18/12/2017
 Site: VIRGINIA STREET (7601440)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,006.00	Asset - Locn.:	7601440/J/00006 - WB, opp water lane	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513830 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,007.00	Asset - Locn.:	7601440/J/00007 - EB Opp Grampian House	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513831 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,008.00	Asset - Locn.:	7601440/J/00008 - WB, Opp Mearns street	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513832 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,009.00	Asset - Locn.:	7601440/J/00009 - EB Castle Ln steps	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513833 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,010.00	Asset - Locn.:	7601440/J/00010 - WB, opp NE corner of Grampian house	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513834 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,011.00	Asset - Locn.:	7601440/J/00011 - EB Opp James St	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513835 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,012.00	Asset - Locn.:	7601440/J/00012 - WB, 2m before James Street junction	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513836 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,013.00	Asset - Locn.:	7601440/J/00014 - WB, opp LP 16	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513837 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,014.00	Asset - Locn.:	7601440/J/00013 - EB Opp LP15	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513838 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,015.00	Asset - Locn.:	7601440/J/00016 - WB, opp LP 14	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513839 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,016.00	Asset - Locn.:	7601440/J/00018 - WB, garage opp LP 14	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513840 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,017.00	Asset - Locn.:	7601440/J/00020 - WB, grey garage opp LP 14	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513841 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							

Effective: 01/01/2016 to 18/12/2017
 Site: VIRGINIA STREET (7601440)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,018.00	Asset - Locn.:	7601440/J/00015 - EB Opp one way sign	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513842 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,019.00	Asset - Locn.:	7601440/J/00022 - WB, grey garage opp LP 12	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513843 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,020.00	Asset - Locn.:	7601440/J/00017 - EB LP13	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513844 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,021.00	Asset - Locn.:	7601440/J/00024 - WB, grey sliding door, opp LP 12	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513845 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,022.00	Asset - Locn.:	7601440/J/00019 - EB Opp #47-61	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513846 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,023.00	Asset - Locn.:	7601440/J/00026 - WB, opp LP 12	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513847 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,024.00	Asset - Locn.:	7601440/J/00021 - EB opp IN sign	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513848 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,025.00	Asset - Locn.:	7601440/J/00028 - WB, opp sub station	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513849 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,026.00	Asset - Locn.:	7601440/J/00023 - EB near opp LP11	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513850 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,027.00	Asset - Locn.:	7601440/J/00030 - WB, under bridge	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513851 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,028.00	Asset - Locn.:	7601440/J/00025 - EB LP9	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513852 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,029.00	Asset - Locn.:	7601440/J/00032 - WB, next to Theatre lane	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513853 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							

Effective: 01/01/2016 to 18/12/2017
 Site: VIRGINIA STREET (7601440)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,030.00	Asset - Locn.:	7601440/J/00027 - EB under bridge	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513854 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,031.00	Asset - Locn.:	7601440/J/00034 - WB, opp LP 7	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513855 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,032.00	Asset - Locn.:	7601440/J/00036 - WB, opp no 7	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513856 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,033.00	Asset - Locn.:	7601440/J/00029 - EB Opp pvt parking	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513857 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,034.00	Asset - Locn.:	7601440/J/00038 - WB, pavement next to Weigh-house square	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513858 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,035.00	Asset - Locn.:	7601440/J/00031 - EB LP5	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513859 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,036.00	Asset - Locn.:	7601440/J/00040 - WB, next Weigh-house square	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513860 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,037.00	Asset - Locn.:	7601440/J/00033 - EB near LP3	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513861 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,038.00	Asset - Locn.:	7601440/J/00035 - EB LP3	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513862 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,039.00	Asset - Locn.:	7601440/J/00037 - EB ped crossing	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513863 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,040.00	Asset - Locn.:	7601440/J/00039 - EB LP1	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513864 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,041.00	Asset - Locn.:	7601440/J/00041 - WB, opp layby before crosing	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513865 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							

Effective: 01/01/2016 to 18/12/2017
Site: VIRGINIA STREET (7601440)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,042.00	Asset - Locn.:	7601440/J/00042 - WB, crossing opp Pure Gym	Feature Type:	RDS Gully		Area: Aberdeen Central	
Batch:	513866 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,043.00	Asset - Locn.:	7601440/J/00043 - WB, 10m before regent quay	Feature Type:	RDS Gully		Area: Aberdeen Central	
Batch:	513867 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							
Asset:	2,044.00	Asset - Locn.:	7601440/J/00044 - WB, LP 2	Feature Type:	RDS Gully		Area: Aberdeen Central	
Batch:	513868 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/09/2016
	No actionable defects found							

Effective: 01/01/2016 to 18/12/2017

Display Action Officer: No

Service: Roads

Site: VIRGINIA STREET (7601440)

Site: VIRGINIA STREET (7601440)

Locality: ABERDEEN, ABERDEEN CITY

Area: Aberdeen Central

Customer Services

Enquiry No.: 724474	Logged by: Contact Centre	on: 16/11/2017 09:11	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: METAL BOLLARD TYPE ITEM MUST HAVE FALLEN OFF OF VEHICLE. CALLER HAS MANAGED TO PULL IT TO THE SIDE OF THE ROAD TO THE LAY BYE BEFORE THE NCP CAR PARK ON VIRGINIA STREET- PHONED THROUGH-JD			
Location: VIRGINIA STREET	Contact: [REDACTED]		
Enquiry No.: 715948	Logged by: Contact Centre	on: 18/08/2017 13:16	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: broken manhole cover - causing issues for traffic --- already phoned through to roads reception to confirm the issue			
Location: VIRGINIA STREET - just up from Market street - sfc	Contact: [REDACTED]		
Enquiry No.: 687646	Logged by: Contact Centre	on: 04/02/2017 00:24	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: ROADS29064 Site (Street/Park/etc) : A956 northbound after Marischal St bridge Location : Aberdeen city Locational Details : In front of house First Type of Fault : Rocking/Noisy/Low Manhole Cover First Fault Details : Pothole at edge, noise increasing daily Additional Information : Problem noted last week or so, drastic worsening last few days, we travel by road but residents must find noise non stop			
Location: A956 northbound after Marischal St bridge Aberdeen city	Contact: [REDACTED]		
Enquiry No.: 684756	Logged by: Contact Centre	on: 09/01/2017 10:20	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: DRAIN COVER LOOSE AND ROCKING APPROX OPPOSITE NO 109 - HAS BEEN LIKE THIS SINCE DECEMBER - [REDACTED]			
Location: approx at 109 VIRGINIA STREET	Contact: [REDACTED]		
Enquiry No.: 681620	Logged by: Contact Centre	on: 30/11/2016 21:58	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No : ROADS28837 Site (Street/Park/etc) : Virginia street Location : Outside 109 Virginia street beside one way sign Locational Details : In front of house First Type of Fault : Rocking/Noisy/Low Manhole Cover Additional Information : The manhole cover on the road is loose and extremely loud when cars drive over it.			
Location: Virginia street	Contact: [REDACTED]		
Enquiry No.: 669890	Logged by: Contact Centre	on: 14/08/2016 20:02	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: An increasing amount of vehicles are using the right hand lane at the traffic lights from Virginia Street to turn left onto Commerce Street. The traffic lights are filtered and have a left hand arrow which comes on before the full green, but recently a large number of vehicles have been waiting in the right hand lane for the full green and then attempting to turn left across the path of vehicles who are travelling in the left hand lane. It's entirely possible that this is just down to extremely poor driving but would it be possible to investigate installing 'Get in Lane' signs before the junction, or painting arrows on the road on the approach to the junction to reduce the possibility of an accident? Although the speed of vehicles at this junction is low, it's a very busy location and any collision could be quite bad and would probably end up snarling up the traffic all throughout the city.			
Location: Junction of Virginia Street & Commerce Street	Contact: ANON AUG 16 ANON AUG 16		

Effective: 01/01/2016 to 18/12/2017
Display Action Officer: No

Service: Roads
Site: VIRGINIA STREET (7601440)

Customer Services

Enquiry No.: 668417 **Logged by:** Contact Centre **on:** 29/07/2016 08:30
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No: ROADS28544. Site (Street/Park/etc): A996 left carriageway. Location: Junction Virginia Street/Marischal Street. Locational Details: In front of house. First Type of Fault: Rocking/Noisy/Low Manhole Cover. First Fault Details: Large manhole seems to be deformed banging overtime a vehicle goes over it. Second Type of Fault: Rocking/Noisy/Low Manhole Cover. Second Fault Details: Very noisy day and night causing a disturbance and presumably possibly dangerous for road users. Could it collapse with a lorry on top? Additional Information: The manhole is in front of the Virginia block which contains number 29. Name: [REDACTED] Address Line 1: Virginia Street Visitor. Email Address: [REDACTED]
Location: 29 VIRGINIA STREET - ROADS28544 - AB

Enquiry No.: 668107 **Logged by:** Contact Centre **on:** 26/07/2016 13:13
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No: NOISE COMPLAINTS13858. Site (Street/Park/etc): Virginia St. Location: Underneath bridge beside electric box. Locational Details: In front of house. First Type of Concern: Traffic. First Concern Details: Drain making noises every time a car /lorry goes over it. Second Type of Concern: Traffic. Second Concern Details: last time drain collapsed. Additional Information: The drain is making a awful noise when traffic goes over it keeping me from hearing my tv or getting a sleep. last time drain was making the same noise it caved in. Name: [REDACTED]
Telephone Number: [REDACTED]. Email Address: [REDACTED]
Location: VIRGINIA STREET - NOISE COMPLAINTS13858 - AB **Contact:** [REDACTED]

Enquiry No.: 662282 **Logged by:** Contact Centre **on:** 12/05/2016 09:20
Service: Roads **Subject:** Oil Spill **Classification:** Enquiry **Enquiry Ref:**
Desc.: **Oil Spill** Driver not sure how far back the spill goes, see route above. [REDACTED]
Location: Virginia Street/Market Street/Esplanade West-JF **Contact:** [REDACTED]

Enquiry No.: 654812 **Logged by:** Contact Centre **on:** 17/02/2016 16:23
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No: ROADS27654. Site (Street/Park/etc): Virginia Street corner with Commerce Street. Location: A956 Northbound. Locational Details: In footpath or lane. First Type of Fault: Pothole. First Fault Details: Not just one but a series of potholes. Second Type of Fault: Poor Road Surface. Additional Information: Coordinates: 57.148481, -2.088593. As you turn left on Commerce Street from A956 on the inside lane. Name: [REDACTED] Address Line 1: [REDACTED]. Postcode: [REDACTED] Email Address: [REDACTED]
Location: VIRGINIA STREET - ROADS27654 - AB **Contact:** Anon

Plot Number: 1,000.00 **Feature Id - Location:** S/30/2389 - VIRGINIA STREET **Feature Type:** RDS Road Section
Job Number: 199284

Enquiry No.: 653113 **Logged by:** Contact Centre **on:** 01/02/2016 16:39
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No: ROADS27492. Site (Street/Park/etc): Commerce Street. Location: junction with Virginia Street. First Type of Fault: Pothole. First Fault Details: Road surface and temporary repairs breaking up. Large Pothole. Second Type of Fault: Poor Road Surface. Second Fault Details: Adjacent road surface cracking and crumbling. Additional Information: North bound carriageway outside lane immediately after turn. Large areas of road surface approx. 1m by 1m breaking up. Deep pothole, deep enough to cause a bang when hit within this area. Temporary repairs may have been attempted within past couple of weeks but these have failed.
Name: [REDACTED]. Address Line 1: [REDACTED]. Address Line 2: [REDACTED] Address Line 3: [REDACTED] Postcode: [REDACTED] Telephone Number: [REDACTED] Email Address: [REDACTED]
Location: COMMERCE STREET - ROADS27492 - AB **Contact:** [REDACTED]

Plot Number: 1,000.00 **Feature Id - Location:** S/30/2389 - VIRGINIA STREET **Feature Type:** RDS Road Section
Job Number: 700179

Effective: 01/01/2016 to 18/12/2017

Display Action Officer: No

Service: Roads

Site: VIRGINIA STREET (7601440)

Customer Services

Enquiry No.: 652724	Logged by: Contact Centre	on: 28/01/2016 15:14	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No: ROADS27464. Site (Street/Park/etc): convergance of Virginia St, Commerce St, Miller Street. Location: Road Surface. First Type of Fault: Poor Road Surface. First Fault Details: Multiple road surface degradation. Additional Information: Terrible road surface over the entire section, particularly whilst turning left onto Commerce St from Virginia St, also going across from Virginia St to Miller St, lots of trenches, holes and loose rocks. Reported many timed before, no action ever taken			
Name: [REDACTED]. Address Line 1: [REDACTED]. Address Line 2: [REDACTED]. Postcode: [REDACTED]. Telephone Number: [REDACTED]. Email: [REDACTED]			
Location: COMMERCE STREET - ROADS27464 - AB		Contact: [REDACTED]	
<hr/>			
Plot Number: 1,000.00	Feature Id - Location: S/30/2389 - VIRGINIA STREET		Feature Type: RDS Road Section
Job Number: 700179			
<hr/>			
Enquiry No.: 650707	Logged by: Contact Centre	on: 12/01/2016 14:21	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No: ROADS27251. Site (Street/Park/etc): Virginia Street. Location: At traffic lights when turning left into Commerce Street. First Type of Fault: Poor Road Surface.			
Name: [REDACTED]. Address Line 1: [REDACTED]. Postcode: [REDACTED]. Email Address: [REDACTED]			
Location: VIRGINIA STREET - ROADS27251 - AB		Contact: [REDACTED]	
<hr/>			
Plot Number: 1,000.00	Feature Id - Location: S/30/2389 - VIRGINIA STREET		Feature Type: RDS Road Section
Job Number: 199284			
<hr/>			
Enquiry No.: 649812	Logged by: Contact Centre	on: 06/01/2016 10:51	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No: ROADS27155. Site (Street/Park/etc): virginia street & Commerce street. Location: left hand lane as you turn onto commerce street heading towards the roundabout. First Type of Fault: Poor Road Surface. First Fault Details: road is covered in patched potholes road is very rough to drive over. Name: [REDACTED]. Address Line 1: [REDACTED]. Address Line 2: [REDACTED]. Postcode: [REDACTED]. Telephone Number: [REDACTED]. Email Address: [REDACTED]			
Location: VIRGINIA STREET - ROADS27155 - AB		Contact: [REDACTED]	
<hr/>			
Plot Number: 1,000.00	Feature Id - Location: S/30/2389 - VIRGINIA STREET		Feature Type: RDS Road Section
Job Number: 199284			

Works Details

Works Ref: BT037-ONEA30686924
LAREF: 2312628
Address: VIRGINIA STREET
 ABERDEEN
Town: ABERDEEN
County: ABERDEEN CITY
Works Type: MINOR WITH EXCAVATION

Works Recorded Date: 18/07/2017 12:58
Proposed start date: 03/08/2017
Actual start date: 03/08/2017
Estimated end date: 04/08/2017
Latest Notice Type: WORKS CLEAR
Status: WORKS CLEAR

Traffic Sensitive

Other

Project:
Promoter: Openreach / BT [REDACTED] (ETHERNET)
Notifiable Authority: Aberdeen City Council / Aberdeen City Council
NSG Ref: 76/01440 **Easting:** 394655.00 **Northing:** 806315.00
Carriageway Reinst.: SPECIAL TYPE - OVER 30 MS **Footway Reinst.:** OTHER FOOTWAYS
Traffic Management: WORKS ENTIRELY ON THE FOOTWAY **Works Technique.:** HAND
Location: At the front of Grampian House, Virginia Street, Aberdeen
Description: Maintenance woks on behalf of BT for engineer to clear blockage in the footway

Sites

Site	Surface	Location	Site status	Site Location	Postcode	Depth	Length	Width
1	FOOTWAY		SITE PERMANENT	At the front of Grampian House, Virginia	AB11 5AT	STD	0.60	0.40
Dimensions:		Length:	0.60	Depth Code:	STD			
		Width:	0.40	Easting:	394,655.00			
Surface Type:				Northing:	806,315.00			
Interim Reinstatement Date:				Permanent Reinstatement Date:	04/08/2017			

Comments

No.	OD	Type	Made date/time	Username
1	BT037	COMMENT OR INFORMATION	10/08/2017 10:10	[REDACTED]
Hi, i have closed this down as works clear rather than works closed in error, can you please provide a reference to amend this				
thank you				
1	CA001	FPN COMMENT	24/08/2017 9:40	[REDACTED]
Fpn had been automatically generated - had the early start been recorded on notice?				
2	BT037	REQUEST FOR FURTHER INFO	10/08/2017 10:15	[REDACTED]
Can you please advise on the FPN, as no follow up notice has been done as early start was agreed by reference number AC/17/3044				

Contacts

Contact type	Contact name	Address	Tel No.	Qualification Ref
ORIGINATOR	[REDACTED]	oak house	[REDACTED]	
CONTRACTOR	[REDACTED]	L34 9FB	[REDACTED]	
		oak house		
		L34 9FB		

Charges

Date/Time	Charge description	Charge value	Net Value	Invoiced
04/08/2017 8:31	FPN SECTION 114(5) S0279	0.00	0.00	No
Adjusted	On hold			

History

Date/Time	Event Type	Details	Username
18/07/2017 12:58	WORKS RECORDED	PROPOSED WORKS: 18/08/2017 - 21/08/2017	[REDACTED]
18/07/2017 12:58	ONE MONTH	PROPOSED WORKS: 18/08/2017 - 21/08/2017	[REDACTED]
18/07/2017 12:58	MAP CONFLICT	SW515-ABV/ABV/501175B0280 Within 500m T/S	[REDACTED]

18/07/2017	12:58	MAP CONFLICT	SW515-ABV/ABV/501775B0281 Within 500m T/S	
18/07/2017	12:58	MAP CONFLICT	SW515-ABV/ABV/501175B0282 Within 500m T/S	
18/07/2017	12:58	MAP CONFLICT	CA001-P000000019373 Within 500m T/S	
18/07/2017	12:58	MAP CONFLICT	CA001-P000000019412 Within 500m T/S	
18/07/2017	12:58	MAP CONFLICT	CA001-P000000019440 Within 500m T/S	
18/07/2017	12:58	MAP CONFLICT	CA001-P000000019442 Same Street - Dates Overlap	
18/07/2017	12:59	WORKS DOCUMENT EMAILED	WORKS - [REDACTED]@[REDACTED].co.uk	
18/07/2017	13:14	VIEW NOTICE ASSESSMENT	SG005	
18/07/2017	13:15	NOTICE ASSESSMENT	SG001-High Interest	
19/07/2017	9:56	NOTICE ASSESSMENT	WO001-High Interest	
20/07/2017	11:44	NOTICE ASSESSMENT	SW100-High Interest	
25/07/2017	8:03	NOTICE ASSESSMENT	SS001-High Interest	
03/08/2017	13:47	WORKS DETAILS CHANGED	PROPOSED WORKS: 03/08/2017 - 04/08/2017	
03/08/2017	13:52	WORKS DOCUMENT EMAILED	WORKS - [REDACTED]@[REDACTED].co.uk	
04/08/2017	8:30	WORKS STATUS CHANGED	PROPOSED WORKS to IN PROGRESS	
04/08/2017	8:30	ACTUAL START	IN PROGRESS: 03/08/2017 - 04/08/2017	
04/08/2017	12:16	WORKS STATUS CHANGED	IN PROGRESS to WORKS CLEAR	
04/08/2017	12:16	WORKS CLEAR	WORKS CLEAR: 03/08/2017 - 04/08/2017	
04/08/2017	12:16	MAP RESOLVED	SYSTEM	
04/08/2017	12:26	SITE DETAILS CHANGED		
04/08/2017	12:27	SITE DETAILS CHANGED		
10/08/2017	10:10	COMMENT OR INFORMATION	BT037-Hi, i have closed this down as works clear r	
10/08/2017	10:15	REQUEST FOR FURTHER INFO	BT037-Can you please advise on the FPN, as no foll	
24/08/2017	9:39	VIEW COMMENT ASSESSMENT	CA001	
24/08/2017	9:40	FPN COMMENT	CA001-Fpn had been automatically generated - had t	
25/08/2017	10:25	VIEW COMMENT ASSESSMENT	CA001	
04/09/2017	10:54	VIEW COMMENT ASSESSMENT	BT037	
04/09/2017	10:55	COMMENT ASSESSMENT	BT037	

Designations

Type	Validity	Start date	End date
TRAFFIC SENSITIVE	EVERYDAY		
Restricted on Weekdays from 0730 to 0915 and from 1600 to 1800 Link Traffic Flow			
OTHER STRUCTURE	EVERYDAY		
S side; Mearns St. - Commerce St.			
Retaining Wall			
OTHER STRUCTURE	EVERYDAY		
N side; opp. James St. - Commerce St.			
Retaining Wall			