

From: [Foi Enquiries](#)
To: [REDACTED]
Subject: EIR-17-1284 - Pedestrian Crossing - Linksfield Road
Date: 29 September 2017 11:35:24
Attachments: [Further Information - Right to Review & Appeal.pdf](#)
[EIR-17-1284 - Linksfield Road Condition Survey.pdf](#)

Dear [REDACTED]

Thank you for your information request of 5 September 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

Pedestrian Crossing on Linksfield Road

I would be obliged to receive information regarding any surveys conducted during 2016 and 2017 at the above crossing.

Please see below a list of observation surveys which have taken place. No further information is held in relation to the surveys.

- A site observation survey was undertaken on the crossing during the week beginning 13 February 2017.
- A site observation survey was undertaken on Linksfield Road between 1900 – 2000 on 12/05/2017.
- A site observation survey was undertaken on Linksfield Road on 29/04/2017.
- A site observation survey was undertaken on the crossing during the week beginning 10 June 2017.
- A site observation survey was undertaken on Linksfield Road on 27/07/2017.
- A site observation survey was undertaken on Linksfield Road on 06/08/2017.
- A site observation survey was undertaken on Linksfield Road on 19/08/2017.
- A site observation survey was undertaken on Linksfield Road between 0930 and 1000, and between 1100 and 1200 on 31/08/2017.
- A site observation survey was undertaken on Linksfield Road between 0900 and 0930 on 7/09/2017.

A site observation survey is when an officer attends a particular site and carries out an observation for a specific period of time.

ACC is aware of a number of traffic management issues ongoing on Linksfield Road, one specifically relates to Linksfield Road pedestrian crossing and the other is a broader issue regarding buses parking over the length on Linksfield Road. Therefore, there have been observation site visits specifically relating to the pedestrian crossing and there have been site visits which were not specifically related to the pedestrian crossing but the crossing would have been included as part of the overall observation survey.

There are no recorded site observation surveys at the Linksfield Road pedestrian crossing during 2016.

ACC is unable to provide you with information **regarding any recorded site observation surveys conducted during 2016 at the above crossing** as it is not held by the Council. In order to

comply with its obligations under the terms of Regulation 10(4)(a) - Information Not Held - of the EIRs, ACC hereby gives notice that this information is not held by it. ACC is required by Regulation 10(1)(b) of the EIRs to inform you as to why in all the circumstances of the case, the public interest in maintaining this exception outweighs the public interest in disclosing this information to you. ACC is satisfied that it does not hold this information and considers that, as there is no information held, the public interest lies with the exception.

Please find attached a condition survey for Linksfield Road, which may be of interest to you, [EIR-17-1284 – Linksfield Road Condition Survey](#). This is an inspection report for the whole road and relates to the road, footway, verge, gullies and hard landscaping surfaces.

The name of the officer who generated the report has been redacted as the officer is below Head of Service level and would not expect ACC to release this information. As such, ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing this information under the terms of Regulation 11(2) in conjunction with 11(3)(a)(i) – Personal Information - of the EIRs.

We hope this helps with your request.

Yours sincerely,

Anna Buchan
Information Compliance Officer

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team
Customer Service
Corporate Governance
Aberdeen City Council
3rd Floor North
Business Hub 17
Marischal College
Broad Street
ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk

Tel 03000 200 292

*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.
Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

Effective: 01/01/2016 to 27/09/2017
 Site: LINKSFIELD ROAD (7600286)

Display Action Officer: No

Site: LINKSFIELD ROAD (7600286)

Locality: ABERDEEN, ABERDEEN CITY

Area: Aberdeen Central

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	N/12/1480 - LINKSFIELD ROAD	Feature Type:	RDS Road Section		Area:	Aberdeen Central
Batch:	537064 - Inspection Batch			Route:	Week: 20 - Area: 11		Date:	03/08/2017
465995	Pothole exposed stone 600 x 200 to fill	03/08/2017	Between 22 and 24 centre of carriageway	Pot Hole	Internal		Committed	717397
465996	Pothole exposed base stone to fill 500 x 300	03/08/2017	At entrance to Sports village car park 1	Pot Hole	Internal		Committed	717396
Batch:	532253 - Inspection Batch			Route:	Week: 08 - Area: 11		Date:	22/05/2017
	No actionable defects found							
Batch:	529180 - Inspection Batch			Route:	Adhoc Inspection		Date:	05/04/2017
463918	3 potholes at speed bumps 300 x 200 and 3 potholes/ exposed base stone to fill	05/04/2017	LINKSFIELD ROAD -at speed bumps outside 12 and between Pittodrie lane and traffic lights King street	Pot Hole	Internal		Committed	714153
Batch:	526480 - Inspection Batch			Route:	Week: 44 - Area: 11		Date:	23/02/2017
463010	Pothole / exposed stone 400 x 300 to fill	23/02/2017	At service entrance opposite Ardarroch road junction	Pot Hole	Internal		Committed	712770
463011	2 potholes 300 x 300 to fill	23/02/2017	At entrance to car park 1	Pot Hole	Internal		Committed	712771
463012	Pothole 400 x 400 to fill	23/02/2017	At exit from car park at Sports Village on old patch opposite 22	Pot Hole	Internal		Committed	712769
Batch:	525231 - Inspection Batch			Route:	Adhoc Inspection		Date:	07/02/2017
462581	3 potholes 400 x 300 to fill at old patch	07/02/2017	Outside 24 near exit from car park for Sports village	Pot Hole	Internal		Committed	712100
Batch:	521045 - Inspection Batch			Route:	Week: 32 - Area: 11		Date:	30/11/2016
	No actionable defects found							
Batch:	519541 - Inspection Batch			Route:	Adhoc Inspection		Date:	09/11/2016
461298	Blocked gully to clear and jet	09/11/2016	At corner with Ardarroch road near lighting column 9	Blocked Gully	Internal		Archived	709842
Batch:	518858 - Inspection Batch			Route:	Adhoc Inspection		Date:	02/11/2016
461197	Blocked gully to clear and jet	02/11/2016	Corner of Sports Village at service vehicles only entrance opposite Ardarroch road junction	Blocked Gully	Internal		Committed	709712
Batch:	513555 - Inspection Batch			Route:	Week: 20 - Area: 11		Date:	07/09/2016
	No actionable defects found							
Batch:	513235 - Inspection Batch			Route:	Week: 20 - Area: 11		Date:	05/09/2016
	No actionable defects found							
Batch:	504191 - Inspection Batch			Route:	Week: 08 - Area: 11		Date:	16/06/2016
459131	Pothole to fill 400 x 300	16/06/2016	Near exit from car park outside 24	Pot Hole	Internal		Archived	706008
Batch:	500207 - Inspection Batch			Route:	Adhoc Inspection		Date:	11/05/2016
458286	Approx 8 potholes/ exposed stone to fill largest being 400 x 200	11/05/2016	From Linksfield Gardens to exit from Tesco Express near traffic lights	Pot Hole	Internal		Archived	704737

Effective: 01/01/2016 to 27/09/2017
 Site: LINKSFIELD ROAD (7600286)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	N/12/1480 - LINKSFIELD ROAD	Feature Type:	RDS Road Section	Area:	Aberdeen Central	
Batch:	500206 - Inspection Batch			Route:	Adhoc Inspection			Date: 11/05/2016
458285	Pothole 300 x 300 to fill	11/05/2016	Near junction Ardarroch Place	Pot Hole	Internal	Archived		704736
Batch:	500205 - Inspection Batch			Route:	Adhoc Inspection			Date: 11/05/2016
458284	Clear all loose stones and fill pothole 600 x 200	11/05/2016	At entrance to car park 1	Pot Hole	Internal	Archived		704735
Batch:	500204 - Inspection Batch			Route:	Adhoc Inspection			Date: 11/05/2016
458283	Pothole 700 x 400 to fill and clear all loose stones which have been thrown out of pithole	11/05/2016	Near to 165 beside speed bump clise to junction Golf road	Pot Hole	Internal	Archived		704734
Batch:	499051 - Inspection Batch			Route:	Adhoc Inspection			Date: 28/04/2016
457857	2 potholes to fill 1m x 200 and 300 x 300	28/04/2016	Outside 12	Pot Hole	Internal	Archived		704223
Batch:	499050 - Inspection Batch			Route:	Adhoc Inspection			Date: 28/04/2016
457856	2 potholes to fill 500 x 400 and 400 x 300	28/04/2016	At manhole near 24	Pot Hole	Internal	Archived		704222
Batch:	495981 - Inspection Batch			Route:	Adhoc Inspection			Date: 22/03/2016
456712	Blocked gully to clear and jet	22/03/2016	Outside 96	Blocked Gully	Internal	Archived		702787
Batch:	495978 - Inspection Batch			Route:	Week: 44 - Area: 11			Date: 22/03/2016
	No actionable defects found							
Batch:	494870 - Inspection Batch			Route:	Adhoc Inspection			Date: 04/03/2016
456255	3 potholes to fill ,2 x 800 x750 and 1 x 400 x 400 , please clear up loose stones that have came out of holes .	04/03/2016	Nearc165 Linksfield road just before ,on and after speed bump	Pot Hole	Internal	Archived		702179
Batch:	493532 - Inspection Batch			Route:	Adhoc Inspection			Date: 17/02/2016
455776	4 potholes to fill	17/02/2016	Car park exit just before Sports Village ,at service entrance just after Sports village and at entrance to car park 1	Pot Hole	Internal	Archived		701598
Asset:	1,001.00	Asset - Locn.:	1 - Footway	Feature Type:	RDS Footway	Area:	Aberdeen Central	
Batch:	537065 - Inspection Batch			Route:	Week: 20 - Area: 11			Date: 03/08/2017
	No actionable defects found							
Batch:	532254 - Inspection Batch			Route:	Week: 08 - Area: 11			Date: 22/05/2017
	No actionable defects found							
Batch:	526481 - Inspection Batch			Route:	Week: 44 - Area: 11			Date: 23/02/2017
	No actionable defects found							
Batch:	521071 - Inspection Batch			Route:	Adhoc Inspection			Date: 30/11/2016
461609	Remove 4 broken slabs and replace with bitmac	30/11/2016	At tree just down from lighting column 13 opposite Ardarroch place junction	Broken Slab	Internal	Committed		710286
Batch:	521046 - Inspection Batch			Route:	Week: 32 - Area: 11			Date: 30/11/2016
	No actionable defects found							

Effective: 01/01/2016 to 27/09/2017
 Site: LINKSFIELD ROAD (7600286)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,001.00	Asset - Locn.: 1 - Footway			Feature Type: RDS Footway			Area: Aberdeen Central	
Batch: 513554 - Inspection Batch				Route: Week: 20 - Area: 11			Date: 07/09/2016	
460532	Slabs broken or raised by tree remove all broken or high slabs approx 11 possibly more and relay area in bitmac .	07/09/2016	Tree pit area outside 165	Broken Slab	Internal		Archived	708373
Batch: 504192 - Inspection Batch	No actionable defects found			Route: Week: 08 - Area: 11			Date: 16/06/2016	
Batch: 495980 - Inspection Batch				Route: Week: 44 - Area: 11			Date: 22/03/2016	
456711	Remove 4 high slabs and replce with bitmac	22/03/2016	Opposite 144 at tree	Broken Slab	Internal		Archived	702784
456710	Area of concrete work has broken out in 2 places, remove all looose material and repair concrete work	22/03/2016	Near 20	Broken Slab	Internal		Archived	702786
456709	Remove 2 high slabs and replce with bitmac	22/03/2016	Opposite 130	Broken Slab	Internal		Archived	702785
Asset: 2,001.00	Asset - Locn.: 7600286/J/00001 - LP20			Feature Type: RDS Gully			Area: Aberdeen Central	
Batch: 513505 - Inspection Batch	No actionable defects found			Route: Adhoc Inspection			Date: 06/09/2016	
Asset: 2,002.00	Asset - Locn.: 7600286/J/00002 - Opp LP 20			Feature Type: RDS Gully			Area: Aberdeen Central	
Batch: 513506 - Inspection Batch	No actionable defects found			Route: Adhoc Inspection			Date: 06/09/2016	
Asset: 2,003.00	Asset - Locn.: 7600286/J/00003 - Outside #164			Feature Type: RDS Gully			Area: Aberdeen Central	
Batch: 513507 - Inspection Batch	No actionable defects found			Route: Adhoc Inspection			Date: 06/09/2016	
Asset: 2,004.00	Asset - Locn.: 7600286/J/00004 - Oitside no 165			Feature Type: RDS Gully			Area: Aberdeen Central	
Batch: 513508 - Inspection Batch	No actionable defects found			Route: Adhoc Inspection			Date: 06/09/2016	
Asset: 2,005.00	Asset - Locn.: 7600286/J/00005 - Outside #126			Feature Type: RDS Gully			Area: Aberdeen Central	
Batch: 513509 - Inspection Batch	No actionable defects found			Route: Adhoc Inspection			Date: 06/09/2016	
Asset: 2,006.00	Asset - Locn.: 7600286/J/00006 - Opp no 122-124			Feature Type: RDS Gully			Area: Aberdeen Central	
Batch: 513510 - Inspection Batch	No actionable defects found			Route: Adhoc Inspection			Date: 06/09/2016	
Asset: 2,007.00	Asset - Locn.: 7600286/J/00007 - Outside #94			Feature Type: RDS Gully			Area: Aberdeen Central	
Batch: 513511 - Inspection Batch	No actionable defects found			Route: Adhoc Inspection			Date: 06/09/2016	
Asset: 2,008.00	Asset - Locn.: 7600286/J/00008 - Opp no 98-100			Feature Type: RDS Gully			Area: Aberdeen Central	
Batch: 513512 - Inspection Batch	No actionable defects found			Route: Adhoc Inspection			Date: 06/09/2016	

Effective: 01/01/2016 to 27/09/2017
 Site: LINKSFIELD ROAD (7600286)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,009.00	Asset - Locn.:	7600286/J/00009 - Ardarroch corner	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513513 - Inspection Batch			Route:	Adhoc Inspection			Date: 06/09/2016
	No actionable defects found							
Asset:	2,010.00	Asset - Locn.:	7600286/J/00011 - LP9	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513514 - Inspection Batch			Route:	Adhoc Inspection			Date: 06/09/2016
	No actionable defects found							
Asset:	2,011.00	Asset - Locn.:	7600286/J/00013 - Crossing bump	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513515 - Inspection Batch			Route:	Adhoc Inspection			Date: 06/09/2016
	No actionable defects found							
Asset:	2,012.00	Asset - Locn.:	7600286/J/00010 - Opp Ardarroch pl entrance	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513516 - Inspection Batch			Route:	Adhoc Inspection			Date: 06/09/2016
	No actionable defects found							
Asset:	2,013.00	Asset - Locn.:	7600286/J/00012 - Opp LP 11	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513517 - Inspection Batch			Route:	Adhoc Inspection			Date: 06/09/2016
	No actionable defects found							
Asset:	2,014.00	Asset - Locn.:	7600286/J/00015 - Outside #22	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513518 - Inspection Batch			Route:	Adhoc Inspection			Date: 06/09/2016
	No actionable defects found							
Asset:	2,015.00	Asset - Locn.:	7600286/J/00014 - Opp LP 9	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513519 - Inspection Batch			Route:	Adhoc Inspection			Date: 06/09/2016
	No actionable defects found							
Asset:	2,016.00	Asset - Locn.:	7600286/J/00017 - Outside #14	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513520 - Inspection Batch			Route:	Adhoc Inspection			Date: 06/09/2016
	No actionable defects found							
Asset:	2,017.00	Asset - Locn.:	7600286/J/00016 - Zebra crossing in front of sports centre	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513521 - Inspection Batch			Route:	Adhoc Inspection			Date: 06/09/2016
	No actionable defects found							
Asset:	2,018.00	Asset - Locn.:	7600286/J/00018 - Opp no 22	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513522 - Inspection Batch			Route:	Adhoc Inspection			Date: 06/09/2016
	No actionable defects found							
Asset:	2,019.00	Asset - Locn.:	7600286/J/00020 - Opp no 12	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513523 - Inspection Batch			Route:	Adhoc Inspection			Date: 06/09/2016
	No actionable defects found							
Asset:	2,020.00	Asset - Locn.:	7600286/J/00022 - LP 3	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	513524 - Inspection Batch			Route:	Adhoc Inspection			Date: 06/09/2016
	No actionable defects found							

Effective: 01/01/2016 to 27/09/2017
Site: LINKSFIELD ROAD (7600286)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,021.00	Asset - Locn.:	7600286/J/00019 - Opp LP3	Feature Type:	RDS Gully	Area:	Aberdeen Central	
Batch:	513530 - Inspection Batch			Route:	Adhoc Inspection			Date: 07/09/2016
	No actionable defects found							