

From: [Foi Enquiries](#)
To: [REDACTED]
Subject: EIR-17-0185 - Malcolm Road
Date: 16 February 2017 14:27:01
Attachments: [Further Information - Right to Review & Appeal.pdf](#)
[0238_001.pdf](#)
[EIR-17-0185 - Malcolm Road Call out.pdf](#)
[EIR-17-0185 - North Deeside Road.pdf](#)

Dear [REDACTED],

Thank you for your information request of 27 January 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

With reference to EIR-16-0405, I attach extracts and would be obliged if you could provide some clarification on your response. Please confirm what remedial work was carried out to clear the blocked gullies on Malcolm Road, Culter, reports of which were received by you on the 12th November 2015 and 30th November 2015. From your response it appears that no maintenance has been carried out following these reports.

I would also be grateful if you could clarify where the gullies reported as blocked were located, as the information has been redacted for where the reports were made from and this does not allow us to locate the blocked gullies.

The reports received on 12/11/2015 were treated as emergency response, I have attached the call out sheet. The gulley was cleaned and jetted to remove the flooding. This gulley was located outside number 68 Malcolm Road.

The report received of a missing gulley cover on 30/11/2015 was actually on North Deeside Road approaching the Rob Roy Bridge, it has been placed under the wrong location in Confirm. As a result of this enquiry the roads inspector attended the site on 30/11/2015 at 11.14am and was unable to locate any actionable safety defects at the location given, please see attached report to confirm this.

We hope this helps with your request.

Yours sincerely,

Information Compliance Team

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team
Communications and Promotion
Office of Chief Executive
Aberdeen City Council
3rd Floor North
Business Hub 17
Marischal College
Broad Street
ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk

01224 523827/523602

Tel 03000 200 292

*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.

Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

Incident Report

Date <u>12/11/15</u>		Location of Incident	
Arrived on site.....		68 MALCOM RD .	
Left site.....			
Incident type		Originator of Callout Message & time received	
FLOOD		R.C.C .	
Vehicles / Plant used	Plant Type <u>GULLY TANKER</u>		
	Plant Number <u>HIRE</u>		
Material used & quantity (eg sand, Viasix, absorbent granules)	/		
Cones / Signs / Barriers used & quantity	/		
Action Taken & any further action required	CLEANED AND JETTED GULLY TO REMOVE FLOOD .		
Any other information (eg Vehicle registration number or Police Office number)	/		

NAME

SIGNATURE

02/02/2017

Enquiry Trace Form - Preview

Enquiry: 646976	Logged by: Contact Centre	on 30/11/2015 06:06
Service: Drainage	Classification: Enquiry	
Subject: Drainage Other	Enquiry Ref:	
Desc.: First Type of Fault : Missing Gully Cover First Fault Details : on the approach to the bridge, heading East, a small manhole is missing its cover Second Type of Fault : Blocked Gully Second Fault Details : the bridge, and thereafter the main road, immediately prior to the junction with Malcolm Rd, flood after it has rained. the flood cover approximately 75% of the carriageway to a depth of 15cm, causing a considerable hazzard to cyclists		
Site: MALCOLM ROAD (7600149), PETERCULTER, ABERDEEN, ABERDEEN CITY Site Address: MALCOLM ROAD Area: Aberdeen South Location: Rob Roy Bridge Ward: 9 Lower Deeside Site Notes: Owner: 1; type: Roads Maintained. Maintained by: RD03-Roads Contact: Telephone: Fax:		
Customer: 650287	Time: 30/11/2015 06:06	Method: Telephone
Name:	Their Cust Ref: 101002882075	
Address:	Telephone:	
	Fax:	
Current Status:		
No. Effective	Status	Officer
4 30/11/2015 11:14:26	Inspected - No Safety Defect	
Notes: Unable to find any actionable safety defects at specified location.		
Status history:		
No. Effective	Status	Officer
3 30/11/2015 09:18	Enquiry Raised	
2 30/11/2015 09:09	Enquiry Raised	
1 30/11/2015 06:06	Enquiry Raised	
First Type of Fault : Missing Gully Cover First Fault Details : on the approach to the bridge, heading East, a small manhole is missing its cover Second Type of Fault : Blocked Gully Second Fault Details : the bridge, and thereafter the main road, immediately prior to the junction with Malcolm Rd, flood after it has rained. the flood cover approximately 75% of the carriageway to a depth of 15cm, causing a considerable hazzard to cyclists Subject changed from "Drainage / Drainage OOH Emergency (R06/2000)		

Revised Status:

Name : Signed : Date : Time :

Report generated by :

09:34:32