From: Foi Enquiries

To:

Subject: EIR-17-1045 - Inspection - Little Belmont Street

**Date:** 02 August 2017 13:37:34

Attachments: Further Information - Right to Review & Appeal.pdf

EIR-17-1045 - Little Belmont Street Customer Enquiries.pdf EIR-17-1045 - Job Sheet Little Belmont Street.pdf EIR-17-1045 - Little Belmont Street Inspection Reports.pdf

Dear

Thank you for your information request of 21 July 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

Accident: 28 October 2016

We refer to the above and would be grateful if you would provide us with the undernoted information relative to repair, maintenance, and inspection of the pedestrian area of Little Belmont Street, Aberdeen

We would be grateful if you would provide us with:

## A copy of the complaint made by Street, Aberdeen about the pavement outside his restaurant

on Little Belmont

There is no complaint recorded in respect of the above.

To provide clarification regarding this result, Aberdeen City Council follow the Scottish Local Authority Complaints Handling Procedure.

Under this procedure, a 'complaint' is defined as "an expression of dissatisfaction regarding our actions, or lack of action, or the standard of service provided by us or on our behalf". There are some topics that cannot be considered as a 'complaint', such as reporting a pothole or pavement defect. This would be classed as a first time service request instead. For more information please visit <a href="http://www.aberdeencity.gov.uk/council\_government/feedback\_complaints/crc\_whatisacomplaint.asp">http://www.aberdeencity.gov.uk/council\_government/feedback\_complaints/crc\_whatisacomplaint.asp</a>

Please see attached a record of all customer enquiries for Little Belmont Street between 1 January 2016 and 27 July 2017.

# A copy of the job sheet for the repair of the pavement outside Poldino's Italian Restaurant, Little Belmont Street, Aberdeen

The only repair carried out at this location since 28 October 2015 was carried out on 31 August 2016, please see job sheet attached.

### A copy of the repair report for the pavement outside Poldino's Italian Restaurant, Little Belmont Street, Aberdeen

As above, the job sheet also contains the repair report.

# A copy of the inspection completed after the repair to the pavement outside Poldino's Italian Restaurant, Little Belmont Street, Aberdeen

The next inspection following this repair was carried out on 2 September 2016, please see inspection report attached, no actionable safety defects present along the whole of Little Belmont Street on this date.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Head of Service level have been redacted from the attached reports. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with 11(3)(a)(i) — Personal Information of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, and the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as ACC considers that disclosure of this information would be a breach of the first Data Protection Principle (that personal information must be processed fairly and lawfully). Third parties and ACC Officers who are below Head of Service level named within the attached documents would not expect ACC to release this information about them into the public domain under the EIRs (or the Freedom of Information (Scotland) Act 2002 (FOISA)).

We hope this helps with your request.

Yours sincerely,

Information Compliance Team

#### INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team
Customer Service
Corporate Governance
Aberdeen City Council
3rd Floor North
Business Hub 17
Marischal College
Broad Street
ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk

Tel 03000 200 292

<sup>\*03000</sup> numbers are free to call if you have 'free minutes' included in your mobile call plan.

Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

27/07/2017		Site History Report	Page 1 of 4
Effective: 01/01/2 Site: LITTLE	Effective: 01/01/2016 to 27/07/2017 Site: LITTLE BELMONT STREET (7601007)	Display Action Officer: No	
Site: LITTLE BELMONT STREET (7601007)	REET (7601007)	Locality: ABERDEEN, ABERDEEN CITY	Area: Aberdeen Central
Customer Services			
Enquiry No.: 1021529 Service: Waste Collection	Logged by: Subject: New Bin Request	on: 17/02/2016 15:38 Classification: Enquiry	
Desc.: STANCHIONS - FIXING STAND Location: SITS ON CORNER BELMONT AT CHURCH LITTLE BELMONT STREET	IXING STAND R BELMONT AT CHURCH F STREET	Contact: ก\ล	
Plot Number: 100,006.00 Job Number: 10075079	Feature Id - Location: 9051081836 -	LITTLE BELMONT STREf Feature Type: W - Commercial Waste Property	nercial Waste Property
Enquiry No.: 1020966 Service: Waste Collection	Logged by: Subject: New Bin Request	on: 09/02/2016 12:56 Classification: Enquiry	
Desc.: Location:		Contact: n\a	
Plot Number: 100,016.00 Job Number: 10074455	Feature Id - Location: 009051132022 -	Little Belmont Stree Feature Type: W - Domestic Waste Property	stic Waste Property
Enquiry No.: 1020713 Service: Waste Collection Service: Option: 1x2401 howen bin	Logged by: Subject: New Bin Request	on: 05/02/2016 13:00 Classiffcation: Enquiry	
Location: LII ILE BELMONI SIREET ABERDEEN AB10 1JG	SIREET	Contact:	
Plot Number: 100,015,00 Job Number: 10074173	Feature Id - Location: 9051117495 -	LITTLE BELMONT STRE Feature Type: W - Commercial Waste Property	nercial Waste Property
Enquiry No.: 1019521 Service: Waste Collection Desc.: Deliver-ASAP 1x 240L black bin	Logged by: Subject: new Bin Request :40L black bin	on: 19/01/2016 16:15 Classification: Enquiry	
Location: Little Belmont Street	184	Contact: n\a	
Plot Number: 100,015.00 Job Number: 10072828	Feature Id - Location: 9051117495 -	LITTLE BELMONT STRE Feature Type: W - Commercial Waste Property	nercial Waste Property
Enquiry No.: 707093 Logged t Service: Wasle Collection Subje Desc.: Please could someone call them back on Location: _ITTLE BELMONT STREET	y: Conlact Cer ct: Conlract Qu	on: 05/06/2017 13:20  ery - WC Classification: Enquiry Et contract from a recycling collection.  Contact:	Enquiry Ref:
Enquiry No.: 706726 Service: Waste Collection Desc.: bins missed for 2 days now overflowing Location: little belmont street	Logged by: Contact Centre Subject; Missed Bin Jays now overflowing	on: 01/06/2017 12:55 Classification: Enquiry Contact:	Enquiry Ref:

Effective: 01/01/2016 to 27/07/2017 Site: LITTLE BELMONT STRE	tive: 01/01/2016 to 27/07/2017 Site: LITTLE BELMONT STREET (7601007)	Display Action Officer: No	icer: No
Customer Services			
Enquiry No.: 702599 Service: Street Care & Cleansing Desc.: Taxi driver reported an oil spill from O'l	ry No.: 702599 Logged by: Contact Centre srvice: Street Care & Cleansing Subject: Environmental Oil Spill Classific Desc.: Taxi driver reported an oil spill from O'Neil's the pub to Little Belmont Street. Co	on: 04/05/2017 09:29 Classification: Enquiry Ittle Belmont Street. Ieff a voicemail on Contact:	99:29 Enquiry Ref: on
Plot Number: 100,001.00 Fe	Feature Id - Location: 9051309376 - LITTLE	LITTLE BELMONT STREET, AB10 1JG	Feature Type: W - Domestic Waste Property
Enquiry No.: 697005  Service: Signs/Street Furniture Subj Desc.: Reference No : PATHS17875 Site (Street/Parketc) : Little Belmont St Location: Heritage tile sign above the ta Locational Details: In front of house First Type of Fault: Poor Surface First Fault Details: There is a broken tile Additional Information: Photo of sign ha	Logged by: Contact Centre Subject: Damaged Sign 17875 Little Belmont St sign above the tailor's sign ront of house or Surface sre is a broken tile in the sign and the s	on: 04/04/2017 00:11 Classification: Enquiry ds a good clean to remove the moss. Or I can resend if required.	00:11 Enquiry Ref:
Name Telephone Number : Emall Address : Location: Little Belmont Su		Contact:	
Enquiry No.: 693277 Service: Waste Collection Desc.: called agai	Contact Centre Subject: Contract Query • WC Classification: Enqui called again about setting up trade waste contract, asks that a price list be emailed to him. Little Belmont Street • ST Contact:	on: 15/03/2017 13:49 Classification: Enquiry lat a price list be emailed to him. Contact:	13:49 Enquiry Ref:
Enquiry No.: 688410 Service: Street Care & Cleansing Desc.: comer with Belmont Street Location: Little Belmont Street	ry No.: 688410 Logged by: Contact Centre on: 10/02/2017 10:09  service: Street Care & Cleansing Subject: Litter (Removal) Classification: Enquiry  Desc.: corner with Belmont Street litter all over the road. Appear a rubbish bag from the large bin has been spread all over the street.id	on: 10/02/2017 10:09 Classification: Enquiry Ig from the large bin has been spread all over the street.jc	10:09  Enquiry Ref: all over the street.jd 17 ANON FEB 17
Enquiry No.: 665648 Service: Waste Collection Desc.: BINS WERE NOT EMPTIED ON SATURE TO BE EMPTIED-JD Location: POLDINOS -LITTLE BELMONT STREET	ry No.: 685648 Logged by: Cantact Centre sarvice: Waste Collection Subject: Missed Bin Desc.: BINS WERE NOT EMPTIED ON SATURDAY WHICH IS FOR 2 BINS. TO BE EMPTIED-JD sation: POLDINOS-LITTLE BELMONT STREET		on: 16/01/2017 12:12 Classification: Enquiry THE MEN CAME TODAY BUT ONLY EMPTIED 1 BIN WHICH THEY ARE CONTRACTED FOR. THEY STILL NEED 1 BIN Contact:
Enquiry No.: 680405 Service: Waste Collection Desc.: Business general wast Location:	ry No.: 680405 Logged by: Contact Centre sarvice: Waste Collection Subject: Missed Bin Desc.: Business general waste has been missed last 2 weeks. Little Belmont Street -	on: 18/11/2016 13:32 Classification: Enquiry Contact:	13:32 Enquiry Ref:
Enquiry No.: 678161 Service: Roads Desc.: Called to report unever Location: Little Belmont Street	ry No.: 678161  Logged by: Contact Centre Subject: General Enquiry Desc.: Called to report uneven cobbles on the footpath. Elderly caller and this cation: Little Belmont Street	on: 28/10/2016 14:28 Classification: Defect Report s caused her to have a fall. Contact:	14:28 nt

Effective: 01/01/2016 to 27/07/2017	16 to 27/07/2017	Display Action Officer: No	
Site: LII ILE B	Site: LII ILE BELMUNI SIREE! (7601007)		
Customer Services			
Enquiry No.: 673405 Service: Waste Collection Desc.: Please contact	Logged by: Conlact Centre Subject: Contract Query - WC to set up a trade account. Tel:	on: 15/09/2016 14:28 Classification: Enquiry	Enquiry Ref.
Location: Little Belmont Sin	Little Belmont Street - trade waste account	Contact:	
Enquiry No.: 671576 Service: Road Works Desc.: uneven slab outside no 7 an pavement Location: 7 little belmont street -	Logged by: Contact Centre Subject: Footways - Road Works no 7 on pavement	on: 29/08/2016 14:12 Classification: Defect Report Contact:	Enquiry Ref.
Plot Number: 1,001.00 Job Number: 708164	Feature Id - Location: 1 - Footway Defect Number: 460413	Feature Type: RDS Footway	Footway
Enquiry No.: 669086 Service: Waste Collection Desc.: New business needs Location:	ry No.: 669086 Logged by: Contact Centre on: 04/08/2016 16:55  Bervice: Waste Collection Subject: Contract Query - WC Classification: Enquiry  Desc.: New business needs a contact asap - says called in 2 weeks ago and have contacted yourselves, but no note on this end - call cation:  Eittle Belmont Street AB10 1JG Contact:	on: 04/08/2016 16:55 Classification: Enquiry Intacled yourselves, but no note on this end - call Contact:	Enauiry Ref.:
Enquiry No.: 663638 Service: Waste Collection Desc.: please cal: Location: little belmont street - cy	Logged by: Contact Centre Subject: Waste Other would like to make changes to glass collections cy	on: 31/05/2016 10:52 Classification: Enquiry Contact:	Enquiry Ref:
Enquiry No.: 661284 Service: Waste Collection Desc.: recycling missed today Location little belmont street - cy	Logged by: Contact Centre Subject: Missed Bin ay 1- cy	on: 29/04/2016 13:38 Classification: Enquiry Contact:	Enquiry Ref:
Enquiry No.: 659751 Service: Waste Collection Desc.: THE GENERAL WAS PLEASE. IT WILL BE Location:	ry No.; 659751  Subject: Missed Bin Basc.: THE GENERAL WASTE WAS NOT EMPTUED ON FRIDAY AND THIS IS THE FIRST DAY THE PLEASE. IT WILL BE PUT OUT TODAY FOR UPLUFT LATER TODAY.  Contact:	2/04/201 nquiry	6 14:53 Enquiry Ref: HAS BEEN OPEN SINCE TO REPORT IT, COULD THE BIN BE EMPTIED ASAP
Enquiry No.: 659293 Service: Waste Collection Desc.: Location:	Logged by: Contact Centre Subject: Waste Other would like to know what are her rubbish uplift days are-jd -LITTLE BELMONT STREET	on: 07/04/2016 08:33 Classification: Enquiry Contact:	Enquiry Ref:
Enquiry No.: 657348 Service: Waste Collection Desc.: Pasta Cooker, paid - Location:	Logged by: Contact Centre Subject: Bulky Uplift WhiteG (Paid) Id - 3elmont Street - back of premisis, access at side of 8 Gaelic Lane	on: 16/03/2016 10:30 Classification: Enquiry Lane Contact:	Enquiry Ref:
Plot Number: 100,007.00 Job Number: 347892	Feature Id - Location: 9051310924 - LITTLE BELMO	BELMONT STREET, AB10 1JG Feature Type: W - D	Feature Type: W - Domestic Waste Property
Enquiry No.: 657125 Service: Waste Collection Subsc.: Have a pasta boller for uplift. Does no to advise - email to waste+recycling-to-advise tute Belmont Street	on: 14/03/2016 12:23  strice: Waste Collection  Subject: Waste Other  Subject: Waste Other  Subject: Waste Other  Desc.: Have a pasta boiler for uplift. Does not plug into electrics at all, works from gas. About size of a small cooker. I am not sure if we would collect it, as it is not electric - please call to advise - email to waste+recycling -  tation:  Contact:	on: 14/03/2016 12:23 Classification: Enquiry s. About size of a small cooker. I am not sure if we wo Contact:	Enquiry Ref: puld collect it, as it is not electric - please call

Display Action Officer: No

Effective: 01/01/2016 to 27/07/2017

27/07/2017

Site: LIT	Site: LITTLE BELMONT STREET (7601007)		
Customer Services			
Enquiry No.: 654417 Service: Waste Collection Desc.: Bin missed today,	ry No.: 654417 Logged by: Contact Centre Subject: Missed Bin Desc.: Bin missed today, if not done by 6pm, advised them to put out for 9am tomorrow-	ass	Enquiry Ref:
Location:	Little Belmont Street	Contact:	
Enquiry No.: 652831 Service: Waste Collection Desc.: Caller previously r bin. Enquires haw aive him a call on Location:	652831  Waste Collection  Subject: New Bin Request Caller previously request a black bin on the 16th of November as he does bin. Enquires have been loaded an emails sent to ask someone to call his and send him an email	on: 29/01/2016 12:01 Classification: Enquiry sn't have one and their are no communal bins m bake regarding this multiple times since then but it to advise what has caused this delay - Contact:	ry No.: 652831  Logged by: Conlact Centre Subject: New Bin Request Besc.: Caller previously request a black bin on the 16th of November as he doesn' t have one and their are no communal bins for him to use (confirm ID: 845759). He still hasn' t received this bin. Enquires have been logged an emails sent to ask someone to call him bake regarding this multiple times since then but no bin has been delivered. Could someone deliver a new black bin and send him an email to advise what has caused this delay -  LITTLE BELMON'S SIREET Confact: **  Contact:
Plot Number: 100,015.00 Job Number: 10074408	Feature Id - Location: 9051117495 -	.ITTLE BELMONT STRE Feature Type: W - Commercial Waste Property.	: W - Commercial Waste Propert,

Job Number	708164	Placed on W.O.	RD01/24353	Archived	i			
Site	LITTLE BELMON	T STREET		7601007				
	ABERDEEN, ABI	RDEEN CITY						
Asset Id	1			Location	Footway			
Asset No	1,001.00 F	DS Footway						
Area	Aberdeen Centra			Ward	8 George Street	/ Harbour		
Description	Lift and relay loose and rocking Calthness slab (Rocking Slab)		ness slab	Work Location	7 fittle belmont s	ireet		
Job Type	NCA No Code Allocated				Estimate	ed Value		
Priority	.RD 7 Day		~		Price Factor S	Standard		~
Cost Code	RCD1901-RC221	1	/ways SLABBE	D			Partial Payments	
Customer	Roads		-		Est. Start Date		00/00/0000 00:00:00	
Customer Refe	erence				Actual S	Start Date	00/00/0000 00:00:00	)
Pref. Contr.	RD01 R	oads Contract (Gen	eral Maint)		Est Con	npletion '	06/09/2016 13:03:50	}
Status	J80 Job Ci	osed			Target Completion 06/09/2016 13:03:			}
Officer					Actual C	Completion	31/08/2016 00:00:00	)

Effective: 30/08/2016 to 03/09/2016

Batch: 512263 - Inspection Batch

Site: LITTLE BELMONT STREET (7601007)

460413 Lift and relay loose and rocking Caithness 30/08/2016 7 little belmont street

Display Action Officer: No

Site: LITTLE BELMONT STRE	EET (7601007)	ocality: ABERDEEN, ABERDEEN CITY		Area: Aberdee	en Central
Condition Survey					
Defect No: Description	Log Date Location	Defect Type	Class. Organisation	n Status	Job No.
<b>Asset:</b> 1,000.00	Asset - Locn.: N/13/1484 - LITTLE BELMONT S	TREET Feature Type: F	RDS Road Section	Area: Aberde	een Central
Batch: 513032 - Inspection B	Batch	Route: Week: 19 - Area: 18			Date: 02/09/2016
No actionable defects fo	und				
Batch: 512308 - Inspection B	Batch	Route: Week: 17 - Area: 18			Date: 30/08/2016
No actionable defects fo	und				
<b>Asset:</b> 1,001.00	Asset - Locn.: 1 - Footway	Feature Type: F	RDS Footway	Area: Aberde	een Central
Batch: 513033 - Inspection B	Batch	Route: Week: 19 - Area: 18			Date: 02/09/2016
No actionable defects fo	und				
Batch: 512309 - Inspection B	Batch	Route: Week: 17 - Area: 18			Date: 30/08/2016
No actionable defects fo	und				

Route: Adhoc Inspection

Rocking Slab

Internal

Date: 30/08/2016

708164

Archived