From: Foi Enquiries

To:
Subject: EIR-17-1115 - Inspection Records
Date: 29 August 2017 15:56:40

Attachments: Further Information - Right to Review & Appeal.pdf

EIR-17-1115 - Justice Mill Lane Reports.pdf

Dear ,

Thank you for your information request of 11 August 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

Accident Date: 18/02/2017

We act for an individual who sustained personal injury as a result of an accident occurring on 18 February 2017 at Justice Mill Lane, Aberdeen and directly opposite Nuffield Health Fitness & Wellbeing Gym.

We request documentation for a period of 12 months prior to 18 February 2017 being:

1. Records of inspection for Justice Mill Lane

Please refer to the attached document under 'Condition Survey'.

- **2.** Maintenance records, including records of independent contractors working in Justice Mill Lane Please refer to the attached document under 'Maintenance Management'.
- 3. Statement of your Road Authorities Policy under the Code of Practice for Highway Maintenance Management 2005 or alternatively records of the minutes of highway authority or local authority meetings where maintenance or repair policy has been discussed or decided Please see link:

http://www.aberdeencity.gov.uk/web/files/Roads/road_safety_inspection_manual.pdf

As **Road Authorities Policy** is otherwise accessible on our website at the link provided above, it is exempt from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby gives notice that we are refusing your request under the terms of Regulation 6(1)(b) - Information Already Publicly Available - of the EIRs.

4. Records of complaints about the state of Justice Mill Lane

There are no complaints recorded regarding the condition of Justice Mill Lane for this time period.

Please note, Aberdeen City Council follow the Scottish Local Authority Complaints Handling Procedure. Under this procedure, a 'complaint' is defined as "an expression of dissatisfaction regarding our actions, or lack of action, or the standard of service provided by us or on our behalf". There are some topics that cannot be considered as a 'complaint', such as reporting a pothole or pavement defect. This would be classed as a first time service request instead. For more information please visit;

http://www.aberdeencity.gov.uk/council_government/feedback_complaints/crc_whatisacomplaint.asp

5. Records of other accidents which have occurred in Justice Mill Lane

Aberdeen City Council has received no reports of any accidents between 18/02/2016 and 18/02/2017

regarding this location. This includes any intimations of claims or claims.

We hope this helps with your request.

Yours sincerely,

Information Compliance Team

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team
Customer Service
Corporate Governance
Aberdeen City Council
3rd Floor North
Business Hub 17
Marischal College
Broad Street
ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk

Tel 03000 200 292

*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.

Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

Effective: 18/02/2016 to 18/02/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: JUSTICE MILL LANE (7601090)

Site: JUSTICE MILL LANE (7601090) Locality: ABERDEEN, ABERDEEN CITY Area: Aberdeen South Condition Survey **Defect No: Description** Log Date Location **Defect Type** Class. Organisation Status Job No. 1,000.00 Asset - Locn.: S/30/1332 - JUSTICE MILL LANE Feature Type: RDS Road Section Area: Aberdeen South Asset: Batch: 525035 - Inspection Batch Route: Week: 40 - Area: 18 Date: 03/02/2017 No actionable defects found Batch: 521433 - Inspection Batch Route: Week: 32 - Area: 18 Date: 07/12/2016 No actionable defects found Route: Week: 24 - Area: 18 Batch: 516582 - Inspection Batch Date: 05/10/2016 No actionable defects found Batch: 511550 - Inspection Batch Route: Week: 16 - Area: 18 Date: 24/08/2016 No actionable defects found Batch: 504671 - Inspection Batch Route: Week: 08 - Area: 18 Date: 23/06/2016 No actionable defects found Batch: 498225 - Inspection Batch Route: Week: 48 - Area: 18 Date: 20/04/2016 No actionable defects found Batch: 494515 - Inspection Batch Route: Week: 40 - Area: 18 Date: 03/03/2016 No actionable defects found Asset: 1,003.00 Asset - Locn.: 1 - Hard Landscaping Feature Type: RDS Hard Landscaping Area: Aberdeen South Batch: 525036 - Inspection Batch Route: Week: 40 - Area: 18 Date: 03/02/2017 No actionable defects found Batch: 521434 - Inspection Batch Route: Week: 32 - Area: 18 Date: 07/12/2016 No actionable defects found Batch: 516583 - Inspection Batch Route: Week: 24 - Area: 18 **Date:** 05/10/2016 No actionable defects found Batch: 511551 - Inspection Batch Route: Week: 16 - Area: 18 Date: 24/08/2016 No actionable defects found Batch: 504672 - Inspection Batch Route: Week: 08 - Area: 18 Date: 23/06/2016 No actionable defects found Batch: 498226 - Inspection Batch Route: Week: 48 - Area: 18 Date: 20/04/2016 No actionable defects found Route: Week: 40 - Area: 18 Batch: 494516 - Inspection Batch Date: 03/03/2016 No actionable defects found 1,004.00 Asset - Locn.: 1 - Footway Feature Type: RDS Footway Area: Aberdeen South Asset: Route: Week: 40 - Area: 18 Batch: 525037 - Inspection Batch Date: 03/02/2017 No actionable defects found Batch: 521435 - Inspection Batch Route: Week: 32 - Area: 18 Date: 07/12/2016 No actionable defects found

Effective: 18/02/2016 to 18/02/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Site: JUSTICE MILL LANE (7601090)

Condition Survey

Defect No: Descrip	otion		Log Date	Location		Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,004.00	Asset - Locn.:	1 - Footway			Feature Type:	: RDS Footway		Area: Aberdee	en South
Batch: 5165	84 - Inspection Ba	atch			Route: Week	c: 24 - Area: 18				Date: 05/10/2016
No action	onable defects fou	ınd								
Batch: 5160	65 - Inspection Ba	atch			Route: Adho	c Inspection				Date: 29/09/2016
	e 2 x triangular pie slabs point footwa		29/09/2016	Outside number 66 beside See photo	scaffolding	Broken Slab	Internal		Archived	708952
Batch: 5160	64 - Inspection Ba	atch			Route: Adho	c Inspection				Date: 29/09/2016
	e broken and loos ay new slab	e 600 x 600 slab	29/09/2016	Outside Bauhaus bar See photo		Broken Slab	Internal		Archived	708951
Batch: 5160	63 - Inspection Ba	atch			Route: Adho	c Inspection				Date: 29/09/2016
460807 Point fo	otway as required		29/09/2016	At lamppost number 10 See photo		Broken Slab	Internal		Archived	708950
Batch: 5115	52 - Inspection Ba	atch			Route: Week	c: 16 - Area: 18				Date: 24/08/2016
No action	onable defects for	ınd								
Batch: 5046	70 - Inspection Ba	atch			Route: Week	c: 08 - Area: 18				Date: 23/06/2016
459269 Point fo	otway as required	1	23/06/2016	At crossing ointment outsic health club	de nutfield	Broken Slab	Internal		Archived	706264
459268 Point fo	otway as required		23/06/2016	Outside Marcos takeaway		Broken Slab	Internal		Archived	706263
Batch: 4982	27 - Inspection Ba	atch			Route: Week	c: 48 - Area: 18				Date: 20/04/2010
	onable defects for									
	17 - Inspection Ba				Route: Week	c: 40 - Area: 18				Date: 03/03/2010
	onable defects for									
	2,001.00	Asset - Locn.:	7601090/J/00	001 - OPP LP 2		Feature Type:	: RDS Gully		Area: Aberdee	
	30 - Inspection Ba				Route: Adho	c Inspection				Date: 27/05/2016
	onable defects for									
	2,002.00	Asset - Locn.:	7601090/J/00	002 - OPP LP 3		Feature Type:	: RDS Gully		Area: Aberdee	en South
	31 - Inspection Ba				Route: Adho	c Inspection				Date: 27/05/2016
	onable defects for									
	2,003.00		7601090/J/00	003 - OPP Middle of LP 3 an		Feature Type:	: RDS Gully		Area: Aberdee	
Batch: 5017	32 - Inspection Ba	atch			Route: Adho	c Inspection				Date: 27/05/2016
	onable defects for									
	2,004.00	Asset - Locn.: 7	7601090/J/00	004 - OPP LP 5		Feature Type:	: RDS Gully		Area: Aberdee	en South
Batch: 5017	33 - Inspection Ba	atch			Route: Adho	c Inspection				Date: 27/05/2016
No action	onable defects for	ınd								
Asset:	2,005.00	Asset - Locn.: 7	7601090/J/00	005 - Nr LP 5		Feature Type:	: RDS Gully		Area: Aberdee	en South
Batch: 5017	34 - Inspection Ba	atch			Route: Adho	c Inspection				Date: 27/05/2016

No actionable defects found

Effective: 18/02/2016 to 18/02/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Site: JUSTICE MILL LANE (7601090)

Condition	Survey
Condition	-

efect No: Description		Log Date Location	Defect Type	Class. Organisation	Status	Job No.
Asset:	2,006.00	Asset - Locn.: 7601090/J/00006 - LP 6	Feature Type: RDS Gu	lly	Area: Aberdeen	South
Batch: 50	01735 - Inspection	n Batch	Route: Adhoc Inspection			Date: 27/05/2016
No a	ctionable defects	found				
Asset:	2,007.00	Asset - Locn.: 7601090/J/00007 - OPP LP 6	Feature Type: RDS Gu	lly	Area: Aberdeen	South
Batch: 50	01736 - Inspection	n Batch	Route: Adhoc Inspection			Date: 27/05/2016
No a	ctionable defects	found				
Asset:	2,008.00	Asset - Locn.: 7601090/J/00008 - Outside Travel Lodge	Hotel Feature Type: RDS Gu	lly	Area: Aberdeen	South
Batch: 50	01737 - Inspection	n Batch	Route: Adhoc Inspection			Date: 27/05/2016
No a	ctionable defects	found				
Asset:	2,009.00	Asset - Locn.: 7601090/J/00009 - OPP LP 7	Feature Type: RDS Gu	lly	Area: Aberdeen	South
Batch: 501738 - Inspection Batch			Route: Adhoc Inspection			Date: 27/05/2016
No a	ctionable defects	found				
Asset:	2,010.00	Asset - Locn.: 7601090/J/00010 - Nr LP 7	Feature Type: RDS Gu	lly	Area: Aberdeen	South
Batch: 50	01739 - Inspection	n Batch	Route: Adhoc Inspection			Date: 27/05/2016
No a	ctionable defects	found				
Asset:	2,011.00	Asset - Locn.: 7601090/J/00011 - Nr Property No.64	Feature Type: RDS Gu	lly	Area: Aberdeen	South
Batch: 50	01740 - Inspection	n Batch	Route: Adhoc Inspection			Date: 27/05/2016
No a	ctionable defects	found				
Asset:	2,012.00	Asset - Locn.: 7601090/J/00012 - Nr LP 9	Feature Type: RDS Gu	lly	Area: Aberdeen	South
Batch: 50	01741 - Inspection	n Batch	Route: Adhoc Inspection			Date: 27/05/2016
No a	ctionable defects	found				

Maintenance Management

a	u	anagomone						
Job No.	Descripti	ion	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00 Asset - Locn.: S/30/1332 - JUSTICE MILL LANE		Feature Type: RDS Road Section		Area: Aberdeen South			
19042	2.pieces	(Rocking Slab)	0	.RD 2 Day	Job Closed	02/04/2008		
	Refresh p	parking bay lines - JOE 2 2460121	3 whole street	.Routine Maintenance	Order Printed	21/04/2015		RD01/9848
	Asset:	1,001.00	Asset - Locn.: 2 - In front of No 2-Footway	Featu	re Type: RDS Footway		Area: Aberdeer	n South
	lift and re (Rocking	lay rocking 2x2 slab Slab)	outside entrance to the rig night club	.RD 7 Day	Job Closed	11/11/2009		
		roken rocking cut slab dge (Broken Slab)	on corner jcn of bon accord terrace	.RD 7 Day	Job Closed	11/11/2009		
		lay 2 rocking 2x2 slabs o kerb edge (Rocking	•	.RD 7 Day	Job Closed	11/11/2009		
		lay rocking 2x2 slab at steps (Rocking Slab)	5 5	.RD 7 Day	Job Closed	11/11/2009		

Effective: 18/02/2016 to 18/02/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01) Site: JUSTICE MILL LANE (7601090)

Maintenance Management							
Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,004.00	sset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen	South
706263	3 Point footway as required (Broken Slab)	Outside Marcos takeaway	.RD 7 Day	Job Closed	23/06/2016	23/06/2016 Ac	t. RD01/23708
706264	4 Point footway as required (Broken Slab)	At crossing point outside nutfield health club	.RD 7 Day	Job Closed	23/06/2016	23/06/2016 Ac	t. RD01/23707
708950	O Point footway as required (Broken Slab)	At lamppost number 10 See photo	.RD 7 Day	Job Closed	29/09/2016	29/09/2016 Ac	t. RD01/24688
708951	1 Remove broken and loose 600 x 600 slab and relay new slab (Broken Slab)	Outside Bauhaus bar See photo	.RD 7 Day	Job Closed	29/09/2016	29/09/2016 Ac	t. RD01/24687
708952	2 Remove 2 x triangular pieces of loose and rocking slabs point footway (Broken Slab)	Outside number 66 beside scaffolding See photo	.RD 7 Day	Job Closed	29/09/2016	29/09/2016 Ac	t. RD01/24686
	Asset: 1,015.00 A	sset - Locn.: 14 - Franklyns Nightclub to Ho burn	Street-Footway	Feature Type: RDS Footway		Area: Aberdeen	South
51143	3 rocking piece of slab (Rocking Slab)	at.64. SHAPE IN STYLE:	.RD 2 Day	Job Closed	27/05/2008		