

From: [Foi Enquiries](#)
To: [REDACTED]
Subject: EIR-17-1194 - Inspection - Forest Avenue
Date: 06 September 2017 15:15:02
Attachments: [Further Information - Right to Review & Appeal.pdf](#)
[EIR-17-1194 - Forest Avenue Reports_Redacted.pdf](#)

Dear [REDACTED],

Thank you for your information request of 16 August 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

We would be obliged to receive the following information in respect of the Forest Avenue, Aberdeen.

- **Copies of inspection and maintenance records February 2014 until present.**

Please refer to the attached, [EIR-17-1194 – Forest Avenue](#), under ‘Condition Survey’.

- **Details of any works carried out on the road or pavement from February 2014 until present.**

Please refer to the attached, [EIR-17-1194 – Forest Avenue](#), under ‘Maintenance Management’.

- **Details of any complaints made in respect of the condition of the road or pavement from February 2014 until present.**

There are no complaints recorded in respect of the condition of the road or pavement at Forest Avenue, from February 2014 to 16 August 2017.

We follow the Scottish Local Authority Complaints Handling Procedure. Under this procedure, a ‘complaint’ is defined as “an expression of dissatisfaction regarding our actions, or lack of action, or the standard of service provided by us or on our behalf”. There are some topics that cannot be considered as a ‘complaint’, such as a first time request for a service e.g. reporting potholes or damaged pavements for repair.

For more information please visit www.aberdeencity.gov.uk/complaints.

We hope this helps with your request.

Yours sincerely,

Information Compliance Team

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team
Customer Service
Corporate Governance
Aberdeen City Council
3rd Floor North
Business Hub 17
Marischal College
Broad Street
ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk

Tel 03000 200 292

*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.

Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

Effective: 01/02/2014 to 16/08/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: FOREST AVENUE (7601223)

Site: FOREST AVENUE (7601223)

Locality: ABERDEEN, ABERDEEN CITY

Area: Aberdeen South

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	S/29/0990 - FOREST AVENUE	Feature Type:	RDS Road Section		Area: Aberdeen South	
Batch:	535856 - Inspection Batch			Route:	Adhoc Inspection			Date: 17/07/2017
465755	Multihog, worn carriageway, bad dip.	17/07/2017	Forest Ave., 147	Pot Hole	Internal		Uncommitt	717007
Batch:	534996 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/06/2017
	No actionable defects found							
Batch:	534634 - Inspection Batch			Route:	Adhoc Inspection			Date: 22/06/2017
465385	Potholes, on centre of carraigeway, 300 x200 x 50	22/06/2017	No 144	Pot Hole	Internal		Committed	716462
Batch:	531984 - Inspection Batch			Route:	Adhoc Inspection			Date: 15/05/2017
464701	Pothole, at manhole frame edge, on centre of carriageway	15/05/2017	NEAR 148 FOREST AVENUE approx 181	Pot Hole	Internal		Committed	715348
Batch:	531567 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 08/05/2017
	No actionable defects found							
Batch:	530904 - Inspection Batch			Route:	Adhoc Inspection			Date: 27/04/2017
464382	Potholes, 400x300x50	27/04/2017	Heading nth,182, and opps ent to st james place company car park.	Pot Hole	Internal		Committed	714835
Batch:	527835 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 16/03/2017
	No actionable defects found							
Batch:	525847 - Inspection Batch			Route:	Adhoc Inspection			Date: 14/02/2017
462816	Series of potholes, at failed re instatement	14/02/2017	205/207 Forest Avenue - pot holes	Pot Hole	Internal		Committed	712386
Batch:	523950 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/01/2017
	No actionable defects found							
Batch:	520702 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 24/11/2016
	No actionable defects found							
Batch:	516115 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 30/09/2016
460816	Potholes, at service lid area on centre of carriageway and corner of gladstone pl, as per attached photo.	30/09/2016	At jct of harlaw rd	Pot Hole	Internal		Archived	708961
460817	Carriageway erosion, 1500x400x50 and failed re instatement. 1000x600x50. As per attached photo.	30/09/2016	No 166, kerbside	Pot Hole	Internal		Archived	708962
460823	Hotpatch, carriageway erosion. cut out and infill, 2 no areas 500x300x50 on corner, and 2000x1000x50, as per attached photo.	30/09/2016	At jct of forest ave lane	Pot Hole	Internal		Archived	708968
Batch:	508559 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 04/08/2016
	No actionable defects found							
Batch:	503612 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 13/06/2016
	No actionable defects found							

Effective: 01/02/2014 to 16/08/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Site: FOREST AVENUE (7601223)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	S/29/0990 - FOREST AVENUE	Feature Type:	RDS Road Section		Area:	Aberdeen South
Batch:	503081 - Inspection Batch			Route:	Adhoc Inspection			Date: 08/06/2016
458957	Uplift plastic red barrier, at end of road.	08/06/2016	Bushes across from 12 LEARNEY PLACE	Damaged Crash Barrier	Internal		Archived	705748
Batch:	500536 - Inspection Batch			Route:	Adhoc Inspection			Date: 16/05/2016
458427	Pothole, 300x300x50	16/05/2016	96 at centre of carriageway	Pot Hole	Internal		Archived	704928
Batch:	498786 - Inspection Batch			Route:	Adhoc Inspection			Date: 25/04/2016
457774	Potholes, uneven sunken patch of carriageway, 67 mm depth. Level off .	25/04/2016	147	Pot Hole	Internal		Archived	704106
Batch:	498072 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/04/2016
457486	Hotpatch, 2no, 2mtrsx2 mtrsx50	18/04/2016	At 147. Heading north and on centre of carraigeway.	Pot Hole	Internal		Archived	703767
Batch:	497770 - Inspection Batch No actionable defects found			Route:	Week: 47 - Area: 17			Date: 14/04/2016
Batch:	497744 - Inspection Batch			Route:	Adhoc Inspection			Date: 14/04/2016
457393	Blocked gullys, clear.2no	14/04/2016	Heading north at gate of 215, and opps side down from nursery, before lane jct.	Blocked Gully	Internal		Archived	703644
Batch:	497734 - Inspection Batch			Route:	Adhoc Inspection			Date: 14/04/2016
457386	Hotpatch ,potholes, carriageway erosion.	14/04/2016	Jct of learney pl, and and 33 to 37	Pot Hole	Internal		Archived	703637
Batch:	495418 - Inspection Batch			Route:	Adhoc Inspection			Date: 11/03/2016
456473	Pothole, 600x500x50, dished, filled by inspector.	11/03/2016	At jct of devonshire rd	Pot Hole	Internal		Archived	702447
Batch:	495415 - Inspection Batch			Route:	Adhoc Inspection			Date: 11/03/2016
456471	Potholes, 2no 500x500x50	11/03/2016	At edge of rails, at no 110, sunken carriageway, potholed., heading south towards roundabout.	Pot Hole	Internal		Archived	702445
Batch:	493728 - Inspection Batch No actionable defects found			Route:	Week: 39 - Area: 17			Date: 19/02/2016
Batch:	491987 - Inspection Batch			Route:	Adhoc Inspection			Date: 27/01/2016
454978	Pothole, 400x400x50	27/01/2016	Opps no 56	Pot Hole	Internal		Archived	700656
Batch:	491468 - Inspection Batch			Route:	Adhoc Inspection			Date: 20/01/2016
454756	Blocked gully	20/01/2016	At corner of no 14.	Blocked Gully	Internal		Archived	700328
Batch:	489686 - Inspection Batch No actionable defects found			Route:	Week: 31 - Area: 17			Date: 23/12/2015
Batch:	485587 - Inspection Batch			Route:	Adhoc Inspection			Date: 05/11/2015
452978	Pothole, 500x500x50, filled by inspector	05/11/2015	147	Pot Hole	Internal		Archived	198106
Batch:	484925 - Inspection Batch No actionable defects found			Route:	Week: 23 - Area: 17			Date: 30/10/2015
Batch:	481532 - Inspection Batch No actionable defects found			Route:	Week: 15 - Area: 17			Date: 28/08/2015

Effective: 01/02/2014 to 16/08/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Site: FOREST AVENUE (7601223)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	S/29/0990 - FOREST AVENUE	Feature Type:	RDS Road Section		Area:	Aberdeen South
Batch:	473839 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 10/07/2015
	No actionable defects found							
Batch:	469404 - Inspection Batch			Route:	Adhoc Inspection			Date: 19/05/2015
450072	Blocked gully,full of debris.	19/05/2015	199 FOREST AVENUE - DRAINAGE15037 - AB	Blocked Gully	Internal		Archived	193511
Batch:	469193 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 15/05/2015
	No actionable defects found							
Batch:	463480 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/03/2015
	No actionable defects found							
Batch:	461106 - Inspection Batch			Route:	Adhoc Inspection			Date: 03/03/2015
98430	Failed re instatement, 3mtrsx1mtrx50	03/03/2015	207	Sunken Carriageway	Internal		Archived	190953
Batch:	454475 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 22/01/2015
	No actionable defects found							
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							
Asset:	1,001.00	Asset - Locn.:	1 - Verge	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	534997 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/06/2017
	No actionable defects found							
Batch:	531566 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 08/05/2017
	No actionable defects found							
Batch:	527837 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 16/03/2017
	No actionable defects found							
Batch:	523949 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/01/2017
	No actionable defects found							
Batch:	520703 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 24/11/2016
	No actionable defects found							

Effective: 01/02/2014 to 16/08/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: FOREST AVENUE (7601223)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,001.00	Asset - Locn.: 1 - Verge			Feature Type: RDS Verge			Area: Aberdeen South	
Batch: 516155 - Inspection Batch	No actionable defects found			Route: Week: 23 - Area: 17				Date: 30/09/2016
Batch: 508560 - Inspection Batch	No actionable defects found			Route: Week: 15 - Area: 17				Date: 04/08/2016
Batch: 503613 - Inspection Batch	No actionable defects found			Route: Week: 07 - Area: 17				Date: 13/06/2016
Batch: 497771 - Inspection Batch	No actionable defects found			Route: Week: 47 - Area: 17				Date: 14/04/2016
Batch: 493727 - Inspection Batch	No actionable defects found			Route: Week: 39 - Area: 17				Date: 19/02/2016
Batch: 489687 - Inspection Batch	No actionable defects found			Route: Week: 31 - Area: 17				Date: 23/12/2015
Batch: 484926 - Inspection Batch	No actionable defects found			Route: Week: 23 - Area: 17				Date: 30/10/2015
Batch: 481533 - Inspection Batch	No actionable defects found			Route: Week: 15 - Area: 17				Date: 28/08/2015
Batch: 473840 - Inspection Batch	No actionable defects found			Route: Week: 07 - Area: 17				Date: 10/07/2015
Batch: 469194 - Inspection Batch	No actionable defects found			Route: Week: 47 - Area: 17				Date: 15/05/2015
Batch: 463481 - Inspection Batch	No actionable defects found			Route: Week: 39 - Area: 17				Date: 17/03/2015
Batch: 454475 - Inspection Batch	No actionable defects found			Route: Week: 31 - Area: 17				Date: 22/01/2015
Batch: 450763 - Inspection Batch	No actionable defects found			Route: Week: 23 - Area: 17				Date: 28/11/2014
Batch: 450267 - Inspection Batch	No actionable defects found			Route: Week: 15 - Area: 17				Date: 30/09/2014
Batch: 39931 - Inspection Batch	No actionable defects found			Route: Week: 07 - Area: 17				Date: 11/08/2014
Batch: 39483 - Inspection Batch	No actionable defects found			Route: Week: 47 - Area: 17				Date: 10/06/2014
Batch: 39057 - Inspection Batch	No actionable defects found			Route: Week: 39 - Area: 17				Date: 17/04/2014
Batch: 38538 - Inspection Batch	No actionable defects found			Route: Week: 31 - Area: 17				Date: 18/02/2014

Effective: 01/02/2014 to 16/08/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: FOREST AVENUE (7601223)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,002.00	Asset - Locn.: 13 - Queens Lane South to Queens Road-Footway			Feature Type: RDS Footway		Area: Aberdeen South	
Batch: 450763 - Inspection Batch	No actionable defects found			Route: Week: 23 - Area: 17			Date: 28/11/2014	
Batch: 450581 - Inspection Batch				Route: Adhoc Inspection			Date: 05/11/2014	
97090	lift and relay 3 x sunken slabs and lift and renew 1 x broken and sunken 900 x 600 slab	05/11/2014	at school entrance beside visi rail see photo	Broken Slab	Internal		Archived	188249
Batch: 450267 - Inspection Batch	No actionable defects found			Route: Week: 15 - Area: 17			Date: 30/09/2014	
Batch: 39931 - Inspection Batch	No actionable defects found			Route: Week: 07 - Area: 17			Date: 11/08/2014	
Batch: 39483 - Inspection Batch	No actionable defects found			Route: Week: 47 - Area: 17			Date: 10/06/2014	
Batch: 39057 - Inspection Batch	No actionable defects found			Route: Week: 39 - Area: 17			Date: 17/04/2014	
Batch: 38538 - Inspection Batch	No actionable defects found			Route: Week: 31 - Area: 17			Date: 18/02/2014	
Asset:	1,003.00	Asset - Locn.: 11 - Gladstone Place to Queens Lane South-Footway			Feature Type: RDS Footway		Area: Aberdeen South	
Batch: 450763 - Inspection Batch	No actionable defects found			Route: Week: 23 - Area: 17			Date: 28/11/2014	
Batch: 450267 - Inspection Batch	No actionable defects found			Route: Week: 15 - Area: 17			Date: 30/09/2014	
Batch: 39931 - Inspection Batch	No actionable defects found			Route: Week: 07 - Area: 17			Date: 11/08/2014	
Batch: 39483 - Inspection Batch	No actionable defects found			Route: Week: 47 - Area: 17			Date: 10/06/2014	
Batch: 39057 - Inspection Batch	No actionable defects found			Route: Week: 39 - Area: 17			Date: 17/04/2014	
Batch: 38538 - Inspection Batch	No actionable defects found			Route: Week: 31 - Area: 17			Date: 18/02/2014	
Asset:	1,004.00	Asset - Locn.: 1 - Footway			Feature Type: RDS Footway		Area: Aberdeen South	
Batch: 535215 - Inspection Batch				Route: Week: 15 - Area: 17			Date: 06/07/2017	
465552	Hotpatch, remove slabs and bitmac infill ,tree root damage to footpath.	06/07/2017	No 32, 59 , 61 ,67 , 73 ,and 141	Broken Slab	Internal		Committed	716744
465551	Lift and relay slabs, level off and infill gaps, and replace where reqd.	06/07/2017	No 25, 46 , 70 , and 140.	Rocking Slab	Internal		Committed	716743
Batch: 531590 - Inspection Batch				Route: Week: 07 - Area: 17			Date: 08/05/2017	
464596	Rocking slab	08/05/2017	At 182, next to parking ticket booth	Rocking Slab	Internal		Committed	715125

Effective: 01/02/2014 to 16/08/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Site: FOREST AVENUE (7601223)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,004.00	Asset - Locn.: 1 - Footway			Feature Type: RDS Footway			Area: Aberdeen South	
Batch: 527836 - Inspection Batch	No actionable defects found			Route: Week: 47 - Area: 17				Date: 16/03/2017
Batch: 523948 - Inspection Batch	No actionable defects found			Route: Week: 39 - Area: 17				Date: 17/01/2017
Batch: 520704 - Inspection Batch	No actionable defects found			Route: Week: 31 - Area: 17				Date: 24/11/2016
Batch: 516116 - Inspection Batch				Route: Week: 23 - Area: 17				Date: 30/09/2016
460825	Lift and raise slabs at both sides of rainwater channel, , as per attached photo.	30/09/2016	No 43	Rocking Slab	Internal		Archived	708970
460827	Repoint service lid, as per attached photo.	30/09/2016	No 135	Broken Slab	Internal		Archived	708974
460826	Repoint at toby lid, aas per attached photo	30/09/2016	At no 71 service lid	Broken Slab	Internal		Archived	708971
460824	Lift and relay ,sunken slab area.at tree pit. As per attached photo.	30/09/2016	No 25	Rocking Slab	Internal		Archived	708969
460818	Hotpatch, remove raised slabs bitmac infill, as per attached phot.	30/09/2016	154,treepit	Tree Root Damage	Internal		Archived	708963
Batch: 510042 - Inspection Batch				Route: Adhoc Inspection				Date: 12/08/2016
460196	Rocking ,sunken slabs,lift and relay, trip hazard make area safe.	12/08/2016	Outside ent to albyn nursey school	Rocking Slab	Internal		Archived	707702
Batch: 508558 - Inspection Batch	No actionable defects found			Route: Week: 15 - Area: 17				Date: 04/08/2016
Batch: 503615 - Inspection Batch	No actionable defects found			Route: Week: 07 - Area: 17				Date: 13/06/2016
Batch: 500240 - Inspection Batch				Route: Adhoc Inspection				Date: 12/05/2016
458309	Remove concrete slabbed area and infill pavoir blocks, re [REDACTED]	12/05/2016	At corner of wine raks ,as per attached photo	Broken Slab	Internal		Archived	704765
Batch: 497772 - Inspection Batch	No actionable defects found			Route: Week: 47 - Area: 17				Date: 14/04/2016
Batch: 497736 - Inspection Batch				Route: Adhoc Inspection				Date: 14/04/2016
457388	Lift and relay, broken slab.level off.	14/04/2016	No 33	Broken Slab	Internal		Archived	703639
Batch: 497733 - Inspection Batch				Route: Adhoc Inspection				Date: 14/04/2016
457385	Hotpatch infill,Lift and remove slabs .make area safe trip hazard.	14/04/2016	At no ,86, 144 and 150.approx 10 no slabs.	Tree Root Damage	Internal		Archived	703636
Batch: 493726 - Inspection Batch	No actionable defects found			Route: Week: 39 - Area: 17				Date: 19/02/2016
Batch: 492939 - Inspection Batch				Route: Adhoc Inspection				Date: 10/02/2016
455474	Lift and relay rocking slabs, and raised edged.	10/02/2016	Opps albyn school,as per attached photo.	Rocking Slab	Internal		Archived	701279
Batch: 489688 - Inspection Batch	No actionable defects found			Route: Week: 31 - Area: 17				Date: 23/12/2015

Effective: 01/02/2014 to 16/08/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Site: FOREST AVENUE (7601223)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,004.00	Asset - Locn.:	1 - Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	484927 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 30/10/2015
	No actionable defects found							
Batch:	481534 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 28/08/2015
	No actionable defects found							
Batch:	473841 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 10/07/2015
	No actionable defects found							
Batch:	469195 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 15/05/2015
	No actionable defects found							
Batch:	463482 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/03/2015
	No actionable defects found							
Batch:	454475 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 22/01/2015
	No actionable defects found							
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							
Asset:	1,005.00	Asset - Locn.:	12 - Queens Lane South to 3 Queens Gate-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							

Effective: 01/02/2014 to 16/08/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Site: FOREST AVENUE (7601223)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,006.00	Asset - Locn.:	10 - Harlaw Road to Queens Lane South-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							
Asset:	1,007.00	Asset - Locn.:	2 - Great Western Road to lane beside No 6-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							
Asset:	1,008.00	Asset - Locn.:	9 - Devonshire Road to Gladstone Place-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							

Effective: 01/02/2014 to 16/08/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Site: FOREST AVENUE (7601223)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,008.00	Asset - Locn.:	9 - Devonshire Road to Gladstone Place-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							
Asset:	1,009.00	Asset - Locn.:	3 - Lane beside No 6 to Annfield Terrace-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							
Asset:	1,010.00	Asset - Locn.:	8 - Learney Place to Harlaw Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							
Asset:	1,011.00	Asset - Locn.:	1 - Great Western Road to Queens Road-Carriageway	Feature Type:	RDS Carriageway		Area:	Aberdeen South
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							

Effective: 01/02/2014 to 16/08/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Site: FOREST AVENUE (7601223)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,011.00	Asset - Locn.:	1 - Great Western Road to Queens Road-Carriageway	Feature Type:	RDS Carriageway		Area:	Aberdeen South
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							
Asset:	1,012.00	Asset - Locn.:	6 - Cromwell Road to Learney Place-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							
Asset:	1,013.00	Asset - Locn.:	7 - Union Grove to Devonshire Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							
Asset:	1,014.00	Asset - Locn.:	5 - Annfield Terrace to Union Grove-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							

Effective: 01/02/2014 to 16/08/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Site: FOREST AVENUE (7601223)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,014.00	Asset - Locn.:	5 - Annfield Terrace to Union Grove-Footway	Feature Type:	RDS Footway		Area: Aberdeen South	
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							
Asset:	1,015.00	Asset - Locn.:	4 - Forest Avenue Lane to Cromwell Road-Footway	Feature Type:	RDS Footway		Area: Aberdeen South	
Batch:	450763 - Inspection Batch			Route:	Week: 23 - Area: 17			Date: 28/11/2014
	No actionable defects found							
Batch:	450267 - Inspection Batch			Route:	Week: 15 - Area: 17			Date: 30/09/2014
	No actionable defects found							
Batch:	39931 - Inspection Batch			Route:	Week: 07 - Area: 17			Date: 11/08/2014
	No actionable defects found							
Batch:	39483 - Inspection Batch			Route:	Week: 47 - Area: 17			Date: 10/06/2014
	No actionable defects found							
Batch:	39057 - Inspection Batch			Route:	Week: 39 - Area: 17			Date: 17/04/2014
	No actionable defects found							
Batch:	38538 - Inspection Batch			Route:	Week: 31 - Area: 17			Date: 18/02/2014
	No actionable defects found							
Asset:	2,001.00	Asset - Locn.:	7601223/J/00001 - Forest Avenue	Feature Type:	RDS Gully		Area: Aberdeen South	
Batch:	506372 - Inspection Batch			Route:	Adhoc Inspection			Date: 21/07/2016
	No actionable defects found							
Asset:	2,002.00	Asset - Locn.:	7601223/J/00002 - Forest Avenue	Feature Type:	RDS Gully		Area: Aberdeen South	
Batch:	506373 - Inspection Batch			Route:	Adhoc Inspection			Date: 21/07/2016
	No actionable defects found							
Asset:	2,003.00	Asset - Locn.:	7601223/J/00003 - Forest Avenue	Feature Type:	RDS Gully		Area: Aberdeen South	
Batch:	506374 - Inspection Batch			Route:	Adhoc Inspection			Date: 21/07/2016
	No actionable defects found							
Asset:	2,004.00	Asset - Locn.:	7601223/J/00004 - Forest Avenue	Feature Type:	RDS Gully		Area: Aberdeen South	
Batch:	506375 - Inspection Batch			Route:	Adhoc Inspection			Date: 21/07/2016
	No actionable defects found							
Asset:	2,005.00	Asset - Locn.:	7601223/J/00005 - Forest Avenue	Feature Type:	RDS Gully		Area: Aberdeen South	
Batch:	506376 - Inspection Batch			Route:	Adhoc Inspection			Date: 21/07/2016
	No actionable defects found							

Effective: 01/02/2014 to 16/08/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: FOREST AVENUE (7601223)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,006.00	Asset - Locn.:	7601223/J/00006 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506377 - Inspection Batch			Route:	Adhoc Inspection			Date: 21/07/2016
	No actionable defects found							
Asset:	2,007.00	Asset - Locn.:	7601223/J/00007 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506378 - Inspection Batch			Route:	Adhoc Inspection			Date: 21/07/2016
	No actionable defects found							
Asset:	2,008.00	Asset - Locn.:	7601223/J/00008 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506379 - Inspection Batch			Route:	Adhoc Inspection			Date: 21/07/2016
	No actionable defects found							
Asset:	2,009.00	Asset - Locn.:	7601223/J/00009 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506380 - Inspection Batch			Route:	Adhoc Inspection			Date: 21/07/2016
	No actionable defects found							
Asset:	2,010.00	Asset - Locn.:	7601223/J/00010 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506765 - Inspection Batch			Route:	Adhoc Inspection			Date: 25/07/2016
	No actionable defects found							
Asset:	2,011.00	Asset - Locn.:	7601223/J/00011 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506766 - Inspection Batch			Route:	Adhoc Inspection			Date: 25/07/2016
	No actionable defects found							
Asset:	2,012.00	Asset - Locn.:	7601223/J/00012 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506767 - Inspection Batch			Route:	Adhoc Inspection			Date: 25/07/2016
	No actionable defects found							
Asset:	2,013.00	Asset - Locn.:	7601223/J/00013 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506768 - Inspection Batch			Route:	Adhoc Inspection			Date: 25/07/2016
	No actionable defects found							
Asset:	2,014.00	Asset - Locn.:	7601223/J/00014 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506769 - Inspection Batch			Route:	Adhoc Inspection			Date: 25/07/2016
	No actionable defects found							
Asset:	2,015.00	Asset - Locn.:	7601223/J/00015 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506770 - Inspection Batch			Route:	Adhoc Inspection			Date: 25/07/2016
	No actionable defects found							
Asset:	2,016.00	Asset - Locn.:	7601223/J/00016 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506771 - Inspection Batch			Route:	Adhoc Inspection			Date: 25/07/2016
	No actionable defects found							
Asset:	2,017.00	Asset - Locn.:	7601223/J/00016 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506772 - Inspection Batch			Route:	Adhoc Inspection			Date: 25/07/2016
	No actionable defects found							

Effective: 01/02/2014 to 16/08/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Site: FOREST AVENUE (7601223)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,018.00	Asset - Locn.:	7601223/J/00017 - Forest Avenue	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	506773 - Inspection Batch			Route:	Adhoc Inspection			Date: 25/07/2016
	No actionable defects found							
Asset:	100,257.00	Asset - Locn.:	9051045337 - 207 FOREST AVENUE, AB15 4UL	Feature Type:	W - Domestic Waste Property		Area:	Aberdeen Central
Batch:	525847 - Inspection Batch			Route:	Adhoc Inspection			Date: 14/02/2017
	No actionable defects found							

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1,000.00	Asset - Locn.:	S/29/0990 - FOREST AVENUE	Feature Type:	RDS Road Section	Area:	Aberdeen South
173396	jet patch series of holes and wearing coat erosion. (Pot Hole)	from union grove to queen street.	.RD 28 Day	Job Closed	15/03/2013	18/06/2014	Act. RD01/6523
181067	lift and relay slabs,approx,6no,make area safe,trip hazard due to tree roots.	at 183 ,as per attached photo.	.RD 7 Day	Job Closed	06/02/2014	10/02/2014	Act. RD01/7373
181434	blocked gullys,clean and jet. 2no	215,,110,	.RD 7 Day	Job Closed	14/02/2014	21/02/2014	Act. RD01/7444
181438	potholes,500x300x55. 2no	147 on bay line,and at kerbside 154.	.RD 2 Day	Job Closed	14/02/2014	17/02/2014	Act. RD01/7429
181506	remove slabs ,make area safe,approx 5no replace with bitmac ,as per instruction	at corner of jct annfield terr.as per attached photo.	.RD 7 Day	Job Cancelled	17/02/2014	24/02/2014	Act. RD01/7430
181508	lift and relay,sunken cassies.area 3ft .as per attached photo.	at kerbside no 30 around gully frame.	.RD 7 Day	Job Closed	17/02/2014	24/02/2014	Act. RD01/7465
181756	remove slabs ,make area safe,approx 5no replace with bitmac ,as per instruction	at corner of jct annfield terr.as per attached photo.	.RD 14 Day	Job Closed	24/02/2014	03/03/2014	Act. RD01/7467
181941	lift and relay ,slab,and infill treepit with bitmac.,make area safe as people have tripped up on this item corner.	outside flower shop ,eden.as per attached photo.	.RD 7 Day	Job Closed	03/03/2014	10/03/2014	Act. RD01/7522
183004	depression in carriageway, 500x500x55, filled by inspector	50yds from roundabout north next to manhole lid	.RD 2 Day	Job Closed	09/04/2014	09/04/2014	Act.
183468	potholes,300x300x55 approx 6no	at jct with devonshire rd,and jct with learney place.	.RD 2 Day	Job Closed	02/05/2014	06/05/2014	Act. RD01/7866
184666	re point, infill missing cement at crossing point at nursery corner.	corner of queens lane, as per attached photo.	.RD 7 Day	Job Closed	10/06/2014	11/06/2014	Act. RD01/8138
184703	pothole,rutts, 2no 500x300x55. kerbside.gutter	heading south,154,and 126.	.RD 7 Day	Job Closed	11/06/2014	12/06/2014	Act. RD01/8141
185038	Find and Fix 2 potholes filled by Response Squad	o/s 189	.Routine Maintenance	Job Closed	23/06/2014	22/06/2014	Act.
186806	Find and Fix 14 potholes filled by	unknown	.Routine Maintenance	Job Closed	28/08/2014	27/08/2014	Act.
187545	lift and relay slabs, 4no.,make area safe.	195, at corner of harlaw. as per attached photo.	.RD 28 Day	Job Closed	01/10/2014	05/10/2014	Act. RD01/8740

Effective: 01/02/2014 to 16/08/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: FOREST AVENUE (7601223)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: S/29/0990 - FOREST AVENUE		Feature Type: RDS Road Section		Area: Aberdeen South	
187546	lift and relay slabs, 4no make area safe.	183, as per attached photo.	.RD 28 Day	Job Closed	01/10/2014	05/10/2014	Act. RD01/8740
187547	lift and relay slabs, 7no, make area safe.	141, as per attached photo.	.RD 28 Day	Job Closed	01/10/2014	04/10/2014	Act. RD01/8740
187553	lift and relay slabs, and remove slabs infill bitmac..7no in total items.	139, as per attached photo.	.RD 28 Day	Job Closed	01/10/2014	04/10/2014	Act. RD01/8740
187555	lift and relay slab. make area safe.	99, as per attached photo.	.RD 28 Day	Job Closed	01/10/2014	05/10/2014	Act. RD01/8740
187556	lift and relay slabs, 4no make area safe.	89, as per attached photo.	.RD 28 Day	Job Closed	01/10/2014	05/10/2014	Act. RD01/8740
187557	remove slabs, increase pit area infill with bitmac, make area safe. 3no.	81, as per attached photo.	.RD 28 Day	Job Closed	01/10/2014	03/11/2014	Act. RD01/8740
187558	lift and infill slabs, 5no, make area safe.	77, as per attached photo.	.RD 28 Day	Job Closed	01/10/2014	03/11/2014	Act. RD01/8740
187559	lift and relay slabs, 6no make area safe.	23, as per attached photo.	.RD 28 Day	Job Closed	01/10/2014	10/10/2014	Act. RD01/8740
187562	lift and replace infill, 6no slabs with bitmac, and relay 3no.	19, as per attached photo.	.RD 28 Day	Job Closed	01/10/2014	10/10/2014	Act. RD01/8740
187565	lift and bitmac infill slabs, make area safe.	3no. as per attached photo.	.RD 28 Day	Job Closed	01/10/2014	05/10/2014	Act. RD01/8740
187566	lift infill slabs, and relay slabs, 5no in total. make area safe.	no 9, as per attached photo.	.RD 28 Day	Job Closed	01/10/2014	05/10/2014	Act. RD01/8740
187663	Find and Fix 9 potholes filled by [REDACTED]	jctn beaconsfield rd, l/p 15, o/s 155-159	.Routine Maintenance	Job Closed	06/10/2014	05/10/2014	Act.
187860	sunken slabs, 12no lift and relay, make area safe. at rian water channels.	146 and 150., raised rainwater channels.	.RD 7 Day	Job Closed	14/10/2014	16/10/2014	Act. RD01/8816
188096	clean and jet 5 gullies	3 at jctn with Great Western Road and 2 at jctn with Forest Avenue Lane as attached plan	.RD 7 Day	Job Closed	28/10/2014	30/10/2014	Act. RD01/8860
188618	parking bays refresh white lining	from cromwell rd roundabout to queens rd jct.	.RD 28 Day	Job Closed	19/11/2014	21/11/2016	Act. RD01/9105
190953	Failed re instatement, 3mtrs x 1mtrs x 50 (Sunken Carriageway)	207	.RD 7 Day	Job Closed	03/03/2015	05/03/2015	Act. RD01/9547
191404	lift and bitmac infill 1no slab	193, as per attached photo.	.RD 7 Day	Job Closed	17/03/2015	17/03/2015	Act. RD01/9622
191405	remove slab and bitmac infill,	at tree pit, 158, as per attached photo	.RD 7 Day	Job Closed	17/03/2015	17/03/2015	Act. RD01/9622
191406	remove 3no slabs, bitmac infill make area safe.	154, tree pit, as per attached photo.	.RD 7 Day	Job Closed	17/03/2015	17/03/2015	Act. RD01/9622
191407	remove slab, bitmac infill, make area safe.	120, tree pit, as per attached photo.	.RD 7 Day	Job Closed	17/03/2015	17/03/2015	Act. RD01/9622
192246	Find and Fix 22 potholes filled by [REDACTED]	whole length	.Routine Maintenance	Job Closed	16/04/2015	12/04/2015	Act.

Effective: 01/02/2014 to 16/08/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: FOREST AVENUE (7601223)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: S/29/0990 - FOREST AVENUE		Feature Type: RDS Road Section		Area: Aberdeen South	
192567	pothole, 500x500x40mm. filled by inspector.	at crossing point next to nargile.	.RD 2 Day	Job Closed	21/04/2015	21/04/2015	Act.
192818	rainwater channel, lift and reset cut in final third if needed to lower height.	at tree pit .as per attached photo.	.RD 14 Day	Job Closed	29/04/2015	01/06/2015	Act. RD01/20106
193511	Blocked gully, full of debris. (Blocked Gully)	199 FOREST AVENUE	.RD 7 Day	Job Closed	19/05/2015	20/05/2015	Act. RD01/20048
194632	rocking slab, sunken. lift and relay	at 209, directly on line of ent as per attached photo.	.RD 7 Day	Job Closed	24/06/2015	26/06/2015	Act. RD01/20324
194633	infill tree pit, earth or compost .	150	.RD 14 Day	Job Closed	24/06/2015	15/07/2015	Act. RD01/20348
195209	clean and jet gully - flooding 07/07/15	o/s 39-41	.RD 7 Day	Job Closed	16/07/2015	09/07/2015	Act. RD01/21085
195223	clean and jet 3 gullies - flooding 07/07/15	jctn Great Western Rd o/s 320/322 and 336/338	.Routine Maintenance	Job Closed	16/07/2015	13/07/2015	Act.
196450	potholes, 500x300x50. 2no.	heading north at kerbside 189 and 191.	.RD 7 Day	Job Closed	27/08/2015	28/08/2015	Act. RD01/20715
196466	lift and relay , 2no slabs, replace 1no if needed.	no 20, as per attached photo.	.RD 14 Day	Job Closed	28/08/2015	31/08/2015	Act. RD01/20720
196467	sunken slabs, lift and relay.to level off rainwater channel.	93 as per attached photo.	.RD 14 Day	Job Closed	28/08/2015	01/09/2015	Act. RD01/20720
196468	raised uneven slabs, lift and relay.approx 12no.	167, as per attached photo.	.RD 14 Day	Job Closed	28/08/2015	01/09/2015	Act. RD01/20720
196469	raised slabs, lift and relay, 9no, and remove one leaning on tree.	151, as per attached photo.	.RD 14 Day	Job Closed	28/08/2015	02/09/2015	Act. RD01/20720
196470	hotpatch remove slabs, approx 8no	155,as per attached photo.	.RD 14 Day	Job Closed	28/08/2015	01/09/2015	Act. RD01/20720
196471	hotpatch, tree pit infill.	81, as per attached photo	.RD 14 Day	Job Closed	28/08/2015	03/09/2015	Act. RD01/20720
196472	hotpatch infill lift remove slabs, approx 10. no	171, as per attached photo.	.RD 14 Day	Job Closed	28/08/2015	03/09/2015	Act. RD01/20720
196473	hotpatch, remove slab infill. 1no.	87, as per attached photo.	.RD 14 Day	Job Closed	28/08/2015	03/09/2015	Act. RD01/20720
196474	hotpatch, remove slabs infill, approx 5no.	51. as per attached photo.	.RD 14 Day	Job Closed	28/08/2015	04/09/2015	Act. RD01/20720
196475	hotpatch, remove slabs, infill. 5no slabs.	58, as per attached photo.	.RD 14 Day	Job Closed	28/08/2015	03/09/2015	Act. RD01/20720
196476	hotpatch, remove slabs, infill, 6no.	48, as per attached photo.	.RD 14 Day	Job Closed	28/08/2015	04/09/2015	Act. RD01/20720
196477	hotpatch, remove slabs, infill, 4no.	44, as per attached photo.	.RD 14 Day	Job Closed	28/08/2015	04/09/2015	Act. RD01/20720
196886	slabs,2no raised ,lift and bitmac infill, hotpatch re tree roots .	71, as per attached photo.	.RD 14 Day	Job Closed	16/09/2015	25/09/2015	Act. RD01/20850
196941	blocked gully, clean.	heading southbound as you approach rounabout with nargile restraint on left hand side, last gully, at railing fence.	.RD 7 Day	Job Closed	18/09/2015	22/09/2015	Act. RD01/20887
197527	various gullies checked and cleared		.Routine Maintenance	Job Closed	14/10/2015	07/10/2015	Act.

Effective: 01/02/2014 to 16/08/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: FOREST AVENUE (7601223)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: S/29/0990 - FOREST AVENUE		Feature Type: RDS Road Section		Area: Aberdeen South	
198106	Pothole, 500x500x50, filled by inspector (Pot Hole)	147	.RD 2 Day	Job Closed	05/11/2015	05/11/2015	Act. RD01/24116
199112	Find and Fix 1 pothole	o/s 181	.Routine Maintenance	Job Closed	09/12/2015	06/12/2015	Act.
700328	Blocked gully (Blocked Gully)	At corner of no 14.	.RD 7 Day	Job Closed	20/01/2016	26/01/2016	Act. RD01/21936
700656	Pothole, 400x400x50 (Pot Hole)	Opps no 56	.RD 7 Day	Job Closed	27/01/2016	29/01/2016	Act. RD01/22000
702445	Potholes, 2no 500x500x50 (Pot Hole)	At edge of rails, at no 110, sunken carriageway, potholed., heading south towards roundabout.	.RD 2 Day	Job Closed	11/03/2016	11/03/2016	Act. RD01/22437
702447	Pothole, 600x500x50, dished, filled by inspector. (Pot Hole)	At jct of devonshire rd	.RD 7 Day	Job Closed	11/03/2016	11/03/2016	Act. RD01/22716
703637	Hotpatch ,potholes, carriageway erosion. (Pot Hole)	Jct of learney pl, and and 33 to 37	.RD 14 Day	Job Closed	14/04/2016	26/04/2016	Act. RD01/22837
703644	Blocked gullies, clear.2no (Blocked Gully)	Heading north at gate of 215, and opps side down from nursery, before lane jct.	.RD 7 Day	Job Closed	14/04/2016	15/04/2016	Act. RD01/22850
703767	Hotpatch, 2no, 2mtrsx2 mtrsx50 (Pot Hole)	At 147. Heading north and on centre of carraigeway.	.RD 14 Day	Job Closed	18/04/2016	27/04/2016	Act. RD01/22883
704106	Potholes, uneven sunken patch of carriageway, 67 mm depth. Level off . (Pot Hole)	147	.RD 2 Day	Job Closed	25/04/2016	25/04/2016	Act. RD01/22994
704753			.Routine Maintenance	Job Cancelled	12/05/2016	12/05/2016	Act.
704928	Pothole, 300x300x50 (Pot Hole)	96 at centre of carriageway	.RD 7 Day	Job Closed	16/05/2016	16/05/2016	Act. RD01/23228
705153	pothole, 400x400x50, cluster.	92, heading south.	.RD 7 Day	Job Closed	20/05/2016	21/05/2016	Act. RD01/23300
705748	Uplift plasric red barrier, at end of road. (Damaged Crash Barrier)	Bushes across from 12 LEARNEY PLACE	.RD 7 Day	Job Closed	08/06/2016	09/06/2016	Act. RD01/23516
705834	pothole, at kerbside, 400x900x50.	heading south 178.as per attached photo.	.RD 7 Day	Job Closed	10/06/2016	11/06/2016	Act. RD01/23554
705836	hotpatch ,carriageway erosion,	no 33, and 39.as per attached photo.	.RD 14 Day	Job Closed	10/06/2016	28/06/2016	Act. RD01/23555
705838	blocked gully, clean.	98, heading south. just as you pass roundabout.	.RD 7 Day	Job Closed	10/06/2016	16/06/2016	Act. RD01/23558
705840	hotpatch, tree pit areas, make safe. remove slabs.	15, 59, and 158. approx 8 sq mtrs	.RD 28 Day	Job Closed	10/06/2016	28/06/2016	Act. RD01/23557
706128	Find and Fix 4 pothole filled by [REDACTED]	jctn devonshire road	.Routine Maintenance	Job Closed	20/06/2016	18/06/2016	Act.
706428			.Routine Maintenance	Job Cancelled	30/06/2016	30/06/2016	Act.
706432	Find and Fix 6 potholes filled by [REDACTED]	jctn queens lane	.Routine Maintenance	Job Closed	30/06/2016	29/06/2016	Act.
707383	blocked gully, clean.	at roundabout heading south at corner of nargile cafe	.RD 7 Day	Job Closed	03/08/2016	18/08/2016	Act. RD01/24154
707384	pothole, 300x600x50.	at kerbside of 124 to 126.	.RD 7 Day	Job Closed	03/08/2016	05/08/2016	Act. RD01/24149
708961	Potholes, at service lid area on centre of carriageway and corner of gladstone pl, as per attached photo. (Pot Hole)	At jct of harlaw rd	.RD 7 Day	Job Closed	30/09/2016	30/09/2016	Act. RD01/24705

Effective: 01/02/2014 to 16/08/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: FOREST AVENUE (7601223)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		Asset - Locn.: S/29/0990 - FOREST AVENUE		Feature Type: RDS Road Section		Area: Aberdeen South	
708962	Carriageway erosion, 1500x400x50 and failed re instatement. 1000x600x50. As per attached photo. (Pot Hole)	No 166, kerbside	.RD 7 Day	Job Closed	30/09/2016	30/09/2016	Act. RD01/24704
708968	Hotpatch, carriageway erosion. cut out and infill, 2 no areas 500x300x50 on corner, and 2000x1000x50. as per attached photo. (Pot Hole)	At jct of forest ave lane	.RD 14 Day	Job Closed	30/09/2016	19/10/2016	Act. RD01/24702
709227	hotpatch, carriageway erosion, 10mtrs x 300mm x 50.	at jct of learney place. as per attached photo.	.RD 14 Day	Job Closed	12/10/2016	01/11/2016	Act. RD01/24884
710263	pothole, sunken carriageway around service li, 400x500x50. filled by inspector.	at jct of annfield terr	.RD Emergency	Job Closed	29/11/2016	29/11/2016	Act.
712386	Series of potholes, at failed re instatement (Pot Hole)	205/207 Forest Avenue - pot holes	.RD 7 Day	Contractor Completed	14/02/2017	18/02/2017	Act. RD01/26143
714835	Potholes, 400x300x50 (Pot Hole)	Heading nth, 182, and opps ent to st james place company car park.	.RD 7 Day	Contractor Completed	27/04/2017	27/04/2017	Act. RD01/27095
715348	Pothole, at manhole frame edge, on centre of carriageway (Pot Hole)	NEAR 148 FOREST AVENUE approx 181	.RD 7 Day	Contractor Completed	15/05/2017	16/05/2017	Act. RD01/27309
715921	pothole, 400x300x50.	at no 3, approx 20 mtrs from jct gwr. heading north.	.RD 7 Day	Contractor Completed	05/06/2017	06/06/2017	Act. RD01/27603
716462	Potholes, on centre of carraigeway, 300 x 200 x 50 (Pot Hole)	No 144	.RD 7 Day	Contractor Completed	22/06/2017	24/06/2017	Act. RD01/27821
717007	Multihog, worn carriageway, bad dip. (Pot Hole)	Forest Ave., 147	.RD Planned Works	Job Raised	17/07/2017	17/07/2022	Est.
Asset: 1,002.00		Asset - Locn.: 13 - Queens Lane South to Queens Road-Footway		Feature Type: RDS Footway		Area: Aberdeen South	
188249	lift and relay 3 x sunken slabs and lift and renew 1 x broken and see photo sunken 900 x 600 slab (Broken Slab)	at school entrance beside visi rail	.RD 7 Day	Job Closed	05/11/2014	12/11/2014	Act. RD01/8918
Asset: 1,004.00		Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen South	
192463	Lift slabs and replace with bitmac	o/s 83 as attached photo	.RD 28 Day	Job Closed	20/04/2015	25/04/2015	Act. RD01/9839
192464	Lift slabs and replace with bitmac	o/s 81 as attached photo	.RD 28 Day	Job Closed	20/04/2015	25/04/2015	Act. RD01/9839
701279	Lift and relay rocking slabs, and raised edged. (Rocking Slab)	Opps a byn school, as per attached photo.	.RD 7 Day	Job Closed	10/02/2016	23/02/2016	Act. RD01/22143
703636	Hotpatch infill, Lift and remove slabs. make area safe trip hazard. (Tree Root Damage)	At no ,86, 144 and 150. approx 10 no slabs.	.RD 14 Day	Job Closed	14/04/2016	23/04/2016	Act. RD01/22828
703639	Lift and relay, broken slab. level off. (Broken Slab)	No 33	.RD 7 Day	Job Closed	14/04/2016	17/04/2016	Act. RD01/22835

Effective: 01/02/2014 to 16/08/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: FOREST AVENUE (7601223)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1,004.00	Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen South	
704765	Remove concrete slabbed area and infill pavor blocks, re bill wilson. (Broken Slab) JOB NUMBER 3080032	At corner of wine raks ,as per attached photo	.RD 28 Day	Job Closed	12/05/2016	29/05/2016 Act.	RD01/23202
705833	lift and relay slabs,and grout in where reqd,	at 42,28 and 145.as per attached photos.	.RD 7 Day	Job Closed	10/06/2016	10/06/2016 Act.	RD01/23551
707389	hotpatch, tree root damaged footpath, make safe. remove approx 10 no slabs, 9 sq mtrs	at no 163 on corner, as per attached photo.	.RD 28 Day	Job Closed	03/08/2016	12/08/2016 Act.	RD01/24152
707702	Rocking ,sunken slabs,lift and relay, trip hazard make area safe. (Rocking Slab)	Outside ent to albyn nurseay school	.RD 7 Day	Job Closed	12/08/2016	21/08/2016 Act.	RD01/24209
708963	Hotpatch, remove raised slabs bitmac infill, as per attached phot. (Tree Root Damage)	154,treetpit	.RD 14 Day	Job Closed	30/09/2016	16/11/2016 Act.	RD01/24703
708969	Lift and relay ,sunken slab area.at tree pit. As per attached photo. (Rocking Slab)	No 25	.RD 14 Day	Job Closed	30/09/2016	01/10/2016 Act.	RD01/24701
708970	Lift and raise slabs at both sides of rainwater channel, , as per attached photo. (Rocking Slab)	No 43	.RD 14 Day	Job Closed	30/09/2016	01/10/2016 Act.	RD01/24700
708971	Repoint at toby lid, aas per attached photo (Broken Slab)	At no 71 service lid	.RD 7 Day	Job Closed	30/09/2016	01/10/2016 Act.	RD01/24699
708974	Repoint service lid, as per attached photo. (Broken Slab)	No 135	.RD 7 Day	Job Closed	30/09/2016	01/10/2016 Act.	RD01/24698
708992	repoint service lid areas.	at st james,128,118,traffic crossing next to union grove,forest ave jct annfield rain water channel.as per attached photos.	.RD 7 Day	Job Closed	30/09/2016	30/09/2016 Act.	RD01/24713
708993	rocking raised slab,lift and relay.	38	.RD 7 Day	Job Closed	30/09/2016	01/10/2016 Act.	RD01/24712
708994	remove slabs bitmac infill create tree pit	jct of devonshire rd, as per attached photo.	.RD 14 Day	Job Closed	30/09/2016	16/11/2016 Act.	RD01/24714
708995	hotpatch ,tree pit area infill.	83,as per attached photo.	.RD 28 Day	Job Closed	30/09/2016	02/11/2016 Act.	RD01/24728
709007	lift and relay slabs,sunken areas level off.	no 34,52,60,76,and further up towards albyn school wall, as per attached photos.	.RD 14 Day	Job Closed	03/10/2016	04/10/2016 Act.	RD01/24723
710195	sunken slabs, lift and relay, level off.	128, as per attached photo.	.RD 7 Day	Job Closed	24/11/2016	27/11/2016 Act.	RD01/25299
710236	sunken slabs lift and relay, kerb edges showing leaving a trip hazard ,make safe.	at corner of queens lane south.as per attached photo.	.RD 7 Day	Contractor Completed	29/11/2016	12/12/2016 Act.	RD01/25324
710565	Lift and relay slabs also install two city centre bollards as per [REDACTED]	o/s 14 as attached photo	.RD 14 Day	Contractor Completed	14/12/2016	04/01/2017 Act.	RD01/25493
710566	Lift slabs and relay with bitmac as [REDACTED]	o/s 12 as marked on attached photo	.RD 14 Day	Contractor Completed	14/12/2016	11/01/2017 Act.	RD01/25494

Effective: 01/02/2014 to 16/08/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: FOREST AVENUE (7601223)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,004.00		Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen South	
711424	clean out joints and mortat to remove tripping hazard as per [REDACTED]	14	.RD 7 Day	Contractor Completed	19/01/2017	19/01/2017 Act.	RD01/25794
715125	Rocking slab (Rocking Slab)	At 182, next to parking ticket booth	.RD 2 Day	Contractor Completed	08/05/2017	09/05/2017 Act.	RD01/27214
715922	sunken slabs 2no ,lift and relay infill gaps.	on east side, at kerbside of no 60.	.RD 7 Day	Contractor Completed	05/06/2017	12/06/2017 Act.	RD01/27638
715962	lift and relay slabs, sunken.approx 5no	62 and 68, as per attached photo.	.RD 7 Day	Contractor Completed	07/06/2017	12/06/2017 Act.	RD01/27620
716743	Lift and relay slabs, level off and infill gaps, and replace where reqd. (Rocking Slab)	No 25, 46 , 70 , and 140.	.RD 14 Day	Contractor Completed	06/07/2017	09/07/2017 Act.	RD01/27933
716744	Hotpatch, remove slabs and bitmac infill ,tree root damage to footpath. (Broken Slab)	No 32, 59 , 61 ,67 , 73 ,and 141	.RD 28 Day	Contractor Completed	06/07/2017	17/07/2017 Act.	RD01/27931
717035	Hotpatch, remove slabs and bitmac infill ,tree root damage to footpath. (Broken Slab)	61	.RD 28 Day	Contractor Completed	18/07/2017	15/08/2017 Act.	RD01/28064
Asset: 1,010.00		Asset - Locn.: 8 - Learney Place to Harlaw Road-Footway		Feature Type: RDS Footway		Area: Aberdeen South	
153395	remove 8- 2x2 slabs and 2 - 3x2 slab and make safe using bitmac (Tree Root Damage)	outside number 189 - DUPLICATE	.Routine Maintenance	Job Cancelled	18/10/2010		
153396	remove 5 -2x2 slabs and make safe using bitmac (Tree Root Damage)	outside number 183 - DUPLICATE	.RD 7 Day	Job Cancelled	18/10/2010		
153397	remove 3x2 slab relay bitmac (Tree Root Damage)	outside number 189 at rainwater channel - DUPLICATE	.RD 7 Day	Job Cancelled	18/10/2010		
Asset: 1,011.00		Asset - Locn.: 1 - Great Western Road to Queens Road-Carriageway		Feature Type: RDS Carriageway		Area: Aberdeen South	
162340	refresh all junction lines and markings (Road Marking)	at Harlaw rd junction	.RD 7 Day	Job Closed	05/11/2011	14/06/2014 Act.	RD01/3757
162341	refresh all junction lines and markings (Road Marking)	at Devonshire rd junction	.RD 7 Day	Job Closed	05/11/2011	14/06/2014 Act.	RD01/3757
Asset: 100,053.00		Asset - Locn.: 9051043271 - [REDACTED] FOREST AVENUE,		Feature Type: W - Domestic Waste Property		Area: Aberdeen Central	
125284	Waste Other - please deliver copy of calendar and food caddy asap-dh (Enquiry 117707)	[REDACTED]	.Routine Maintenance	Job Cancelled	02/06/2010		
Asset: 100,118.00		Asset - Locn.: 9051043245 - [REDACTED] FOREST AVENUE, AB15 4TL		Feature Type: W - Domestic Waste Property		Area: Aberdeen Central	
124584	Waste Other - WHITE BAG -SD (Enquiry 115226)	[REDACTED] FOREST AVENUE	.Routine Maintenance	Job Cancelled	28/05/2010		

Effective: 01/02/2014 to 16/08/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: FOREST AVENUE (7601223)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 100,146.00 Asset - Locn.: 9051043255 - [REDACTED] FOREST AVENUE, AB15 4TL Feature Type: W - Domestic Waste Property Area: Aberdeen Central							
123061	Waste Other - PLEASE SEND OUT BROWN BIN + FOOD CADDY + FOOD BAGS + WHOTE BAG + BLACK BOX -SD (Enquiry 112355)	[REDACTED] FOREST AVENUE	.Routine Maintenance	Job Cancelled	25/05/2010		
Asset: 100,194.00 Asset - Locn.: 9051045363 - [REDACTED] FOREST AVENUE, AB15 4UP Feature Type: W - Domestic Waste Property Area: Aberdeen Central							
10096135	Waste - Aditonal Bin Payment - Payment successful for additional bin, Ref 1040310, receipt ABWS00738012 (Enquiry 683797)	[REDACTED] Forest Avenue - ST	.Routine Maintenance	Job Raised	29/12/2016		
Asset: 100,199.00 Asset - Locn.: 9051045368 - [REDACTED] FOREST AVENUE, AB15 4UP Feature Type: W - Domestic Waste Property Area: Aberdeen Central							
124031	Waste Other - MORE BIO LINERS-JD (Enquiry 113152)	[REDACTED] FOREST AVENUE	.Routine Maintenance	Job Cancelled	27/05/2010		
Asset: 100,210.00 Asset - Locn.: 9051045324 - 1 [REDACTED] FOREST AVENUE, AB15 4UJ Feature Type: W - Domestic Waste Property Area: Aberdeen Central							
123869	Waste Other - MORE BIO LINERS PLEASE (Enquiry 113079)	[REDACTED] FOREST AVENUE - AW	.Routine Maintenance	Job Cancelled	27/05/2010		
Asset: 100,246.00 Asset - Locn.: 9051045381 - [REDACTED] FOREST AVENUE, AB15 4UU Feature Type: W - Domestic Waste Property Area: Aberdeen Central							
10094029	Missed Bin - Hi, I must have been a touch to late this morning as I noticed my black bins were still full. Is there an option to collect them still? Apologies! [REDACTED]	[REDACTED] forest avenue Aberdeen AB15 4UU	.Routine Maintenance	Job Raised	16/11/2016		