From: Foi Enquiries

To:

Subject: EIR-17-1735 - Inspection and Maintenance - Union Street

**Date:** 07 December 2017 15:10:49

Attachments: Further Information - Right to Review & Appeal.pdf

EIR-17-1735 - Union Street Customer Enquiries Redacted.pdf EIR-17-1735 - Union Street customer enquiries 2 Redacted.pdf

EIR-17-1735 - Union Street Reports Redacted.pdf EIR-17-1735 - lakeland 1 KA Redacted.pdf EIR-17-1735 - lakeland 2 KA Redacted.pdf

Dear

Your Reference:

Thank you for your information request of 15 November 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

Date of Accident: 08 September 2017

Location of Accident: Union Street, Aberdeen

Please see attached photographs.

For 12 months prior to the accident and to date (15 November 2017):

- Records of inspection for the relevant stretch of highway;

Please see attached under Union Street customer enquiries and report 'condition survey'

 Maintenance records including records of independent contractors working in relevant area;

Please see attached lakeland 1/2 KA under 'maintenance management'

The only works recorded within the vicinity of the above address during the dates specified were undertaken by Twenty Twelve Civils in relation to the new bus stop installation in November 2016. These works would not have impacted on this specific section of lock-block. The works information is provided.

 Records of the minutes of Highway Authority meetings where maintenance or repair policy has been discussed or decided;

Please see link below to the 'Road Safety Inspection Manual' which has been in place since 2012.

https://www.aberdeencity.gov.uk/sites/aberdeencms/files/Roads%20Safety%20Inspection%20Manual.pdf

As **Records of the minutes of Highway Authority meetings where maintenance or repair policy has been discussed or decided** is otherwise accessible at the link provided above, it is exempt from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby gives notice that we are refusing your request under the terms of Regulation 6(1)(b) - Information Already Publicly Available - of the EIRs.

Records of complaints about the state of highways (Union Street, Aberdeen);

There are no complaints logged regarding the condition of Union Street, Aberdeen for 12 months prior to the accident up to 15 November 2017.

We follow the Scottish Local Authority Complaints Handling Procedure. Under this procedure, a 'complaint' is defined as "an expression of dissatisfaction regarding our actions, or lack of action, or the standard of service provided by us or on our behalf". There are some topics that cannot be considered as a 'complaint', including first time requests for a service e.g. reporting a pothole or broken paving slab.

For more information please visit <a href="https://www.aberdeencity.gov.uk/index.php/services/have-your-say/make-complaint">https://www.aberdeencity.gov.uk/index.php/services/have-your-say/make-complaint</a> and refer to the 'What is a complaint?' section.

#### - Records of other accidents which have occurred on the relevant stretch of highway.

In the given timescale Aberdeen City Council have received two claims for personal injury and one intimation for personal injury on Union Street relating to footways. Neither of which occurred at the given location. Please see attached reports under 'customer enquiries' which details other incidents on Union Street during the given timescale.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Head of Service level have been redacted (blacked out) from the attached Site History Report. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with 11(3)(a)(i) – Personal Information - of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, and the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as ACC considers that disclosure of this information would be a breach of the first Data Protection Principle (that personal information must be processed fairly and lawfully). The individuals named in the correspondence would not expect ACC to release this information about them into the public domain under the EIRs (or the Freedom of Information (Scotland) Act 2002 (FOISA)).

We hope this helps with your request.

Yours sincerely,

Information Compliance Team

#### INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice

that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team Customer Service Corporate Governance Aberdeen City Council 3rd Floor North Business Hub 17 Marischal College Broad Street ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk

Tel 03000 200 292

\*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.

Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

Site: UNION STREET (7600082)

Service: Footways

Site: UNION STREET (7600082) Locality: ABERDEEN, ABERDEEN CITY Area: Aberdeen Central

Customer Services

**Display Action Officer: No** 

Logged by: Contact Centre on: 01/10/2017 10:56 Enquiry No.: 719932

Subject: Footways OOH Emergency Service: Footways Classification: Enquiry **Enquiry Ref:** 

Desc.: Burger King side - slab missing from pavement - passed to standby ARR

Location: Union Street Contact: ANON SEPT 17 ANON SEPT 17

**Enquiry No.: 719335** Logged by: Contact Centre on: 23/09/2017 22:35

Classification: Enquiry **Enquiry Ref:** Service: Footways Subject: Broken Slab

Desc.: AO: ACC Roads Response service,

Reference No: PATHS18201

Site (Street/Park/etc): Union Street, Aberdeen

Location: Opposite from Waterstones Bookshop on Union Bridge side

Locational Details: In footpath or lane First Type of Fault : Broken/Rocking Slab(s)

Additional Information: My 80 year old mother in law fell today on Union Street due to a very broken paving slab with a bit protruding up causing her to trip up. Thankfully she will be okay but quite bruised etc as it could have been worse. Walking on this side of Union Street I notice there are a lot of similar broken paving slabs. Can you please fix these so no other people come to harm.

Name

Telephone Number Email Address:

Location: UNION STREET

Plot Number: 1.001.00 Feature Id - Location: 1 - Footway

Job Number: 718397

Logged by: Contact Centre **Enquiry No.:** 718415

Subject: Rocking Slab Service: Footways Classification: Enquiry **Enquiry Ref:** 

Desc.; Reference No: PATHS18172. Site (Street/Park/etc): 422/424 Union Street. Location: Outside Aberdein Considine. Locational Details: In footpath or lane. First Type of Fault: Broken/Rocking Contact

Contact

Slab(s). First Fault Details: Rocking slab. Name:

Telephone Number:

Email Address:

on: 13/09/2017 11:21

Location: 422-424 UNION STREET

Plot Number: 1.001.00 Feature Id - Location: 1 - Footway

Feature Type: RDS Footway

Job Number: 718181

**Enquiry No.: 718414** Logged by: Contact Centre on: 13/09/2017 11:19

Service: Footways Subject: Rocking Slab Classification: Enquiry

Desc.: Reference No: PATHS18171. Site (Street/Park/etc): Corner Chapel Street / Union Street. Location: East side at juction. Locational Details: In front of house. First Type of Fault: Broken/Rocking

Slab(s). First Fault Details: The slab is actaully a big slab of cement which looks pretty untidy. Name: Telephone Number: Email Address:

Location: UNION STREET Contact:

Plot Number: 1,001.00 Feature Id - Location: 1 - Footway

Job Number: 718181

Feature Type: RDS Footway

**Enquiry Ref:** 

Feature Type: RDS Footway

Contact:

**Effective:** 08/09/2016 to 15/11/2017 **Service:** Footways

Display Action Officer: No Site: UNION STREET (7600082)

**Customer Services** 

**Enquiry No.:** 715547 **Logged by:** Contact Centre **on:** 16/08/2017 00:33

Service: Footways Subject: Rocking Slab Classification: Enquiry Enquiry Ref:

Desc.: PATHS18117

Site (Street/Park/etc): 262 Union Street Location: Outside Natwast bank Locational Details: In front of house First Type of Fault: Broken/Rocking Slab(s)

First Fault Details : Rocking slab

Location: 262 Union Street Outside Natwast bank

Plot Number: 1,001.00 Feature Id - Location: 1 - Footway Feature Type: RDS Footway

**Job Number:** 717669

**Enquiry No.:** 711871 **Logged by:** Contact Centre **on:** 11/07/2017 11:04

Service: Footways Subject: Broken Slab Classification: Enquiry Enquiry Ref:

Desc.: 2 LOOSE AND ROCKING SLABS

Location: OUTSIDE EDINBURGH WOOLEN MILL, 187 UNION STREET Contact:

Plot Number: 1,001.00 Feature Id - Location: 1 - Footway Feature Type: RDS Footway

**Job Number:** 716846

**Enguiry No.:** 711795 **Logged by:** Contact Centre **on:** 10/07/2017 14:32

Service: Footways Subject: Rocking Slab Classification: Defect Report Enquiry Ref:

Desc.: MRS ADVISES THAT SHE TRIPPED ON PAVEMENT - SLAB STICKING UP APPROX 2 INCHES, SHE IS SORE AND HAS A HEADACHE BUT HAS NOT SOUGHT MEDICAL ADVICE-

**Enquiry Ref:** 

SHE WILL PHONE BACK TOMORROW IF SHE DOES NOT FEEL WELL

Location: OUTSIDE EDINBURGH WOOLEN MILL- UNION STREET Contact:

Plot Number: 1,001.00 Feature Id - Location: 1 - Footway Feature Type: RDS Footway

Job Number: 716846 Defect Number: 465626

**Enquiry No.:** 710960 **Logged by:** Contact Centre **on:** 04/07/2017 00:13

Service: Footways Subject: Broken Slab Classification: Service Requested

Desc.: FAO: ACC Roads Response service,

Reference No: PATHS18040
Site (Street/Park/etc): Union Street
Location: opposite Abercrombie Bar
Locational Details: Opposite side of road
First Type of Fault: Broken/Rocking Slab(s)
First Fault Details: Severely cracked slabs

Additional Information: slabs are cracked causing trip hazards almost caused an accident today. Can they please be repaired.

Name : Telephone Number

Location: Contact:

**Enquiry No.:** 710557 **Logged by:** Contact Centre **on:** 30/06/2017 08:23

Service: Footways Subject: Rocking Slab Classification: Enquiry Enquiry Ref:

Desc.: ROCKING SLAB OUTSIDE CHAOPHRAYA. 5 SLABS IN FROM BIN (MONKEY HOUSE)

Location: CHAOPHRAYA, UNION STREET Contact:

Plot Number: 1,001.00 Feature Id - Location: 1 - Footway Feature Type: RDS Footway

**Job Number:** 716519

Effective: 08/09/2016 to 15/11/2017 Service: Footways

Display Action Officer: No Site: UNION STREET (7600082)

Customer Services **Enquiry No.:** 702364

Logged by: Contact Centre

on: 03/05/2017 10:05

Service: Footways

Subject: Rocking Slab

Classification: Defect Report **Enquiry Ref:** 

Desc.: ROCKING SLAB. REPORTED BY

Location: OUTSIDE JOHNSONS DRY CLEANERS

Contact:

**Plot Number: 1.001.00** 

Feature Id - Location: 1 - Footway

Feature Type: RDS Footway

Job Number: 714643

**Enquiry No.:** 690335 Logged by: Contact Centre Subject: Rocking Slab Service: Footways

on: 28/02/2017 13:48

**Enquiry Ref:** 

Desc.: ROCKING SLAB 5 SLABS OUT FROM DIGBY BROWNS FRONT DOOR. NO220

Location: DIGBY BROWN, 214 UNION STREET

Contact:

Classification: Defect Report

Enquiry No.: 688411 Service: Footways Logged by: Contact Centre Subject: Rocking Slab

on: 10/02/2017 10:10 Classification: Defect Report

**Enquiry Ref:** 

Desc.: ROCKING SLAB OUTSIDE 231A HALFWAY TO ROAD

ROCKING SLAB OUTSIDE SALLY. 2 OUT FROM BUILDING, 2 LEFT FROM PINK SLABS

ROCKING SLAB, OUTSIDE 227, 2 SMALL SLABS THEN 2ND LARGE SLAB AWAY FROM ROAD

Location: UNION STREET FROM BRIDGE STREET TO 231 UNION STREET

Contact:

Logged by: Contact Centre

on: 06/02/2017 10:00

**Enquiry Ref:** 

**Enquiry Ref:** 

Service: Footways Subject: Rocking Slab **Desc.:** Uneven, rocking slabs in front of old Hydro Electric shop.

Location: 156 Union Street - ST

Contact:

**Enquiry No.:** 686314

**Enquiry No.:** 687686

Logged by: Contact Centre

on: 23/01/2017 10:25

Classification: Defect Report

Service: Footways

Subject: Rocking Slab Classification: Defect Report

Desc.: DANGEROUSLY LOOSE PAVING SLAB

Location: UNION STREET MIDWAY BETWEEN BIKE RACKS AT FRONT OF CO-OP AT

Contact:

204-206 UNION STREET

Plot Number: 1.001.00

Feature Id - Location: 1 - Footway

**Job Number:** 711482

**Enquiry No.:** 683390

Logged by: Contact Centre

on: 19/12/2016 12:54

**Enquiry Ref:** 

Service: Footways

Subject: Rocking Slab

Classification: Enquiry

Desc.: Reference No: PATHS17735. Site (Street/Park/etc): Union Street. Location: On Union Bridge above the railway line. Locational Details: In footpath or lane. First Type of Fault: Broken/Rocking

Slab(s). First Fault Details: 3 different rocking slabs on North side of street. Name:

Telephone Number:

**Email Address:** 

Location: UNION BRIDGE - PATHS17735 - AB

Contact:

Logged by: Contact Centre

on: 07/10/2016 22:28

Service: Footways

Location: Union Street

**Enquiry No.:** 676026

Subject: Rocking Slab

Classification: Defect Report

**Enquiry Ref:** 

Desc.: Location: 19 Union Street

Locational Details: In front of house First Type of Fault: Broken/Rocking Slab(s)

First Fault Details : Loose pavement slab

Contact

Plot Number: 1.001.00 Job Number: 709158

Feature Id - Location: 1 - Footway

Feature Type: RDS Footway

Feature Type: RDS Footway

Service: Footways Site: UNION STREET (7600082) Display Action Officer: No

Service: Roads

Effective: 08/09/2016 to 15/11/2017

Display Action Officer: No Site: UNION STREET (7600082)

Site: UNION STREET (7600082) Locality: ABERDEEN, ABERDEEN CITY Area: Aberdeen Central

Customer Services

**Enquiry No.:** 724390 **Logged by:** Contact Centre **on:** 15/11/2017 11:01

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: Reference No : PATHS18303

Site (Street/Park/etc): Union Street (bus stop next to Michies Chemist)

Location: Bus stop next to Michies Chemist Locational Details: In footpath or lane First Type of Fault: Broken/Rocking Slab(s)

First Fault Details: Pavement not level - 1/2" high slabs

Second Type of Fault : Broken/Rocking Slab(s)

Additional Information: Fell on the pavement, falling on my chest, hurt my face and hand.

Name : Telephone Number

Location: Bus stop next to Michies Chemist on Union Street

Contact:

Contact:

Enquiry No.: 723537 Logged by: Contact Centre on: 07/11/2017 09:19

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: GULLY IS BLOCKED AND WATER IS POOLING ONTO PAVEMENT. PREVIOUS REPORTED BUT NOT UNBLOCKED REF.721724

Location: UNION STREET OPPOSITE SHOEZONE AT BUS STOP)

AT BUS STOP) Contact:

Enquiry No.: 720801 Logged by: Contact Centre on: 10/10/2017 15:30

Service: Roads Subject: Pot Hole - Road Classification: Enquiry Enquiry Ref:

Desc.: caller was crossing the road after coming out Heart Foundation shop, heading towards 19 bus stop when she tripped on a lump in middle of the road, hurting her knee and elbow

Location: Union Street Aberdeen near to 236

Plot Number: 1,000.00 Feature Id - Location: S/30/2358 - UNION STREET Feature Type: RDS Road Section

Job Number: 718687

Enquiry No.: 720283 Logged by: Contact Centre on: 04/10/2017 12:59

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: Reference No : ROADS30380

Site (Street/Park/etc): Union Street

Location: Box junction on Union Street at Market Street heading west southwest

First Type of Fault : Poor Road Surface First Fault Details : Hole in road surface

Second Type of Fault: Other

Second Fault Details: Exposed and worn through cable

Additional Information: I noticed the exposed and worn through cable when crossing the road this morning. It is towards the corner where you turn left from Union Street on to Market Street.

Name:
Address Line 1:
Address Line 2:
Address Line 3:
Postcode:
Telephone Number:

Location: Union Street/Market Street box junction

Contact:

Email Address

Effective: 08/09/2016 to 15/11/2017 Service: Roads

**Display Action Officer: No** Site: UNION STREET (7600082)

Customer Services

Logged by: Contact Centre **Enquiry No.: 714809** Subject: General Enquiry Service: Roads

Desc.: Pavements - reported by

Location: Union Street (ZONE 8)

Enquiry No.: 709013 Logged by: Contact Centre Subject: General Enquiry

Service: Roads Desc.: Locational Details : In front of house

> First Type of Fault : Other First Fault Details : Peterkins Sign Second Type of Fault: Other

Second Fault Details: Downpipe to the left of closed bank next door to Monkey House

Additional Information: Union Street continues to be in an almost incredulous state of disrepair, uncared for and almost shambolic. Peterkins have had a temporary targaulin sign up for months, the leaking downpipe near the monkey house has been leaking for years and would cost nothing hardly to fix, the steps down to the Green from the old Boots building are in a total state of disrepair. Union Bridge has had a temporary fence stapled to it for over a year. I believe there is a city centre masterplan, but the state of Union Street doesn't seem to be involved in it. Strange seeing

Classification: Enquiry

Classification: Defect Report

Classification: Defect Report

Contact:

on: 09/08/2017 10:46

on: 16/06/2017 21:36

on: 02/06/2017 16:23

**Enquiry Ref:** 

**Enquiry Ref:** 

**Enquiry Ref:** 

as that&apos:s the main city centre street. Are we ever going to see any progress?

Bus lane enforcement

Location: Path Contact

Enquiry No.: 706947 Logged by: Contact Centre Service: Roads Subject: Existing Road Marking

Desc.: FAO: ACC Roads Response service.

Reference No: ROADS29893

Site (Street/Park/etc): Union Row / Union Street

Location: Junction at Union Row and Union Street by Pret A Manger

First Type of Fault: Poor/Lack of Road Markings First Fault Details : No Stop Line Painted

Additional Information: This is a traffic light controlled junction, the Stop Line is no longer visible please can it be re-painted.

Name Address Line 1 Address Line 2: Address Line 3: Postcode Telephone Number:

Email Address:

Location: Outside Pret a Manger Union Street

Contact:

Effective: 08/09/2016 to 15/11/2017 Service: Roads

**Display Action Officer: No** Site: UNION STREET (7600082)

#### Customer Services

Logged by: Contact Centre on: 29/05/2017 14:09 **Enquiry No.: 706185** 

Subject: Pot Hole - Road Classification: Defect Report **Enquiry Ref:** Service: Roads

Desc.: Reference No: ROADS29877 Site (Street/Park/etc): Union street Location: approach to holburn junction Locational Details: In footpath or lane

First Type of Fault : Pothole First Fault Details : pothole no 2 Second Type of Fault: Pothole Second Fault Details : same location

Additional Information: The potholes concerning me as cyclist are situated in a fast moving, busy and restricted location at approach to traffic lights in cycle lane

Name Address Line 1 Address Line 2 Address Line 3: Postcode Telephone Number: Email Address

Location: ROADS29877 Contact: Enquiry No.: 705503 Logged by: Contact Centre on: 23/05/2017 12:11

Service: Roads Subject: Claims - Roads Classification: Defect Report **Enquiry Ref:** 

FELL WHILE CROSSING UNION STREET TOWARD BROAD STREET ON THE 3RD OF MARCH, SHE SUSTAINED SERIOUS INJURIES AND IS GETTING THERAPY FROM Desc.: MRS THE HOSPITAL, MR HAS REQYUESTED A CLAIM FORM ON THE 7TH MARCH AND HE HAS NOT RECIEVED IT YET, CAN NEW CLAIM FORMS BE SENT ASAP TO ALLOW

TO MAKE A CLAIM

Location: UNION STREET - BROAD STREET JUNCTION - SH Contact Logged by: Contact Centre on: 11/05/2017 12:22 Enquiry No.: 703939

Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Service: Roads

Desc.: caller would I ke to speak to someone regarding all the loose paving slabs on her walk to work from union Street to Foresterhill (covering Union Street. Esslemont Avenue, Watson Street to name a

Contact:

few) and further loose paving slabs throughout Aberdeen -caller enquired did her council tax help pay for mainting this -

Location: 206 Union Street Contact:

Logged by: Contact Centre on: 06/05/2017 12:25 Enquiry No.: 703057

Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Service: Roads

Desc.: missing manhole cover on pavement outside bar - passed to standby ARR

Enquiry No.: 694180 on: 20/03/2017 15:26 Logged by: Contact Centre

Service: Roads Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** 

Desc.: Reference No : PATHS17857 Site (Street/Park/etc): Union Street Location: Outside 420 Union street Locational Details: In footpath or lane First Type of Fault : Other

Location: outside McGinty's, Union Street

First Fault Details: Diversion sign has been run over by several busses and now on footpath as a trip hazard

Name

Email Address:

Location: 420 UNION STREET Contact: **Effective**: 08/09/2016 to 15/11/2017 **Service**: Roads

Display Action Officer: No Site: UNION STREET (7600082)

Customer Services

Enquiry No.: 694146 Logged by: Contact Centre on: 20/03/2017 14:06

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: Traffic diversion sign has been knocked over and is blocking pavement for pedestrians

Location: Between Cafe Nero and Pizza Express Union Street Contact: ANON MAR 17 ANON MAR 17

Enquiry No.: 693620 Logged by: Contact Centre on: 16/03/2017 16:47

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: Reference No : PATHS17854

Site (Street/Park/etc): Union Street Footpath

Location: Aberdeen - union Street Locational Details: In front of house First Type of Fault: Poor Surface

First Fault Details: Footpath is uneven and traps water in rainy weather

Additional Information: My complaint relates to Aberdeens' Union Street and the state of the footpath on both sides of the street. The paving is uneven and a trip hazard in many places along the street. In wet weather it traps water and certain paving slabs collect water which then splash out when stepped on causing trousers legs and shoes to get soaked. Finally the sides of the street do not drain quickly enough/gather water meaning that buses splash water onto pedestrians at crossing and bus stops. Yours sincerely (and unwillingly drenched).

Name : Telephone Number : Email Address :

Location: UNION STREET

Contact:
Enquiry No.: 691782

Logged by: Contact Centre

on: 08/03/2017 15:04

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: LARGE POTHOLE SHOWING EXPOSED CABLES ON ROAD AT TRAFFIC LIGHTS IN FRONT OF STARBUCKS 498 UNION ST

Location: 498 UNION STREET:

Plot Number: 1,000.00 Feature Id - Location: S/30/2358 - UNION STREET

 Job Number: 713073
 Logged by: Contact Centre
 on: 07/03/2017 12:33

Service: Roads Subject: Claims - Roads Classification: Defect Report Enquiry Ref:

Desc.: THE PART OF THE PEDESTRIAN CROSSING WITH THE STUDS ON IT CAME LOOSE AND CALLER FELL OVER AND BROKE HER WRIST AND HIT HER FACE. 2 CITY WARDENS

ATTENDED AND TOOK HER INTO THE TOURIST INFO SHOP TO RECOVER AND SHE LATER WENT TO HOSPITAL. WANTS A CLAIM FORM TO BE SENT OUT TO HIM FOR

Feature Type: RDS Road Section

THE INCIDENT

INFO SHOP TO OLD EAND M'S

Enquiry No.: 691025 Logged by: Contact Centre on: 06/03/2017 12:32

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: called to report his wife fell between the tourist information office and the kerbside. She ended up with a broken hand and having stitches in her eye. This has happened numerous times

Contact:

to other people.

Location: Outside Tourist information office Union Street

Location: STUDDED PART OF CROSSING ON UNION STREET GOING FROM TOURIST

Enquiry No.: 690760 Logged by: Contact Centre on: 03/03/2017 11:25

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: Lifted slab, fell over it, slammed into the large planter, injuring herself. Wants this looked into as it could have serious repercussions for an elderly person -

Location: Union Street, junction with Chapel Street, outside Aberdein Considine Contact:

**Effective:** 08/09/2016 to 15/11/2017 **Service:** Roads

Display Action Officer: No Site: UNION STREET (7600082)

**Customer Services** 

**Enquiry No.:** 690129 **Logged by:** Contact Centre **on:** 27/02/2017 11:34

Service: Roads Subject: Sunken Carriageway Classification: Defect Report Enquiry Ref:

Desc.: HAZARD TYPE: Pothole
APPROX. SIZE: ? Water-filled
APPROX. DEPTH: ? Water-filled

APPROX. DISTANCE FROM KERB: 0.5 metres

DATE ENCOUNTERED: 2017-02-26

**DEFECT DESCRIPTION:** 

Water-filled pothole causing pedestrians to be soaked by

passing traffic

Location: Union Street, eastbound, shortly before Huntly Street

Enquiry No.: 687687 Logged by: Contact Centre on: 06/02/2017 10:02

Service: Roads Subject: Claims - Roads Classification: Defect Report Enquiry Ref:

Desc.: Caller tripped on rocking, uneven slabs in front of old Hydro Electric shop. New trousers ripped as a result of the fall.

Location: 156 Union Street - ST

Contact:

Enquiry No.: 685470 Logged by: Contact Centre on: 13/01/2017 12:56

Service: Roads Subject: General Enquiry Classification: Defect Report

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: Ms would like to discuss with someone the condition of the pavements on her walk for Union Street to Foresterhill Hospital call her on -jd

Location: UNION STREET TO FORESTERHILL HOSPITAL

Enguiry No.: 685355 Logged by: Contact Centre on: 12/01/2017 13:33

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: LOOSE PAVING SLAB AT WALKWAY AT BUILDING SITE-DANGEROUS 2 PEOPLE HAVE FALLEN TODAY ALREADY- PHONED THROUGH-

Location: UNION STREET- NEW SILVERFINN BUILDING Contact

Location: Onion STREET-NEW SIEVERTININ BOILDING

Plot Number: 1,001.00 Feature Id - Location: 1 - Footway Feature Type: RDS Footway

Job Number: 711240

**Enquiry No.**: 685027 **Logged by:** Contact Centre **on**: 10/01/2017 12:26

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: LOOSE PAVING AT FRONT OF STORE-JD

Location: EDINBURGH WOOLLEN MILL -187 UNION STREET Contact

Plot Number: 1,000.00 Feature Id - Location: S/30/2358 - UNION STREET Feature Type: RDS Road Section

**Job Number:** 711108

Enquiry No.: 684499 Logged by: Contact Centre on: 05/01/2017 15:06

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: Reference No: PATHS17747. Site (Street/Park/etc): 414 union street. Location: 414 union street. Locational Details: In footpath or lane. First Type of Fault: Broken/Rocking Slab(s). First Fault

Contact

Contact:

Contact:

Details: Metal stud protracting from pavement

Name: Telephone Number:

Location: 414 UNION STREET - PATHS17747 - AB

**Enquiry No.**: 683041 **Logged by:** Contact Centre **on**: 14/12/2016 15:19

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: Deisel spill caused by a leak from bus, stretching from Holburn Street up Union Street to the depot on King Street. As reported by

Location: Union Street Contact:

Page 5 of 8

Effective: 08/09/2016 to 15/11/2017 Service: Roads

**Display Action Officer: No** Site: UNION STREET (7600082)

Customer Services

Logged by: Contact Centre on: 12/12/2016 16:07 Enquiry No.: 682807

Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Service: Roads

Desc.: Reference No: ROADS28862

Site (Street/Park/etc): Union Street Junction

Location: In Yellow Junction box in Bon-Accord Street/Union Row

First Type of Fault: Rocking/Noisy/Low Manhole Cover

Additional Information: The Union Street where Bon-Accord Street/Union Row meet. The low manhole cover has been an issue for sometime, could you please action? It is in the yellow junction

**Enquiry Ref:** 

**Enquiry Ref:** 

Feature Type: RDS Footway

Feature Type: RDS Footway

box

Name Address Line 1 Email Address

Location: ROADS28862 - Union Street

Contact:

Enquiry No.: 682203 Logged by: Contact Centre on: 06/12/2016 15:05

Service: Roads Subject: General Enquiry Classification: Defect Report

Desc.: Reference No : PATHS17713 Site (Street/Park/etc): Union Street Location: Outside 381 / Bruce Millars Locational Details: In footpath or lane First Type of Fault : Broken/Rocking Slab(s)

First Fault Details: A cluster of 6 slabs and 2 are rocking

Name

Telephone Number:

Email Address

Location: 381 UNION STREET

Contact

Plot Number: 1.001.00 Feature Id - Location: 1 - Footway

Job Number: 710449 Defect Number: 461693

**Enquiry No.: 679944** Logged by: Contact Centre on: 15/11/2016 08:46 Subject: General Enquiry Classification: Defect Report Service: Roads

Desc.: Called to report that there is a loose paying slab causing a trip hazard at this location

Location: Union Street-outside Capitol Theatre next to black bollard.

Plot Number: 1.001.00 Feature Id - Location: 1 - Footway

Job Number: 709991 Defect Number: 461410

Enquiry No.: 679553 Logged by: Contact Centre on: 10/11/2016 13:26

Service: Roads Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** 

Desc.: Reference No: PATHS17666. Site (Street/Park/etc): Union Street. Location: 252. Locational Details: In front of house. First Type of Fault: Rocking/Low Manhole or Toby Cover. First Fault

Details: Plastic stop-cock cover completely missing, thereby making this a trip hazard. Name:

Telephone Number Email Address:

Location: 252 UNION STREET - PATHS17666 - AB

Effective: 08/09/2016 to 15/11/2017 Service: Roads

**Display Action Officer: No** Site: UNION STREET (7600082)

Customer Services

Logged by: Contact Centre on: 08/11/2016 15:47 **Enquiry No.:** 679346

Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Service: Roads

Desc.; Reference No: ROADS28769. Site (Street/Park/etc): union street. Location: pavement between game and ponden shops. Locational Details: In footpath or lane. First Type of Fault: Other. First Fault Details: loose slabs on pavement. Additional Information: The pavement between game and ponden home shops on union street has very hazardous loose slabs have seen many people trip over them.. Just after the bridge street crossing across from barclays bank. Hopefully gets fixed promptly before someone really gets hurt. Name:

Telephone Number:

Location: 177-181 UNION STREET - ROADS28769 -Contact: Anon

Plot Number: 1.001.00 Feature Id - Location: 1 - Footway Feature Type: RDS Footway

Job Number: 709833 Defect Number: 461292

**Enquiry No.: 679009** Logged by: Contact Centre on: 06/11/2016 23:48

Service: Roads Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** 

Desc.: FAO: ACC Roads Response service,

Reference No: PATHS17661 Site (Street/Park/etc): Castlegate

Location: About four yards from pedestrian crossing

Locational Details: In footpath or lane First Type of Fault : Poor Surface

First Fault Details: Uneven and loose slabs

Additional Information: On 28 October at approximately 10:15 my mother fell and injured herself as a direct result of the very poor walkway at the Castlegate. The incident was witnessed by two parking attendants who along with my father helped her to her feet. My father took her to the accident and emergency at Aberdeen royal infirmary. Can you please send me a form to claim for

compensation for personal injury.

Telephone Number:

**Email Address** Location: CASTLEGATE

Enquiry No.: 676613 on: 14/10/2016 14:09 Logged by: Contact Centre

Service: Roads Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** 

Desc.: Reference No: DRAINAGE15778. Site (Street/Park/etc): Pavement Gully that runs down the centre is blocked. Location: outside lush at 81 Union Street. Locational Details: In footpath or lane. Email Address: Telephone Number:

Contact:

First Type of Fault: Blocked Gully. First Fault Details: Large puddle being created by the blocked gully. Name:

Location: 81 UNION STREET - DRAINAGE15778 - AB

Contact:

Enquiry No.: 676510 Logged by: Contact Centre on: 13/10/2016 14:31

Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Service: Roads

Desc.: Reference No: ROADS28701. Site (Street/Park/etc): union st./ junction of holburn st. Location: gutter beside traffic lights westbound. Locational Details: In footpath or lane. First Type of Fault: Pothole. First Fault Details: pothole surrounding manhole. Additional Information: I have previously contacted you about this dangerous pothole in vulnerable road user lane. You informed me that this is respons bility of scottish water, they have investigated and return that manhole belongs to council. I have photo which I can forward in email if required. Name: Address Line

Address Line 3: Postcode: Telephone Number: Email Address: Location: UNION STREET - ROADS28701 - AB Contact

Plot Number: 1.000.00 Feature Id - Location: S/30/2358 - UNION STREET Feature Type: RDS Road Section

Job Number: 709281

Effective: 08/09/2016 to 15/11/2017 Service: Roads **Display Action Officer: No** Site: UNION STREET (7600082) Customer Services Logged by: Contact Centre on: 08/10/2016 06:05 Enquiry No.: 676032 Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Service: Roads Desc.: Reference No : PATHS17618 Site (Street/Park/etc): Union Street Location: Next to new wayshowing sign at top of Back Wynd Steps Locational Details: In front of house First Type of Fault : Broken/Rocking Slab(s) First Fault Details : 2 slabs are loose Location: Union Street Contact: Plot Number: 1.001.00 Feature Id - Location: 1 - Footway Feature Type: RDS Footway Job Number: 709157 Enquiry No.: 675371 Logged by: Contact Centre on: 30/09/2016 16:06 Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Service: Roads Desc.: Loose slabs. Location: 206 Union Street and around corner onto Huntly Street - ST Contact: Plot Number: 1.000.00 Feature Id - Location: S/30/2358 - UNION STREET Feature Type: RDS Road Section Job Number: 709005 **Enquiry No.: 673522** Logged by: Contact Centre on: 16/09/2016 11:38 Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Service: Roads Desc.: red pavement slab sticking up very dangerous .jd Location: Union Street-outside Justice Mill Contact Logged by: Contact Centre on: 13/09/2016 15:20 Enquiry No.: 673126 Service: Roads Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Desc.; Reference No: ROADS28658. Site (Street/Park/etc): union st. Location: before lights at hoburn junction. Locational Details: Opposite side of road. First Type of Fault: Pothole. Additional Information: pothole is in cycle lane and causes chain to come off bike possibly fouling and causing further instability in congested traffic, also downhill slope induces speed on cycle. I have reported this before and you state that it is responsibility of scottish water. s.w. reply they are only responsible for manholes not pot holes. Name: Address Line 1 Address Line 2: Postcode: Telephone Number: Email Address: Location: UNION STREET - ROADS28658 Contact: Logged by: Contact Centre on: 10/09/2016 14:22 Enquiry No.: 672822 Subject: General Enquiry Classification: Defect Report Service: Roads **Enquiry Ref:** Desc.: MASON FALLING OFF ROOF CALLED IN BY PASSED TO STANDBY CLOSED PATH/ROAD TO KEEP PUBLIC SAFE VB 14:13 Location: TOWN UNION HOUSE Contact: Logged by: Contact Centre on: 09/09/2016 15:51 Enquiry No.: 672807

Effective: 08/09/2016 to 15/11/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)
Site: UNION STREET (7600082)

Site: UNIO	N STREET (7600082)		Locality: ABERDEE	N, ABERDEEN CITY			Area: Aberdee	n Central
ondition Su	rvey							
efect No: Desc	cription	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00 Asset - Lo	ocn.: S/30/2358 - U	NION STREET	Feature Typ	e: RDS Road Sect	ion	Area: Aberde	en Central
Batch: 53	37955 - Inspection Batch		Route: V	Veek: 21 - Area: 18				Date: 18/08/2017
No a	ctionable defects found							
Batch: 53	37157 - Inspection Batch		Route: V	Veek: 19 - Area: 18				Date: 04/08/2017
No a	ctionable defects found							
Batch: 53	36376 - Inspection Batch		Route: V	Veek: 17 - Area: 18				Date: 21/07/2017
No a	ctionable defects found							
	35104 - Inspection Batch		Route: V	Veek: 15 - Area: 18				Date: 04/07/2017
	air pothole as required approxim x 300 x 40mm	ately 03/07/2017	Outside number 492 Starbucks coffe shop at crossing	e Pot Hole	Internal		Committed	716677
Batch: 53	34076 - Inspection Batch		Route: V	Veek: 13 - Area: 18				Date: 14/06/2017
No a	ctionable defects found							
Batch: 53	34062 - Inspection Batch		Route: V	Veek: 11 - Area: 18				Date: 14/06/2017
No a	ctionable defects found							
Batch: 53	32489 - Inspection Batch		Route: V	Veek: 09 - Area: 18				Date: 23/05/2017
No a	ctionable defects found							
Batch: 53	32326 - Inspection Batch		Route: V	Veek: 07 - Area: 18				Date: 22/05/2017
No a	ctionable defects found							
Batch: 53	31089 - Inspection Batch		Route: V	Veek: 05 - Area: 18				Date: 29/04/2017
No a	ctionable defects found							
Batch: 53	30410 - Inspection Batch		Route: V	Veek: 03 - Area: 18				Date: 22/04/2017
No a	ctionable defects found							
Batch: 52	29137 - Inspection Batch		Route: V	Veek: 01 - Area: 18				Date: 31/03/2017
No a	ctionable defects found							
Batch: 52	27927 - Inspection Batch		Route: V	Veek: 47 - Area: 18				Date: 17/03/2017
No a	ctionable defects found							
Batch: 52	26998 - Inspection Batch		Route: V	Veek: 45 - Area: 18				Date: 07/03/2017
463193 Repa	air pothole as required exposed es	06/03/2017	Outside 484 brook street agency at traffic lights down from Alford place	Pot Hole	Internal		Committed	713073
Batch: 52	25871 - Inspection Batch		Route: V	Veek: 43 - Area: 18				Date: 19/02/2017
requ	air all potholes and surface deferired around gully		Outside Pret A Manger junction with union row at gully	Pot Hole	Internal		Committed	712587
	air pothole as required approxim x 200 x 25mm	ately 19/02/2017	Footway Crossing point at junction w chapel street	rith Pot Hole	Internal		Committed	71258
400	air pothole as required approxim x 400 x 40mm de crossing see photo	ately 19/02/2017	At junction with st Nicholas street outside bank	Pot Hole	Internal		Committed	712568
	air pothole as required around so	unken 19/02/2017	At gully outside McDonald's restaura See photo	nt Pot Hole	Internal		Committed	712569

Effective: 08/09/2016 to 15/11/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01) Site: UNION STREET (7600082)

fect No: Description	Log Date	Location	Defect Type	Class. Organisati	on Status	Job No
Asset: 1,000.00 Asset - Locn.:	S/30/2358 - U	NION STREET	Feature Type: R	DS Road Section	Area: Aberde	en Central
Batch: 525871 - Inspection Batch		Route: W	eek: 43 - Area: 18			Date: 19/02/2017
462925 Lift and reset sunken gully	19/02/2017	Outside Pret A Manger junction with union row	Iron Works	Internal	Committed	712588
462907 Lift and reset sunken loose and rocking gully	19/02/2017	Outside McDonald's restaurant	Iron Works	Internal	Committed	712570
462926 Repair all potholes and surface defects (sunken carriageway) as required	19/02/2017	Outside skipton building society junction with union row	Pot Hole	Internal	Committed	712589
462829 Repair pothole as required approximately 200 x 200 x 45mm	14/02/2017	Outside pre a manger east bound in middle lane	Pot Hole	Internal	Committed	712399
Batch: 525634 - Inspection Batch		Route: W	eek: 41 - Area: 18			Date: 13/02/2017
No actionable defects found						
Batch: 524481 - Inspection Batch		Route: W	eek: 39 - Area: 18			Date: 26/01/2017
No actionable defects found						
Batch: 523900 - Inspection Batch		Route: W	eek: 37 - Area: 18			Date: 17/01/2017
No actionable defects found						
Batch: 522277 - Inspection Batch	<u> </u>	Route: W	eek: 35 - Area: 18			Date: 21/12/2016
461857 Repair pothole around gully	16/12/2016	Outside pret a manger at junction with Union row	Pot Hole	Internal	Committed	71067
461858 Lift and reset gully	16/12/2016	Outside pret a manger at junction with Union row	Iron Works	Internal	Committed	71067
Batch: 522249 - Inspection Batch		Route: W	eek: 33 - Area: 18			Date: 16/12/2016
No actionable defects found						
Batch: 520863 - Inspection Batch		Route: W	eek: 31 - Area: 18			Date: 25/11/2016
No actionable defects found						
Batch: 520032 - Inspection Batch		Route: W	eek: 29 - Area: 18			Date: 15/11/2016
No actionable defects found						
Batch: 518392 - Inspection Batch		Route: W	eek: 27 - Area: 18			Date: 30/10/2016
461120 Sunken carriageway (depression ) approximately 1m x 50cm x 50mm deep	30/10/2016	Opposite back wynd stairs	Sunken Carriageway	Internal	Archived	709612
461121 Repair pothole as required approximately 250 x 250 x 50	30/10/2016	Outside pret a manger coffee shop	Pot Hole	Internal	Archived	709613
Batch: 517982 - Inspection Batch		Route: W	eek: 25 - Area: 18			Date: 25/10/2016
No actionable defects found						
Batch: 515928 - Inspection Batch	<u> </u>	Route: W	eek: 23 - Area: 18			Date: 28/09/2016
No actionable defects found						
Batch: 514861 - Inspection Batch		Route: W	eek: 21 - Area: 18			Date: 16/09/2016
No actionable defects found						

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01) Site: UNION STREET (7600082)

efect No: Desc	ription		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,001.00	Asset - Locn.:	1 - Footway		Feature Typ	e: RDS Footway		Area: Aberde	en Central
Batch: 53	7811 - Inspectio	n Batch		Route: V	Veek: 21 - Area: 18				Date: 18/08/2017
466163 Lift ar	nd relay loose a	nd rocking slab	15/08/2017	On union bridge second lion down fr telephone box New slab	om Rocking Slab	Internal		Committed	717615
466181 Lift ar	nd relay loose a	nd rocking slabs	16/08/2017	Outside number 262 and NatWest b cash machine See photos	ank Rocking Slab	Internal		Committed	717669
Batch: 53	7158 - Inspectio	n Batch		Route: V	Veek: 19 - Area: 18				Date: 04/08/2017
No ac	ctionable defects	s found							
Batch: 53	6377 - Inspectio	n Batch		Route: V	Veek: 17 - Area: 18				Date: 21/07/2017
No ac	ctionable defects	s found							
Batch: 53	5556 - Inspectio	on Batch		Route: A	dhoc Inspection				Date: 11/07/2017
465626 Rese	t 2 rocking slab	s and 4 lock blocks	11/07/2017	OUTSIDE EDINBURGH WOOLEN MILL187 - UNION STREET	Rocking Slab	Internal		Committed	716840
Batch: 53	4784 - Inspectio	n Batch		Route: V	Veek: 15 - Area: 18				Date: 04/07/2017
	ove broken and 600 x 600 slab	loose slab and relay	27/06/2017	Outside eclectic bar	Broken Slab	Internal		Committed	71651
465415 Lift ar	nd relay loose a	nd rocking slabs	27/06/2017	3 slabs outside the thia restaurant 1 outside the closed TSB Bank See photos	Rocking Slab	Internal		Committed	71651
465513 Lift ar	nd relay loose a	nd rocking slabs	04/07/2017	Outside number 220 Digby Brown Solicitor	Rocking Slab	Internal		Committed	71669
Batch: 53	4077 - Inspectio	n Batch		Route: V	Veek: 13 - Area: 18				Date: 14/06/2017
No ac	ctionable defect	s found							
Batch: 53	4063 - Inspectio	n Batch		Route: V	Veek: 11 - Area: 18				Date: 14/06/2017
No ac	ctionable defect	s found							
Batch: 53	2490 - Inspectio	on Batch		Route: \	Veek: 09 - Area: 18				Date: 23/05/2017
No ac	ctionable defect	s found							
Batch: 53	2212 - Inspection	on Batch		Route: V	Veek: 07 - Area: 18				Date: 22/05/2017
464769 Lift ar slabs	,	sunken red dimple	18/05/2017	Outside Barclays Bank and Sally's Hairdresser	Rocking Slab	Internal		Committed	71548
Batch: 53	1088 - Inspectio	on Batch		Route: V	Veek: 05 - Area: 18				Date: 29/04/2017
464424 Rese			29/04/2017	173 Union Street	Rocking Slab	Internal		Committed	71488
464423 Rese			29/04/2017	Outside 245	Rocking Slab	Internal		Committed	71488
464422 Rese	-			199 outside ShuropodyEnter	Rocking Slab	Internal		Committed	714886
464421 Rese	•		29/04/2017	179 Near bus stop at Ponden home	Rocking Slab	Internal		Committed	71488
Batch: 53	0409 - Inspectio	n Batch			Veek: 03 - Area: 18				Date: 22/04/2017
464249 Rese	t rocking slab		22/04/2017	Near 185 Supercuts	Rocking Slab	Internal		Committed	71463
464248 Rese	t rocking slab		22/04/2017	On Footway of bridge over Denburn opposite HMV	Rocking Slab	Internal		Committed	714647

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01) Site: UNION STREET (7600082)

fect No: Description	Log Date	Location	Defect Type	Class. Organ	isation Status	Job No.
<b>Asset:</b> 1,001.00 <b>Asset - Locn.:</b>	1 - Footway		Feature 7	Type: RDS Footway	Area: Aberdeen	Central
Batch: 530409 - Inspection Batch		Route: Wee	ek: 03 - Area: 18			Date: 22/04/2017
464247 Reset rocking slab	22/04/2017	Along the frontage of Aberdein Considine 422-424	Rocking Slab	Internal	Committed	714646
464246 Reset 1 rocking tactile paving slab	22/04/2017	At corner of Chapel Street outside Aberdein Considine	Rocking Slab	Internal	Committed	714645
464245 Reset 1 rocking tactile paving slab and repair broken concrete work	22/04/2017	At corner of Chapel Street outside 432 Gavin Bain and Co	Rocking Slab	Internal	Committed	714644
464244 Reset rocking slab	22/04/2017	Between 476-478 ,Johnsons Dry cleaners and Cinnamon	Rocking Slab	Internal	Committed	71464
464243 Replace 1 x 900 x 600 broken rocking slab	22/04/2017	Outside 431 Capitol	Broken Slab	Internal	Committed	714642
464241 Reset rocking slab and 2 lock blocks	22/04/2017	265 Trailfinders	Rocking Slab	Internal	Committed	714640
464240 Reset rocking slab	22/04/2017	Near 187 Edinburgh Woolen mill near bus stop	Rocking Slab	Internal	Committed	714639
464242 Reset rocking slab	22/04/2017	Outside door of 407 near Tiger Bar	Rocking Slab	Internal	Committed	71464 <sup>-</sup>
Batch: 528676 - Inspection Batch		Route: Wee	ek: 01 - Area: 18			Date: 31/03/2017
463785 Lift and relay loose and rocking slab	28/03/2017	Beside flower planter at traffic light control opposite RBS Bank See photo	Rocking Slab	Internal	Committed	71393
Batch: 527928 - Inspection Batch		Route: Wee	ek: 47 - Area: 18			Date: 17/03/2017
No actionable defects found						
Batch: 526833 - Inspection Batch		Route: Wee	ek: 45 - Area: 18			Date: 07/03/2017
463121 Lift and relay loose and rocking slabs	28/02/2017	Outside number 220 digby browns	Rocking Slab	Internal	Committed	71297
Batch: 526091 - Inspection Batch		Route: Wee	ek: 43 - Area: 18			Date: 19/02/2017
462914 Lift and relay loose and rocking slab	19/02/2017	Outside alliance house number 453	Rocking Slab	Internal	Committed	71257
462913 Lift and relay raised red dimple slabs to remove trip	19/02/2017	Outside the justice mill bar at crossing	Rocking Slab	Internal	Committed	71257
462912 Lift and relay loose and rocking slabs	19/02/2017	Outside number 363	Rocking Slab	Internal	Committed	71257
462911 Lift and relay loose and rocking slab	19/02/2017	Outside soul bar See photo	Rocking Slab	Internal	Committed	71257
462910 Remove all loose material and point footway	19/02/2017	At greggs baker shop up from Dee street at rain water chnnel	Broken Slab	Internal	Committed	712573
462909 Lift and reset sunken footway gully as required	19/02/2017	Outside McDonald's restaurant	Iron Works	Internal	Committed	71257
462908 Replace broken and loose Caithness slab	19/02/2017	At right hand side of entrance into st Nicholas church	Broken Slab	Internal	Committed	71257 <sup>-</sup>
462923 Lift and relay loose and rocking slab	19/02/2017	Outside number 252 blue arrow beside cash machine	Rocking Slab	Internal	Committed	712586
462922 Lift and relay loose and rocking slab	19/02/2017	Outside number 252 blue arrow	Rocking Slab	Internal	Committed	71258
462921 Lift and relay loose and rocking slab	19/02/2017	Outside number 262	Rocking Slab	Internal	Committed	712584
462920 Lift and relay loose and rocking slabs	19/02/2017	Outside W H smith closed shop	Rocking Slab	Internal	Committed	712583
462919 Lift and relay loose and rocking slab	19/02/2017	Outside Aberdein considine property shop down from chapel street	Rocking Slab	Internal	Committed	712582

Effective: 08/09/2016 to 15/11/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)
Site: UNION STREET (7600082)

fect No: Desc	ription		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No
Asset:	1,001.00	Asset - Locn.: 1	- Footway		Feature Typ	e: RDS Footway		Area: Aberdee	en Central
Batch: 52	26091 - Inspection Ba	ch		Route: We	ek: 43 - Area: 18				Date: 19/02/2017
462917 Remo	ove all loose material vay	and point	19/02/2017	At cafe Nero junction with rose street	Broken Slab	Internal		Committed	71258
462916 Lift a	nd relay loose and ro	cking slabs	19/02/2017		Rocking Slab	Internal		Committed	712579
462915 Lift a	nd relay loose and ro	cking slab	19/02/2017	Outside Enid hutt gallery down from Alford place	Rocking Slab	Internal		Committed	71257
Batch: 52	25137 - Inspection Ba	ch		Route: We	ek: 41 - Area: 18				Date: 13/02/2017
462724 Lift a	nd relay loose and ro	cking slabs	10/02/2017	Outside hello hairdresser	Rocking Slab	Internal		Committed	71228
	nd relay loose and ro		10/02/2017	At black door next to game store	Rocking Slab	Internal		Committed	71224
462689 Lift a	nd relay loose and ro	cking slab	10/02/2017	Outside the old monkey house	Rocking Slab	Internal		Committed	71223
slabs			10/02/2017	Outside Sally hairdresser shop	Rocking Slab	Internal		Committed	71223
	nd relay loose and ro		10/02/2017	Outside mostyn and Mackenzie shoe shop number 227	Rocking Slab	Internal		Committed	71223
(very	nd relay loose and ro slight movement)		06/02/2017	Outside number 158 cafe Nero number	r Rocking Slab	Internal		Committed	71203
Batch: 52	24482 - Inspection Ba	ch		Route: We	ek: 39 - Area: 18				Date: 26/01/2017
No a	ctionable defects four	ıd							
Batch: 52	24360 - Inspection Ba	ch		Route: Adh	noc Inspection				Date: 23/01/2017
702270 Ent di	nd relay loose and ro	Stang Glab	23/01/2017	204-208 Union street at coop down from huntly street Note: iPad unable to locate Union street have been trying different location without any success This has been reported on numerous occasions	Rocking Slab	Internal		Committed	71148
Batch: 52	23901 - Inspection Ba	ch		Route: We	ek: 37 - Area: 18				Date: 17/01/2017
No a	ctionable defects four	ıd							
Batch: 52	22009 - Inspection Ba	ch		Route: We	ek: 35 - Area: 18				Date: 21/12/2016
461856 Lift a	nd relay all raised rec	dimple slabs at	16/12/2016	At crossing point outside soul bar See photo	Rocking Slab	Internal		Committed	71067
remo covei Very	nd relay loose and ro ove poor cement repair r and repoint. poor utility company to repair	r around nal	16/12/2016	Outside cafe Nero at number 454	Rocking Slab	Internal		Committed	71068
461860 Lift a	nd relay loose and ro	cking slabs	16/12/2016	Outside number 420 Aberdein considine	Rocking Slab	Internal		Committed	71067
	nd relay loose and ro		16/12/2016	Outside number 252 amicable house	Rocking Slab	Internal		Committed	71067
slab	nd relay loose and ro nd relay loose and ro		16/12/2016	At crossing point outside soul bar See photo	Rocking Slab	Internal		Committed	71067

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01) Site: UNION STREET (7600082)

efect No: Description	Log Date	Location	Defect Type	Class. Organisation	Status	Job No
<b>Asset:</b> 1,001.00 <b>Asset - Locn.:</b>	1 - Footway		Feature Typ	oe: RDS Footway	Area: Aberdeer	n Central
Batch: 522009 - Inspection Batch		Route: Wee	ek: 35 - Area: 18			Date: 21/12/2016
461854 Remove all loose material and point footway around cover	16/12/2016	At BT Manhole cover outside soul bar See photo	Broken Slab	Internal	Committed	710673
461795 Lift and relay raised 400 x 400 slab	14/12/2016	Outside number 160 beside cafe Nero See photo	Rocking Slab	Internal	Committed	710599
461794 Lift and relay all loose rocking and raised slabs	14/12/2016	On Union bridge from telephone bad to jamiesons and carry See photo	Rocking Slab	Internal	Committed	710598
Batch: 521992 - Inspection Batch		Route: Wee	ek: 33 - Area: 18			Date: 14/12/2016
461793 Remove broken loose 600 x 600 broken slab and replace with new slab Lift and relay loose and rocking slab	14/12/2016	Outside the monkey house See photo	Broken Slab	Internal	Committed	710597
461792 Lift and relay raised slab	14/12/2016	Outside the monkey house See photo	Rocking Slab	Internal	Committed	710596
461791 Lift and relay sunken slab	14/12/2016	Outside number 148 closed TSB Bank	Rocking Slab	Internal	Committed	71059
Batch: 521387 - Inspection Batch		Route: Adh	oc Inspection			Date: 07/12/2016
461695 Lift and relay all loose raised and rocking grey setts	07/12/2016	Outside Virgin Money at and beside post box See photo	Setts	Internal	Committed	71045
Batch: 521386 - Inspection Batch		Route: Adh	oc Inspection			Date: 07/12/2016
461694 Lift and relay loose and rocking slab	07/12/2016	Outside number 371 Toni and guy hairdresser	Rocking Slab	Internal	Committed	71045
Batch: 521385 - Inspection Batch		Route: Adh	oc Inspection			Date: 07/12/2016
461693 Lift and relay all loose and rocking slabs	07/12/2016	Outside number 363 Bruce millars	Rocking Slab	Internal	Committed	71044
Batch: 520904 - Inspection Batch		Route: Adh	oc Inspection			Date: 28/11/2016
461569 Lift and relay loose and rocking 600 x 600 slab	28/11/2016	Outside trailfinders travel shop at gas toby on UNION STREET iPad unable to locate Union street		Internal	Archived	71023
Batch: 520783 - Inspection Batch		Route: Wee	ek: 31 - Area: 18			Date: 25/11/2016
461554 Lift all sunken and raised grey lock block and relay level	24/11/2016	At crossing point outside KFC at junction with Diamond Street See photo	Setts	Internal	Committed	71020
461553 Remove all loose material and point footway	24/11/2016	Outside number 146 at BT Cover at New Restaurant old Monkey house See photo	Broken Slab	Internal	Archived	71019
461555 Lift and relay sunken 900 x 600 slab causing trip hazard	24/11/2016	Outside BETFRED down from South Silver Street See photo	Rocking Slab	Internal	Archived	71020
Batch: 520080 - Inspection Batch			oc Inspection			Date: 15/11/2016
461410 Lift and relay loose raised and rocking slat Lift and replace broken and rocking 900 x 600 slab	15/11/2016	Union Street-outside Capitol Theatre next to black bollard.	Broken Slab	Internal	Archived	70999 <sup>2</sup>

Contract: Roads Contract (General Maint) (RD01) Site: UNION STREET (7600082) Effective: 08/09/2016 to 15/11/2017 Display Action Officer: No

**Condition Survey** 

efect No: Des	cription		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.	
Asset:	1,001.00	Asset - Locn.: '	1 - Footway		Feature Ty	pe: RDS Footway		Area: Aberd	leen Central	
Batch: 52	20033 - Inspection	Batch		Route: We	ek: 29 - Area: 18				Date: 15/11/2016	
No a	actionable defects f	ound								
Batch: 5	19530 - Inspection	Batch		Route: Adhoc Inspection				Date: 09/11/2016		
	s and grey lock blo	raised and sunken ck in area marked	09/11/2016	177-181 between the Game Store & Holden Home Store	Rocking Slab	Internal		Archived	709833	
Batch: 5	17989 - Inspection	Batch		Route: We	ek: 27 - Area: 18				Date: 30/10/2016	
461058 Lift a	and relay 4 x sunke	n grey setts	25/10/2016	Outside number 245 next to Nevis spor	t Setts	Internal		Archived	709496	
Batch: 5	16891 - Inspection	Batch		Route: We	ek: 25 - Area: 18				Date: 25/10/2016	
460898 Lift a		I rocking Caithness	09/10/2016	Outside number 19 at rain water channel (Rs Mcolls)	Rocking Slab	Internal		Archived	709158	
	and relay 2 x rockir ened by fitting of n	ng Caithness slabs ( ew sign)	09/10/2016	At top of back Wyndham steps next to new information sign	Rocking Slab	Internal		Archived	709157	
Batch: 5	15929 - Inspection	Batch		Route: We	ek: 23 - Area: 18				Date: 28/09/2016	
No a	actionable defects f	ound								
Batch: 5	15147 - Inspection	Batch		Route: Adh	oc Inspection				Date: 20/09/2016	
460653 Lift a	and relay loose roc	king slabs	20/09/2016	On union bridge See photo numbers 1 & 2 on photo	Rocking Slab	Internal		Archived	708640	
Batch: 5	15146 - Inspection	Batch		Route: Adh	oc Inspection				Date: 20/09/2016	
	nove 2 x broken sla ace with new slabs		20/09/2016	On union bridge See photo numbers 3 & 4 on photo	Broken Slab	Internal		Archived	708639	
Batch: 5	14843 - Inspection	Batch		Route: We	ek: 21 - Area: 18				Date: 16/09/2016	
	and relay sunken s ind cover	ab and point	16/09/2016	Outside cafe Nero at junction with rose street	Rocking Slab	Internal		Archived	708597	
This not r	and relay raised red slab appears to ha relayed flush with for e optics contractor	ave been lifted and botway	16/09/2016	Outside the justice mill bar at crossing	Rocking Slab	Internal		Archived	708596	

# Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1,000.00	Asset - Locn.: S/30/2358 - UNION STREET	Fe	ature Type: RDS Road Section		Area: Aberdeen	Central
6491	6 Pot Hole	1	.RD 7 Day	Job Closed	10/11/2009	18/11/2009 Est	
6600	4 clean and jet gulley completed blocked (Blocked Gully)	tely outside KFC	.RD 14 Day	Job Closed	17/12/2009		
6786	2 rocking gully and fire hydrar	nt Office 101/103	.RD 14 Day	Job Cancelled	01/03/2010	15/03/2010 Est	
15370	1 Jammed gully lid	at Court	.RD 3 Months	Job Cancelled	04/11/2010	01/02/2011 Est	
15370	2 Jammed gully lid	opposite Court	.RD 3 Months	Job Cancelled	04/11/2010	01/02/2011 Est	
15394	8 reset gulley frame loose and rocking	d outside gamestation	.RD 7 Day	Job Cancelled	15/11/2010	22/11/2010 Est	
17313	3 clean and jet blocked gully	outside KFC at corner diamond street	.RD 7 Day	Job Cancelled	07/03/2013	14/03/2013 Est	

**Display Action Officer:** No

Contract: Roads Contract (General Maint) (RD01)

Contractor Completed

Contractor Completed

Job Closed

Site: UNION STREET (7600082)

		inagement	Location	Driority	Job Status	Entered	Completion	Works Order
OD NO.	Description			Priority		Entered	Completion	
	Asset:	· · · · · · · · · · · · · · · · · · ·	Asset - Locn.: S/30/2358 - UNION STREET		ture Type: RDS Road Section		Area: Aberdeen (	
177365		a of raised carraigway d to make safe	beside first bus travel centre opposite bus shelter ( see	.RD 28 Day	Job Cancelled	26/08/2013	23/09/2013 Est.	
	as require	d to make safe	on double yellow lines at pedestrian crossing at junction of crown street See Photo number 2)	.RD 28 Day	Job Cancelled	26/08/2013	23/09/2013 Est.	
177367		a of sunken carraigway d to make safe	in middle of carraigway at manhole opposite Gilcomstone Church See Photo number 3)	.RD 28 Day	Job Cancelled	26/08/2013	23/09/2013 Est.	
177368		a of sunken carraigway d to make safe	on bus lane just before junction bon accord street See Photo number 4)	.RD 28 Day	Job Cancelled	26/08/2013	23/09/2013 Est.	
181632	carraigewa	1 sq mtr of sunken ay at utility track Carriageway)	outside number 218 at smile dentalcare at old failed utility **	.RD 14 Day	Job Cancelled	20/02/2014	06/03/2014 Est.	
	3	abs, 2no lift and relay.	1st beside sevice lids, at black and lizars opticians, opps ho burn jct, 2nd 30 yds east bound.at enid hut.	.RD 2 Day	Order Printed	09/10/2015	13/10/2015 Est.	RD01/21022
707190	potholes d basis owin	se and rocking gully develop on a regular ng to movement of gull I for pothole (Iron	Outside macdonalds restaurant	.RD 14 Day	Contractor Completed	26/07/2016	19/03/2017 Act.	RD01/25630
709005	lift and related slabs	ay loose and rocking	outside sainsbury direct at junction with huntly street	.RD 7 Day	Job Closed	03/10/2016	03/10/2016 Act.	RD01/24725
709281		00x300x50.at service onal shaped.exposed	at top of union str at traffic lights heading towards ho burn str ,next to keb,	.RD 7 Day	Job Closed	17/10/2016	18/10/2016 Act.	RD01/24866
	2 Sunken ca ) approxim 50mm dee Carriagew	nately 1m x 50cm x ep (Sunken ay)	Opposite back wynd stairs	.RD 7 Day	Job Closed	30/10/2016	31/10/2016 Act.	RD01/25015
709613		thole as required ately 250 x 250 x 50	Outside pret a manger coffee shop	.RD 7 Day	Job Closed	30/10/2016	31/10/2016 Act.	RD01/25001
710463	Find and F	Fix 8 potholes filled by	various	.Routine Maintenance	e Job Closed	08/12/2016	07/12/2016 Act.	

.RD 7 Day

.RD 28 Day

.Routine Maintenance

711092 clean and jet 22 gullies

710677 Lift and reset gully (Iron Works)

Hole)

710676 Repair pothole around gully (Pot Outside pret a manger at junction

with Union row

with Union row

Outside pret a manger at junction

from union row to king street

16/12/2016 19/12/2016 Act. RD01/25557

16/12/2016 26/02/2017 Act. RD01/25629

10/01/2017 22/12/2016 Act.

Display Action Officer: No

Maintenance Management						
Job No. Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00 A	sset - Locn.: S/30/2358 - UNION STREET	Feature	Type: RDS Road Section		Area: Aberdeen C	entral
711108 Lift and relay rocking slab.	Outside entrance to EDINBURGH WOOLEN MILL (187 Union Street).	.RD 2 Day	Contractor Completed	10/01/2017	10/01/2017 Act.	RD01/25668
711189 clean and jet 30 gullies done on cyclic maintenance by	from union street to holburn street then back down to summer street	.Routine Maintenance	Job Closed	11/01/2017	07/12/2016 Act.	
712399 Repair pothole as required approximately 200 x 200 x 45mm (Pot Hole)	Outside pre a manger east bound in middle lane	.RD 7 Day	Contractor Completed	14/02/2017	14/02/2017 Act.	RD01/26127
712568 Repair pothole as required approximately 400 x 400 x 40mm Beside crossing see photo (Pot Hole)	At junction with st Nicholas street outside bank	.RD 7 Day	Contractor Completed	19/02/2017	22/02/2017 Act.	RD01/26180
712569 Repair pothole as required around sunken gully (Pot Hole)	At gully outside McDonald's restaurant See photo	.RD 7 Day	Contractor Completed	19/02/2017	22/02/2017 Act.	RD01/26180
712570 Lift and reset sunken loose and rocking gully (Iron Works)	Outside McDonald's restaurant	.RD 14 Day	Contractor Completed	19/02/2017	19/03/2017 Act.	RD01/26204
712581 Repair pothole as required approximately 300 x 200 x 25mm (Pot Hole)	Footway Crossing point at junction with chapel street	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26180
712587 Repair all potholes and surface defects as required around gully (Pot Hole)	Outside Pret A Manger junction with union row at gully	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26180
712588 Lift and reset sunken gully (Iron Works)	Outside Pret A Manger junction with union row	.RD 28 Day	Contractor Completed	19/02/2017	26/02/2017 Act.	RD01/26205
712589 Repair all potholes and surface defects (sunken carriageway) as required (Pot Hole)	Outside skipton building society junction with union row	.RD 7 Day	Contractor Completed	19/02/2017	22/02/2017 Act.	RD01/26180
712618 clean and jet 3 gullies	on Union Bridge	.RD 14 Day	Job Closed		18/02/2017 Act.	
713073 Repair pothole as required exposed cables (Pot Hole)	Outside 484 brook street agency at traffic lights down from Alford place	.RD 7 Day	Contractor Completed	06/03/2017	06/03/2017 Act.	RD01/26366
716490 clean and jet gully -	opp O2 shop	.Routine Maintenance	Contractor Completed	26/06/2017	22/06/2017 Act.	
716677 Repair pothole as required approximately 300 x 300 x 40mm (Pot Hole)	Outside number 492 Starbucks coffee shop at crossing	.RD 7 Day	Contractor Completed	03/07/2017	04/07/2017 Act.	RD01/27908
718319 clean and jet blocked gully	o/s sainsbury's local at ho burn street jctn as attached photo	.RD 14 Day	Contractor Completed	19/09/2017	25/09/2017 Act.	RD01/28550
718687 pothole, rutt approx 700x200x70	opps british heart foundation heading west on bus lane.	.RD 2 Day	Contractor Completed	11/10/2017	12/10/2017 Act.	RD01/28730
718695 Find and Fix - lift and relay 6 slabs repaired by	250-248	.Routine Maintenance	Contractor Completed	12/10/2017	11/10/2017 Act.	
718758 Clean and jet 2 gullies	junction with Summer Street	.RD 14 Day	Contractor Completed		20/10/2017 Act.	
718811 clean and jet gully	between Size and Shoe Zone	.RD 14 Day	Contractor Completed	24/10/2017	26/10/2017 Act.	RD01/28805

Display Action Officer: No

ob No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1,001.00 <b>As</b>	sset - Locn.: 1 - Footway	Fear	ture Type: RDS Footway		Area: Aberdeen	Central
64314	test (Broken Slab)	test	.RD 2 Day	Job Closed	21/10/2009		
	remove all broken and loose slabs and relay new slabs ( traffic overriding) (Broken Slab)	Outside betfred down from South silver street	.RD 7 Day	Order Printed	12/11/2015	19/11/2015 Est	RD01/21394
198471	lift and relay sunken nal cover and all sunken slabs and setts (Sunken Footway)	Outside betfred down from South silver street	.RD 7 Day	Order Printed	12/11/2015	19/11/2015 Est	RD01/21394
708117	Lift and relay all sunken/loose grey setts at crossing point (Setts)	Outside 422-424 union street Aberdeen considine	.RD 7 Day	Job Closed	29/08/2016	15/09/2016 Act	RD01/24335
	Lift and relay raised red dimple slab This slab appears to have been lifted and not relayed flush with footway Fibre optics contractor? (Rocking Slab)	Outside the justice mill bar at crossing	.RD 7 Day	Job Closed	16/09/2016	16/09/2016 Act	RD01/24543
	Lift and relay sunken slab and point around cover (Rocking Slab)	Outside cafe Nero at junction with rose street	.RD 7 Day	Job Closed	16/09/2016	17/09/2016 Act	RD01/24547
		On union bridge See photo numbers 3 & 4 on photo	.RD 7 Day	Job Closed	20/09/2016	26/09/2016 Act	RD01/24570
	Lift and relay loose rocking slabs (Rocking Slab)	On union bridge See photo numbers 1 & 2 on photo	.RD 7 Day	Job Closed	20/09/2016	26/09/2016 Act	RD01/24569
	Lift and relay 2 x rocking Caithness slabs ( loosened by fitting of new sign) (Rocking Slab)	At top of back Wyndham steps next to new information sign	.RD 7 Day	Job Closed	09/10/2016	11/10/2016 Act	RD01/24832
	Lift and relay loose and rocking Caithness slab (Rocking Slab)	Outside number 19 at rain water channel (Rs Mcolls)	.RD 7 Day	Job Closed	09/10/2016	11/10/2016 Act	RD01/24832
	Lift and relay 4 x sunken grey setts (Setts)	Outside number 245 next to Nevis sport	.RD 7 Day	Job Closed	25/10/2016	25/10/2016 Act	RD01/24952
	Lift and relay all loose raised and sunken slabs and grey lock block in area marked on photo (Rocking Slab)		.RD Emergency	Job Closed	09/11/2016	10/11/2016 Act	RD01/25119
	rocking slab,loose tile, lift and relay.	at side of cafe neros towards corner of market str as per attached photo.	.RD 2 Day	Job Closed	15/11/2016	15/11/2016 Act	RD01/25195
	Lift and relay loose raised and rocking slab Lift and replace broken and rocking 900 x 600 slab (Broken Slab)	Union Street-outside Capitol Theatre next to black bollard.	.RD 2 Day	Job Closed	15/11/2016	15/11/2016 Act	RD01/25198

Display Action Officer: No

	ance Management						
ob No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1,001.00 <b>A</b>	sset - Locn.: 1 - Footway		eature Type: RDS Footway		Area: Aberdeen C	Central
710199	Remove all loose material and point footway (Broken Slab)	Outside number 146 at BT Cover at New Restaurant old Monkey house See photo	.RD 7 Day	Job Closed	24/11/2016	27/11/2016 Act.	RD01/25303
710200	Lift all sunken and raised grey lock block and relay level (Setts)	At crossing point outside KFC at junction with Diamond Street See photo	.RD 7 Day	Contractor Completed	24/11/2016	01/12/2016 Act.	RD01/25307
710201	Lift and relay sunken 900 x 600 slab causing trip hazard (Rocking Slab)	Outside BETFRED down from g South Silver Street See photo	.RD 7 Day	Job Closed	24/11/2016	28/11/2016 Act.	RD01/25306
710234	Lift and relay loose and rocking 600 x 600 slab (Rocking Slab)	Outside trailfinders travel shop at gas toby on UNION STREET iPad unable to locate Union street	.RD 7 Day	Job Closed	28/11/2016	29/11/2016 Act.	RD01/25326
710449	Lift and relay all loose and rocking slabs (Rocking Slab)	Outside number 363 Bruce millars	.RD 7 Day	Contractor Completed	07/12/2016	09/12/2016 Act.	RD01/25413
	Lift and relay loose and rocking slab (Rocking Slab)	Outside number 371 Toni and guy hairdresser	.RD 7 Day	Contractor Completed	07/12/2016	09/12/2016 Act.	RD01/25418
710451	Lift and relay all loose raised and rocking grey setts (Setts)	Outside Virgin Money at and beside post box See photo	.RD 7 Day	Contractor Completed	07/12/2016	10/12/2016 Act.	RD01/25424
710595	5 Lift and relay sunken slab (Rocking Slab)	Outside number 148 closed TSB Bank	.RD 7 Day	Contractor Completed	14/12/2016	14/12/2016 Act.	RD01/25504
710596	Lift and relay raised slab (Rocking Slab)	Outside the monkey house See photo	.RD 7 Day	Contractor Completed	14/12/2016	14/12/2016 Act.	RD01/25503
710597	Remove broken loose 600 x 600 broken slab and replace with new slab Lift and relay loose and rocking slab (Broken Slab)		.RD 7 Day	Contractor Completed	14/12/2016	14/12/2016 Act.	RD01/25512
710598	B Lift and relay all loose rocking and raised slabs (Rocking Slab)	On Union bridge from telephone bad to jamiesons and carry See photo	.RD 7 Day	Contractor Completed	14/12/2016	14/12/2016 Act.	RD01/25511
710599	D Lift and relay raised 400 x 400 slab (Rocking Slab)	Outside number 160 beside cafe Nero See photo	.RD 7 Day	Contractor Completed	14/12/2016	14/12/2016 Act.	RD01/25510
710673	Remove all loose material and point footway around cover (Broken Slab)	At BT Manhole cover outside soul bar See photo	.RD 7 Day	Contractor Completed	16/12/2016	08/01/2017 Act.	RD01/25562
710674	Lift and relay loose and rocking red dimple slab Lift and relay loose and rocking 600 x 600 slab (Rocking Slab)	At crossing point outside soul bar See photo	.RD 7 Day	Contractor Completed	16/12/2016	06/01/2017 Act.	RD01/25562
710675	5 Lift and relay all raised red dimple slabs at crossing (Rocking Slab)	At crossing point outside soul bar See photo	.RD 7 Day	Contractor Completed	16/12/2016	10/01/2017 Act.	RD01/25562

Display Action Officer: No

Maintena	nce Management						
lob No. D	Description	Location	Priority	Job Status	Entered	Completion	Works Order
A	Asset: 1,001.00 A	sset - Locn.: 1 - Footway	Feature	Type: RDS Footway		Area: Aberdeer	Central
S	ift and relay loose and rocking labs (Rocking Slab)	Outside number 252 amicable house	.Routine Maintenance	Contractor Completed	16/12/2016	04/01/2017 Ad	et. RD01/25590
	lift and relay loose and rocking labs (Rocking Slab)	Outside number 420 Aberdein considine	.RD 2 Day	Contractor Completed	16/12/2016	19/12/2016 Ad	et. RD01/25559
si re re V th	Lift and relay loose and rocking slab and remove poor cement epair around nal cover and epoint.  Very poor utility company repair hat we have to repair (Rocking Slab)	Outside cafe Nero at number 454	.RD 7 Day	Contractor Completed	16/12/2016	06/01/2017 Ad	at. RD01/25562
710942 F	Find and Fix 1 pothole filled by	498	.Routine Maintenance	Job Closed	06/01/2017	02/01/2017 Ad	et.
	ind and Fix - pointed around bt cover and made safe -	chapel street crossing point	.Routine Maintenance	Job Closed	10/01/2017	03/01/2017 Ad	et.
	ft and relay rocking slba	o/s silverfinn building as attached photo directly across from Rose Street jctn	.RD 2 Day	Contractor Completed	12/01/2017	13/01/2017 Ad	et. RD01/25707
	ift and relay loose and rocking lab (Rocking Slab)	204-208 Union street at coop down from huntly street Note: iPad unable to locate Union street have been trying different location without any success This has been reported on numerous occasions	.RD 7 Day	Contractor Completed	23/01/2017	10/02/2017 Ad	tt. RD01/25824
C fi	ift and relay 2 x rocking Caithness slabs ( loosened by itting of new sign) (Rocking Slab) ***HOLD***	At top of back Wynd steps next to new information sign	.Routine Maintenance	Job Raised	30/01/2017	27/02/2017 Es	st.
712031 L s	ift and relay loose and rocking labs (very slight movement) Rocking Slab)	Outside number 158 cafe Nero number	.RD 7 Day	Contractor Completed	06/02/2017	13/02/2017 Ad	et. RD01/26011
	ift and relay loose and rocking labs (Rocking Slab)	Outside mostyn and Mackenzie shoe shop number 227	.RD 7 Day	Contractor Completed	10/02/2017	12/02/2017 Ad	et. RD01/26103
	ift and relay loose and rocking loo x 400 slabs (Rocking Slab)	Outside Sally hairdresser shop	.RD 7 Day	Contractor Completed	10/02/2017	12/02/2017 Ad	et. RD01/26102
712239 L	ift and relay loose and rocking slab (Rocking Slab)	Outside the old monkey house	.RD 7 Day	Contractor Completed	10/02/2017	12/02/2017 Ad	et. RD01/26101
712240 L	ift and relay loose and rocking labs (Rocking Slab)	At black door next to game store	.RD 7 Day	Contractor Completed	10/02/2017	12/02/2017 Ad	et. RD01/26100
712286 L	ift and relay loose and rocking labs (Rocking Slab)	Outside hello hairdresser	.RD 7 Day	Contractor Completed	13/02/2017	23/02/2017 Ad	et. RD01/26124
712571 R	Replace broken and loose Caithness slab (Broken Slab)	At right hand side of entrance into st Nicholas church	.RD 7 Day	Contractor Completed	19/02/2017	21/02/2017 Ad	et. RD01/26195
712572 L	ift and reset sunken footway jully as required (Iron Works)	Outside McDonald's restaurant	.RD 7 Day	Order Printed	19/02/2017	27/02/2017 Es	st. RD01/26194

Display Action Officer: No

							:
b No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
		sset - Locn.: 1 - Footway		eature Type: RDS Footway		Area: Aberdeen C	entral
712573	Remove all loose material and point footway (Broken Slab)	At greggs baker shop up from Dee street at rain water chnnel	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26193
712574	Lift and relay loose and rocking slab (Rocking Slab)	Outside soul bar See photo	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26192
712575	Lift and relay loose and rocking slabs (Rocking Slab)	Outside number 363	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26191
	Lift and relay raised red dimple slabs to remove trip (Rocking Slab)	Outside the justice mill bar at crossing	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26190
712577	Lift and relay loose and rocking slab (Rocking Slab)	Outside alliance house number 453	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26189
712578	Lift and relay loose and rocking slab (Rocking Slab)	Outside Enid hutt gallery down from Alford place	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26188
712579	Lift and relay loose and rocking slabs (Rocking Slab)	Outside brook street agency	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26187
712580	Remove all loose material and point footway (Broken Slab)	At cafe Nero junction with rose street	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26186
712582	Lift and relay loose and rocking slab (Rocking Slab)	Outside Aberdein considine property shop down from chapel street	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26185
712583	Lift and relay loose and rocking slabs (Rocking Slab)	Outside W H smith closed shop	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26184
712584	Lift and relay loose and rocking slab (Rocking Slab)	Outside number 262	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26183
712585	Lift and relay loose and rocking slab (Rocking Slab)	Outside number 252 blue arrow	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26182
	Lift and relay loose and rocking slab (Rocking Slab)	Outside number 252 blue arrow beside cash machine	.RD 7 Day	Contractor Completed	19/02/2017	20/02/2017 Act.	RD01/26181
	Lift and relay loose and rocking slabs (Rocking Slab)	Outside number 220 digby browns	.RD 7 Day	Contractor Completed	28/02/2017	06/03/2017 Act.	RD01/26325
713937	Lift and relay loose and rocking slab (Rocking Slab)	Beside flower planter at traffic light control opposite RBS Bank See photo	.RD 7 Day	Contractor Completed	28/03/2017	29/03/2017 Act.	RD01/26741
	Reset rocking slab (Rocking Slab)	Near 185 Supercuts	.RD 14 Day	Contractor Completed	22/04/2017	02/05/2017 Act.	RD01/27035
	Reset rocking slab (Rocking Slab)	Near 187 Edinburgh Woolen mill near bus stop	.RD 14 Day	Contractor Completed	22/04/2017	02/05/2017 Act.	RD01/27034
714640	Reset rocking slab and 2 lock blocks (Rocking Slab)	265 Trailfinders	.RD 14 Day	Contractor Completed	22/04/2017	05/02/2017 Act.	RD01/27033
714641	Reset rocking slab (Rocking Slab)	Outside door of 407 near Tiger Bar	.RD 14 Day	Contractor Completed	22/04/2017	03/05/2017 Act.	RD01/27032
714642	Replace 1 x 900 x 600 broken rocking slab (Broken Slab)	Outside 431 Capitol	.RD 14 Day	Contractor Completed	22/04/2017	03/05/2017 Act.	RD01/27031
714643	Reset rocking slab (Rocking Slab)	Between 476-478 ,Johnsons Dry cleaners and Cinnamon	.RD 14 Day	Contractor Completed	22/04/2017	03/05/2017 Act.	RD01/27030

Display Action Officer: No

Maintenance	Management

ob No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1,001.00 <b>As</b>	sset - Locn.: 1 - Footway	Featur	e Type: RDS Footway		Area: Aberdeen	Central
	Reset 1 rocking tactile paving slab and repair broken concrete work (Rocking Slab)	At corner of Chapel Street outside 432 Gavin Bain and Co	.RD 14 Day	Contractor Completed	22/04/2017	04/05/2017 Act	. RD01/27029
714645	Reset 1 rocking tactile paving slab (Rocking Slab)	At corner of Chapel Street outside Aberdein Considine	.RD 14 Day	Contractor Completed	22/04/2017	04/05/2017 Act	. RD01/27028
	Reset rocking slab (Rocking Slab)	Along the frontage of Aberdein Considine 422-424	.RD 14 Day	Contractor Completed	22/04/2017	04/05/2017 Act	. RD01/27027
714647	Reset rocking slab (Rocking Slab)	On Footway of bridge over Denburn opposite HMV	.RD 14 Day	Contractor Completed	22/04/2017	03/05/2017 Act	. RD01/27026
714884	Reset rocking slab (Rocking Slab)	173 Union Street	.RD 14 Day	Contractor Completed	29/04/2017	08/05/2017 Act	. RD01/27123
714885	Reset rocking slab (Rocking Slab)	179 Near bus stop at Ponden home	.RD 14 Day	Contractor Completed	29/04/2017	08/05/2017 Act	. RD01/27122
714886	Reset rocking slab (Rocking Slab)	199 outside ShuropodyEnter	.RD 14 Day	Contractor Completed	29/04/2017	08/05/2017 Act	. RD01/27121
714887	Reset rocking slab (Rocking Slab)	Outside 245	.RD 14 Day	Contractor Completed	29/04/2017	08/05/2017 Act	. RD01/27120
	Lift and relay raised / sunken red dimple slabs (Rocking Slab)	Outside Barclays Bank and Sally's Hairdresser	.RD 7 Day	Contractor Completed	18/05/2017	21/05/2017 Act	. RD01/27380
715674	Find and Fix - point around bt box repaired by	o/s black & lizars	.Routine Maintenance	Contractor Completed	29/05/2017	28/05/2017 Act	
715675	Find and Fix -reset rocking 2' x 2' slab repaired by	498	.Routine Maintenance	Contractor Completed	29/05/2017	28/05/2017 Act	
	Find and Fix - pointing at kerb of ped xing	o/s sainsburys local	.Routine Maintenance	Contractor Completed	29/05/2017	28/05/2017 Act	
	Find and Fix pointing at buchan trap repaired by	480	.Routine Maintenance	Contractor Completed	29/05/2017	28/05/2017 Act	
715678	Find and Fix - reset part slab and lift and relay 2 400 x 400 slabs and point kerb	468	.Routine Maintenance	Contractor Completed	29/05/2017	28/05/2017 Act	
716518	Remove broken and loose slab and relay new 600 x 600 slab (Broken Slab)	Outside eclectic bar	.RD 7 Day	Contractor Completed	27/06/2017	30/06/2017 Act	. RD01/27845
	Lift and relay loose and rocking slabs (Rocking Slab)	3 slabs outside the thia restaurant 1 outside the closed TSB Bank See photos	.RD 7 Day	Contractor Completed	27/06/2017	30/06/2017 Act	. RD01/27846
	Lift and relay loose and rocking slabs (Rocking Slab)	Outside number 220 Digby Brown Solicitor	.RD 7 Day	Contractor Completed	04/07/2017	11/07/2017 Act	. RD01/27910
	Reset 2 rocking slabs and 4 lock blocks (Rocking Slab)	OUTSIDE EDINBURGH WOOLEN MILL187 - UNION STREET	.RD 2 Day	Contractor Completed	11/07/2017	11/07/2017 Act	. RD01/27967
	Lift and relay loose and rocking slab (Rocking Slab)	On union bridge second lion down from telephone box New slab	.RD 7 Day	Contractor Completed	15/08/2017	16/08/2017 Act	. RD01/28315

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Contractor Completed

Contractor Completed

Contractor Completed

Contractor Completed

Contractor Completed

Contractor Completed

Site: UNION STREET (7600082)

	Description	Location	Priority	Job Status	Entorod	Completion	Works Order
OD NO.	•		Priority		Entered	•	
	<u> </u>	sset - Locn.: 1 - Footway		ure Type: RDS Footway		Area: Aberdeen (	
717669	9 Lift and relay loose and rocking slabs (Rocking Slab)	Outside number 262 and NatWest bank cash machine See photos	.RD 7 Day	Contractor Completed	16/08/2017	17/08/2017 Act.	RD01/28322
717843	3 rocking slabs,lift and relay infill gaps	2no areas both on side of no 498,	.RD 7 Day	Contractor Completed	25/08/2017	28/08/2017 Act.	RD01/28386
718180	0 rocking slab,lift and relay.	outside capitol hotel.	.RD Emergency	Contractor Completed	13/09/2017	13/09/2017 Act.	
71818 <sup>-</sup>	1 rocking slab.lift and relay.	at corner of chapel street ,at edge of traffic utility lid.outside considienes.	.RD 7 Day	Contractor Completed	13/09/2017	19/09/2017 Act.	RD01/28495
718308	8 Lift and relay sunken slab	at burger king	.RD 7 Day	Contractor Completed	19/09/2017	15/09/2017 Act.	
718312	2 Reset rocking slab	between the Town House Door and Sherrif Court Door as attached photo	.RD 7 Day	Contractor Completed	19/09/2017	20/09/2017 Act.	RD01/28536
718379	9 rainwater channel ,infill gap cover with walking board.	r at saks pure,heading west just before capitol.	.RD 2 Day	Contractor Completed	22/09/2017	26/09/2017 Act.	RD01/28591
718380	0 rocking slabs,lift and relay,infill gaps.	440 at bryant .	.RD 7 Day	Contractor Completed	22/09/2017	24/09/2017 Act.	RD01/28592
71838 <sup>2</sup>	1 rocking slabs,lift and relay infill gaps approx 8no	at aberdeen considiene .chappel st jct.	.RD 7 Day	Contractor Completed	22/09/2017	24/09/2017 Act.	RD01/28593
718382	2 rocking slabs,lift and relay.infill gaps.appox 6no.	outside capitol.	.RD 7 Day	Contractor Completed	22/09/2017	24/09/2017 Act.	RD01/28594
718383	3 rocking slabs,lift and relay,3no infill gaps.	opps rose street jct.	.RD 7 Day	Contractor Completed	22/09/2017	24/09/2017 Act.	RD01/28595
718397	7 Replace broken rocking slab (Broken Slab)	On Union bridge Footway opposite Waterstones bookshop	.RD 14 Day	Contractor Completed	25/09/2017	26/09/2017 Act.	RD01/28611
718398	8 Rocking slab to reset (Rocking Slab)	On Union bridge Footway opposite HMV shop	.RD 14 Day	Contractor Completed	25/09/2017	26/09/2017 Act.	RD01/28610
	9 Rocking slab to reset (Rocking Slab)	231 near Nevis sports	.RD 14 Day	Contractor Completed	25/09/2017	26/09/2017 Act.	RD01/28608
	more and 6 lock blocks (Rocking Slab)	Near 179 Pondon homes shop	.RD 14 Day	Contractor Completed	25/09/2017	26/09/2017 Act.	RD01/28607
	9 Reset 2 rocking slabs one is red tactile paving (Rocking Slab)	Near corner of Bridge street outside Sally	.RD 14 Day	Contractor Completed	26/09/2017	27/09/2017 Act.	RD01/28618
718432	2 Reset rocking slab (Rocking Slab)	Near corner Union terrace outside Chaophraya	.RD 7 Day	Contractor Completed	26/09/2017	27/09/2017 Act.	RD01/28617
718688	8 lift and relay slabs,infill gaps.6no.	248,heading sth as per attached photo.	.RD 2 Day	Contractor Completed	11/10/2017	12/10/2017 Act.	RD01/28733
718689	9 rocking slabs,lift and relay,infill gaps. 8no	heading west 363, as per attached photo.	.RD 2 Day	Contractor Completed	11/10/2017	12/10/2017 Act.	RD01/28732
			55.75				DD01/00000

.RD 7 Day

.RD 2 Day

718914 Lift and Relay rocking slab

719142 Lift and relay rocking slab

719143 Lift and relay rocking slab

719144 Lift and relay rocking slab

719146 Lift and relay rocking slab

719145 Lift and relay rocking lock block

outside Sainsbury's

o/s pret a manger

154 - Lakeland

164

262

432

31/10/2017 01/11/2017 Act. RD01/28838

15/11/2017 16/11/2017 Act. RD01/28978

15/11/2017 16/11/2017 Act. RD01/28978

15/11/2017 16/11/2017 Act. RD01/28978

15/11/2017 16/11/2017 Act. RD01/28978

15/11/2017 16/11/2017 Act. RD01/28972

Display Action Officer: No

ob No. Descri	ption	Location	Priority		Job Status	Entered	Completion	<b>Works Order</b>
Asset:	1,001.00	Asset - Locn.: 1 - Footway		Feature	Type: RDS Footway		Area: Aberdeen 0	Central
719147 Lift and	relay rocking slab	148	.RD 7 Day		Contractor Completed	15/11/2017	16/11/2017 Act.	RD01/28978
719148 Lift and	relay loose lock block	154 - Lakeland	.RD 7 Day		Order Printed	15/11/2017	22/11/2017 Est.	RD01/28977
719149 Lift and	relay loose slabs and	o/s soul bar	.RD 7 Day		Order Printed	15/11/2017	22/11/2017 Est.	RD01/28974
tiles							_	
	relay loose setts and	o/s michie's chemist	.RD 7 Day		Order Printed	15/11/2017	22/11/2017 Est.	RD01/28973
blocks	relay loose slabs	outside capitol	.RD 7 Day		Order Printed	15/11/2017	22/11/2017 Est.	PD01/28075
	relay loose slabs I relay loose tactile slab	•	.RD 7 Day		Order Printed Order Printed		17/11/2017 Est.	
Asset:	•	Asset - Locn.: 7 - Market Street to Bridge Street-Footway	.itb 2 bay	Foature	Type: RDS Footway	13/11/2017	Area: Aberdeen 0	
	d Gully (Blocked Gully	<u>-</u>	Standard	i cature	Job Closed	08/08/2007	Alea. Abelueell	Jentiai
		Asset - Locn.: 9 - Belmont Street to Union Terrace-Footway	Stariuaru	Facture		06/06/2007	Area: Aberdeen 0	Sontrol .
Asset:	*	•	55.75	reature	Type: RDS Footway	0.111.10000	Area: Aberdeen C	entrai
64800 DUPLI		DUPLICATE	.RD 7 Day		Job Closed	04/11/2009		
64801 DUPLI		DUPLICATE	.RD 7 Day		Job Closed	04/11/2009		
Asset:	1,006.00	Asset - Locn.: 19 - Summer Street to Chapel Street-Footway			Type: RDS Footway		Area: Aberdeen (	Central
12926 yjepjzn		vcbzc	.Routine Mainte		Job Closed	05/10/2007		
Asset:	1,011.00	Asset - Locn.: 5 - Adelphi to Market Street-Footway		Feature	Type: RDS Footway		Area: Aberdeen (	Central
	relay 1 No 3x2 rocking eplace 1 No smashed		.RD 7 Day		Job Closed	13/08/2008	20/08/2008 Est.	
Asset:	1,014.00	Asset - Locn.: 20 - Bon-Accord Terrace to Holburn Street-Foot	way	Feature	Type: RDS Footway		Area: Aberdeen 0	Central
52737 setts si Columi	ubsided kerbside. (Rep	aint 0	.RD 2 Day		Job Closed	30/06/2008		
Asset:	1,020.00	Asset - Locn.: 14 - South Silver Street to Huntly Street-Footwa	у	Feature	Type: RDS Footway		Area: Aberdeen 0	Central
59145 2 x2 sla	ab rocking (Rocking SI	ab) at information umbrella at music hall	.RD Emergency		Job Closed	16/03/2009	17/03/2009 Est.	
Asset:	1,021.00	Asset - Locn.: 15 - Dee Street to Bon-Accord Street-Footway		Feature	Type: RDS Footway		Area: Aberdeen 0	Central
marked	3x2. and piece of slab I. (Rocking Slab)	o. 0	.RD 2 Day		Job Closed	10/12/2007		
16237 2x2. ro Slab)	ck. marked. (Rocking	0	.RD 2 Day		Job Closed	28/01/2008		
Asset:	10,000.00	Asset - Locn.: 1 - AT NO 5		Feature	Type: SL - Street Lamp		Area: Aberdeen (	Central
497714			.Routine Mainte	nance	Job Raised	26/08/2015		
Asset:	100,050.00	<b>Asset - Locn.:</b> 9051082682 - UNION STREET, AB11 5BN		Feature	Type: W - Commercial Wa	ste Property	Area: Aberdeen 0	Central
COLLE	Bin - **MISSED CLING BIN CTION** Two missed ng bins (Enquiry 67708)	Union Street	.Routine Mainte	nance	Job Raised	21/10/2016		

Contract: Roads Contract (General Maint) (RD01)

Site: UNION STREET (7600082)

Job Raised

29/07/2016

#### Maintenance Management

**Display Action Officer: No** 

Job No. Description Location Priority Job Status Entered Completion Works Order

Asset: 100,491.00 Asset - Locn.: 9051060492 UNION STREET, AB10 1TS Feature Type: W - Domestic Waste Property Area: Aberdeen Central

.Routine Maintenance

10085826 Complaint - Waste - Good Afternoon,

Union Street

reported that their bins were missed earlier today (confirm ID: 668458). Their general waste bin has now been collected but no one has returned for their mixed recycling. Could someone go back ASAP to uplift this please?

Thanks for your time.

Kind regards,

via Waste and Recycling -ContactCentre

- <ContactCentre@aberdeencity.gc
- 29/7/2016 2:06pm 29/7/2016
- 4:49pm CS. (Enquiry 1031129)

# Street Works Report



### **Works Details**

Works Ref: CA001-S000000017292

LAREF: Works Recorded Date: 26/07/2016 17:53 2129712

**UNION STREET** Address: Proposed start date: 12/01/2017 Actual start date: 12/01/2017 **ABERDEEN** 

Town: **ABERDEEN** Estimated end date: 13/01/2017 County: ABERDEEN CITY Latest Notice Type: WORKS CLOSED

Status: WORKS CLOSED Works Type: REMEDIAL OTHER

Project:

Promoter: Aberdeen City Council / Aberdeen City Council **Notifiable Authority:** Aberdeen City Council / Aberdeen City Council

NSG Ref: 76/00082 Easting: 393826.29 **Northing:** 806050.37

CARRIAGEWAY TYPE 1 - 10 TO 30 MS Carriageway Reinst.: Footway Reinst.: OTHER FOOTWAYS

WORKS ENTIRELY ON THE FOOTWAY Works Technique.: **Traffic Management:** MACHINE

Location: At 156 - footway **Description:** Electric connection

Sites

Site Surface Location Site status Site Location **Postcode** Depth Length Width PROP. REM. SITE At 156 - footway STD 0.00 0.00

STD Length: 0.00 **Depth Code: Dimensions:** 

> Width: 0.00

Easting: Surface Type: Northing:

**Interim Reinstatement Date: Permanent Reinstatement Date:** 

Contacts

Qualification Ref Contact type **Contact name Address** Tel No.

LICENSEE Twenty Twelve Civils Ltd 112-114 Oxford Road Clacton-On-Sea

Essex CO15 3TH

н	10	to	ry
	10	ιU	ע וי

Date/Time		Event Type	Details	Username
26/07/2016	17:53	WORKS RECORDED	PROPOSED WORKS: 23/08/2016 - 24/09/2016	
26/07/2016	17:53	SEVEN DAY	PROPOSED WORKS: 23/08/2016 - 24/09/2016	
26/07/2016	17:53	MAP CONFLICT	CA001-S000000013562 Restriction	
26/07/2016	17:53	MAP CONFLICT	CA001-S000000016262 Same Street - Dates Overlap	
26/07/2016	17:53	MAP CONFLICT	SW100-05449230/KIER Same Street - Dates Overlap	
26/07/2016	17:53	MAP CONFLICT	CA001-P000000016722 Same Street - Dates Overlap	
26/07/2016	17:53	MAP CONFLICT	SW100-05506730/OMC Same Street - Dates Overlap	
26/07/2016	17:53	MAP CONFLICT	BT024-ONEA730596B1 Within 100m	
26/07/2016	17:53	MAP CONFLICT	CA001-S000000017289 Same Street - Dates Overlap	
26/07/2016	17:53	MAP CONFLICT	CA001-S000000017290 Same Street - Dates Overlap	
26/07/2016	17:53	MAP CONFLICT	CA001-S000000017291 Same Street - Dates Overlap	
26/07/2016	18:05	WORKS DOCUMENT EMAILED	WORKS - stedavidson@aberdeencity.gov.uk	
27/07/2016	8:17	NOTICE ASSESSMENT	SW100-High Interest	
27/07/2016	12:19	VIEW NOTICE ASSESSMENT	KL501	
27/07/2016	12:24	NOTICE ASSESSMENT	KL501-High Interest	
27/07/2016	12:42	NOTICE ASSESSMENT	KL511-High Interest	
28/07/2016	13:43	NOTICE ASSESSMENT	WO001-High Interest	
29/07/2016	9:17	NOTICE ASSESSMENT	ZP001-High Interest	

00/00/0040	40.45	NOTICE ACCESSIVENT	00005 15 1 1 1	
02/08/2016		NOTICE ASSESSMENT	SG005-High Interest	
19/08/2016		WORKS DETAILS CHANGED	PROPOSED WORKS: 26/09/2016 - 28/09/2016	
19/08/2016		SEVEN DAY	PROPOSED WORKS: 26/09/2016 - 28/09/2016	
19/08/2016		MAP RESOLVED	SYSTEM	
19/08/2016	17:10	MAP CONFLICT	CA001-S000000013562 Restriction	
19/08/2016	17:10		CA001-P000000016722 Same Street - Dates Overlap	
19/08/2016		MAP CONFLICT	BT024-ONEA730596B1 Within 100m	
19/08/2016		MAP CONFLICT	CA001-S000000017289 Same Street - Dates Overlap	
19/08/2016		MAP CONFLICT	CA001-S000000017290 Same Street - Dates Overlap	
19/08/2016		MAP CONFLICT	CA001-S000000017291 Same Street - Dates Overlap	
19/08/2016	17:10	MAP CONFLICT	CA001-S000000017313 Same Street - Dates Overlap	
19/08/2016	17:10		CA001-S000000017314 Same Street - Dates Overlap	
19/08/2016		MAP CONFLICT	CA001-S000000017315 Same Street - Dates Overlap	
19/08/2016		MAP CONFLICT	CA001-S000000017318 Same Street - Dates Overlap	
19/08/2016	17:10		CA003-3687057 Same Street - Planned Major	
22/08/2016	8:06	NOTICE ASSESSMENT	SW100-High Interest	
22/08/2016	8:58	VIEW NOTICE ASSESSMENT	KL501	
22/08/2016	9:03	NOTICE ASSESSMENT	KL501-High Interest	
22/08/2016		NOTICE ASSESSMENT	WO001-High Interest	
22/08/2016		NOTICE ASSESSMENT	SG005-High Interest	
23/08/2016	13:37		KL511-High Interest	
30/08/2016	8:06	NOTICE ASSESSMENT	ZP001-High Interest	
16/09/2016	9:07	MAP RESOLVED	USER TAGGING	
16/09/2016	9:07	NOTICE ASSESSMENT	CA001-Map Co-ordination	
30/09/2016		WORKS STATUS CHANGED	PROPOSED WORKS to IN PROGRESS	
30/09/2016		ACTUAL START	IN PROGRESS: 26/09/2016 - 28/09/2016	
30/09/2016		WORKS STATUS CHANGED	IN PROGRESS to WORKS CLOSED	
30/09/2016		WORKS CLOSED	WORKS CLOSED: 26/09/2016 - 30/09/2016	
09/01/2017		WORKS STATUS CHANGED	WORKS CLOSED to PROPOSED REMEDIAL	
09/01/2017		24 HOUR	PROPOSED REMEDIAL: 12/01/2017 - 13/01/2017	
		MAP CONFLICT	CA001-S000000013562 Restriction	
09/01/2017		MAP CONFLICT	CA001-S000000017289 Same Street - Dates Overlap	
09/01/2017		MAP CONFLICT	CA001-S000000017665 Restriction	
09/01/2017		MAP CONFLICT	CA001-P000000017937 Same Street - Dates Overlap	
09/01/2017		MAP CONFLICT	SG021-1247237 Within 100m	
09/01/2017		MAP CONFLICT	CA001-P00000018033 Within 100m	
09/01/2017		NOTICE ASSESSMENT	WO001-Optional Response	
10/01/2017	7:33	NOTICE ASSESSMENT	SW100-Optional Response	
10/01/2017	9:38	VIEW NOTICE ASSESSMENT	KL501	
10/01/2017	9:46	NOTICE ASSESSMENT	KL501-Optional Response	
10/01/2017		NOTICE ASSESSMENT	ZP001-Optional Response	
10/01/2017		NOTICE ASSESSMENT	SG005-Optional Response	
11/01/2017		NOTICE ASSESSMENT	KL511-Optional Response	
13/01/2017		WORKS STATUS CHANGED	PROPOSED REMEDIAL to IN PROGRESS	
13/01/2017		ACTUAL START	IN PROGRESS: 12/01/2017 - 13/01/2017	
13/01/2017		WORKS STATUS CHANGED	IN PROGRESS to WORKS CLOSED	
13/01/2017		WORKS CLOSED	WORKS CLOSED: 12/01/2017 - 13/01/2017	
13/01/2017	21:10	MAP RESOLVED	SYSTEM	

# Street Works Report



#### **Works Details**

Works Ref: CA001-S000000017318

LAREF: 2130915 Works Recorded Date: 28/07/2016 14:27

Address: UNION STREET Proposed start date: 06/11/2016

ABERDEEN Actual start date: 06/11/2016
ABERDEEN Estimated end date: 10/11/2016

County: ABERDEEN CITY Latest Notice Type: WORKS CLOSED

Works Type: REMEDIAL OTHER Status: WORKS CLOSED

Traffic Sensitive Engineering Difficulty Other

Project:

Town:

**Promoter:** Aberdeen City Council / Aberdeen City Council **Notifiable Authority:** Aberdeen City Council / Aberdeen City Council

NSG Ref: 76/00082 Easting: 393828.70 Northing: 806051.62

Carriageway Reinst.: CARRIAGEWAY TYPE 1 - 10 TO 30 MS Footway Reinst.: OTHER FOOTWAYS

Traffic Management: LANE CLOSURE Works Technique.: MACHINE

Location: At 156 - f/way

Description: New Bus Shelter

Sites

Site Surface LocationSite statusSite LocationPostcodeDepthLengthWidth1PROP. REM. SITEAt 156 - f/waySTD0.000.00

Dimensions: Length: 0.00 Depth Code: STD

Width: 0.00

Surface Type: Easting:

Interim Reinstatement Date: Permanent Reinstatement Date:

Contacts

Contact type Contact name Address Tel No. Qualification Ref

LICENSEE Twenty Twelve Civils Ltd 112-114 Oxford Road

Clacton-On-Sea

Essex CO15 3TH

Charges

 Date/Time
 Charge description
 Charge value
 Net Value
 Invoiced

 04/11/2016
 10:58
 FPN SECTION 114(5) S0093
 0.00
 0.00
 No

Adjusted On hold

History

 Date/Time
 Event Type
 Details
 Username

 28/07/2016
 14:27
 WORKS RECORDED
 PROPOSED WORKS: 23/08/2016 - 24/09/2016

 28/07/2016
 14:27
 SEVEN DAY
 PROPOSED WORKS: 23/08/2016 - 24/09/2016

 28/07/2016
 14:27
 MAP CONFLICT
 CA001-S000000013562 Restriction

 28/07/2016
 14:27
 MAP CONFLICT
 CA001-S000000016262 Same Street - Dates Overlap

 28/07/2016
 14:27
 MAP CONFLICT
 CA001-P000000016722 Same Street - Dates Overlap

 28/07/2016
 14:27
 MAP CONFLICT
 SW100-05506730/OMC Same Street - Dates Overlap

28/07/2016 14:27 MAP CONFLICT BT024-ONEA730596B1 Within 100m

 28/07/2016
 14:27
 MAP CONFLICT
 CA001-S000000017289 Same Street - Dates Overlap

 28/07/2016
 14:27
 MAP CONFLICT
 CA001-S000000017290 Same Street - Dates Overlap

 28/07/2016
 14:27
 MAP CONFLICT
 CA001-S000000017291 Same Street - Dates Overlap

 28/07/2016
 14:27
 MAP CONFLICT
 CA001-S000000017292 Same Street - Dates Overlap

28/07/2016 14:27 MAP CONFLICT CA001-S000000017313 Same Street - Dates Overlap
28/07/2016 14:27 MAP CONFLICT CA001-S000000017314 Same Street - Dates Overlap

28/07/2016 14:27 MAP CONFLICT CA001-S000000017315 Same Street - Dates Overlap 28/07/2016 14:47 NOTICE ASSESSMENT SW100-High Interest

28/07/2016	16:39	VIEW NOTICE ASSESSMENT	KL501	
28/07/2016	16:41	NOTICE ASSESSMENT	KL501-High Interest	
29/07/2016	9:18	NOTICE ASSESSMENT	ZP001-High Interest	
29/07/2016	14:59	NOTICE ASSESSMENT	WO001-High Interest	
01/08/2016		NOTICE ASSESSMENT	KL511-High Interest	
02/08/2016		NOTICE ASSESSMENT	SG005-High Interest	
26/08/2016		WORKS DETAILS CHANGED	PROPOSED WORKS: 26/09/2016 - 28/09/2016	
26/08/2016		SEVEN DAY	PROPOSED WORKS: 26/09/2016 - 28/09/2016	
26/08/2016	18:03	MAP RESOLVED	SYSTEM	
26/08/2016		MAP CONFLICT	CA001-S000000013562 Restriction	
26/08/2016	18:03		CA001-P000000016722 Same Street - Dates Overlap	
26/08/2016	18:03	MAP CONFLICT	BT024-ONEA730596B1 Within 100m	
26/08/2016	18:03	MAP CONFLICT	CA001-S000000017289 Same Street - Dates Overlap	
26/08/2016	18:03	MAP CONFLICT	CA001-S000000017203 Same Street - Dates Overlap	
26/08/2016	18:03	MAP CONFLICT	CA001-S000000017291 Same Street - Dates Overlap	
26/08/2016	18:03	MAP CONFLICT	CA001-S000000017292 Same Street - Dates Overlap	
26/08/2016	18:03	MAP CONFLICT	CA001-S000000017292 Same Street - Dates Overlap	
26/08/2016	18:03	MAP CONFLICT	CA001-S000000017313 Same Street - Dates Overlap	
26/08/2016	18:03	MAP CONFLICT	CA001-S000000017315 Same Street - Dates Overlap	
26/08/2016	18:03	MAP CONFLICT	CA003-3687057 Same Street - Planned Major	
29/08/2016	8:05	NOTICE ASSESSMENT	SW100-High Interest	
29/08/2016	9:20	NOTICE ASSESSMENT	SG005-High Interest	
30/08/2016	8:04	VIEW NOTICE ASSESSMENT	KL501	
30/08/2016	8:07	NOTICE ASSESSMENT	ZP001-High Interest	
30/08/2016	8:17	NOTICE ASSESSMENT	-	
31/08/2016	11:39	NOTICE ASSESSMENT	KL501-High Interest KL511-High Interest	
31/08/2016	14:45	NOTICE ASSESSMENT	WO001-High Interest	
16/09/2016	9:07	MAP RESOLVED	USER TAGGING	
16/09/2016	9:07	NOTICE ASSESSMENT	CA001-Map Co-ordination	
29/09/2016	14:10	WORKS STATUS CHANGED	PROPOSED WORKS to IN PROGRESS	
29/09/2016		ACTUAL START	IN PROGRESS: 26/09/2016 - 28/09/2016	
		WORKS STATUS CHANGED	IN PROGRESS to WORKS CLOSED	
		WORKS CLOSED	WORKS CLOSED: 26/09/2016 - 30/09/2016	
04/11/2016		WORKS STATUS CHANGED	WORKS CLOSED to PROPOSED REMEDIAL	
04/11/2016		THREE DAY	PROPOSED REMEDIAL: 06/11/2016 - 06/11/2016	
04/11/2016	10:56	MAP CONFLICT	CA001-S000000013562 Restriction	
04/11/2016		MAP CONFLICT	CA001-9000000015302 Restriction  CA001-P000000016025 Within 500m T/S	
04/11/2016		MAP CONFLICT	CA001-P000000010023 Within 300in 173  CA001-P000000016722 Same Street - Dates Overlap	
04/11/2016	10:56		CA003-3687057 Same Street - Planned Major	
04/11/2016		MAP CONFLICT	CA001-S000000017665 Restriction	
04/11/2016	10:56		CA001-P000000017003 Restriction  CA001-P000000017937 Same Street - Dates Overlap	
04/11/2016		VIEW NOTICE ASSESSMENT	KL501	
04/11/2016		NOTICE ASSESSMENT	KL511-High Interest	
04/11/2016		NOTICE ASSESSMENT	SW100-High Interest	
04/11/2016	13:58		ZP001-High Interest	
04/11/2016		VIEW NOTICE ASSESSMENT	KL501	
04/11/2016	15:03	NOTICE ASSESSMENT	KL501-High Interest	
07/11/2016	8:42	NOTICE ASSESSMENT	SG001-High Interest	
08/11/2016		NOTICE ASSESSMENT	WO001-High Interest	
10/11/2016		WORKS STATUS CHANGED	PROPOSED REMEDIAL to IN PROGRESS	
10/11/2016		ACTUAL START	IN PROGRESS: 06/11/2016 - 06/11/2016	
10/11/2016		WORKS STATUS CHANGED	IN PROGRESS: 06/11/2016 - 06/11/2016 IN PROGRESS to WORKS CLOSED	
10/11/2016		WORKS CLOSED	WORKS CLOSED: 06/11/2016 - 10/11/2016	
		MAP RESOLVED	SYSTEM	
Decience		IVID INCOCEVED	O I O I LIVI	

Type Validity Start date End date

**BRIDGE EVERYDAY** 

From 35 metres north east of junction with Union Terrace and Bridge Street for 25 metres north east

Bridge (Road Over Rail) Named - A9013 UNION STREET, ABERDEEN Referenced by Network Rail as - ELR: ANI1 No: 7

**EVERYDAY** 

TRAFFIC SENSITIVE **EVERYDAY** 

Restricted on Weekdays from 0730 to 0915 and from 1600 to 1800 Critical Signalized Junction

SPECIAL ENGINEERING DIFFICULTY Footway S side; Bon-accord St. - Bon-accord Terr.

Waterproofing membrane under basecourse

**BRIDGE EVERYDAY** 

Union Street Arches - Under Bridge

PRIVATE APPARATUS **EVERYDAY** 

Footway at Caledonian House (nos.232 - 238)

Lightning conductors

PRIVATE APPARATUS **EVERYDAY** 

S footway Exchequer Row - Market St.

Private duct