From: Foi Enquiries

To:

Subject: EIR-17-1881 - Inspection - Oldcroft Place

Date: 11 January 2018 11:56:38

Attachments: Further Information - Right to Review & Appeal.pdf

EIR-17-1881 - Site History Report.pdf

Dear

Thank you for your clarified information request of 12 December 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

I would be grateful if you would provide the following information in relation Oldcroft Place, Stockethill, Aberdeen.

Dates of all safety inspections undertaken on the carriageway/road, 6th December 2015
 to 6th December 2017

Please refer to 'Condition Survey' in the attached Site History Report, <u>EIR-17-1881 – Site History Report</u>.

 Details of all carriageway defects identified during safety inspections, 6th December 2015 to 6th December 2017

Please refer to 'Maintenance Management' in the attached Site History Report, <u>EIR-17-1881 – Site History Report</u>.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Head of Service level have been redacted (blacked out) from the attached Site History Report. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with Regulation 3(a)(i) — Personal Information - of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, and the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as ACC considers that disclosure of this information would be a breach of the first Data Protection Principle (that personal information must be processed fairly and lawfully) and second Data Protection Principle (personal information must only be processed for a specific and lawful purpose).

Third parties named within the attached document and ACC Officers below Head of Service level would not expect ACC to release this information about them into the public domain under the EIRs (or the Freedom of Information (Scotland) Act 2002 (FOISA)).

 Details of how carriageway safety inspections are undertaken, including whether walked or driven, the speed of the inspection vehicle and the number of persons in the vehicle. Please refer to the following web link below to the Road Safety Inspection Manual, under page 7:

https://www.aberdeencity.gov.uk/sites/aberdeencms/files/Roads%20Safety%20Inspection%20Manual.pdf

As details of how carriageway safety inspections are undertaken, including whether walked or driven, the speed of the inspection vehicle and the number of persons in the vehicle is otherwise accessible in the Road Safety Inspection Manual, available at the above web link, it is exempt from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby gives notice that we are refusing your request under the terms of Regulation 6(1)(b) - Information Already Publicly Available - of the EIRs.

The intended frequency of carriageway safety inspections.

Inspection frequencies differ between roads depending on the classification. The inspection frequency for Oldcroft Place is 6 monthly.

Details of all complaints and/or enquiries relating to the carriageway 6th December 2015 to 6th December 2017

Please refer to 'Customer Services' in the attached Site History Report, <u>EIR-17-1881 – Site History Report</u>.

ACC has received no official complaints for the location specified during the timescale given. There are no complaints logged in the Complaints system regarding the carriageway of Oldcroft Place, Stockethill between 6 December 2015 and 6 December 2017.

ACC follows the Scottish Local Authority Complaints Handling Procedure. Under this procedure, a 'complaint' is defined as "an expression of dissatisfaction regarding our actions, or lack of action, or the standard of service provided by us or on our behalf". There are some topics that cannot be considered as a 'complaint', including first time requests for a service e.g. reporting a pothole or broken paving slab.

For more information please visit <u>www.aberdeencity.gov.uk/complaints</u> and refer to the 'What is a complaint?' section.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Head of Service level have been redacted (blacked out) from the attached Site History Report. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with Regulation 3(a)(i) — Personal Information - of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, and the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as ACC considers that disclosure of this information would be a breach of the first Data Protection Principle (that personal information must be processed fairly and lawfully) and second Data Protection Principle (personal information must only be processed for a specific and lawful purpose).

Third parties named within the attached document and ACC Officers below Head of Service level would not expect ACC to release this information about them into the public domain under the EIRs (or the Freedom of Information (Scotland) Act 2002 (FOISA)).

• The hierarchy classification.

This road has been classified as a Secondary Road.

• The road/section number. Clarification: if the road fell into a particular local office jurisdiction.

All Roads and Footways which are adopted by ACC are maintained in general by the Roads Department, there are no specific local offices per Road/Street.

 The defect intervention criteria adopted in relation to the identification of all categories of carriageway potholes.

Please refer to the online Road Safety Inspection Manual, pages 15-19: <a href="https://www.aberdeencity.gov.uk/sites/aberdeencuty.gov.uk/sites/aber

As the defect intervention criteria adopted in relation to the identification of all categories of carriageway potholes is otherwise accessible in the Road Safety Inspection Manual, available at the above web link, it is exempt from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby gives notice that we are refusing your request under the terms of Regulation 6(1)(b) - Information Already Publicly Available - of the EIRs.

• The time period(s) adopted between identification and repair (temporary and permanent) of all categories of carriageway defects.

Please refer to the online Road Safety Inspection Manual, pages 15-19: <a href="https://www.aberdeencity.gov.uk/sites/aberdeencuty.gov.uk/sites/aber

As the time period(s) adopted between identification and repair (temporary and permanent) of all categories of carriageway defects is otherwise accessible in the Road Safety Inspection Manual, available at the above web link, it is exempt from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby gives notice that we are refusing your request under the terms of Regulation 6(1)(b) - Information Already Publicly Available - of the EIRs.

 Whether or not the authority has formally adopted all or part of the standards contained within the national code of practice for highways maintenance management.

ACC has created a Road Safety Inspection Manual which is in line with the principles of 'Well-maintained Highways: Code of Practice for Highway Maintenance Management July 2005' (CoP). Please refer to the online Road Safety Inspection Manual on page 4 for further information:

https://www.aberdeencity.gov.uk/sites/aberdeencms/files/Roads%20Safety%20Inspection%20Manual.pdf

As information on whether or not the authority has formally adopted all or part of the standards contained within the national code of practice for highways maintenance management is otherwise accessible in the Road Safety Inspection Manual, available at the above web link, it is exempt from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby gives notice that we are refusing your request under the terms of Regulation 6(1)(b) - Information Already Publicly Available - of the EIRs.

We hope this helps with your request.

Yours sincerely,

Anna Buchan
Information Compliance Officer

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team
Customer Service
Corporate Governance
Aberdeen City Council
3rd Floor North
Business Hub 17
Marischal College
Broad Street
ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk

Tel 03000 200 292

*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.

Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

Contract: Roads Contract (General Maint) (RD01)

Site: OLDCROFT PLACE (7601355)

Service: Roads Display Action Officer: No

Site: OLDCROFT PLACE (7601355) Locality: ABERDEEN, ABERDEEN CITY Area: Aberdeen Central Condition Survey **Defect No: Description** Log Date Location **Defect Type** Class. Organisation Status Job No. 1.000.00 Asset - Locn.: N/19/1775 - OLDCROFT PLACE Feature Type: RDS Road Section Area: Aberdeen Central Asset: Batch: 537605 - Inspection Batch Route: Adhoc Inspection Date: 14/08/2017 466122 Jet patch all potholes and surface defects 14/08/2017 From forresterhill road to numbers Jet Patching Required Internal Uncommitted 717567 as required 96-146 oldcroft place Batch: 537604 - Inspection Batch Route: Adhoc Inspection Date: 14/08/2017 466121 Repair all potholes and surface defects as 14/08/2017 From forresterhill road to numbers Pot Hole Internal Committed 717566 96-146 oldcroft place Batch: 534687 - Inspection Batch Route: Adhoc Inspection Date: 26/06/2017 465395 Repair all potholes and surface defects as 26/06/2017 At opposite side of Road from numbers Pot Hole Internal Committed 716475 97-103 required Batch: 530820 - Inspection Batch Route: Week: 04 - Area: 12 Date: 26/04/2017 No actionable defects found Batch: 524380 - Inspection Batch Route: Adhoc Inspection Date: 24/01/2017 462291 Repair all potholes and surface defects as 24/01/2017 From car park entrance to numbers Pot Hole Internal Committed 711530 required various sizes approximately 500 x 48-94 to lamppost number 3 east 500 x 50mm (hot tar repair) bound Date: 16/01/2017 Batch: 523800 - Inspection Batch Route: Adhoc Inspection 462163 Reset sunken gully 16/01/2017 Beside telephone box opposite premier Iron Works Internal Committed 711285 stores Batch: 523799 - Inspection Batch Route: Adhoc Inspection Date: 16/01/2017 462162 Repair all potholes and surface defects as 16/01/2017 At entrance into car park opposite Internal 711284 Pot Hole Committed required premier stores Batch: 523798 - Inspection Batch Date: 16/01/2017 Route: Adhoc Inspection 462161 Blocked gully and gully cover fitted upside 16/01/2017 Beside telephone box opposite premier Blocked Gully Internal Committed 711283 down store Batch: 521339 - Inspection Batch Date: 06/12/2016 Route: Adhoc Inspection 461688 Repair pothole as required approximately 06/12/2016 Opposite car park lay by at flats Pot Hole Internal Committed 710436 500 x 500 x 70mm numbers 48-94 Batch: 518790 - Inspection Batch Route: Week: 28 - Area: 12 Date: 01/11/2016 No actionable defects found Batch: 499972 - Inspection Batch Route: Week: 04 - Area: 12 Date: 11/05/2016 458223 Repair pothole as required approximately 10/05/2016 At junction with oldcroft gardens Pot Hole Internal Archived 704665 200 x 200 x 45mm Batch: 494277 - Inspection Batch Route: Adhoc Inspection Date: 01/03/2016 456130 jet patch repair or multi hog repair trench 01/03/2016 From Croft tavern pub to forresterhill Pot Hole Internal Archived 702025 of road on left hand side heading towards road forresterhill road

Contract: Roads Contract (General Maint) (RD01) Site: OLDCROFT PLACE (7601355) Service: Roads
Display Action Officer: No

Condition Survey

fect No: Desc	cription		Log Date	Location		Defect Type	Class. Organisati	on Status	Job No.
Asset:	1,000.00	Asset - Locn.:	V/19/1775 - C	LDCROFT PLACE		Feature	Type: RDS Road Section	Area: Aberde	een Central
Batch: 49	94276 - Inspection	Batch			Route: Adh	noc Inspection			Date: 01/03/2016
requ	ir all pot holes and ired various sizes m deep to 300 x 3	from 900 x 900 x	01/03/2016	From number 96 to forres	sterhill road	Pot Hole	Internal	Archived	702024
Batch: 49	91092 - Inspection	Batch			Route: Adh	noc Inspection			Date: 15/01/2016
	ir all pot holes rutti cts as required	ng and surface	15/01/2016	OLDCROFT PLACE From to forresterhill road	m number 96	Pot Hole	Internal	Archived	700128
Asset:	1,001.00	Asset - Locn.:	1 - Forresterh	ill Road to No 33-47-Footw	ay	Feature	Type: RDS Footway	Area: Aberde	een Central
Batch: 53	30821 - Inspection	Batch			Route: We	ek: 04 - Area: 12			Date: 26/04/2017
No a	actionable defects f	ound							
Batch: 5'	18791 - Inspection	Batch			Route: We	ek: 28 - Area: 12			Date: 01/11/2016
No a	actionable defects f	ound							
Batch: 50	00171 - Inspection	Batch			Route: We	ek: 04 - Area: 12			Date: 11/05/2016
No a	actionable defects f	ound							
Asset:	1,002.00	Asset - Locn.:	7 - In front of	No 121-125-Footway		Feature	Type: RDS Footway	Area: Aberde	een Central
Batch: 53	30822 - Inspection	Batch			Route: We	ek: 04 - Area: 12			Date: 26/04/2017
No a	actionable defects f	ound							
Batch: 5'	18792 - Inspection	Batch			Route: We	ek: 28 - Area: 12			Date: 01/11/2016
No a	actionable defects f	ound							
Batch: 50	00172 - Inspection	Batch			Route: We	ek: 04 - Area: 12			Date: 11/05/2016
No a	actionable defects f								
Asset:	1,003.00	Asset - Locn.:	2 - Forresterh	ill Road to Croft House-Foo	otway	Feature	Type: RDS Footway	Area: Aberde	een Central
Batch: 53	30823 - Inspection	Batch			Route: We	ek: 04 - Area: 12			Date: 26/04/2017
No a	actionable defects f	ound							
Batch: 51	18793 - Inspection	Batch			Route: We	ek: 28 - Area: 12			Date: 01/11/2016
No a	actionable defects f	ound							
Batch: 50	00173 - Inspection	Batch			Route: We	ek: 04 - Area: 12			Date: 11/05/2016
No a	actionable defects t								
Asset:	1,004.00	Asset - Locn.:	3 - No 73-79 t	o 113-119-Footway		Feature	Type: RDS Footway	Area: Aberde	een Central
Batch: 53	30824 - Inspection	Batch			Route: We	ek: 04 - Area: 12			Date: 26/04/2017
	actionable defects f								
Batch: 51	18794 - Inspection	Batch			Route: We	ek: 28 - Area: 12			Date: 01/11/2016
	actionable defects f								
Batch: 50	00174 - Inspection	Batch			Route: We	ek: 04 - Area: 12			Date: 11/05/2016
No a	actionable defects f	ound							

Contract: Roads Contract (General Maint) (RD01) Site: OLDCROFT PLACE (7601355) Service: Roads
Display Action Officer: No

Condition Survey

ect No: Des	cription	Lo	g Date Location	Defec	t Type	Class.	Organisation	Status	Job No
Asset:	1,005.00	Asset - Locn.: 4 - C	croft House to car park at	18-94-Footway	Feature Type	e: RDS Footway		Area: Abero	deen Central
Batch: 53	30825 - Inspection Ba	atch		Route: Week: 04 -	Area: 12				Date: 26/04/2017
No a	actionable defects fou	ınd							
Batch: 5	18795 - Inspection Ba	atch		Route: Week: 28 -	Area: 12				Date: 01/11/2016
No a	actionable defects fou	ınd							
Batch: 50	00175 - Inspection Ba	atch		Route: Week: 04 -	Area: 12				Date: 11/05/2016
No a	actionable defects for	ınd							
Asset:	1,006.00	Asset - Locn.: 5 - C	ar park at 48-94 to car pa	rk at 144-190-Footway	Feature Type	e: RDS Footway		Area: Abero	deen Central
Batch: 53	30826 - Inspection Ba	atch		Route: Week: 04 -	Area: 12				Date: 26/04/2017
No a	actionable defects for	ınd							
Batch: 5	18796 - Inspection Ba	atch		Route: Week: 28 -	Area: 12				Date: 01/11/2016
No a	actionable defects for	ınd							
Batch: 50	00176 - Inspection Ba	atch		Route: Week: 04 -	Area: 12				Date: 11/05/2016
No a	actionable defects fou	ınd							
Asset:	1,007.00	Asset - Locn.: 6 - C	Opposite No 121-125-Foot	way	Feature Type	e: RDS Footway		Area: Abero	deen Central
Batch: 53	30827 - Inspection Ba	atch		Route: Week: 04 -	Area: 12				Date: 26/04/2017
No a	actionable defects for	ınd							
Batch: 5	18797 - Inspection Ba	atch		Route: Week: 28 -	Area: 12				Date: 01/11/2016
No a	actionable defects fou	ınd							
Batch: 50	00177 - Inspection Ba	atch		Route: Week: 04 -	Area: 12				Date: 11/05/2016
No a	actionable defects fou								
Asset:	1,008.00	Asset - Locn.: 1 - F	orresterhill Road to Stock	ethill Crescent-Carriageway	Feature Type	e: RDS Carriagew	ay	Area: Abero	deen Central
Batch: 53	30828 - Inspection Ba	atch		Route: Week: 04 -	Area: 12				Date: 26/04/2017
No a	actionable defects fou	ınd							
Batch: 5	18798 - Inspection Ba	atch		Route: Week: 28 -	Area: 12				Date: 01/11/2016
	actionable defects fou								
Batch: 50	00178 - Inspection Ba	atch		Route: Week: 04 -	Area: 12				Date: 11/05/2016
No a	actionable defects fou								
Asset:	1,012.00	Asset - Locn.: 15 -	N side, Foresterhill Rd (Castleton Cresc. including brand	the Feature Type	e: RDS Footway		Area: Abero	deen Central
Batch: 53	30829 - Inspection Ba	atch		Route: Week: 04 -	Area: 12				Date: 26/04/2017
	actionable defects fou	-							
Batch: 5	18799 - Inspection Ba	atch		Route: Week: 28 -	Area: 12				Date: 01/11/2016
	actionable defects fou	-							
Batch: 50	00179 - Inspection Ba	atch		Route: Week: 04 -	Area: 12				Date: 11/05/2016
No a	actionable defects fou	ınd							

Contract: Roads Contract (General Maint) (RD01) Site: OLDCROFT PLACE (7601355) Service: Roads
Display Action Officer: No

Condition Survey

ect No: Desc	cription	Log Date Log	cation	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,013.00	Asset - Locn.: 16 - S side, whole		71		3	Area: Aberdee	
	30830 - Inspection Ba		. g,	Route: Week: 04 - Area: 12	,, 5 . coay			Date: 26/04/2017
	ctionable defects four							
	18800 - Inspection Ba			Route: Week: 28 - Area: 12				Date: 01/11/2016
	ctionable defects four							
Batch: 50	0180 - Inspection Ba	atch		Route: Week: 04 - Area: 12				Date: 11/05/2016
No a	ctionable defects four	nd						
Asset:	2,001.00	Asset - Locn.: 7601355/J/00001 -	Outside phonebox	Feature	Type: RDS Gully		Area: Aberdee	n Central
Batch: 51	13075 - Inspection Ba	atch		Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects four	nd						
Asset:	2,002.00	Asset - Locn.: 7601355/J/00002 -	Opp phonebox	Feature	Type: RDS Gully		Area: Aberdee	n Central
Batch: 51	13076 - Inspection Ba	atch		Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects four	nd						
Asset:	2,003.00	Asset - Locn.: 7601355/J/00003 -	Outside #113-119	Feature	Type: RDS Gully		Area: Aberdee	n Central
Batch: 51	13077 - Inspection Ba	atch		Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects four	nd						
Asset:	2,004.00	Asset - Locn.: 7601355/J/00004 -	Opp #113-119	Feature	Type: RDS Gully		Area: Aberdee	n Central
Batch: 51	13078 - Inspection Ba	atch		Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects four							
Asset:	2,005.00	Asset - Locn.: 7601355/J/00005 -	Outside #97-103	Feature	Type: RDS Gully		Area: Aberdee	
Batch: 51	13079 - Inspection Ba	atch		Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects four	•						
Asset:	2,006.00	Asset - Locn.: 7601355/J/00006 -	Opp #97-103		Type: RDS Gully		Area: Aberdee	n Central
	13080 - Inspection Ba			Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects four							
Asset:	2,007.00	Asset - Locn.: 7601355/J/00007 -	Outside #73-79		Type: RDS Gully		Area: Aberdee	
	13081 - Inspection Ba			Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects four							
Asset:	2,008.00	Asset - Locn.: 7601355/J/00008 -	Outside #73-79		Type: RDS Gully		Area: Aberdee	
	13082 - Inspection Ba			Route: Adhoc Inspection				Date: 02/09/2016
	ctionable defects four							
Asset:	2,009.00	Asset - Locn.: 7601355/J/00009 -	Opp #33-47		Type: RDS Gully		Area: Aberdee	
	13083 - Inspection Ba			Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects four	nd						

Contract: Roads Contract (General Maint) (RD01) Site: OLDCROFT PLACE (7601355)

Service: Roads Display Action Officer: No

Condition Survey

Defect No: Desc	cription	Log Date Location	Defect Type	Class.	Organisation	Status	Job No
Asset:	2,010.00	Asset - Locn.: 7601355/J/00010 - Outside #17-45	Feature Type	: RDS Gully		Area: Aberdeen	Central
Batch: 5	13084 - Inspectio	n Batch F	Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects	s found					
Asset:	2,011.00	Asset - Locn.: 7601355/J/00011 - Opp #17-45	Feature Type	: RDS Gully		Area: Aberdeen	Central
Batch: 5°	13085 - Inspectio	n Batch F	Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects	found					
Asset:	2,012.00	Asset - Locn.: 7601355/J/00012 - Opp #1-15	Feature Type	: RDS Gully		Area: Aberdeen	Central
Batch: 5°	13086 - Inspectio	n Batch F	Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects	s found					
Asset:	2,013.00	Asset - Locn.: 7601355/J/00013 - Near roundabout	Feature Type	: RDS Gully		Area: Aberdeen	Central
Batch: 5°	13087 - Inspectio	n Batch F	Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects	s found					
Asset:	2,014.00	Asset - Locn.: 7601355/J/00014 - Near roundabout	Feature Type	: RDS Gully		Area: Aberdeen	Central
Batch: 5	13088 - Inspectio	n Batch F	Route: Adhoc Inspection				Date: 02/09/2016
No a	ctionable defects	s found					

Customer Services

Enquiry No.: 726288 Logged by: Contact Centre on: 04/12/2017 12:25

Service: Roads Subject: Claims - Roads Classification: Claim **Enquiry Ref:**

taxi driver reporting that he hit a pothole on Oldcroft Place, near the roundabout at Foresterhill Road on Saturday 2nd December 2017 in the early hours, his front offside tyre is Desc.:

damaged and his 19 inch alloy wheel is also damaged.

Location: Oldcroft Place, Aberdeen Contact:

Enquiry No.: 726196 Logged by: Contact Centre on: 03/12/2017 23:29

Subject: Pot Hole - Road Classification: Enquiry **Enquiry Ref:** Service: Roads

Desc.: ROADS30678

Site (Street/Park/etc): Street

Location: Side of road, in front of 108 Oldcroft Place, Aberdeen, AB16 5UD

Locational Details: In front of house

First Type of Fault : Pothole

First Fault Details: Huge pot hols from the side of the road all the way into the middle. Can no longer drive round them. Someone is going to loose a tyre. This happens every year

Additional Information: I have photos. Needs to be filled in properly, not just with chuckies as done previously

Location: Side of road, in front of 108 Oldcroft Place, Aberdeen, AB16 5UD Contact:

Plot Number: 1,000.00 Feature Id - Location: N/19/1775 - OLDCROFT PLACE

Feature Type: RDS Road Section

Job Number: 719419

Contract: Roads Contract (General Maint) (RD01)

Site: OLDCROFT PLACE (7601355)

Service: Roads Display Action Officer: No

Customer Services

Enquiry No.: 726174 **Logged by:** Contact Centre **on:** 02/12/2017 22:45

Service: Roads Subject: Pot Hole - Road Classification: Enquiry Enquiry Ref:

Desc.: Reference No : ROADS30662

Site (Street/Park/etc): Oldcroft Place

Location : Stockethill

Locational Details: Opposite side of road

First Type of Fault : Pothole First Fault Details : Huge potholes Second Type of Fault : Poor Road Surface

Additional Information: Numerous huge potholes next to one another

Location: Oldcroft Place Stockethill Contact:

Plot Number: 1.000.00 Feature Id - Location: N/19/1775 - OLDCROFT PLACE

Job Number: 719432

Enquiry No.: 724853 Logged by: Contact Centre on: 21/11/2017 08:57

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: Caller reporting the road surface and pavements on Oldcroft Place are in a bad state of repair, the road has been patched in so many places that it is bumpy and the pavement is crumbling. He

would like this looked into.

Location: Oldcroft Place Contact:

Enquiry No.: 715053 **Logged by:** Contact Centre **on:** 10/08/2017 21:31

Service: Roads Subject: Pot Hole - Road Classification: Defect Report Enquiry Ref:

Desc.: Reference No: ROADS30178

Site (Street/Park/etc): Street Location: Oldcroft Place, Aberdeen Locational Details: Opposite side of road

First Type of Fault : Pothole

Additional Information: From the roundabout on Foresterhill Road to the enterence to 96-142 Oldcroft Place, has potholes the whole length of it. The enterence to the car park across from the

Premier Shops on Oldcroft Place has potholes.

Location: OLDCROFT PLACE Contact:

Plot Number: 1,000.00 Feature Id - Location: N/19/1775 - OLDCROFT PLACE Feature Type: RDS Road Section

Job Number: 717566 Defect Number: 466121

Enquiry No.: 709792 **Logged by:** Contact Centre **on:** 23/06/2017 10:30

Service: Roads Subject: Pot Hole - Road Classification: Defect Report

Desc.: Reference No : ROADS30001

Site (Street/Park/etc): oldcroft place Location: near public house and shops

First Type of Fault : Pothole

Additional Information: Several potholes along Oldcroft Place

Name : ____ Address Line 1 :

Telephone Number : Email Address :

Location: ROADS30001 Contact:

Plot Number: 1,000.00 Feature ld - Location: N/19/1775 - OLDCROFT PLACE

Job Number: 716475 Defect Number: 465395

Feature Type: RDS Road Section

Enquiry Ref:

Feature Type: RDS Road Section

Contract: Roads Contract (General Maint) (RD01)

Site: OLDCROFT PLACE (7601355)

Service: Roads Display Action Officer: No

Customer Services **Enquiry No.:** 686352 Logged by: Contact Centre on: 23/01/2017 11:27 Subject: Pot Hole - Road Classification: Enquiry **Enquiry Ref:** Service: Roads Desc.: Reference No: ROADS28995. Site (Street/Park/etc): Oldcroft place Aberdeen. Location: Stockethill. First Type of Fault: Poor Road Surface. Second Type of Fault: Pothole. Additional Information: This road has always been in a poor condition and it is getting worse it's playing havoc with our cars. Address Line 1: Address Line 2: . Postcode: Email Address: Location: OLDCROFT PLACE, STOCKETHILL - ROADS28995 - AB Contact: Plot Number: 1.000.00 Feature Id - Location: N/19/1775 - OLDCROFT PLACE Feature Type: RDS Road Section Job Number: 711301 Logged by: Contact Centre on: 06/12/2016 14:09 **Enquiry No.:** 682190 **Enquiry Ref:** Service: Roads Subject: Claims - Roads Classification: Defect Report Desc.: CLAIM FORM REQUESTED FOR POTHOLE. DAMAGED CAR ON SUNDAY 27/11/16 AT APPROX 4.15PM. Location: OLDCROFT PLACE APPROX 300METERS FROM ENTRANCE FROM Contact: FORESTERHILL ROAD Logged by: Contact Centre on: 06/12/2016 09:16 **Enquiry No.:** 682093 Classification: Defect Report Subject: General Enquiry **Enquiry Ref:** Service: Roads Desc.: Road in bad condition with pothole in road, thought to be 10& quot; deep. Pavement also in bad condition. Uneven, cracked, etc. Location: Road and pavement frrom Oldcroft Gardens to first block of flats on Oldcroft Place Contact: (nos. 48-62) **Plot Number: 1,000.00** Feature Id - Location: N/19/1775 - OLDCROFT PLACE Feature Type: RDS Road Section Job Number: 710436 Defect Number: 461688 **Enquiry No.:** 660233 Logged by: Contact Centre on: 18/04/2016 14:27 Service: Roads Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Desc.: Reference No: ROADS28164. Site (Street/Park/etc): Oldcroft Place. Location: stocket Hill. Locational Details: Opposite side of road. First Type of Fault: Poor Road Surface. First Fault Details: also has pot holes and no road markings. Second Type of Fault: Pothole. Second Fault Details: multiple potholes. Additional Information: I would presume this has been reported due to the severity of the road condition, cones were placed on the worst areas but have since disappeared a few weeks ago. Name: Address Line 1: Address Line 2: Postcode: Telephone Number: Email Address: Location: OLDCROFT PLACE - ROADS28164 - AB Contact Plot Number: 1,000.00 Feature Id - Location: N/19/1775 - OLDCROFT PLACE Feature Type: RDS Road Section Job Number: 702025 **Enquiry No.:** 657338 Logged by: Contact Centre on: 16/03/2016 09:58 Service: Roads Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Desc.: Reference No: ROADS27965. Site (Street/Park/etc): Street. Location: Oldcroft Place. First Type of Fault: Poor Road Surface. Second Type of Fault: Pothole. Additional Information: On entrance to Oldcroft Place from Foresterhill Road, between the first and second right turn entrances; the road surface is broken up, with numerous large potholes. Name: Address Line Address Line 2: Postcode: Telephone Number: Email Address: Location: OLDCROFT PLACE - ROADS27965 - AB Plot Number: 1.000.00 Feature Id - Location: N/19/1775 - OLDCROFT PLACE Feature Type: RDS Road Section Job Number: 702025

Contract: Roads Contract (General Maint) (RD01)

Site: OLDCROFT PLACE (7601355)

Service: Roads Display Action Officer: No

Customer Services

Enquiry No.: 655895 **Logged by:** Contact Centre **on:** 29/02/2016 20:57

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: Reference No : ROADS27837

Site (Street/Park/etc): Oldcroft Place Location: 100m from Foresterhill Road. Locational Details: Opposite side of road

First Type of Fault : Pothole

First Fault Details: There are 2 potholes trying to mate and start a family causing drivers to swerve to avoid.

Additional Information: These potholes have been & amp; quot; filled & amp; quot; previously but not to an acceptable standard and are now liable to damage vehicles for anyone unwary of their depth.

Location: OLDCROFT PLACE Contact:

Plot Number: 1,000.00 Feature Id - Location: N/19/1775 - OLDCROFT PLACE Feature Type: RDS Road Section

Job Number: 702024 Defect Number: 456129

Enquiry No.: 651196 **Logged by:** Contact Centre **on:** 15/01/2016 08:42

Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:

Desc.: ROAD IS POTHOLED AND HAS UNEVEN SURFACE. REPORTED BY

Location: OLDCROFT PLACE Contact:

Plot Number: 1,000.00 Feature Id - Location: N/19/1775 - OLDCROFT PLACE

Job Number: 700128 Defect Number: 454615

Feature Type: RDS Road Section

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00 A	sset - Locn.: N/19/1775 - OLDCROFT PLACE	Feature	e Type: RDS Road Section		Area: Aberdee	n Central
5662	0 large pothole in c/way	at. 44./98	.Routine Maintenance	Job Closed	10/12/2008		
5666	4 large pothole in c/way.	48/94	.Routine Maintenance	Job Closed	11/12/2008		
18290	3 repair all surface defects as required (suggestion : can this be done with MULTI-HOG?)	from number 48 to foresterhill road see photos	.RD 14 Day	Job Cancelled	07/04/2014	21/04/2014 E	st.
19517	0 jet patch all surface defects and rutting as required (Pot Hole)	From flats 48 to forresterhill road	.RD 28 Day	Job Closed	15/07/2015	11/01/2017 A	ct. RD01/21203
70012	8 repair all pot holes rutting and surface defects as required (Pot Hole)	OLDCROFT PLACE From number 96 to forresterhill road	.RD 2 Day	Job Closed	15/01/2016	16/01/2016 A	ct. RD01/21857
70033	3 repair defects on footway crossing point as required to make safe	at goods delivery entrance next to shop see photo	.RD 7 Day	Job Closed	21/01/2016	21/01/2016 A	ct. RD01/21930
70202	4 repair all pot holes and surface defects as required various sizes from 900 x 900 x 95mm deep to 300 x 300 x 60mm deep (Pot Hole)	From number 96 to forresterhill road	.RD 2 Day	Job Closed	01/03/2016	02/03/2016 A	ct. RD01/22320
70202	5 hot patch repair repair trench of road on left hand side heading towards forresterhill road (Pot Hole)	From Croft tavern pub to forresterhill road	.RD 28 Day	Job Closed	01/03/2016	22/04/2016 A	ct. RD01/22878

Effective: 06/12/2015 to 06/12/2017 Contract: Roads Contract (General Maint) (RD01) Site: OLDCROFT PLACE (7601355)

Display Action Officer: No

Service: Roads

Maintenance Management

b No.	Description	า	Location	Priority	Job Status	Entered	Completion	Works Order	
	Asset:	1,000.00 A	sset - Locn.: N/19/1775 - OLDCROFT PLACE	Feature	e Type: RDS Road Section	Area: Aberdeen Central			
		ole as required ely 200 x 200 x 45mm	At junction with oldcroft gardens	.RD 7 Day	Job Closed	10/05/2016	11/05/2016 Act.	RD01/23165	
708677	Find and Fix	x 1 potholes filled by	97	.Routine Maintenance	Job Closed	21/09/2016	17/09/2016 Act.		
		ole as required ely 500 x 500 x 70mm	Opposite car park lay by at flats numbers 48-94	.RD Emergency	Contractor Completed	06/12/2016	06/12/2016 Act.	RD01/25403	
		ly and gully cover e down (Blocked	Beside telephone box opposite premier store	.RD 14 Day	Contractor Completed	16/01/2017	19/01/2017 Act.	RD01/25727	
		otholes and surface equired (Pot Hole)	At entrance into car park opposite premier stores	.RD 7 Day	Contractor Completed	16/01/2017	16/01/2017 Act.	RD01/25726	
711285	Reset sunke	en gully (Iron Works)		.RD 28 Day	Contractor Completed	16/01/2017	01/02/2017 Act.	RD01/25796	
	repair all su	pair or multi hog rface defects ely 100m x 1m	from numbers 48-94 to oldcroft gardens	.RD 14 Day	Order Printed	16/01/2017	30/01/2017 Est.	RD01/26872	
	defects as re approximate		From car park entrance to numbers 48-94 to lamppost number 3 east bound	.RD 7 Day	Contractor Completed	24/01/2017	25/01/2017 Act.	RD01/25835	
	Clean and je cyclic mainte	et 19 gullies done on enance	whole street	.Routine Maintenance	Contractor Completed	10/05/2017	02/05/2017 Act.		
715191	Clean and je	et 3 gullies missed on enance due to	n o/s 17, 73, 97	.RD 14 Day	Order Printed	10/05/2017	24/05/2017 Est.	RD01/27245	
716475	Repair all po	otholes and surface equired (Pot Hole)	At opposite side of Road from numbers 97-103	.RD 2 Day	Contractor Completed	26/06/2017	26/06/2017 Act.	RD01/27826	
717566	Repair all po	otholes and surface equired (Pot Hole)	From forresterhill road to numbers 96-146 oldcroft place	.RD 7 Day	Contractor Completed	14/08/2017	14/08/2017 Act.	RD01/28280	
717567	Jet patch all	l potholes and ects as required (Jet	From forresterhill road to numbers 96-146 oldcroft place	.RD Planned Works	Job Raised	14/08/2017	14/08/2022 Est.		
	Find and Fix	x 4 potholes repaired	across from shops and car park	.Routine Maintenance	Contractor Completed	09/10/2017	06/10/2017 Act.		
		x pothole repaired by	outside 108	.Routine Maintenance	Contractor Completed	04/12/2017	04/12/2017 Act.		
719432	repaired by		whole road	.Routine Maintenance	Contractor Completed	05/12/2017	04/12/2017 Act.		
	Asset:	1,008.00 A	sset - Locn.: 1 - Forresterhill Road to Stockethill Cres	<u> </u>	e Type: RDS Carriageway		Area: Aberdeen C	Central	
		en white lines less risible (Road	Foresterhill rd	.RD 3 Months	Job Closed	25/06/2008	18/09/2008 Est.		

Effective: 06/12/2015 to 06/12/2017
Contract: Roads Contract (General Maint) (RD01)
Site: OLDCROFT PLACE (7601355)

Service: Roads Display Action Officer: No