From: Foi Enquiries
Sent: 20 May 2019 09:02

Subject: EIR-19-0548 - Inspection - Great Western Road

Thank you for your information request of 16 April 2019 and please accept our sincere apologies for delay in getting back to you. Aberdeen City Council (ACC) has completed the necessary search for the information requested. Our response is now detailed below.

Your ref: NDA/KW STIR0085/00001

Accident date: 19 January 2018
Locus: Great Western Road, outside Mannofield Church

1.Records of inspection for the stretch of footpath on Great Western Road between Countesswells Road and Craigton Road (the relevant area) from 12 months prior to the accident and to the present date.
Please find enclosed document ref: EIR-19-0548 – Great Western Road Reports under 'condition survey'.

2. Maintenance records including records of independent contractors working in the relevant area for a period of 12 months prior to the accident and to the present date.
Please find enclosed document ref: EIR-19-0548 – Great Western Road Reports under 'maintenance management'. The Scottish Roadworks Register shows no records of Independent contractors working at the location in the given timescale.

ACC is unable to provide you with information on **records of independent contractors working in the relevant area for a period of 12 months prior to the accident and to the present date** as it is not held by the Council. In order to comply with its obligations under the terms of Regulation 10(4)(a) - Information Not Held - of the EIRs, ACC hereby gives notice that this information is not held by it. ACC is required by Regulation 10(1)(b) of the EIRs to inform you as to why in all the circumstances of the case, the public interest in maintaining this exception outweighs the public interest in disclosing this information to you. ACC is satisfied that it does not hold this information and considers that, as there is no information held, the public interest lies with the exception.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Chief Officer level have been redacted from the attached report. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with 11(3)(a)(i) – Personal Information - of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, of which the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as we consider that disclosure of this information would be a breach of the 'lawfulness, fairness and transparency' principle. These individuals have not consented to the disclosure of this information and ACC does not consider that they would expect ACC to release this information about them into the public domain under the FOISA.

3. Records of works completed in the relevant area for 12 months prior to the accident date to the present date.
Please find enclosed document ref: EIR-19-0548 – Great Western Road Reports under 'maintenance management'

Please note that third party names and personal details, as well as the names of ACC Officers who are below Chief Officer level have been redacted from the attached report. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with 11(3)(a)(i) – Personal Information - of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, of which the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as we consider that disclosure of this information would be a breach of the 'lawfulness, fairness and transparency' principle. These individuals have not consented to the disclosure of this information and ACC does not consider that they would expect ACC to release this information about them into the public domain under the FOISA.

4. Records of complaints in relation to the relevant area for a period of 12 months prior to the accident to the present date.
Please find enclosed document ref: EIR-19-0548 – Great Western Road Reports under 'customer services'.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Chief Officer level have been redacted from the attached report. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with 11(3)(a)(i) – Personal Information - of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, of which the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as we consider that disclosure of this information would be a breach of the 'lawfulness, fairness and transparency' principle. These individuals have not consented to the disclosure of this information and ACC does not consider that

they would expect ACC to release this information about them into the public domain under the FOISA.

5. Records of accidents occurring in the relevant area for a period of 12 months prior to the accident to the present date.
Please find enclosed document ref: EIR-19-0548 – Great Western Road Reports under 'customer services'.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Chief Officer level have been redacted from the attached report. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with 11(3)(a)(i) – Personal Information - of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, of which the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as we consider that disclosure of this information would be a breach of the 'lawfulness, fairness and transparency' principle. These individuals have not consented to the disclosure of this information and ACC does not consider that they would expect ACC to release this information about them into the public domain under the FOISA.

We can also confirm that ACC have received one intimations for this stretch of footway in the given timescale, the claim was not pursued.

6. Please confirm the frequency of inspections for the relevant area.
This footway is subject to a monthly inspection frequency.

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

We hope this helps with your request.

Yours sincerely,

Access to Information Team
Aberdeen City Council | Access to Information Team | Customer Feedback |Customer
Marischal College | Business Hub 17 | 3rd Floor | Broad Street | Aberdeen | AB10 1AQ

Dial: 01224 522166
www.aberdeencity.gov.uk | Twitter: @AberdeenCC | Facebook.com/AberdeenCC

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Site: GREAT WESTERN ROAD (7600111) **Locality:** ABERDEEN, ABERDEEN CITY **Area:** Aberdeen South

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,000.00	**Asset - Locn.:** S/29/1135 - GREAT WESTERN ROAD			**Feature Type:** RDS Road Section			**Area:** Aberdeen South	
Batch: 565554 - Inspection Batch			**Route:** Week: 10 - Area: 29					**Date:** 01/04/2019
	No actionable defects found							
Batch: 564620 - Inspection Batch			**Route:** Adhoc Inspection Roads					**Date:** 27/02/2019
470887	Repair/fill pothole at edge of manhole as identified in attached pics.	27/02/2019	Great Western Road outside the Spires apartments at the pedestrian sanctuary.	Pot Hole	Internal		Committed	729085
Batch: 564056 - Inspection Batch			**Route:** Week: 02 - Area 29					**Date:** 05/02/2019
	No actionable defects found							
Batch: 563947 - Inspection Batch			**Route:** Adhoc Inspection Roads					**Date:** 31/01/2019
470678	Repair/fill pothole as identified in attached pics.	31/01/2019	Oakdale Terrace outside number 7 at Bustop (Great Western Road opposite Tesco Store)	Pot Hole	Internal		Committed	728425
Batch: 563487 - Inspection Batch			**Route:** Week: 46 - Area: 24					**Date:** 21/01/2019
	No actionable defects found							
Batch: 563397 - Inspection Batch			**Route:** Week: 46 - Area: 29					**Date:** 21/01/2019
	No actionable defects found							
Batch: 562755 - Inspection Batch			**Route:** Week: 42 - Area: 29					**Date:** 18/12/2018
	No actionable defects found							
Batch: 561921 - Inspection Batch			**Route:** Week: 38 - Area: 29					**Date:** 21/11/2018
	No actionable defects found							
Batch: 561371 - Inspection Batch			**Route:** Adhoc Inspection Roads					**Date:** 08/11/2018
470148	Repair/fill pothole as identified in attached pic.	08/11/2018	Oakdale Terrace outside number 7 at Bus Stop.	Pot Hole	Internal		Committed	727095
Batch: 560460 - Inspection Batch			**Route:** Week: 34 - Area: 29					**Date:** 17/10/2018
	No actionable defects found							
Batch: 559889 - Inspection Batch			**Route:** Adhoc Inspection Roads					**Date:** 03/10/2018
469929	Roads General Enquiry - Keep clear road markings have been erased and vehicles persistently block the exit (Enquiry 50103924)	03/10/2018	Thorngrove Avenue AB15 7XS -- Thorngrove avenue at junction with Great Western rd	Road Marking	Internal		Committed	726538
Batch: 559366 - Inspection Batch			**Route:** Week: 30 - Area: 29					**Date:** 18/09/2018
	No actionable defects found							
Batch: 558236 - Inspection Batch			**Route:** Adhoc Inspection Roads					**Date:** 29/08/2018
469631	Pothole, 300x100x50, at fire hydrant service frame.	29/08/2018	Heading east,between claremont road jct and great western pl jct	Pot Hole	Internal		Committed	725952
Batch: 557659 - Inspection Batch			**Route:** Week: 26 - Area: 29					**Date:** 27/08/2018
	No actionable defects found							

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,000.00	**Asset - Locn.:** S/29/1135 - GREAT WESTERN ROAD			**Feature Type:** RDS Road Section			**Area:** Aberdeen South	
Batch: 553294 - Inspection Batch			**Route:** Week: 22 - Area: 29					**Date:** 18/07/2018
No actionable defects found								
Batch: 550786 - Inspection Batch			**Route:** Week: 18 - Area: 29					**Date:** 27/06/2018
469230	Blocked gullys,clean, complete length of carriageway.	27/06/2018	All gullys Both sides of road	Blocked Gully	Internal		Committed	724812
469224	Pothole, rutt on previous repair, 600x300x50	25/06/2018	At jct of craigton rd	Pot Hole	Internal		Committed	724792
Batch: 549418 - Inspection Batch			**Route:** Week: 14 - Area: 29					**Date:** 04/06/2018
No actionable defects found								
Batch: 547708 - Inspection Batch			**Route:** Week: 10 - Area: 29					**Date:** 30/04/2018
No actionable defects found								
Batch: 546867 - Inspection Batch			**Route:** Adhoc Inspection Roads					**Date:** 09/04/2018
468399	Repair/fill potholes as identified in attached pic. Case ref number; 72266858 refers.	09/04/2018	Great Western Road outside Mr Chips.	Pot Hole	Internal		Committed	722947
Batch: 546813 - Inspection Batch			**Route:** Week: 06 - Area: 29					**Date:** 05/04/2018
No actionable defects found								
Batch: 545974 - Inspection Batch			**Route:** Week: 02 - Area 29					**Date:** 16/03/2018
468112	Pothole, 400x400x50, kerbside	16/03/2018	Heading west,past anderson dr jct , no 453	Pot Hole	Internal		Committed	722021
Batch: 544440 - Inspection Batch			**Route:** Week: 46 - Area: 29					**Date:** 07/02/2018
No actionable defects found								
Batch: 544362 - Inspection Batch			**Route:** Week: 46 - Area: 24					**Date:** 07/02/2018
467527	Blocked gullys, clean.	06/02/2018	At no 374 and 376	Blocked Gully	Internal		Committed	720694
Batch: 544340 - Inspection Batch			**Route:** Adhoc Inspection Roads					**Date:** 02/02/2018
467505	Pothole,300x300x50, exposed utility frames.	02/02/2018	Heading west as you approach sth anderson dr no 431,kerbside.	Pot Hole	Internal		Committed	720637
Batch: 543578 - Inspection Batch			**Route:** Week: 42 - Area: 29					**Date:** 16/01/2018
No actionable defects found								
Batch: 542504 - Inspection Batch			**Route:** Week: 38 - Area: 29					**Date:** 20/12/2017
No actionable defects found								
Batch: 541295 - Inspection Batch			**Route:** Week: 34 - Area: 29					**Date:** 15/11/2017
No actionable defects found								
Batch: 540335 - Inspection Batch			**Route:** Week: 30 - Area: 29					**Date:** 18/10/2017
No actionable defects found								
Batch: 539045 - Inspection Batch			**Route:** Week: 26 - Area: 29					**Date:** 15/09/2017
No actionable defects found								

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,000.00	**Asset - Locn.:** S/29/1135 - GREAT WESTERN ROAD			**Feature Type:** RDS Road Section			**Area:** Aberdeen South	
Batch: 537934 - Inspection Batch			**Route:** Week: 22 - Area: 29					**Date:** 18/08/2017
466189	Blocked gully,clean.	18/08/2017	Headind west onto n.d.r. Just past morningside rd jct	Blocked Gully	Internal		Committed	717710
Batch: 536522 - Inspection Batch			**Route:** Week: 18 - Area: 29					**Date:** 26/07/2017
No actionable defects found								
Batch: 534771 - Inspection Batch			**Route:** Week: 14 - Area: 29					**Date:** 26/06/2017
No actionable defects found								
Batch: 532829 - Inspection Batch			**Route:** Week: 10 - Area: 29					**Date:** 30/05/2017
No actionable defects found								
Batch: 531392 - Inspection Batch			**Route:** Week: 06 - Area: 29					**Date:** 04/05/2017
No actionable defects found								
Batch: 529519 - Inspection Batch			**Route:** Week: 02 - Area 29					**Date:** 10/04/2017
No actionable defects found								
Batch: 528122 - Inspection Batch			**Route:** Week: 46 - Area: 24					**Date:** 20/03/2017
No actionable defects found								
Batch: 527458 - Inspection Batch			**Route:** Week: 46 - Area: 29					**Date:** 14/03/2017
No actionable defects found								
Batch: 527455 - Inspection Batch			**Route:** Week: 46 - Area: 24					**Date:** 14/03/2017
No actionable defects found								
Batch: 525312 - Inspection Batch			**Route:** Week: 42 - Area: 29					**Date:** 07/02/2017
No actionable defects found								
Batch: 525004 - Inspection Batch			**Route:** Adhoc Inspection Roads					**Date:** 03/02/2017
462490	Pothole, 400x400x60. On failed re instatement.	03/02/2017	Great Western Road,heading west bound,just past traffic light s.a.d. Jct. no 453	Pot Hole	Internal		Committed	711969
Asset: 1,001.00	**Asset - Locn.:** S/28/2562 - GREAT WESTERN ROAD (17)			**Feature Type:** RDS Road Section			**Area:** Aberdeen South	
Batch: 563774 - Inspection Batch			**Route:** Week: 46 - Area: 24					**Date:** 28/01/2019
No actionable defects found								
Batch: 544432 - Inspection Batch			**Route:** Week: 46 - Area: 24					**Date:** 07/02/2018
No actionable defects found								
Batch: 528126 - Inspection Batch			**Route:** Week: 46 - Area: 24					**Date:** 20/03/2017
No actionable defects found								
Batch: 527460 - Inspection Batch			**Route:** Week: 46 - Area: 24					**Date:** 14/03/2017
No actionable defects found								
Asset: 1,002.00	**Asset - Locn.:** 1 - Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 565617 - Inspection Batch			**Route:** Week: 10 - Area: 29					**Date:** 04/04/2019
No actionable defects found								

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,002.00	**Asset - Locn.:** 1 - Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 564057 - Inspection Batch				**Route:** Week: 02 - Area 29				**Date:** 05/02/2019
No actionable defects found								
Batch: 563486 - Inspection Batch				**Route:** Week: 46 - Area: 24				**Date:** 21/01/2019
No actionable defects found								
Batch: 563398 - Inspection Batch				**Route:** Week: 46 - Area: 29				**Date:** 21/01/2019
No actionable defects found								
Batch: 562756 - Inspection Batch				**Route:** Week: 42 - Area: 29				**Date:** 18/12/2018
No actionable defects found								
Batch: 561922 - Inspection Batch				**Route:** Week: 38 - Area: 29				**Date:** 21/11/2018
No actionable defects found								
Batch: 560482 - Inspection Batch				**Route:** Week: 34 - Area: 29				**Date:** 18/10/2018
No actionable defects found								
Batch: 559739 - Inspection Batch				**Route:** Adhoc Inspection Roads				**Date:** 01/10/2018
469908	Reset city bollards,uprooted and leaning,	01/10/2018	At corner of ashley rd and head east at no 82,as per attached photos confirm.	Damaged Bollard	Internal		Committed	726492
Batch: 559367 - Inspection Batch				**Route:** Week: 30 - Area: 29				**Date:** 18/09/2018
No actionable defects found								
Batch: 557660 - Inspection Batch				**Route:** Week: 26 - Area: 29				**Date:** 27/08/2018
No actionable defects found								
Batch: 553295 - Inspection Batch				**Route:** Week: 22 - Area: 29				**Date:** 18/07/2018
No actionable defects found								
Batch: 550781 - Inspection Batch				**Route:** Week: 18 - Area: 29				**Date:** 27/06/2018
469221	Reoint tem fill,	25/06/2018	At cranford rd sllip	Broken Slab	Internal		Committed	724789
469222	Re slab and install bollards to suit	25/06/2018	At slip corner of cranford rd,	Broken Slab	Internal		Committed	724790
469223	Bitmac corner patch.expsed edge frame.	25/06/2018	Outside 481	Broken Slab	Internal		Committed	724791
Batch: 549419 - Inspection Batch				**Route:** Week: 14 - Area: 29				**Date:** 04/06/2018
No actionable defects found								
Batch: 547707 - Inspection Batch				**Route:** Week: 10 - Area: 29				**Date:** 30/04/2018
No actionable defects found								
Batch: 546812 - Inspection Batch				**Route:** Week: 06 - Area: 29				**Date:** 05/04/2018
No actionable defects found								
Batch: 545973 - Inspection Batch				**Route:** Week: 02 - Area 29				**Date:** 16/03/2018
No actionable defects found								
Batch: 545962 - Inspection Batch				**Route:** Adhoc Inspection Roads				**Date:** 15/03/2018
468102	Lift and reset sunken paving slab as identified in attached pic. Case ref number; 70338421	15/03/2018	Great Western Road at junction with Thorngrove Avenue.	Sunken Footway	Internal		Committed	721981

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,002.00	**Asset - Locn.:** 1 - Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 544532 - Inspection Batch				**Route:** Adhoc Inspection Roads				**Date:** 09/02/2018
467583	Lift and reset raised slab as identified in attached pic. The trip hazard measured was 20mm	09/02/2018	Great Western Road beside Mannofield Church close to Bus Shelter in front of lampost number 57.	Sunken Footway	Internal		Committed	720775
Batch: 544441 - Inspection Batch				**Route:** Week: 46 - Area: 29				**Date:** 07/02/2018
No actionable defects found								
Batch: 544433 - Inspection Batch				**Route:** Week: 46 - Area: 24				**Date:** 07/02/2018
No actionable defects found								
Batch: 543580 - Inspection Batch				**Route:** Week: 42 - Area: 29				**Date:** 16/01/2018
No actionable defects found								
Batch: 542505 - Inspection Batch				**Route:** Week: 38 - Area: 29				**Date:** 20/12/2017
No actionable defects found								
Batch: 541380 - Inspection Batch				**Route:** Week: 34 - Area: 29				**Date:** 17/11/2017
No actionable defects found								
Batch: 540336 - Inspection Batch				**Route:** Week: 30 - Area: 29				**Date:** 18/10/2017
No actionable defects found								
Batch: 539593 - Inspection Batch				**Route:** Week: 26 - Area: 29				**Date:** 26/09/2017
No actionable defects found								
Batch: 537933 - Inspection Batch				**Route:** Week: 22 - Area: 29				**Date:** 18/08/2017
466188	Rocking slabs,lift and relay	18/08/2017	Opps nellfield pl	Rocking Slab	Internal		Committed	717709
Batch: 536525 - Inspection Batch				**Route:** Week: 18 - Area: 29				**Date:** 26/07/2017
No actionable defects found								
Batch: 534864 - Inspection Batch				**Route:** Week: 14 - Area: 29				**Date:** 28/06/2017
No actionable defects found								
Batch: 533177 - Inspection Batch				**Route:** Week: 10 - Area: 29				**Date:** 02/06/2017
No actionable defects found								
Batch: 531508 - Inspection Batch				**Route:** Week: 06 - Area: 29				**Date:** 07/05/2017
No actionable defects found								
Batch: 530743 - Inspection Batch				**Route:** Adhoc Inspection Roads				**Date:** 26/04/2017
464330	Supply and fit 3 footway bollards.	26/04/2017	On footway outside number 532	Damaged Bollard	Internal		Committed	714769
Batch: 529692 - Inspection Batch				**Route:** Week: 02 - Area 29				**Date:** 11/04/2017
No actionable defects found								
Batch: 528130 - Inspection Batch				**Route:** Week: 46 - Area: 24				**Date:** 20/03/2017
No actionable defects found								
Batch: 527465 - Inspection Batch				**Route:** Week: 46 - Area: 24				**Date:** 14/03/2017
No actionable defects found								

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,002.00	**Asset - Locn.:** 1 - Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 527463 - Inspection Batch			**Route:** Week: 46 - Area: 29				**Date:** 14/03/2017	
No actionable defects found								
Batch: 525316 - Inspection Batch			**Route:** Week: 42 - Area: 29				**Date:** 07/02/2017	
No actionable defects found								
Asset: 1,003.00	**Asset - Locn.:** 9 - South Anderson Drive to Granville Place-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 563485 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 21/01/2019	
No actionable defects found								
Batch: 544434 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 07/02/2018	
No actionable defects found								
Batch: 528133 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 20/03/2017	
No actionable defects found								
Batch: 527469 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 14/03/2017	
No actionable defects found								
Asset: 1,004.00	**Asset - Locn.:** 16 - Forbesfield Road to Forest Avenue-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen Central	
Batch: 563484 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 21/01/2019	
No actionable defects found								
Batch: 544435 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 07/02/2018	
No actionable defects found								
Batch: 528135 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 20/03/2017	
No actionable defects found								
Batch: 527471 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 14/03/2017	
No actionable defects found								
Asset: 1,005.00	**Asset - Locn.:** 37 - Nellfield Place to Nellfield Cemetery-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 563483 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 21/01/2019	
No actionable defects found								
Batch: 544436 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 07/02/2018	
No actionable defects found								
Batch: 528136 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 20/03/2017	
No actionable defects found								
Batch: 527472 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 14/03/2017	
No actionable defects found								
Asset: 1,006.00	**Asset - Locn.:** 47 - Corner of Countesswells Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 563482 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 21/01/2019	
No actionable defects found								
Batch: 544437 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 07/02/2018	
No actionable defects found								

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,006.00	**Asset - Locn.:** 47 - Corner of Countesswells Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 528139 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 20/03/2017	
No actionable defects found								
Batch: 527473 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 14/03/2017	
No actionable defects found								
Asset: 1,007.00	**Asset - Locn.:** 1 - Hard Landscaping			**Feature Type:** RDS Hard Landscaping			**Area:** Aberdeen South	
Batch: 565531 - Inspection Batch			**Route:** Week: 10 - Area: 29				**Date:** 01/04/2019	
No actionable defects found								
Batch: 564058 - Inspection Batch			**Route:** Week: 02 - Area 29				**Date:** 05/02/2019	
No actionable defects found								
Batch: 563481 - Inspection Batch			**Route:** Week: 46 - Area: 24				**Date:** 21/01/2019	
No actionable defects found								
Batch: 563404 - Inspection Batch			**Route:** Week: 46 - Area: 29				**Date:** 21/01/2019	
No actionable defects found								
Batch: 562757 - Inspection Batch			**Route:** Week: 42 - Area: 29				**Date:** 18/12/2018	
No actionable defects found								
Batch: 561923 - Inspection Batch			**Route:** Week: 38 - Area: 29				**Date:** 21/11/2018	
No actionable defects found								
Batch: 560461 - Inspection Batch			**Route:** Week: 34 - Area: 29				**Date:** 17/10/2018	
No actionable defects found								
Batch: 559368 - Inspection Batch			**Route:** Week: 30 - Area: 29				**Date:** 18/09/2018	
No actionable defects found								
Batch: 557661 - Inspection Batch			**Route:** Week: 26 - Area: 29				**Date:** 27/08/2018	
No actionable defects found								
Batch: 553296 - Inspection Batch			**Route:** Week: 22 - Area: 29				**Date:** 18/07/2018	
No actionable defects found								
Batch: 550872 - Inspection Batch			**Route:** Week: 18 - Area: 29				**Date:** 27/06/2018	
No actionable defects found								
Batch: 549420 - Inspection Batch			**Route:** Week: 14 - Area: 29				**Date:** 04/06/2018	
No actionable defects found								
Batch: 547706 - Inspection Batch			**Route:** Week: 10 - Area: 29				**Date:** 30/04/2018	
No actionable defects found								
Batch: 546811 - Inspection Batch			**Route:** Week: 06 - Area: 29				**Date:** 05/04/2018	
No actionable defects found								
Batch: 545972 - Inspection Batch			**Route:** Week: 02 - Area 29				**Date:** 16/03/2018	
No actionable defects found								

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,007.00	**Asset - Locn.:** 1 - Hard Landscaping			**Feature Type:** RDS Hard Landscaping			**Area:** Aberdeen South	
Batch: 544442 - Inspection Batch				**Route:** Week: 46 - Area: 29				**Date:** 07/02/2018
No actionable defects found								
Batch: 544438 - Inspection Batch				**Route:** Week: 46 - Area: 24				**Date:** 07/02/2018
No actionable defects found								
Batch: 543579 - Inspection Batch				**Route:** Week: 42 - Area: 29				**Date:** 16/01/2018
No actionable defects found								
Batch: 542506 - Inspection Batch				**Route:** Week: 38 - Area: 29				**Date:** 20/12/2017
No actionable defects found								
Batch: 541336 - Inspection Batch				**Route:** Week: 34 - Area: 29				**Date:** 16/11/2017
No actionable defects found								
Batch: 540312 - Inspection Batch				**Route:** Week: 30 - Area: 29				**Date:** 16/10/2017
No actionable defects found								
Batch: 539049 - Inspection Batch				**Route:** Week: 26 - Area: 29				**Date:** 15/09/2017
No actionable defects found								
Batch: 537927 - Inspection Batch				**Route:** Week: 22 - Area: 29				**Date:** 17/08/2017
No actionable defects found								
Batch: 536527 - Inspection Batch				**Route:** Week: 18 - Area: 29				**Date:** 26/07/2017
No actionable defects found								
Batch: 534742 - Inspection Batch				**Route:** Week: 14 - Area: 29				**Date:** 26/06/2017
No actionable defects found								
Batch: 532831 - Inspection Batch				**Route:** Week: 10 - Area: 29				**Date:** 30/05/2017
No actionable defects found								
Batch: 531395 - Inspection Batch				**Route:** Week: 06 - Area: 29				**Date:** 04/05/2017
No actionable defects found								
Batch: 529518 - Inspection Batch				**Route:** Week: 02 - Area 29				**Date:** 10/04/2017
No actionable defects found								
Batch: 528141 - Inspection Batch				**Route:** Week: 46 - Area: 24				**Date:** 20/03/2017
No actionable defects found								
Batch: 527474 - Inspection Batch				**Route:** Week: 46 - Area: 24				**Date:** 14/03/2017
No actionable defects found								
Batch: 527467 - Inspection Batch				**Route:** Week: 46 - Area: 29				**Date:** 14/03/2017
No actionable defects found								
Batch: 525319 - Inspection Batch				**Route:** Week: 42 - Area: 29				**Date:** 07/02/2017
No actionable defects found								

Effective: 19/01/2017 to 18/04/2019 **Service:** Footways
Contract: Roads Contract (General Maint) (RD01) **Display Action Officer:** No
Site: GREAT WESTERN ROAD (7600111)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.

Asset: 1,008.00 **Asset - Locn.:** 3 - Opposite No 505-Hard Landscaping **Feature Type:** RDS Hard Landscaping **Area:** Aberdeen South

Batch: 563477 - Inspection Batch **Route:** Week: 46 - Area: 24 **Date:** 21/01/2019
No actionable defects found

Batch: 544439 - Inspection Batch **Route:** Week: 46 - Area: 24 **Date:** 07/02/2018
No actionable defects found

Batch: 528179 - Inspection Batch **Route:** Week: 46 - Area: 24 **Date:** 20/03/2017
No actionable defects found

Batch: 527646 - Inspection Batch **Route:** Week: 46 - Area: 24 **Date:** 14/03/2017
No actionable defects found

Customer Services

Enquiry No.: 50104678 **Logged by:** Contact Centre **on:** 23/10/2018 00:00
Service: Footways **Subject:** Overhanging Vegetation **Classification:** Enquiry **Enquiry Ref:** FS-Case-92866667
Desc.: Overhanging vegetation blocking pavement
Location: Great Western Road AB10 6NY – Outside 391 and 416 Great Western Road **Contact:**

Enquiry No.: 50101710 **Logged by:** Contact Centre **on:** 25/06/2018 00:00
Service: Footways **Subject:** Other - F/way **Classification:** Enquiry **Enquiry Ref:** FS-Case-79624323
Desc.: Pavement breaking up.
Location: Outside 481 Great Western Road **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 724792

Enquiry No.: 50101539 **Logged by:** Contact Centre **on:** 12/06/2018 00:00
Service: Footways **Subject:** Overhanging Vegetation **Classification:** Enquiry **Enquiry Ref:** FS-Case-78586797
Desc.: Branches overhanging the carriageway and regularly hitting buses.
Location: Garden of 285 Great Western Road **Contact:**

Enquiry No.: 732797 **Logged by:** Contact Centre **on:** 07/02/2018 10:54
Service: Footways **Subject:** Sunken Footway **Classification:** Enquiry **Enquiry Ref:**
Desc.: Reference No: ROADS31630. Site (Street/Park/etc): Great Western Road. Location: corner of great western road and throngrove avenue. Locational Details: In footpath or lane. First Type of Fault: Other. First Fault Details: sinking pavement. Additional Information: The pavement on the corner of Great Western Road and Thorngrove Avenue is sinking, it has been sinking over a number of months and with the snow/ice the pavement is really dangerous and you could slip into the path of an on coming car coming down Thorngrove Avenue
Name: Address Line 1: Address Line 2: Address Line 3: Postcode:
Telephone Number: Email Address:
Location: GREAT WESTERN ROAD **Contact:**

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order

Asset: 1,000.00 **Asset - Locn.:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section **Area:** Aberdeen South

54818	refresh KEEP CLEAR marking on c/w (Road Marking)	junction to Thorngrove Ave	.RD 28 Day	Job Closed	08/09/2008	06/10/2008	Est.

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		**Asset - Locn.:** S/29/1135 - GREAT WESTERN ROAD		**Feature Type:** RDS Road Section		**Area:** Aberdeen South	
59686	4 gulleys on south side of carriageway (Blocked Gully)	between junction with morningside road and entrance to reservoir	.RD 28 Day	Job Closed	07/04/2009	07/05/2009 Est.	RD01/2076
63353	reseat existing bollard in new concrete base (Bollard Damaged/Loose/Msg)	west side of junction with hammerfield avenue	.RD 14 Day	Job Closed	04/09/2009	18/09/2009 Est.	RD01/2421
67279	2 Potholes both approx' 1 metre by 0.5 metre by 70mm deep	at junction with Duthie Terrace	.RD 7 Day	Job Closed	10/02/2010	17/02/2010 Est.	
67572	JET PATCH series of potholes approx' total area 20 square metres	on eastbound carriageway between Junction with Thorngrove Avenue and junction with Anderson drive	.RD 28 Day	Job Closed	18/02/2010	18/03/2010 Est.	
68397	JET PATCH approx' 15 square metres (Pot Hole)	between junction with anderson drive and junction with thorngrove avenue	.RD 14 Day	Job Cancelled	25/03/2010		
68398	JET PATCH approx' 20 square metres (Pot Hole)	between junction with duthie terrace and junction with countesswells road	.RD 14 Day	Job Closed	25/03/2010		
151367	Refresh all markings at light controlled crossing	outside number 489	.RD 28 Day	Job Cancelled	21/07/2010	18/08/2010 Est.	
158978	refresh right turn lane markings (Road Marking)	at junction with craigton road	.RD 28 Day	Job Cancelled	08/06/2011	06/07/2011 Est.	
171857			.Routine Maintenance	Job Closed	28/01/2013		
711969	Pothole, 400x400x60. On failed re instatement. (Pot Hole)	Great Western Road,heading west bound,just past traffic light s.a.d. Jct. no 453	.RD 2 Day	Contractor Completed	03/02/2017	03/02/2017 Act.	RD01/25983
712623	pothole, sunken re instatement. ,600x700x50 level off make safe.,	at no 453,.just after anderson dr jct as you pass westbound.	.RD 2 Day	Contractor Completed	20/02/2017	20/02/2017 Act.	RD01/26211
713242	find and fix pothole repaired by	o/s 6 OAKDALE TERRACE	.Routine Maintenance	Contractor Completed	10/03/2017	09/03/2017 Act.	
713312	pothole, worn surface rutt. 400x400x50.	tesco express ,opps bus stop st john st err, as per attached photo.	.RD 2 Day	Contractor Completed	13/03/2017	13/03/2017 Act.	RD01/26463
713313	hotpatch, areas of worn surface 3 sq mtrs,sunken carriageway.	at jct of craigton rd,as per attached photo.	.RD 14 Day	Contractor Completed	13/03/2017	16/03/2017 Act.	RD01/26476
713314	blocked gully,clean.	heading east no 543	.RD 7 Day	Job Cancelled	13/03/2017	13/03/2017 Act.	RD01/26470
713317	repoint, service lid, make safe trip hazard. 200x200x40	567,outside boiler maintenance shop.asper attached photo.	.RD 7 Day	Contractor Completed	13/03/2017	14/03/2017 Act.	RD01/26468
713320	pothole, 400x100x50.	at edge of service lid frame, at spires flats opps craigton rd. as per attached photo.	.RD 2 Day	Contractor Completed	13/03/2017	13/03/2017 Act.	RD01/26466
713322	blocked gully,clean.	heading east 560, as per attached photo.	.RD 7 Day	Contractor Completed	13/03/2017	15/03/2017 Act.	RD01/26470

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	**Asset - Locn.:** S/29/1135 - GREAT WESTERN ROAD		**Feature Type:** RDS Road Section		**Area:** Aberdeen South	
713323	hotpatch ,sunken worn carriageway,1 sq mtr	548, as per attached photo.	.RD 14 Day	Contractor Completed	13/03/2017	20/03/2017 Act.	RD01/26475
713338	reset loose gully frame.	heading east as you approach traffic lights of sth anderson drive, as per attached photo.	.RD 28 Day	Contractor Completed	13/03/2017	28/04/2017 Act.	RD01/26483
713930	Clean and jet slow running gulley.	On Westbound carriageway West side of junction with Duthie Terrace.	.RD 14 Day	Contractor Completed	28/03/2017	30/03/2017 Act.	RD01/26745
715090	blocked gullys, 2no clean.	at both corners of hammersmith rd	.RD 14 Day	Contractor Completed	08/05/2017	13/05/2017 Act.	RD01/27218
717207	blocked gullys,clean. 2no.	heading east,at no 204 and 162. as per attached photo.	.RD 7 Day	Contractor Completed	26/07/2017	30/07/2017 Act.	RD01/28143
717710	Blocked gully,clean. (Blocked Gully)	Headind west onto n.d.r. Just past morningside rd jct	.RD 7 Day	Contractor Completed	18/08/2017	19/08/2017 Act.	RD01/28331
718652	Find and Fix 7 potholes repaired by	unknown	.Routine Maintenance	Contractor Completed	09/10/2017	07/10/2017 Act.	
719413	clean and jet blocked gully	outside 388	.RD 14 Day	Contractor Completed	04/12/2017	14/01/2018 Act.	RD01/29129
719719	pothole, 400x400x50.	at kerbside of jct cranford rd, beside mr chips.	.RD 7 Day	Contractor Completed	04/01/2018	05/01/2018 Act.	RD01/29238
719720	pothole, sunken worn area 500x500x50square	heading east,at gully frame no 396	.RD 7 Day	Contractor Completed	04/01/2018	05/01/2018 Act.	RD01/29238
719844	Find and fix pothole repaired by	I/p 2	.Routine Maintenance	Contractor Completed	08/01/2018	24/12/2017 Act.	
720637	Pothole,300x300x50, exposed utility frames. (Pot Hole)	Heading west as you approach sth anderson dr no 431,kerbside.	.RD 7 Day	Contractor Completed	02/02/2018	04/02/2018 Act.	RD01/29610
720694	Blocked gullys, clean. (Blocked Gully)	At no 374 and 376	.RD 7 Day	Contractor Completed	06/02/2018	15/02/2018 Act.	RD01/29647
722021	Pothole, 400x400x50, kerbside (Pot Hole)	Heading west,past anderson dr jct , no 453	.RD 7 Day	Contractor Completed	16/03/2018	17/03/2018 Act.	RD01/30082
722734	clean and jet gully - fsc71701833	outside 372	.RD 14 Day	Contractor Completed	04/04/2018	06/04/2018 Act.	RD01/30274
722947	Repair/fill potholes as identified in attached pic. Case ref number; 72266858 refers. (Pot Hole)	Great Western Road outside Mr Chips.	.RD 2 Day	Contractor Completed	09/04/2018	09/04/2018 Act.	RD01/30334
724324	pothole, re sunken carriageway, level off.depression.500x500x50.	at bus stop area kerbside of 376 heading eastbound.	.RD 7 Day	Contractor Completed	05/06/2018	06/06/2018 Act.	RD01/31024
724420	Find and Fix pothole repaired by dr/kc - 300x300x60 - fsc78394920	358	.Routine Maintenance	Contractor Completed	12/06/2018	11/06/2018 Act.	
724524	clean and jet 5 gullies - fsc77533436	between duthie terrace and 535 as attached plan both sides of c/way	.RD 14 Day	Contractor Completed	13/06/2018	01/07/2018 Act.	RD01/31123
724792	Pothole, rutt on previous repair, 600x300x50 (Pot Hole)	At jct of craigton rd	.RD 7 Day	Contractor Completed	25/06/2018	26/06/2018 Act.	RD01/31315
724812	Clean and jet 55 gullies	whole length both sides of carriagway	.RD 14 Day	Contractor Completed	27/06/2018	28/07/2018 Act.	RD01/31324

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		**Asset - Locn.:** S/29/1135 - GREAT WESTERN ROAD		**Feature Type:** RDS Road Section		**Area:** Aberdeen South	
725952	Pothole, 300x100x50, at fire hydrant service frame. (Pot Hole)	Heading east,between claremont road jct and great western pl jct	.RD 7 Day	Contractor Completed	29/08/2018	29/08/2018 Act.	RD01/32100
726019	hotpatch, manhole frame worn section of re instatement ,approx 1 sq mtr	opps salisbury jct,as per attached photo.	.RD 14 Day	Contractor Completed	03/09/2018	09/10/2018 Act.	RD01/32158
726538	Refresh "Keep Clear" road markings as identified in attached pics. Great Western Road at junction with Thorngrove Avenue.	Great Western Road at junction with Thorngrove Avenue.	.RD 28 Day	Order Printed	03/10/2018	31/10/2018 Est.	RD01/32549
727095	Repair/fill pothole as identified in attached pic. (Pot Hole)	Oakdale Terrace outside number 7 at Bus Stop.	.RD 2 Day	Contractor Completed	08/11/2018	08/11/2018 Act.	RD01/32898
728425	Repair/fill pothole as identified in attached pics. (Pot Hole)	Oakdale Terrace outside number 7 at Bustop (Great Western Road opposite Tesco Store)	.RD 2 Day	Contractor Completed	31/01/2019	31/01/2019 Act.	RD01/33644
728884	Road inspected by early morning patrol - no actionable safety defects. Checked by		.Routine Maintenance	Contractor Completed	20/02/2019	13/02/2019 Act.	
729085	Repair/fill pothole at edge of manhole as identified in attached pics. (Pot Hole)	Great Western Road outside the Spires apartments at the pedestrian sanctuary.	.RD 2 Day	Contractor Completed	27/02/2019	27/02/2019 Act.	RD01/33895
Asset: 1,002.00		**Asset - Locn.:** 1 - Footway		**Feature Type:** RDS Footway		**Area:** Aberdeen South	
712325	reset bollard,uprooted still in approx position.	at ent to graveyard.re opps gosh hairdresser.	.RD 7 Day	Job Closed	13/02/2017	14/02/2017 Act.	
713319	repoint, edge of service manhole framework. remove old cementwork.	opps mannofield shops,as per attached photo.	.RD 7 Day	Contractor Completed	13/03/2017	14/03/2017 Act.	RD01/26467
714769	Supply and fit 3 City Centre footway bollards. (Damaged Bollard) after RTC	On footway outside number 532	.RD 7 Day	Contractor Completed	26/04/2017	27/04/2017 Act.	RD01/27069
715089	rocking slab, lift and relay.	341,at traffic light jct of as per attached photo	.RD 7 Day	Contractor Completed	08/05/2017	08/05/2017 Act.	RD01/27199
717206	sunken slabs, lift and relay. around service lid.	heading east at no536	.RD 7 Day	Contractor Completed	26/07/2017	27/07/2017 Act.	RD01/28138
717353	reset bollard back from kerbline as marked see attached photo -	jctn Hammerfield Avenue	.RD 7 Day	Contractor Completed	01/08/2017	04/08/2017 Act.	RD01/28198
717709	Rocking slabs,lift and relay (Rocking Slab)	Opps nellfield pl	.RD 7 Day	Contractor Completed	18/08/2017	18/08/2017 Act.	RD01/28332
719722	replace broken bollard,city crest.	heading west outside no 417	.RD 14 Day	Contractor Completed	04/01/2018	10/01/2018 Act.	RD01/29235
720775	Lift and reset raised slab as identified in attached pic. The trip hazard measured was 20mm (Sunken Footway)	Great Western Road beside Mannofield Church close to Bus Shelter in front of lampost number 57.	.RD 2 Day	Contractor Completed	09/02/2018	13/02/2018 Act.	RD01/29683

Effective: 19/01/2017 to 18/04/2019 **Service:** Footways
Contract: Roads Contract (General Maint) (RD01) **Display Action Officer:** No
Site: GREAT WESTERN ROAD (7600111)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,002.00	**Asset - Locn.:** 1 - Footway		**Feature Type:** RDS Footway		**Area:** Aberdeen South		
721981	Lift and reset sunken paving slab as identified in attached pic. Case ref number; 70338421 (Sunken Footway)	Great Western Road at junction with Thorngrove Avenue.	.RD 7 Day	Contractor Completed	15/03/2018	21/03/2018 Act.	RD01/30085
724789	Reoint tem fill, (Broken Slab)	At cranford rd silip	.RD 7 Day	Contractor Completed	25/06/2018	26/06/2018 Act.	RD01/31318
724790	Re slab and install bollards to suit (Broken Slab)	At slip corner of cranford rd,	.RD Planned Works	Contractor Completed	25/06/2018	16/07/2018 Act.	RD01/31317
724791	Bitmac corner patch.expsed edge frame. (Broken Slab)	Outside 481	.RD 7 Day	Contractor Completed	25/06/2018	26/06/2018 Act.	RD01/31316
724825	Find and Fix - replace visi rail 1 panel, 1 post done by	outside archibalds	.Routine Maintenance	Contractor Completed	28/06/2018	06/05/2018 Act.	
726492	Reset city bollards,uprooted and leaning, (Damaged Bollard)	At corner of ashley rd and head east at no 82,as per attached photos confirm.	.RD 7 Day	Contractor Completed	01/10/2018	06/10/2018 Act.	RD01/32504
728028	Reset morpeth bollard done by MF/GA	junction Hammerfield Avenue	.Routine Maintenance	Contractor Completed	09/01/2019	02/01/2019 Act.	
Asset: 1,006.00	**Asset - Locn.:** 47 - Corner of Countesswells Road-Footway		**Feature Type:** RDS Footway		**Area:** Aberdeen South		
15	sign damaged (Traffic Sign Damaged)	entrance to thorngrove house	.RD 28 Day	Job Closed	15/08/2007	12/09/2007 Est.	
17	sign damaged (Damaged Street Name Sign)	entrance to thorngrove house	.RD 7 Day	Job Closed	15/08/2007	22/08/2007 Est.	
Asset: 1,033.00	**Asset - Locn.:** 21 - Brighton Place to Ashley Park Drive-Footway		**Feature Type:** RDS Footway		**Area:** Aberdeen Central		
13976	Bollard Damaged/Loose/Msg	Brighton pl	.RD 28 Day	Job Closed	13/11/2007	11/12/2007 Est.	
14008			.Routine Maintenance	Job Closed	14/11/2007		
Asset: 1,040.00	**Asset - Locn.:** 2 - South Anderson Drive to St Johns Terrace-Carriageway		**Feature Type:** RDS Carriageway		**Area:** Aberdeen South		
161775	refresh all hatching lines , 2 x double direction arrows ,2 x right turn arrows , and 2 x straight ahead arrows (Road Marking)	at hatching area from Cranford rd to Countesswells rd	.RD 14 Day	Job Cancelled	06/10/2011	21/10/2011 Est.	
Asset: 100,042.00	**Asset - Locn.:** 9051061337 - GREAT WESTERN ROAD,		**Feature Type:** W - Domestic Waste Property		**Area:** Aberdeen South		
124000	Waste Other - no letter/calendar - send copy please - also querying if recycling available - box and bag required if poss (Enquiry 114354)	great western road -	.Routine Maintenance	Job Cancelled	27/05/2010		

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 100,220.00	**Asset - Locn.:** 9051044493 - GREAT WESTERN ROAD,		**Feature Type:** W - Domestic Waste Property		**Area:** Aberdeen South	
126003	Waste Other - 5 SINGLE APARTMENTS AT HMO BLOCK ADDRESS - REQUIRES 5 X FOOD CADDYS + BIO LINERS + 1 X BROWN WHEELED BIN + 1 X ADDITIONAL BLACK WHEELED BIN AS THEY ONLY HAVE 2 FOR BLOCK + DID NOT RECEIVE CALENDAR WITH NEW COLLECTION DATES. (Enquiry 118448)	GREAT WESTERN ROAD -	.Routine Maintenance	Job Cancelled	08/06/2010		
	Asset: 100,225.00	**Asset - Locn.:** 9051044495 - GREAT WESTERN ROAD, AB10 6PB		**Feature Type:** W - Domestic Waste Property		**Area:** Aberdeen South	
10102866	Jett - Delivery queries - Last Wednesday we received our new general waste bin. However, our property has two households & we have only been provided one bin. So would need another one general waste bin (Enquiry 1046449)	Great Western Road AB10 6PB	.Routine Maintenance	Job Raised	21/03/2017		
	Asset: 100,249.00	**Asset - Locn.:** 9051044533 - GREAT WESTERN ROAD, AB10 6PS		**Feature Type:** W - Domestic Waste Property		**Area:** Aberdeen South	
123664	Waste Other - PLEASE SUPPLY BIO LINERS, WHITE BAG, CALANDER - THANKS (Enquiry 113971)	GREAT WESTERN ROAD	.Routine Maintenance	Job Cancelled	26/05/2010		
	Asset: 100,295.00	**Asset - Locn.:** 9051044516 - GREAT WESTERN ROAD,		**Feature Type:** W - Domestic Waste Property		**Area:** Aberdeen South	
10047635	Waste Other - NET REQUIRED FOR BLACK BOX. (Enquiry 619021)	GREAT WESTERN ROAD	.Routine Maintenance	Job Raised	12/01/2015		
	Asset: 100,366.00	**Asset - Locn.:** 9051041618 - GREAT WESTERN ROAD, AB10 6PP		**Feature Type:** W - Domestic Waste Property		**Area:** Aberdeen South	
10000084	Waste Other - NEW OCCUPIER HAS A LARGE AND SMALL BLACK BIN -SMALL BIN IS NOT REQUIRED CAN THIS BE UPLIFTED PLEASE - SMALL BIN HAS NO 319 ON IT. UPLIFT FROM REAR OF PROPERTY**PI FASE LEAVE LARGE BIN ** (Enquiry 545930)	GREAT WESTERN ROAD	.Routine Maintenance	Job Cancelled	25/02/2013		

Effective: 19/01/2017 to 18/04/2019
Contract: Roads Contract (General Maint) (RD01)
Site: GREAT WESTERN ROAD (7600111)
Service: Footways
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 100,444.00	**Asset - Locn.:** 9051310003 - GREAT WESTERN ROAD, AB10 6NY	**Feature Type:** W - Domestic Waste Property		**Area:** Aberdeen South		
10099672	Missed Bin - Good afternoon, I live at Great Western Road AB10 6NY and I noticed that the brown bin waste used by the flats of ' an has not been collected for the past few weeks and the bin is now close to full. Could you please advise if you are aware of this issue and when it will be solved. Thank you for your attention. Regards (Enquiry 1043661)	Great Western Road AB10 6NY	.Routine Maintenance	Job Raised	16/02/2017		
	Asset: 100,592.00	**Asset - Locn.:** 9051029334 - THORNGROVE, GREAT WESTERN ROAD	**Feature Type:** W - Domestic Waste Property		**Area:** Aberdeen South		
10095121	Missed Bin - Hi just to let you know our recycling was not collected for the second week running I did phone yesterday and got a return phone call from your depot promising it would be uplifted today how ever this has not happened . The bin room has been opened at 6.30 amWednesday Thursday and Friday . Sent from my iPad (Enquiry 1039432)	Great Western Road	.Routine Maintenance	Job Raised	05/12/2016		
10095989	Waste Other - Request for bulk order of food waste recycling bags- two boxes are normally delivered. (Enquiry 683324)	Great Western Road	.Routine Maintenance	Job Raised	22/12/2016		
10118542	Waste Other - WOULD LIKE 2 X BOXES OF BIO LINERS,THEY ADVISE THIS IS THEIR USUAL ORDERS AND THEY DISTRABUTE TO THE RESIDENTS (Enquiry 719264)	GREAT WESTERN ROAD	.Routine Maintenance	Job Raised	22/09/2017		

Effective: 19/01/2017 to 18/04/2019 **Service:** Roads
Display Action Officer: No **Site:** GREAT WESTERN ROAD (7600111)

Site: GREAT WESTERN ROAD (7600111) **Locality:** ABERDEEN, ABERDEEN CITY **Area:** Aberdeen South

Customer Services

Enquiry No.: 50109205 **Logged by:** Contact Centre **on:** 19/02/2019 00:00
Service: Roads **Subject:** Pot Hole - Road **Classification:** Enquiry **Enquiry Ref:** FS-Case-106303786
Desc.: POTHOLE
Location: 468 Great Western Road, Aberdeen, United Kingdom, AB10 6NP -- Nearest road to the pin placed on the map (automatically generated by Bing Maps): 474 Great Western Road, Aberdeen, AB10 6NP
Nearest postcode to the pin placed on the map (automatically generated): AB10 6NN (46m away **Contact:**

Enquiry No.: 50108478 **Logged by:** Contact Centre **on:** 31/01/2019 00:00
Service: Roads **Subject:** Roads General Enquiry **Classification:** Enquiry **Enquiry Ref:** FS-Case-104303532
Desc.: There is a pothole in the cycle lane in front of bus stop. A cyclist could have a nasty accident if their wheel got stuck in this.
Location: Oakdale Terrace AB15 7PJ -- Opposite Tesco on Great Western Road and right beside the bus stop. **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 728425

Enquiry No.: 50104080 **Logged by:** Contact Centre **on:** 08/10/2018 00:00
Service: Roads **Subject:** Roads General Enquiry **Classification:** Enquiry **Enquiry Ref:** FS-Case-91041471
Desc.: FS-Case-86744493
6 weeks and no contact.
Location: Great Western Road AB10 6PP -- drain cover on gt western road across from Salisbury junction **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 726019

Enquiry No.: 50103924 **Logged by:** Contact Centre **on:** 02/10/2018 00:00
Service: Roads **Subject:** Roads General Enquiry **Classification:** Enquiry **Enquiry Ref:** FS-Case-90364952
Desc.: Keep clear road markings have been erased and vehicles persistently block the exit
Location: Thorngrove Avenue AB15 7XS -- Thorngrove avenue at junction with Great Western rd **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 726538 **Defect Number:** 469929

Enquiry No.: 50103169 **Logged by:** Contact Centre **on:** 04/09/2018 00:00
Service: Roads **Subject:** Roads General Enquiry **Classification:** Enquiry **Enquiry Ref:** FS-Case-87047396
Desc.: I was walking home last night and the next thing I knew I was on my side and had whacked my head off the pavement. My glasses were all bent and I have scarred pretty near my right eye. I have injured my left hand too. Luckily two community police officers happened to see me and help me up.
Location: Great Western Place AB10 -- Beside the entrance to the hairdressers on great western place **Contact:**

Enquiry No.: 50103097 **Logged by:** Contact Centre **on:** 02/09/2018 00:00
Service: Roads **Subject:** Pot Hole - Road **Classification:** Enquiry **Enquiry Ref:** FS-Case-86744493
Desc.: Pothole before drain meaning edge of drain exposed. Caused me to fall of bike
Location: Great Western Road AB10 6PL -- Cycle lane on way into town opposite Salisbury Terrace **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 726019

Effective: 19/01/2017 to 18/04/2019 **Service:** Roads
Display Action Officer: No **Site:** GREAT WESTERN ROAD (7600111)

Customer Services

Enquiry No.: 50101500 **Logged by:** Contact Centre **on:** 11/06/2018 00:00
Service: Roads **Subject:** Pot Hole - Road **Classification:** Enquiry **Enquiry Ref:** FS-Case-78394920
Desc.: Pothole in road
Location: In front of no.358 great western road. (The nursery) **Contact:**
Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 724420

Enquiry No.: 50101401 **Logged by:** Contact Centre **on:** 04/06/2018 00:00
Service: Roads **Subject:** Pot Hole - Road **Classification:** Enquiry **Enquiry Ref:** FS-Case-77647732
Desc.: Pothole
Location: There is a large pothole which almost took me off my bicycle. The pothole is several centimetres deep and approximately 20 cm x 20cm. It takes you surprise and is very dangerous. It is pretty obvious but I can provide a photo if needed. **Contact:**
Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 724420

Enquiry No.: 50100403 **Logged by:** Contact Centre **on:** 06/04/2018 00:00
Service: Roads **Subject:** Roads General Enquiry **Classification:** Enquiry **Enquiry Ref:** FS-Case-72266858
Desc.: Pothole
Location: Major pothole! **Contact:**
Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 722947

Enquiry No.: 729750 **Logged by:** Contact Centre **on:** 03/01/2018 14:14
Service: Roads **Subject:** Sunken Carriageway **Classification:** Enquiry **Enquiry Ref:**
Desc.: Reference No : ROADS31092
Site (Street/Park/etc) : street
Location : outside 453 gt western rd heading to mannofield
Locational Details : In front of house
First Type of Fault : Pothole
Name :
Address Line 1 :
Postcode :
Telephone number :
Email Address :
Location: great western road-roads31092 **Contact:**

Enquiry No.: 729297 **Logged by:** Contact Centre **on:** 21/12/2017 17:01
Service: Roads **Subject:** Roads General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No: ROADS30976. Site (Street/Park/etc): South Anderson Drive. Location: northbound @ junction with Gt Western Road. First Type of Fault: Poor Road Surface. First Fault Details: very uneven and dangerous road surface approaching traffic lights, for about 50 metres. Additional Information: When turning left into Gt Western Road, the surface approaching the turn, at the turn, and again 25 metres along Gt W Rd, is very badly pitted, causing traffic to slow down almost to walking pace, or else to take a very wide and dangerous turn.
Name: [redacted] Address Line 1: [redacted] Address Line 3: [redacted] Postcode: [redacted] Telephone Number: [redacted] Email Address: [redacted]
Location: GREAT WESTERN ROAD **Contact:** [redacted]

Effective: 19/01/2017 to 18/04/2019 **Service:** Roads
Display Action Officer: No **Site:** GREAT WESTERN ROAD (7600111)

Customer Services

Enquiry No.: 729268 **Logged by:** Contact Centre **on:** 21/12/2017 13:11
Service: Roads **Subject:** Roads General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No : ROADS30972
Site (Street/Park/etc) : Anderson Drive - heading north
Location : at junction with Great Western Road
First Type of Fault : Pothole
First Fault Details : series of potholes and damaged road surface
Additional Information : A large area of very poor road surface and a series of potholes is causing drivers to swerve out of lane to avoid. The poor road surface condition is causing unsafe driving. This is a safety issue as well as a maintenence issue.

Name :
Address Line 1 :
Address Line 3 :
Postcode :
Email Address :
Location: GREAT WESTERN ROAD NEAR JUNCTOIN WITH ANDERSON DRIVE **Contact:**

Enquiry No.: 726154 **Logged by:** Contact Centre **on:** 01/12/2017 17:00
Service: Roads **Subject:** Roads General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reporting gully outside 388 Great Western Road is blocked - he has cleared some of the leaves and mulch. Also the gully just round the corner on Burns Road.
Location: 388 GREAT WESTERN ROAD **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 719413

Enquiry No.: 725181 **Logged by:** Contact Centre **on:** 23/11/2017 11:49
Service: Roads **Subject:** Claims - Roads **Classification:** Claim **Enquiry Ref:**
Desc.: junc of great western road and hammersmith . car is still in the garage . rear end suspension spring has gone. will get a detailed repair list from the garage
Location: JUN of great western road and hammersmith LARGE POT HOLE -tuesday 21/11/2017 **Contact:**

Enquiry No.: 715628 **Logged by:** Contact Centre **on:** 16/08/2017 11:04
Service: Roads **Subject:** Pot Hole - Road **Classification:** Defect Report **Enquiry Ref:**
Desc.: FAO : ACC Roads Response service,

Reference No : ROADS30202
Site (Street/Park/etc) : street
Location : Great western road - just down from south anderson traffic lights
Locational Details : In front of house
First Type of Fault : Pothole
First Fault Details : massive Pot hole just down from lights, causing cars to swerve and lose control when hit
Second Type of Fault : Pothole
Second Fault Details : as above
Additional Information : pot hole has been here some time, i am aware and missing this. saw two cars go over pot hole which caused the car to lose control slightly. this is very dangerous
Location: Great western road - just down from south anderson traffic lights **Contact:**

Enquiry No.: 709343 **Logged by:** Contact Centre **on:** 20/06/2017 14:32
Service: Roads **Subject:** Pot Hole - Road **Classification:** Enquiry **Enquiry Ref:**
Desc.: REPORTED A LARGE SECTION OF ORNAGE CABLE IS SHWOING THROUGH THE TARMAC ON THE ROAD ON THE RIGHT HAND SIDE
Location: GREAT WESTERN ROAD-south anderson drive - daw **Contact:**

Effective: 19/01/2017 to 18/04/2019 **Service:** Roads
Display Action Officer: No **Site:** GREAT WESTERN ROAD (7600111)

Customer Services

Enquiry No.: 692409 **Logged by:** Contact Centre **on:** 11/03/2017 23:47
Service: Roads **Subject:** Pot Hole - Road **Classification:** Enquiry **Enquiry Ref:**
Desc.: Reference No : ROADS29464
Site (Street/Park/etc) : Great Western Road
Location : Road outside Tesco at Mannofield on the north side
Locational Details : Opposite side of road
First Type of Fault : Pothole
Location: great western road **Contact:**
Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 713312

Enquiry No.: 692408 **Logged by:** Contact Centre **on:** 11/03/2017 23:33
Service: Roads **Subject:** Pot Hole - Road **Classification:** Enquiry **Enquiry Ref:**
Desc.: Reference No : ROADS29464
Site (Street/Park/etc) : Great Western Road
Location : Road outside Tesco at Mannofield on the north side
Locational Details : Opposite side of road
First Type of Fault : Pothole
Location: great western road **Contact:**
Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 713312

Enquiry No.: 692400 **Logged by:** Contact Centre **on:** 10/03/2017 22:04
Service: Roads **Subject:** Pot Hole - Road **Classification:** Enquiry **Enquiry Ref:**
Desc.: Reference No : ROADS29461
Site (Street/Park/etc) : great western road
Location : beside bus stop opposite Tesco Metro at Mannofield
First Type of Fault : Pothole
Name : cindy blackmore
Location: GREAT WESTERN ROAD **Contact:**
Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 713312

Enquiry No.: 692172 **Logged by:** Contact Centre **on:** 10/03/2017 08:55
Service: Roads **Subject:** Pot Hole - Road **Classification:** Enquiry **Enquiry Ref:**
Desc.: Potholes
Huge crate eastbound opposite tesco. Considering the crazy high council tax we pay this is unacceptable.
Location: GREAT WESTERN ROAD **Contact:**

Effective: 19/01/2017 to 18/04/2019 **Service:** Roads
Display Action Officer: No **Site:** GREAT WESTERN ROAD (7600111)

Customer Services

Enquiry No.: 689417 **Logged by:** Contact Centre **on:** 20/02/2017 13:39
Service: Roads **Subject:** General Condition **Classification:** Enquiry **Enquiry Ref:**
Desc.: Reference No : ROADS29242
Site (Street/Park/etc) : street
Location : South Anderson drive near to its junction with Great Western Rd near the new flats next to traffic lights
Locational Details : In front of house
First Type of Fault : Poor Road Surface
First Fault Details : Exposed wiring possibly for traffic lights
Second Type of Fault : Pothole
Second Fault Details : Wires clearly visible
Name :
Address Line 1 :
Address Line 2 :
Postcode :
Telephone Number :
Email Address :
Location: 459 great western rod - cy **Contact:**

Enquiry No.: 689313 **Logged by:** Contact Centre **on:** 20/02/2017 08:11
Service: Roads **Subject:** Pot Hole - Road **Classification:** Defect Report **Enquiry Ref:**
Desc.: FAO : ACC Roads Response service,

Reference No : ROADS29236
Site (Street/Park/etc) : Great Western Road
Location : outside 451/453
First Type of Fault : Pothole
First Fault Details : Utility dug a hole. Filled it. Filling sunk creating significant dip. Dip filled. Significant dip forming again.
Name :
Address Line 1 :
Email Address :
Location: Outside 451/453 Great Western Road **Contact**

Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 712623

Effective: 19/01/2017 to 18/04/2019 **Service:** Roads
Display Action Officer: No **Site:** GREAT WESTERN ROAD (7600111)

Customer Services

Enquiry No.: 687501 **Logged by:** Contact Centre **on:** 02/02/2017 14:49
Service: Roads **Subject:** Pot Hole - Road **Classification:** Enquiry **Enquiry Ref:**
Desc.: FAO : ACC Roads Response service,

Reference No : ROADS29055
Site (Street/Park/etc) : street
Location : Gt Western rd opposite no 455
Locational Details : In front of house
First Type of Fault : Pothole
First Fault Details : Large pothole developing
Additional Information : As above

Name :
Address Line 1 :
Address Line 2 :
Postcode :
Telephone Number :
Email Address :
CM

Location: Great Western Road **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** S/29/1135 - GREAT WESTERN ROAD **Feature Type:** RDS Road Section
Job Number: 711969 **Defect Number:** 462490