

From: [Foi Enquiries](#)
To: [REDACTED]
Subject: EIR-17-0201 - Inspection - Queens Road
Date: 16 February 2017 14:38:19
Attachments: [Further Information - Right to Review & Appeal.pdf](#)
[EIR-17-0201 - Queen"s Road History 1 Redacted.pdf](#)
[EIR-17-0201 - Queen"s Road History 2 Redacted.pdf](#)

Dear [REDACTED]

Thank you for your information request of 2 February 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

Locus: Just outside 146 Queens Road, Aberdeen.

For a period of twelve months (11/05-2014 – 11/05/2015);

(i) Records of Inspection for the relevant stretch of road.

Please see attached Site History Report under 'Condition Survey'.

(ii) Maintenance records including records of independent contractors working in the relevant area.

Please see attached Site History Report under 'Maintenance Management'.

BT works 1: 13/05/14 to 15/09/14 ; BT works 2: 25/08/14 to 27/08/14

(cable –pulling on footway, no excavations)

SGN works: 30/03/15 to 24/08/15

(on south side of carriageway)

(iii) Statement of the Roads Authority's policy under the code of practice for delivering best value in Highway Maintenance 2001 or alternatively records of the Minutes of Highway Authority or Local Authority meetings where maintenance or repair policy has been discussed or decided.

Please see link:

http://www.aberdeencity.gov.uk/web/files/Roads/road_safety_inspection_manual.pdf

As **Statement of the Roads Authority's policy under the code of practice for delivering best value in Highway Maintenance 2001 or alternatively records of the Minutes of Highway Authority or Local Authority meetings where maintenance or repair policy has been discussed or decided** is otherwise accessible at the link provided above, it is exempt from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby gives notice that we are refusing your request under the terms of Regulation 6(1)(b) - Information Already Publicly Available - of the EIRs.

(iv) Records of complaints about the state of roads at the accident locus.

There are no complaints recorded about the state of Queens Road.

(v) Records of other accidents which have occurred on the relevant stretch of road.

Please see attached Site History Report under 'Customer Services'.

I can also confirm that since a year prior to the incident date of 11/05/2015 we have had a total of five intimations and claims for the whole of Queen's Road. Four of which are personal injury claims relating to footway defects and one is a motor claim involving a council vehicle. These are from May 2014, January 2015, October 2015, December 2015 and January 2016. These are for the whole of Queen's Road, there have been no other intimations or claims put forward for the given location relating to carriageway defects.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Head of Service level have been redacted (blacked out) from the attached Site History Report. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with 11(3)(a)(i) of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, and the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as ACC considers that disclosure of this information would be a breach of the first Data Protection Principle (that personal information must be processed fairly and lawfully). Third parties and ACC Officers who are below Head of Service level named within the attached documents would not expect ACC to release this information about them into the public domain under the EIRs (or the Freedom of Information (Scotland) Act 2002 (FOISA)).

We hope this helps with your request.

Yours sincerely,

Information Compliance Team

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team
Communications and Promotion
Office of Chief Executive

Aberdeen City Council
3rd Floor North
Business Hub 17
Marischal College
Broad Street
ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk

01224 523827/523602

Tel 03000 200 292

*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.

Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Site: QUEEN'S ROAD (7600044)

Locality: ABERDEEN, ABERDEEN CITY

Area: Aberdeen South

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	S/25/1928 - QUEENS ROAD (22)	Feature Type:	RDS Road Section		Area:	Aberdeen South
Batch:	524881 - Inspection Batch			Route:	Adhoc Inspection			Date: 02/02/2017
462465	Remove loose rocking and broken slabs Temporary repair Both entrances are having the slabs removed and hot tarred.	02/02/2017	70 Carden Place outside lefevre litigations Note: Ipad maps unable to locate Carden Place .	Broken Slab	Internal		Committed	711934
Batch:	524612 - Inspection Batch			Route:	Adhoc Inspection			Date: 30/01/2017
462352	Repair pothole approx' 300 x 300 x 50.	30/01/2017	Outside number 13.	Pot Hole	Internal		Committed	711724
Batch:	523736 - Inspection Batch No actionable defects found			Route:	Week: 38 - Area: 22			Date: 13/01/2017
Batch:	521319 - Inspection Batch No actionable defects found			Route:	Week: 34 - Area: 22			Date: 06/12/2016
Batch:	519888 - Inspection Batch No actionable defects found			Route:	Week: 30 - Area: 22			Date: 14/11/2016
Batch:	517036 - Inspection Batch No actionable defects found			Route:	Week: 26 - Area: 22			Date: 11/10/2016
Batch:	515590 - Inspection Batch No actionable defects found			Route:	Week: 22 - Area: 22			Date: 26/09/2016
Batch:	510773 - Inspection Batch No actionable defects found			Route:	Week: 18 - Area: 22			Date: 17/08/2016
Batch:	508670 - Inspection Batch			Route:	Adhoc Inspection			Date: 05/08/2016
460078	Repair pothole approx' 600 x 200 x 50.	05/08/2016	At junction with ROYAL COURT.	Pot Hole	Internal		Archived	707556
Batch:	506044 - Inspection Batch No actionable defects found			Route:	Week: 14 - Area: 22			Date: 19/07/2016
Batch:	505438 - Inspection Batch			Route:	Adhoc Inspection			Date: 11/07/2016
459479	Pothole, 400x400x50, filled by inspector,	11/07/2016	223 Queen's Road - ST	Pot Hole	Internal		Archived	706660
Batch:	504320 - Inspection Batch No actionable defects found			Route:	Week: 10 - Area: 22			Date: 20/06/2016
Batch:	501332 - Inspection Batch No actionable defects found			Route:	Week: 06 - Area: 22			Date: 25/05/2016
Batch:	501273 - Inspection Batch			Route:	Adhoc Inspection			Date: 24/05/2016
458628	Adjacent to bus stop opposite lamppost number 93.	24/05/2016	QUEENS ROAD - AB	Blocked Gully	Internal		Archived	705255
Batch:	500241 - Inspection Batch			Route:	Adhoc Inspection			Date: 12/05/2016
458310	Repair approx' 3 square metres of uneven and damaged carriageway surface.	12/05/2016	On Westbound carriageway adjacent to junction with HAZLEHEAD GARDENS.	Pot Hole	Internal		Archived	704766

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	S/25/1928 - QUEENS ROAD (22)	Feature Type:	RDS Road Section		Area:	Aberdeen South
Batch:	499547 - Inspection Batch			Route:	Adhoc Inspection			Date: 05/05/2016
458012	Repair pothole approx' 450 x 450 x 60.	05/05/2016	On slip road outside number 342	Pot Hole	Internal		Archived	704420
Batch:	498818 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/04/2016
	No actionable defects found							
Batch:	496829 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 31/03/2016
	No actionable defects found							
Batch:	495537 - Inspection Batch			Route:	Adhoc Inspection			Date: 15/03/2016
456544	Repair pothole approx' 300 x 200 x 50.	15/03/2016	On Westbound carriageway adjacent to lampost 89.	Pot Hole	Internal		Archived	702521
Batch:	494973 - Inspection Batch			Route:	Adhoc Inspection			Date: 07/03/2016
456286	Replace 2panel and 2 posts.	07/03/2016	As you head north from st swithen str roundabout jct,as per attached photo.	Damaged Crash Barrier	Internal		Archived	702220
Batch:	494612 - Inspection Batch			Route:	Adhoc Inspection			Date: 03/03/2016
456197	Repair 8 potholes, all approx' 300 x 300 x 50.	03/03/2016	On slip road between junction with main road opposite number 298 and number 340.	Pot Hole	Internal		Archived	702115
Batch:	494412 - Inspection Batch			Route:	Week: 42 - Area: 22			Date: 02/03/2016
	No actionable defects found							
Batch:	494283 - Inspection Batch			Route:	Adhoc Inspection			Date: 01/03/2016
456132	repair all pot holes and surface defects various sizes about 40-50mm (unable to measure owing to traffic)	01/03/2016	At roundabout at junction with kings gate at each junction and around roundabout	Pot Hole	Internal		Archived	702027
Batch:	492931 - Inspection Batch			Route:	Adhoc Inspection			Date: 09/02/2016
455466	Repair pothole approx' 450 x 200 x 50.	09/02/2016	On exit from KINGSGATE ROUNDABOUT city bound.	Pot Hole	Internal		Archived	701268
Batch:	492163 - Inspection Batch			Route:	Week: 38 - Area: 22			Date: 01/02/2016
455089	Repair pothole approx' 450 x 150 x 60.	01/02/2016	OnWestbound carriageway outside numbers 215 - 217.	Pot Hole	Internal		Archived	700807
Batch:	490920 - Inspection Batch			Route:	Adhoc Inspection			Date: 14/01/2016
454554	Repair pothole approx' 300 x 200 x 50.	14/01/2016	On Eastbound carriageway opposite lampost number 88.	Pot Hole	Internal		Archived	700055
Batch:	490055 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 06/01/2016
454262	Repair pothole approx' 500 x 400 x 50.	06/01/2016	At junction with HAZLEHEAD GARDENS.	Pot Hole	Internal		Archived	199606
454259	Repair pothole approx' 250 x 250 x 50.	06/01/2016	On Westbound carriageway opposite number 10.	Pot Hole	Internal		Archived	199603
454261	Repair pothole approx' 450 x 450 x 50.	06/01/2016	At junction with ROYALCOURT.	Pot Hole	Internal		Archived	199605
Batch:	489312 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/12/2015
454057	1m2x40est SUNKEN C/WAY.	18/12/2015	Entrance to Queens Parade. (On box junction)	Sunken Carriageway	Internal		Archived	199358

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	S/25/1928 - QUEENS ROAD (22)	Feature Type:	RDS Road Section		Area:	Aberdeen South
Batch:	488553 - Inspection Batch			Route:	Adhoc Inspection			Date: 11/12/2015
453920	Repair pothole approx' 300 x 300 x 55.	11/12/2015	On Westbound carriageway opposite junction with CRAIGDEN.	Pot Hole	Internal		Archived	199181
Batch:	488171 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/12/2015
	No actionable defects found							
Batch:	485863 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 10/11/2015
453102	Repair 3 potholes, all approx' 300 x 300 x 50.	10/11/2015	On footway crossing outside numbers 282 - 284.	Pot Hole	Internal		Archived	198287
Batch:	484125 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 16/10/2015
	No actionable defects found							
Batch:	483678 - Inspection Batch			Route:	Adhoc Inspection			Date: 05/10/2015
452408	Repair 3 potholes, all approx 300 x 200 x 55.	05/10/2015	On slip road opposite numbers 338 - 340.	Pot Hole	Internal		Archived	197353
Batch:	482742 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 15/09/2015
	No actionable defects found							
Batch:	480155 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 18/08/2015
	No actionable defects found							
Batch:	478171 - Inspection Batch			Route:	Adhoc Inspection			Date: 04/08/2015
451593	Replace damaged gully cover with new one.	04/08/2015	On slip road opposite 3 ROYAL COURT.	Iron Works	Internal		Archived	195780
Batch:	478170 - Inspection Batch			Route:	Adhoc Inspection			Date: 04/08/2015
451592	Clean and jet gully.	04/08/2015	On Eastbound carriageway outside number 88. NO PARKING CONES REQUIRED.	Blocked Gully	Internal		Archived	195779
Batch:	475680 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 21/07/2015
	No actionable defects found							
Batch:	472005 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 18/06/2015
	No actionable defects found							
Batch:	470132 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 27/05/2015
	No actionable defects found							
Batch:	467853 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 28/04/2015
99587	Repair 2 potholes, both approx 300 x 300 x 55.	28/04/2015	On slip road for ROYAL COURT.	Pot Hole	Internal		Archived	192723
99588	Remove approx 1 square metre of damaged concrete causing trip hazards and replace with bitmac.	28/04/2015	On footway at junction with slip road for ROYAL COURT.	Pot Hole	Internal		Archived	192724

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	S/25/1928 - QUEENS ROAD (22)	Feature Type:	RDS Road Section		Area:	Aberdeen South
Batch:	466368 - Inspection Batch			Route:	Adhoc Inspection			Date: 08/04/2015
99189	Clean and jet 6 blocked gullies.	08/04/2015	Between roundabout at HAZLEHEAD AVENUE and junction with GROATS ROAD.	Blocked Gully	Internal		Archived	192032
Batch:	465260 - Inspection Batch			Route:	Week: 42 - Area: 22			Date: 31/03/2015
	No actionable defects found							
Batch:	462164 - Inspection Batch			Route:	Week: 38 - Area: 22			Date: 10/03/2015
	No actionable defects found							
Batch:	455757 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39738 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 16/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,002.00	Asset - Locn.:	S/25/1925 - QUEENS GATE	Feature Type:	RDS Road Section		Area:	Aberdeen South
Batch:	455758 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,002.00	Asset - Locn.:	S/25/1925 - QUEENS GATE	Feature Type:	RDS Road Section		Area:	Aberdeen South
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,004.00	Asset - Locn.:	1 - Grass verge	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	523737 - Inspection Batch			Route:	Week: 38 - Area: 22			Date: 13/01/2017
	No actionable defects found							
Batch:	521321 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 06/12/2016
	No actionable defects found							
Batch:	519889 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 14/11/2016
	No actionable defects found							
Batch:	517037 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 11/10/2016
	No actionable defects found							
Batch:	515589 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 26/09/2016
	No actionable defects found							
Batch:	510772 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 17/08/2016
	No actionable defects found							
Batch:	506043 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 19/07/2016
	No actionable defects found							
Batch:	504321 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 20/06/2016
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,004.00	Asset - Locn.:	1 - Grass verge	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	501333 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 25/05/2016
	No actionable defects found							
Batch:	498819 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/04/2016
	No actionable defects found							
Batch:	496830 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 31/03/2016
	No actionable defects found							
Batch:	494413 - Inspection Batch			Route:	Week: 42 - Area: 22			Date: 02/03/2016
	No actionable defects found							
Batch:	492169 - Inspection Batch			Route:	Week: 38 - Area: 22			Date: 01/02/2016
	No actionable defects found							
Batch:	490057 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 06/01/2016
	No actionable defects found							
Batch:	488172 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/12/2015
	No actionable defects found							
Batch:	485867 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 10/11/2015
	No actionable defects found							
Batch:	484124 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 16/10/2015
	No actionable defects found							
Batch:	482743 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 15/09/2015
	No actionable defects found							
Batch:	480156 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 18/08/2015
	No actionable defects found							
Batch:	475682 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 21/07/2015
	No actionable defects found							
Batch:	472006 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 18/06/2015
	No actionable defects found							
Batch:	470133 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 27/05/2015
	No actionable defects found							
Batch:	467859 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 28/04/2015
	No actionable defects found							
Batch:	465261 - Inspection Batch			Route:	Week: 42 - Area: 22			Date: 31/03/2015
	No actionable defects found							
Batch:	462165 - Inspection Batch			Route:	Week: 38 - Area: 22			Date: 10/03/2015
	No actionable defects found							
Batch:	455759 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,004.00	Asset - Locn.:	1 - Grass verge	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,005.00	Asset - Locn.:	2 - central island-landscaping	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	455760 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,005.00	Asset - Locn.:	2 - central island-landscaping	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,006.00	Asset - Locn.:	5 - Roundabout, Kings Gate/Hazlehead Avenue, South corner-G	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	455761 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,007.00	Asset - Locn.:	2 - Northburn Avenue to Angusfield House-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455762 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,007.00	Asset - Locn.:	2 - Northburn Avenue to Angusfield House-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,008.00	Asset - Locn.:	11 - Springfield Road to Angusfield Avenue-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455763 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,008.00	Asset - Locn.:	11 - Springfield Road to Angusfield Avenue-Footway	Feature Type:	RDS Footway		Area: Aberdeen South	
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,009.00	Asset - Locn.:	13 - Hill of Rubislaw to number 142-Footway	Feature Type:	RDS Footway		Area: Aberdeen South	
Batch:	455764 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,010.00	Asset - Locn.:	26 - Kings Gate to Woodend Crescent-Footway	Feature Type:	RDS Footway		Area: Aberdeen South	
Batch:	455765 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,010.00	Asset - Locn.:	26 - Kings Gate to Woodend Crescent-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,011.00	Asset - Locn.:	30 - Queens Cross to Albyn School-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455766 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,011.00	Asset - Locn.:	30 - Queens Cross to Albyn School-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,012.00	Asset - Locn.:	43 - Woodend Crescent to No 366-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455767 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,013.00	Asset - Locn.:	2 - Anderson Drive to Skene Road-Carriageway	Feature Type:	RDS Carriageway		Area:	Aberdeen South
Batch:	455768 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,013.00	Asset - Locn.:	2 - Anderson Drive to Skene Road-Carriageway	Feature Type:	RDS Carriageway		Area:	Aberdeen South
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,014.00	Asset - Locn.:	60 - Anderson Drive-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455769 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,014.00	Asset - Locn.:	60 - Anderson Drive-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,015.00	Asset - Locn.:	3 - Roundabout, Kings Gate/Hazlehead Avenue, East corner-Gr	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	455770 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,016.00	Asset - Locn.:	6 - Roundabout, Kings Gate/Hazlehead Avenue, South corner-G	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	455771 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,016.00	Asset - Locn.:	6 - Roundabout, Kings Gate/Hazlehead Avenue, South corner-G	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,017.00	Asset - Locn.:	3 - Angusfield House-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455772 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,018.00	Asset - Locn.:	12 - Angusfield Avenue to Rubislaw Park Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455773 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,019.00	Asset - Locn.:	14 - Rubislaw Park Road to Unnamed Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455774 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,019.00	Asset - Locn.:	14 - Rubislaw Park Road to Unnamed Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,020.00	Asset - Locn.:	27 - Hazlehead Avenue to Provost Graham Avenue-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455775 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,021.00	Asset - Locn.:	31 - Queens Cross to Queens Gardens-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455776 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,021.00	Asset - Locn.:	31 - Queens Cross to Queens Gardens-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,022.00	Asset - Locn.:	44 - No 368 to No 370-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455777 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,022.00	Asset - Locn.:	44 - No 368 to No 370-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,023.00	Asset - Locn.:	2 - Hazlehead Avenue-Hard landscaping	Feature Type:	RDS Hard Landscaping		Area:	Aberdeen South
Batch:	455778 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,024.00	Asset - Locn.:	4 - Roundabout, Kings Gate/Hazlehead Avenue, North corner-G	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	455779 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,024.00	Asset - Locn.:	4 - Roundabout, Kings Gate/Hazlehead Avenue, North corner-G	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,025.00	Asset - Locn.:	7 - Roundabout, Kings Gate/Hazlehead Avenue, West corner-Gr	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	455781 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,025.00	Asset - Locn.:	7 - Roundabout, Kings Gate/Hazlehead Avenue, West corner-Gr	Feature Type:	RDS Verge		Area:	Aberdeen South
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,026.00	Asset - Locn.:	4 - Angusfield House to number 224-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455783 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,027.00	Asset - Locn.:	15 - Unnamed Road to Viewfield Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455785 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,027.00	Asset - Locn.:	15 - Unnamed Road to Viewfield Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,028.00	Asset - Locn.:	28 - Number 298 to 352-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455786 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,028.00	Asset - Locn.:	28 - Number 298 to 352-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,029.00	Asset - Locn.:	32 - Queens Gardens to Forest Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455788 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,030.00	Asset - Locn.:	45 - Access to No 354-374 to Craigden-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455790 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,030.00	Asset - Locn.:	45 - Access to No 354-374 to Craigden-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,031.00	Asset - Locn.:	3 - Kings Gate Roundabout-Hard landscaping	Feature Type:	RDS Hard Landscaping		Area:	Aberdeen South
Batch:	455791 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,031.00	Asset - Locn.:	3 - Kings Gate Roundabout-Hard landscaping	Feature Type:	RDS Hard Landscaping	Area:	Aberdeen South	
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,032.00	Asset - Locn.:	5 - Number 224 to Westholme Avenue-Footway	Feature Type:	RDS Footway	Area:	Aberdeen South	
Batch:	455793 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,033.00	Asset - Locn.:	16 - number 142 to number 136-Footway	Feature Type:	RDS Footway	Area:	Aberdeen South	
Batch:	455795 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,033.00	Asset - Locn.:	16 - number 142 to number 136-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,034.00	Asset - Locn.:	29 - Provost Graham Avenue to Provost Graham Avenue-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455797 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,035.00	Asset - Locn.:	33 - A byn School to Forest Avenue-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455798 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,036.00	Asset - Locn.:	46 - Provost Graham Avenue-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455800 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,036.00	Asset - Locn.:	46 - Provost Graham Avenue-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,037.00	Asset - Locn.:	4 - Kings Gate Roundabout-Hard landscaping	Feature Type:	RDS Hard Landscaping		Area:	Aberdeen South
Batch:	455802 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,038.00	Asset - Locn.:	6 - Westholme Avenue to Angusfield Avenue-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455804 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,038.00	Asset - Locn.:	6 - Westholme Avenue to Angusfield Avenue-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,039.00	Asset - Locn.:	17 - 124 to 126-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455805 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,039.00	Asset - Locn.:	17 - 124 to 126-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,040.00	Asset - Locn.:	34 - Forest Avenue to No 59-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455807 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,041.00	Asset - Locn.:	47 - Provost Graham Avenue to Groats Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455809 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,041.00	Asset - Locn.:	47 - Provost Graham Avenue to Groats Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,042.00	Asset - Locn.:	5 - Kings Gate Roundabout-Hard landscaping	Feature Type:	RDS Hard Landscaping		Area:	Aberdeen South
Batch:	455810 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,042.00	Asset - Locn.:	5 - Kings Gate Roundabout-Hard landscaping	Feature Type:	RDS Hard Landscaping	Area:	Aberdeen South	
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,043.00	Asset - Locn.:	7 - Angusfield Avenue to Hill of Rubislaw-Footway	Feature Type:	RDS Footway	Area:	Aberdeen South	
Batch:	455812 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,044.00	Asset - Locn.:	19 - 122 to Queens Avenue-Footway	Feature Type:	RDS Footway	Area:	Aberdeen South	
Batch:	455813 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,044.00	Asset - Locn.:	19 - 122 to Queens Avenue-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,045.00	Asset - Locn.:	35 - Forest Road to Spademill Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455815 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,045.00	Asset - Locn.:	35 - Forest Road to Spademill Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,046.00	Asset - Locn.:	48 - Craigden to Queens Den-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455817 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,047.00	Asset - Locn.:	1 - Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	523738 - Inspection Batch			Route:	Week: 38 - Area: 22			Date: 13/01/2017
	No actionable defects found							
Batch:	521315 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 06/12/2016
461677	Remove 3 uneven slabs causing trip hazards due to tree root disturbance and replace with bitmac.	06/12/2016	On footway at entrance GORE VEGA (opposite number 46).	Sunken Footway	Internal		Committed	710422
461676	Remove damaged and broken concrete causing trip hazard and replace with bitmac, approx' 1 square metre.	06/12/2016	At exit from ALBYN SCHOOL.	Sunken Footway	Internal		Committed	710421

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,047.00	Asset - Locn.:	1 - Footway	Feature Type:	RDS Footway	Area:	Aberdeen South	
Batch:	521315 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 06/12/2016
461678	Remove 3 uneven slabs causing trip hazards and replace with bitmac. Tree root disturbance.	06/12/2016	On footway outside entrance to TBP (opposite number 50) against wall.	Sunken Footway	Internal		Committed	710424
Batch:	519890 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 14/11/2016
	No actionable defects found							
Batch:	517038 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 11/10/2016
	No actionable defects found							
Batch:	515588 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 26/09/2016
	No actionable defects found							
Batch:	510771 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 17/08/2016
	No actionable defects found							
Batch:	508669 - Inspection Batch			Route:	Adhoc Inspection			Date: 05/08/2016
460077	Remove raised slab causing trip hazard and replace with bitmac.	05/08/2016	Adjacent to tree pit opposite number 80.	Rocking Slab	Internal		Archived	707555
Batch:	507199 - Inspection Batch			Route:	Adhoc Inspection			Date: 27/07/2016
459879	Remove depressed and broken triangular slab causing trip hazard and replace with bitmac.	27/07/2016	On footway outside A byn School opposite number 20.	Rocking Slab	Internal		Archived	707209
Batch:	506042 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 19/07/2016
	No actionable defects found							
Batch:	505169 - Inspection Batch			Route:	Adhoc Inspection			Date: 05/07/2016
459420	on footpath-300x160x60, pothole.	05/07/2016	Junction to Angusfield Avenue.	Pot Hole	Internal		Archived	706549
Batch:	504322 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 20/06/2016
	No actionable defects found							
Batch:	501334 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 25/05/2016
	No actionable defects found							
Batch:	500059 - Inspection Batch			Route:	Adhoc Inspection			Date: 11/05/2016
458274	Fill depression in footway causing trip hazard. Approx' 300 x 300 x 45.	11/05/2016	On footway adjacent to lampost number 10.	Pot Hole	Internal		Archived	704724
Batch:	498815 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/04/2016
457794	Repair void in footway causing trip hazard to pedestrians.	26/04/2016	On footway outside number 40.	Pot Hole	Internal		Archived	704126
457787	Remove cobble stone causing trip hazard to pedestrians and replace with bitmac.	26/04/2016	Around tree on footway at West side of junction with WESTHOLME AVENUE.	Broken Kerb	Internal		Archived	704119

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,047.00	Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen South		
Batch:	497460 - Inspection Batch			Route: Adhoc Inspection			Date: 08/04/2016	
457265	Remove 6 broken, depressed and rocking slabs causing trip hazards and replace with bitmac.	08/04/2016	On footway at lampost number 17.	Broken Slab	Internal		Archived	703490
Batch:	496831 - Inspection Batch			Route: Week: 46 - Area: 22			Date: 31/03/2016	
	No actionable defects found							
Batch:	494740 - Inspection Batch			Route: Adhoc Inspection			Date: 03/03/2016	
456219	Repair approx' 1 square metre of damaged footway causing trip hazards.	03/03/2016	On footway crossing at entrance to ANGUSFIELD NURSING HOME.	Pot Hole	Internal		Archived	702138
Batch:	494414 - Inspection Batch			Route: Week: 42 - Area: 22			Date: 02/03/2016	
	No actionable defects found							
Batch:	492170 - Inspection Batch			Route: Week: 38 - Area: 22			Date: 01/02/2016	
	No actionable defects found							
Batch:	491981 - Inspection Batch			Route: Adhoc Inspection			Date: 27/01/2016	
454973	Fill redundant tree pit with bitmac.	27/01/2016	On footway outside number 245.	Pot Hole	Internal		Archived	700650
Batch:	490056 - Inspection Batch			Route: Week: 34 - Area: 22			Date: 06/01/2016	
454260	Repair damaged concrete surface causing trip hazard.	06/01/2016	On footway outside number 13.	Broken Slab	Internal		Archived	199604
Batch:	488173 - Inspection Batch			Route: Week: 30 - Area: 22			Date: 08/12/2015	
	No actionable defects found							
Batch:	485868 - Inspection Batch			Route: Week: 26 - Area: 22			Date: 10/11/2015	
	No actionable defects found							
Batch:	484123 - Inspection Batch			Route: Week: 22 - Area: 22			Date: 16/10/2015	
	No actionable defects found							
Batch:	482744 - Inspection Batch			Route: Week: 18 - Area: 22			Date: 15/09/2015	
	No actionable defects found							
Batch:	481308 - Inspection Batch			Route: Adhoc Inspection			Date: 26/08/2015	
451910	Repair pothole causing trip hazard. approx' 450 x 75 x 50.	26/08/2015	Around manhole on footway opposite lampost number 92.	Pot Hole	Internal		Archived	196406
Batch:	480157 - Inspection Batch			Route: Week: 14 - Area: 22			Date: 18/08/2015	
	No actionable defects found							
Batch:	475667 - Inspection Batch			Route: Week: 10 - Area: 22			Date: 21/07/2015	
451299	Remove 4 depressed and broken slabs and replace with bitmac.	21/07/2015	Around toby lid on footway outside THE CHESTER HOTEL.	Rocking Slab	Internal		Archived	195331
Batch:	472007 - Inspection Batch			Route: Week: 06 - Area: 22			Date: 18/06/2015	
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,047.00	Asset - Locn.:	1 - Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	470134 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 27/05/2015
	No actionable defects found							
Batch:	467860 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 28/04/2015
	No actionable defects found							
Batch:	465262 - Inspection Batch			Route:	Week: 42 - Area: 22			Date: 31/03/2015
	No actionable defects found							
Batch:	462166 - Inspection Batch			Route:	Week: 38 - Area: 22			Date: 10/03/2015
	No actionable defects found							
Batch:	455818 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,048.00	Asset - Locn.:	20 - Viewfield Road to Gas Gov-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455820 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,048.00	Asset - Locn.:	20 - Viewfield Road to Gas Gov-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,049.00	Asset - Locn.:	36 - Spademill Road to No 72-76-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455821 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,049.00	Asset - Locn.:	36 - Spademill Road to No 72-76-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,050.00	Asset - Locn.:	49 - Queens Den to opposite Groats Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455823 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,051.00	Asset - Locn.:	8 - #NAME?	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455824 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,051.00	Asset - Locn.:	8 - #NAME?	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,052.00	Asset - Locn.:	21 - Gas Gov to R.G.U.-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455825 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,052.00	Asset - Locn.:	21 - Gas Gov to R.G.U.-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,053.00	Asset - Locn.:	37 - No 61-81-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455826 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,054.00	Asset - Locn.:	9 - Unnamed Road to Hazledene Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455827 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,054.00	Asset - Locn.:	9 - Unnamed Road to Hazledene Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,055.00	Asset - Locn.:	22 - Queens Avenue to Royfold Crescent-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455828 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,055.00	Asset - Locn.:	22 - Queens Avenue to Royfold Crescent-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,056.00	Asset - Locn.:	38 - Access to Royal Court to Bayview Road South-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455829 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,057.00	Asset - Locn.:	10 - Hazledene Road to number 225 Springfield Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455831 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,057.00	Asset - Locn.:	10 - Hazledene Road to number 225 Springfield Road-Footway	Feature Type:	RDS Footway		Area: Aberdeen South	
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,058.00	Asset - Locn.:	23 - Royfold Crescent to Number 100-Footway	Feature Type:	RDS Footway		Area: Aberdeen South	
Batch:	455832 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,059.00	Asset - Locn.:	39 - No 72-76-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455834 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,060.00	Asset - Locn.:	24 - Number 100 to Anderson Drive-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455835 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,060.00	Asset - Locn.:	24 - Number 100 to Anderson Drive-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,061.00	Asset - Locn.:	40 - No 72-76 to Bayview Road-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455836 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,062.00	Asset - Locn.:	25 - R.G.U. to Anderson drive-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455837 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,062.00	Asset - Locn.:	25 - R.G.U. to Anderson drive-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,063.00	Asset - Locn.:	41 - Bayview Road South to Anderson Drive-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455839 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,063.00	Asset - Locn.:	41 - Bayview Road South to Anderson Drive-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,064.00	Asset - Locn.:	42 - Bayview Road to Anderson Drive-Footway	Feature Type:	RDS Footway		Area:	Aberdeen South
Batch:	455840 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,065.00	Asset - Locn.:	1 - Queens Cross to Anderson Drive-Carriageway	Feature Type:	RDS Carriageway		Area:	Aberdeen South
Batch:	455841 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,065.00	Asset - Locn.:	1 - Queens Cross to Anderson Drive-Carriageway	Feature Type:	RDS Carriageway		Area:	Aberdeen South
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	1,066.00	Asset - Locn.:	1 - Hard Landscaping	Feature Type:	RDS Hard Landscaping		Area:	Aberdeen South
Batch:	523739 - Inspection Batch			Route:	Week: 38 - Area: 22			Date: 13/01/2017
	No actionable defects found							
Batch:	521322 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 06/12/2016
	No actionable defects found							
Batch:	519891 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 14/11/2016
	No actionable defects found							
Batch:	517039 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 11/10/2016
	No actionable defects found							
Batch:	515587 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 26/09/2016
	No actionable defects found							
Batch:	510770 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 17/08/2016
	No actionable defects found							
Batch:	506041 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 19/07/2016
	No actionable defects found							
Batch:	504323 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 20/06/2016
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,066.00	Asset - Locn.:	1 - Hard Landscaping	Feature Type:	RDS Hard Landscaping	Area:	Aberdeen South	
Batch:	501335 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 25/05/2016
	No actionable defects found							
Batch:	498820 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/04/2016
	No actionable defects found							
Batch:	496832 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 31/03/2016
	No actionable defects found							
Batch:	494415 - Inspection Batch			Route:	Week: 42 - Area: 22			Date: 02/03/2016
	No actionable defects found							
Batch:	492171 - Inspection Batch			Route:	Week: 38 - Area: 22			Date: 01/02/2016
	No actionable defects found							
Batch:	490058 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 06/01/2016
	No actionable defects found							
Batch:	488174 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/12/2015
	No actionable defects found							
Batch:	485869 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 10/11/2015
	No actionable defects found							
Batch:	484122 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 16/10/2015
	No actionable defects found							
Batch:	482745 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 15/09/2015
	No actionable defects found							
Batch:	480158 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 18/08/2015
	No actionable defects found							
Batch:	475684 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 21/07/2015
	No actionable defects found							
Batch:	472008 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 18/06/2015
	No actionable defects found							
Batch:	470135 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 27/05/2015
	No actionable defects found							
Batch:	467895 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 28/04/2015
	No actionable defects found							
Batch:	465263 - Inspection Batch			Route:	Week: 42 - Area: 22			Date: 31/03/2015
	No actionable defects found							
Batch:	462167 - Inspection Batch			Route:	Week: 38 - Area: 22			Date: 10/03/2015
	No actionable defects found							
Batch:	455843 - Inspection Batch			Route:	Week: 34 - Area: 22			Date: 03/02/2015
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,066.00	Asset - Locn.:	1 - Hard Landscaping	Feature Type:	RDS Hard Landscaping		Area:	Aberdeen South
Batch:	451045 - Inspection Batch			Route:	Week: 30 - Area: 22			Date: 08/01/2015
	No actionable defects found							
Batch:	450788 - Inspection Batch			Route:	Week: 26 - Area: 22			Date: 08/12/2014
	No actionable defects found							
Batch:	450666 - Inspection Batch			Route:	Week: 22 - Area: 22			Date: 18/11/2014
	No actionable defects found							
Batch:	450447 - Inspection Batch			Route:	Week: 18 - Area: 22			Date: 14/10/2014
	No actionable defects found							
Batch:	450140 - Inspection Batch			Route:	Week: 14 - Area: 22			Date: 16/09/2014
	No actionable defects found							
Batch:	39939 - Inspection Batch			Route:	Week: 10 - Area: 22			Date: 14/08/2014
	No actionable defects found							
Batch:	39786 - Inspection Batch			Route:	Week: 06 - Area: 22			Date: 22/07/2014
	No actionable defects found							
Batch:	39784 - Inspection Batch			Route:	Week: 05 - Area: 16			Date: 22/07/2014
	No actionable defects found							
Batch:	39584 - Inspection Batch			Route:	Week: 02 - Area: 22			Date: 26/06/2014
	No actionable defects found							
Batch:	39337 - Inspection Batch			Route:	Week: 46 - Area: 22			Date: 27/05/2014
	No actionable defects found							
Asset:	2,001.00	Asset - Locn.:	7600044/J/00002 - Just before roundabout	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	480216 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/08/2015
	No actionable defects found							
Asset:	2,002.00	Asset - Locn.:	7600044/J/00004 - LP 3	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	480220 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/08/2015
	No actionable defects found							
Asset:	2,003.00	Asset - Locn.:	Opp The Sportsman's Club	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	480221 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/08/2015
	No actionable defects found							
Asset:	2,004.00	Asset - Locn.:	7600044/J/00007 - Just Along from Forest Road bus stop	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	480222 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/08/2015
	No actionable defects found							
Asset:	2,005.00	Asset - Locn.:	7600044/J/00008 - Just before roundabout, opp LP 11	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	480229 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/08/2015
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,006.00	Asset - Locn.:	7600044/J/00009 - LP 11	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	480240 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/08/2015
	No actionable defects found							
Asset:	2,007.00	Asset - Locn.:	7600044/J/00005 - Opp Youth Hostel	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	480242 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/08/2015
	No actionable defects found							
Asset:	2,008.00	Asset - Locn.:	7600044/J/00006 - In front of youth hostel	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	480244 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/08/2015
	No actionable defects found							
Asset:	2,009.00	Asset - Locn.:	7600044/J/00003 - Opp LP 3	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	480245 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/08/2015
	No actionable defects found							
Asset:	2,010.00	Asset - Locn.:	7600044/J/00001 - RHS before Queen's Cross	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	480246 - Inspection Batch			Route:	Adhoc Inspection			Date: 18/08/2015
	No actionable defects found							
Asset:	2,011.00	Asset - Locn.:	7600044/J/00010 - Opp IS Solicitors	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	480524 - Inspection Batch			Route:	Adhoc Inspection			Date: 20/08/2015
	No actionable defects found							
Asset:	2,012.00	Asset - Locn.:	7600044/J/00011 - Queen's rd, LP 29, just off roundabout	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	510765 - Inspection Batch			Route:	Adhoc Inspection			Date: 17/08/2016
	No actionable defects found							
Asset:	2,013.00	Asset - Locn.:	7600044/J/00012 - Queen's rd, next to Earls Court entrance	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511114 - Inspection Batch			Route:	Adhoc Inspection			Date: 22/08/2016
	No actionable defects found							
Asset:	2,014.00	Asset - Locn.:	7600044/J/00013 - Queen's rd, opp LP 26	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511115 - Inspection Batch			Route:	Adhoc Inspection			Date: 22/08/2016
	No actionable defects found							
Asset:	2,015.00	Asset - Locn.:	7600044/J/00014 - Queens Rd, junction with Bayview rd	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511117 - Inspection Batch			Route:	Adhoc Inspection			Date: 22/08/2016
	No actionable defects found							
Asset:	2,016.00	Asset - Locn.:	7600044/J/00015 - Queen's rd, opp LP 22	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511119 - Inspection Batch			Route:	Adhoc Inspection			Date: 22/08/2016
	No actionable defects found							
Asset:	2,017.00	Asset - Locn.:	7600044/J/00016 - Queen's rd, opp entrance to Royal Court	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511121 - Inspection Batch			Route:	Adhoc Inspection			Date: 22/08/2016
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,018.00	Asset - Locn.:	7600044/J/00017 - Queen's rd, Hamilton School bus stop	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511131 - Inspection Batch		Route:	Adhoc Inspection				Date: 22/08/2016
	No actionable defects found							
Asset:	2,019.00	Asset - Locn.:	7600044/J/00018 - Queen's rd, post box opp no 33	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511898 - Inspection Batch		Route:	Adhoc Inspection				Date: 26/08/2016
	No actionable defects found							
Asset:	2,020.00	Asset - Locn.:	7600044/J/00019 - Queen's rd, spademill rd junction	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511899 - Inspection Batch		Route:	Adhoc Inspection				Date: 26/08/2016
	No actionable defects found							
Asset:	2,021.00	Asset - Locn.:	7600044/J/00020 - Queen's rd, Ped crossing opp LP 13	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511900 - Inspection Batch		Route:	Adhoc Inspection				Date: 26/08/2016
	No actionable defects found							
Asset:	2,022.00	Asset - Locn.:	7600044/J/00021 - Queen's rd, LP 16	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511901 - Inspection Batch		Route:	Adhoc Inspection				Date: 26/08/2016
	No actionable defects found							
Asset:	2,023.00	Asset - Locn.:	7600044/J/00022 - Queen's rd, opp Hamilton school bus stop	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511903 - Inspection Batch		Route:	Adhoc Inspection				Date: 26/08/2016
	No actionable defects found							
Asset:	2,024.00	Asset - Locn.:	7600044/J/00023 - Queen's rd, Next to Royal Court entrance	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511904 - Inspection Batch		Route:	Adhoc Inspection				Date: 26/08/2016
	No actionable defects found							
Asset:	2,025.00	Asset - Locn.:	7600044/J/00024 - Queen's rd, nr LP 22	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511905 - Inspection Batch		Route:	Adhoc Inspection				Date: 26/08/2016
	No actionable defects found							
Asset:	2,026.00	Asset - Locn.:	7600044/J/00025 - Queens rd, Bayview rd bus stop	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511906 - Inspection Batch		Route:	Adhoc Inspection				Date: 26/08/2016
	No actionable defects found							
Asset:	2,027.00	Asset - Locn.:	7600044/J/00026 - Queens rd, LP 26	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511907 - Inspection Batch		Route:	Adhoc Inspection				Date: 26/08/2016
	No actionable defects found							
Asset:	2,028.00	Asset - Locn.:	7600044/J/00027 - Queens rd, opp Earls Court entrance	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511908 - Inspection Batch		Route:	Adhoc Inspection				Date: 26/08/2016
	No actionable defects found							
Asset:	2,029.00	Asset - Locn.:	7600044/J/00028 - Queens rd, LP 28	Feature Type:	RDS Gully		Area:	Aberdeen South
Batch:	511909 - Inspection Batch		Route:	Adhoc Inspection				Date: 26/08/2016
	No actionable defects found							

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3,000.00	Asset - Locn.:	H9 - (WB) Queens road approach to Kings Gate Roundabout.	Feature Type:	RDS Signs		Area:	Aberdeen South
Batch:	476698 - Inspection Batch			Route:	Adhoc Inspection			Date: 24/07/2015
	No actionable defects found							
Asset:	3,001.00	Asset - Locn.:	H10 - (WB) Queens Road 15m west of Kings Gate Roundabout.	Feature Type:	RDS Signs		Area:	Aberdeen South
Batch:	476699 - Inspection Batch			Route:	Adhoc Inspection			Date: 24/07/2015
	No actionable defects found							

Customer Services

Enquiry No.:	687394	Logged by:	Contact Centre	on:	01/02/2017 17:16	Enquiry Ref:	
Service:	Footways	Subject:	Broken Slab	Classification:	Enquiry		
Desc.:	Reference No : ROADS29045 Site (Street/Park/etc) : 70 carden place aberdeen ab10 1ul Location : on pavement just at entrance /exit Locational Details : In front of house First Type of Fault : Other First Fault Details : loose and cracked paving slabs on pavement Additional Information : the slabs are broken and loose on the pavement at the entrance to 70 Carden place Aberdeen .						
Location:	Carden Place -	Contact:					
Plot Number:	1,000.00	Feature Id - Location:	S/25/1928 - QUEENS ROAD (22)	Feature Type:	RDS Road Section		
Job Number:	711934	Defect Number:	462465				
Enquiry No.:	599864	Logged by:	Contact Centre	on:	20/06/2014 15:15	Enquiry Ref:	
Service:	Footways	Subject:	Overhanging Vegetation	Classification:	Enquiry		
Desc.:	Reference No : PATHS16328 Site (Street/Park/etc) : Westhill Cycle Path Location : Various location along route Locational Details : In footpath or lane First Type of Fault : Other First Fault Details : Vegetation Second Type of Fault : Lack of Footway Second Fault Details : Overgrowing Vegetation Additional Information : Cycle path being restricted by vegetation and tree growth across cycle path at various locations along route: e.g. Hazlehead by old fo ks home. Kingswells separated footpath width restriction at Prime Four Business Park due to tree growth						
Name :							
Telephone Number :							
Email Address :							
	Cycleway 7600044.						
Location:	Cycleway along Queen's Road to Westhill -	Contact:					

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Customer Services

Enquiry No.: 598983

Logged by: Contact Centre

on: 12/06/2014 12:37

Service: Footways

Subject: Broken Slab

Classification: Enquiry

Enquiry Ref:

Desc.: Paving lifted cracked and causing a trip hazard - [REDACTED] has a daughter with learning disabilities who tripped and fell - [REDACTED]

Location: Queens Road, eastbound, same side as The Chester Hotel, just after Bayview Road South

Contact: [REDACTED]

Plot Number: 1,000.00

Feature Id - Location: S/25/1928 - QUEENS ROAD (22)

Feature Type: RDS Road Section

Job Number: 183373

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		Asset - Locn.: S/25/1928 - QUEENS ROAD (22)		Feature Type: RDS Road Section		Area: Aberdeen South	
10289	test		.RD 28 Day	Job Closed	30/05/2007		
160675	Clean and jet 8 (eight) Gulleys	Both sides of road between junction with Hazledene Road and Kingsgate roundabout	.RD 14 Day	Job Closed	17/08/2011	14/06/2014	Act. RD01/4233
169349	investigate subsidence at manhole	142	.RD 28 Day	Job Closed	03/10/2012	17/06/2014	Act. RD01/5069
173971	Repoint 6 x damaged concrete footway crossings	North side of carriageway between Forrest Road roundabout and Queen's Gardens.	.RD 7 Day	Job Closed	03/04/2013	11/02/2016	Act. RD01/5877
180774	Clean and jet 4 x gullies. NO PARKING CONES WILL BE REQUIRED.	On Westbound carriageway between junctions with Viewfield Road and Rubislaw Park Road.	.RD 28 Day	Job Closed	31/01/2014	11/08/2014	Act. RD01/7797
183372	Lift and relay 6 x uneven slabs.	Outside number 39.	.RD 7 Day	Job Closed	29/04/2014	14/07/2016	Act. RD01/7835
183373	Replace 4 x broken and depressed slabs, 2 of 900 x 600 and 2 of 600 x 600	Outside number 86 at pay and display machine.	.RD 7 Day	Job Closed	29/04/2014	12/06/2014	Act. RD01/7835
183527	Clean and jet 6 x gullies.	On Westbound carriageway between Kingsgate roundabout and junction with Hazlehead Gardens.	.RD 14 Day	Job Closed	07/05/2014	28/08/2014	Act. RD01/8068
183737	Clean and jet all gullies (20)	On slip road from house number 298 to 374 (Pay particular attention to the gully outside number 330.)	.RD 7 Day	Job Closed	13/05/2014	22/06/2014	Act. RD01/7923
184175	Repair pothole approx' 600 by 600 by 60mm deep.	On slip road outside number 9 Royal Court.	.RD 2 Day	Job Closed	27/05/2014	27/05/2014	Act. RD01/8022
184497	Refresh road markings as per [REDACTED]	at hazlehead roundabout	.RD 28 Day	Job Closed	04/06/2014	03/06/2014	Act.
184600	Remove 3 uneven slabs and replace with bitmac.	Around tree outside St Joseph's School.	.RD 7 Day	Job Closed	09/06/2014	10/06/2014	Act. RD01/8120
185198	Remove approx' 1 square metre of damaged concrete footway and replace with bitmac.	Footway outside number 46.	.RD 7 Day	Job Closed	26/06/2014	26/06/2014	Act. RD01/8242
185571	Clean and jet all gullies	On slip road o/s number 330	.RD 28 Day	Job Cancelled	10/07/2014	11/07/2014	Act.

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		Asset - Locn.: S/25/1928 - QUEENS ROAD (22)		Feature Type: RDS Road Section		Area: Aberdeen South	
185698	Clean and jet gulley.	East side of junction with Westholme Avenue.	.RD 14 Day	Job Closed	17/07/2014	12/08/2014	Act. RD01/8383
186481	Clean and jet 3 x gullies.	Between junctions with Springfield Road and Westholme Avenue on Eastbound carriageway.	.RD 14 Day	Job Closed	14/08/2014	27/08/2014	Act. RD01/8480
186909	footpath,potholed, uneven surface, 20mtrs x3 mtrs , smooth over make area safe.	r s mc mcalls,queens rd, as per attached photo.	.RD 7 Day	Job Closed	02/09/2014	02/09/2014	Act. RD01/8574
186911	uneven slabs lift and relay,also re point service lid ,make area safe	queens road for ave ,to spade mill jct.crossing point.	.RD 7 Day	Job Closed	02/09/2014	03/09/2014	Act. RD01/8572
187158	Clean and jet gulley	Outside number 140.	.RD 14 Day	Job Closed	16/09/2014	22/09/2014	Act. RD01/8635
187390	Repair area of damaged carriageway surface, approx' 450 by 450 by 50mm deep.	On Eastbound carriageway at junction with Craigden.	.RD 7 Day	Job Closed	25/09/2014	26/09/2014	Act. RD01/8691
187742	Remove 8 x uneven slabs around tree causing trip hazard and replace with bitmac.	On footway around tree opposite number 82.	.RD 7 Day	Job Closed	08/10/2014	08/10/2014	Act. RD01/8786
187743	Remove 3 x uneven slabs and area of damaged concrete causing trip hazard and replace with bitmac. Total area approx' 5 square metres.	On footway adjacent to lamppost number 22.	.RD 7 Day	Job Closed	08/10/2014	08/10/2014	Act. RD01/8786
187861	Repair pothole approx' 400 by 150 by 55mm deep.	Around gulley on Eastbound carriageway at West side of junction with Angusfield Road.	.RD 7 Day	Job Closed	14/10/2014	14/10/2014	Act. RD01/8815
187971	Clean and jet 4 x gullies on Westbound carriageway.	Between junctions with Springfield Road and roundabout at Kingsgate.	.RD 14 Day	Job Closed	23/10/2014	25/10/2014	Act. RD01/8844
188020	Repair 2 x potholes, both approx' 300 by 300 by 55mm deep.	On slip road outside numbers 77 and 81.	.RD 7 Day	Job Closed	24/10/2014	24/10/2014	Act. RD01/8845
188195	Remove damaged concrete footway crossing causing trip hazard and replace with bitmac, total approx' 5 square metres.	At footway crossing adjacent to lamppost number 10 opposite school.	.RD 14 Day	Job Closed	03/11/2014	30/11/2014	Act. RD01/8895
188533	Repair damaged footway crossing causing trip hazards. Total approx' 8 square metres.	At entrance to Angusfield House.	.RD 14 Day	Job Closed	18/11/2014	30/11/2014	Act. RD01/9000
188534	Repair pothole approx' 300 by 150 by 55mm deep.	Around gulley on Eastbound carriageway at West side of junction with Angusfield Avenue.	.RD 7 Day	Job Closed	18/11/2014	18/11/2014	Act. RD01/8998
189058	Clean and jet 5 x gullies (Where accessible)	On Westbound carriageway between Rubislaw Park Road and Springfield Road.	.RD 14 Day	Job Closed	08/12/2014	18/12/2014	Act. RD01/9136
190766	clean and jet 6 gullies	from 274 to 256 both sides of c/w as attached plan	.RD 14 Day	Job Closed	24/02/2015	25/02/2015	Act. RD01/9502

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		Asset - Locn.: S/25/1928 - QUEENS ROAD (22)		Feature Type: RDS Road Section		Area: Aberdeen South	
191581	Find and Fix 4 potholes filled	o/s 306	.Routine Maintenance	Job Closed	23/03/2015	18/03/2015	Act.
192032	Clean and jet 6 blocked gullies. (Blocked Gully)	Between roundabout at HAZLEHEAD AVENUE and junction with GROATS ROAD.	.RD 14 Day	Job Cancelled	08/04/2015	14/05/2015	Act. RD01/9774
192723	Repair 2 potholes, both approx 300 x 300 x 55. (Pot Hole)	On slip road for ROYAL COURT.	.RD 7 Day	Job Closed	28/04/2015	28/04/2015	Act. RD01/9898
192724	Remove approx 1 square metre of damaged concrete causing trip hazards and replace with bitmac. (Pot Hole)	On footway at junction with slip road for ROYAL COURT.	.RD 7 Day	Job Closed	28/04/2015	28/04/2015	Act. RD01/9902
192751	Clean and jet blocked gully	On westside just past the junction with Royfold Crescent	.RD 14 Day	Job Closed	28/04/2015	29/04/2015	Act. RD01/9909
192754	Clean and jet blocked gully	opp no. 32 (TSB offices)	.RD 14 Day	Job Closed	28/04/2015	29/04/2015	Act. RD01/9909
193379	Clean and jet all gullies. (Blocked Gully)	Between roundabout at HAZLEHEAD AVENUE and junction with GROATS ROAD both sides of c/way.	.RD 14 Day	Job Closed	14/05/2015	19/08/2016	Act. RD01/20017
194264	Fill area of subsidence in carriageway, total area approx' 1 square metre.	Adjacent to entrance to slip road outside 142.	.RD 7 Day	Job Closed	10/06/2015	12/06/2015	Act. RD01/20228
195501	Repair series of 6 small potholes, total area approx' 2 square metres.	Both side of carriageway between lamposts 84 and 88.	.RD 7 Day	Job Closed	24/07/2015	25/07/2015	Act. RD01/20504
195680	Clean and jet 30 gullies.	Both sides of carriageway, where access ble, between RUBISLAW PARK ROAD and KINGSGATE.	.RD 28 Day	Job Closed	30/07/2015	23/08/2015	Act. RD01/20540
195779	Clean and jet gulley. (Blocked Gully)	On Eastbound carriageway outside number 88. NO PARKING CONES REQUIRED.	.RD 14 Day	Job Closed	04/08/2015	15/09/2015	Act. RD01/20824
195780	Replace damaged gulley cover with new one. (Iron Works)	On slip road opposite 3 ROYAL COURT.	.RD 14 Day	Job Closed	04/08/2015	18/08/2015	Act. RD01/20576
195885	Find and Fix 6 pothole filled by [REDACTED]	on r/about at jctn with hazlehead avenue	.Routine Maintenance	Job Closed	07/08/2015	26/07/2015	Act.
196860	clean and jet all gullies	from North Anderson Drive to Queen's Cross R/About both sides of C/Way	.RD 14 Day	Job Closed	16/09/2015	18/09/2015	Act. RD01/20837
197027	Find and Fix 5 potholes filled by [REDACTED]	116 to anderson drive, opp l/p 76 and opp l/p 78	.Routine Maintenance	Job Closed	22/09/2015	21/09/2015	Act.
197129	Find and Fix 1 potholes filled by [REDACTED]	at queen's parade	.Routine Maintenance	Job Closed	23/09/2015	20/09/2015	Act.
197353	Repair 3 potholes, all approx 300 x 200 x 55. (Pot Hole)	On slip road opposite numbers 338 - 340.	.RD 7 Day	Job Closed	05/10/2015	06/10/2015	Act. RD01/20999
197832	Clean and jet gulley.	Outside 169 - 171.	.RD 14 Day	Job Closed	28/10/2015	03/11/2015	Act. RD01/21260
198167	Clean and jet gulley	At junction with HAZLEDENE ROAD.	.RD 14 Day	Job Closed	09/11/2015	11/11/2015	Act. RD01/21351

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		Asset - Locn.: S/25/1928 - QUEENS ROAD (22)		Feature Type: RDS Road Section		Area: Aberdeen South	
198287	Repair 3 potholes, all approx' 300 x 300 x 50. (Pot Hole)	On footway crossing outside numbers 282 - 284.	.RD 7 Day	Job Closed	10/11/2015	10/11/2015	Act. RD01/21354
199181	Repair pothole approx' 300 x 300 x 55. (Pot Hole)	On Westbound carriageway opposite junction with CRAIGDEN.	.RD 2 Day	Job Closed	11/12/2015	11/12/2015	Act. RD01/21634
199358	1m2x40est SUNKEN C/WAY. (Sunken Carriageway)	Entrance to Queens Parade. (On box junction)	.RD 14 Day	Job Closed	18/12/2015	25/05/2016	Act. RD01/23293
199603	Repair pothole approx' 250 x 250 x 50. (Pot Hole)	On Westbound carriageway opposite number 10.	.RD 7 Day	Job Closed	06/01/2016	09/01/2016	Act. RD01/21744
199605	Repair pothole approx' 450 x 450 x 50. (Pot Hole)	At junction with ROYALCOURT.	.RD 2 Day	Job Closed	06/01/2016	06/01/2016	Act. RD01/21741
199606	Repair pothole approx' 500 x 400 x 50. (Pot Hole)	At junction with HAZLEHEAD GARDENS.	.RD 2 Day	Job Closed	06/01/2016	06/01/2015	Act. RD01/21741
199963	repair pothole 450 x 450 x 60	e/b c/way beside jctn with Springfield Road	.RD 2 Day	Job Closed	12/01/2016	12/01/2016	Act. RD01/21811
199965	Repair failed reinstatement 1m x 1m x 55	westbound c/w at jctn with Queen's Parade	.RD 2 Day	Job Closed	12/01/2016	12/01/2016	Act. RD01/21811
700055	Repair pothole approx' 300 x 200 x 50. (Pot Hole)	On Eastbound carriageway opposite lamppost number 88.	.RD 7 Day	Job Closed	14/01/2016	19/01/2016	Act. RD01/21831
700807	Repair pothole approx' 450 x 150 x 60. (Pot Hole)	On Westbound carriageway outside numbers 215 - 217.	.RD 2 Day	Job Closed	01/02/2016	01/02/2016	Act. RD01/22041
701163	Repair pothole 450 x 300 x 65	outside 215	.RD 2 Day	Job Closed	08/02/2016	08/02/2016	Act. RD01/22107
701268	Repair pothole approx' 450 x 200 x 50. (Pot Hole)	On exit from KINGSGATE ROUNDABOUT city bound.	.RD 2 Day	Job Closed	09/02/2016	09/02/2016	Act. RD01/22127
702027	repair all pot holes and surface defects various sizes about 40-50mm (unable to measure owing to traffic) (Pot Hole)	At roundabout at junction with kings gate at each junction and around roundabout	.RD 7 Day	Job Closed	01/03/2016	04/03/2016	Act. RD01/22319
702115	Repair 8 potholes, all approx' 300 x 300 x 50. (Pot Hole)	On slip road between junction with main road opposite number 298 and number 340.	.RD 7 Day	Job Closed	03/03/2016	03/03/2016	Act. RD01/22342
702220	Replace 2panel and 2 posts. (Damaged Crash Barrier)	As you head north from st swithen str roundabout jct,as per attached photo.	.RD 14 Day	Job Closed	07/03/2016	08/03/2016	Act. RD01/22384
702521	Repair pothole approx' 300 x 200 x 50. (Pot Hole)	On Westbound carriageway adjacent to lamppost 89.	.RD 7 Day	Job Closed	15/03/2016	15/03/2016	Act. RD01/22469
702887	Find and Fix 1 potholes filled	112	.Routine Maintenance	Job Closed	24/03/2016	21/03/2016	Act.
703773	Clean and jet 2 gullies.	Outside and opposite number 171.	.RD 14 Day	Job Closed	19/04/2016	28/04/2016	Act. RD01/22903
704420	Repair pothole approx' 450 x 450 x 60. (Pot Hole)	On slip road outside number 342	.RD 2 Day	Job Closed	05/05/2016	06/05/2016	Act. RD01/23092
704766	Repair approx' 3 square metres of uneven and damaged carriageway surface. (Pot Hole)	On Westbound carriageway adjacent to junction with HAZLEHEAD GARDENS.	.RD 14 Day	Job Closed	12/05/2016	03/06/2016	Act. RD01/23187

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		Asset - Locn.: S/25/1928 - QUEENS ROAD (22)		Feature Type: RDS Road Section		Area: Aberdeen South	
705255	clean ans jet gully	Adjacent to bus stop opposite lampost number 93. (Blocked Gully)	.RD 14 Day	Job Closed	24/05/2016	26/05/2016	Act. RD01/23322
706660	Pothole, 400x400x50, filled by inspector, (Pot Hole)	223 Queen's Road - ST	.RD 7 Day	Job Closed	11/07/2016	11/07/2016	Act. RD01/23860
707197	Clean and jet all gullies (20)	Between junction with Hazlehead Avenue and junction with Groats Road.	.RD 14 Day	Job Closed	27/07/2016	30/09/2016	Act. RD01/24057
707244	Repair pothole 150 x 150 x 60 around gully	west bound c/way around gully 10m from jctn with anderson drive	.RD 2 Day	Job Closed	28/07/2016	28/07/2016	Act. RD01/24080
707556	Repair pothole approx' 600 x 200 x 50. (Pot Hole)	At junction with ROYAL COURT.	.RD 7 Day	Job Closed	05/08/2016	06/08/2016	Act. RD01/24194
709043	Repair potholes various sizes approx 6 sq m	on slip road between 5 - 11 Royal Court	.RD 7 Day	Job Closed	04/10/2016	04/10/2016	Act. RD01/24748
709656	clean and jet 120 gullies done on cyclic maintenance by [REDACTED]	whole street	.Routine Maintenance	Contractor Completed	31/10/2016	25/10/2016	Act.
710474	Repair failing reinstatement approx' 2 square metres.	On Westbound carriageway at junction with Queen's Parade.	.RD 7 Day	Contractor Completed	08/12/2016	14/12/2016	Act. RD01/25434
710889	Find and Fix 1 potholes filled by [REDACTED]	265	.Routine Maintenance	Contractor Completed	05/01/2017	22/12/2016	Act.
710968	Find and Fix 3 potholes filled by [REDACTED]	248	.Routine Maintenance	Contractor Completed	09/01/2017	08/01/2017	Act.
711511	Find and Fix 3 potholes filled by [REDACTED]	297 and l/p 82	.Routine Maintenance	Contractor Completed	24/01/2017	21/01/2017	Act.
711724	Repair pothole approx' 300 x 300 x 50. (Pot Hole)	Outside number 13.	.RD 7 Day	Contractor Completed	30/01/2017	30/01/2017	Act. RD01/25890
711934	Remove loose rocking and broken slabs Temporary repair Both entrances are having the slabs removed and hot tarred. (Broken Slab)	70 Carden Place outside lefevre litigations Note: IPad maps unable to locate Carden Place .	.RD 2 Day	Contractor Completed	02/02/2017	05/02/2017	Act. RD01/25972
Asset: 1,001.00		Asset - Locn.: . - QUEENS ROAD (23)		Feature Type: RDS Road Section		Area: Aberdeen South	
10288	Test job		.Routine Maintenance	Job Closed	30/05/2007		
Asset: 1,047.00		Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen South	
191137	Repair damaged footway crossing, total area approx' 8 square metres.	Outside number 136.	.RD 14 Day	Job Closed	11/03/2015	16/06/2015	Act. RD01/9639
195331	Remove 4 depressed and broken slabs and replace with bitmac. (Rocking Slab)	Around toby lid on footway outside THE CHESTER HOTEL.	.RD 7 Day	Job Closed	21/07/2015	21/07/2015	Act. RD01/20468
196406	Repair pothole causing trip hazard. approx' 450 x 75 x 50. (Pot Hole)	Around manhole on footway opposite lampost number 92.	.RD 2 Day	Job Closed	26/08/2015	27/08/2015	Act. RD01/20699

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,047.00		Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen South	
197191	Repair damaged concrete footway crossing as required.	Outside number 89.	.RD 7 Day	Job Closed	28/09/2015	28/09/2015	Act. RD01/20943
197192	Remove 2 uneven slabs causing trip hazards and replace with bitmac.	On footway around BT cover adjacent to number 89.	.RD 7 Day	Job Closed	28/09/2015	28/09/2015	Act. RD01/20942
198372	reset cycle lane sign	fixed to l/p 39 outside 169	.RD 7 Day	Job Closed	11/11/2015	11/11/2015	Act. RD01/21370
199604	Repair damaged concrete surface causing trip hazard. (Broken Slab)	On footway outside number 13.	.RD 7 Day	Job Closed	06/01/2016	14/01/2016	Act. RD01/21766
700641	refix cycle lane sign to lamp post 47		.RD 14 Day	Job Closed	27/01/2016	28/01/2016	Act. RD01/21998
700650	Fill redundant tree pit with bitmac. (Pot Hole)	On footway outside number 245.	.RD 7 Day	Job Closed	27/01/2016	29/01/2016	Act. RD01/22005
702138	Repair approx' 1 square metre of damaged footway causing trip hazards. (Pot Hole)	On footway crossing at entrance to ANGUSFIELD NURSING HOME.	.RD 7 Day	Job Closed	03/03/2016	04/03/2016	Act. RD01/22357
703490	Remove 6 broken, depressed and rocking slabs causing trip hazards and replace with bitmac. (Broken Slab)	On footway at lamppost number 17.	.RD 7 Day	Job Closed	08/04/2016	10/04/2016	Act. RD01/22777
704119	Remove cobble stone causing trip hazard to pedestrians and replace with bitmac. (Broken Kerb)	Around tree on footway at West side of junction with WESTHOLME AVENUE.	.RD 7 Day	Job Closed	26/04/2016	30/04/2016	Act. RD01/22998
704126	Repair void in footway causing trip hazard to pedestrians. (Pot Hole)	On footway outside number 40.	.RD 2 Day	Job Closed	26/04/2016	27/04/2016	Act. RD01/23002
704724	Fill depression in footway causing trip hazard. Approx' 300 x 300 x 45. (Pot Hole)	On footway adjacent to lamppost number 10.	.RD 2 Day	Job Closed	11/05/2016	11/05/2016	Act. RD01/23167
706549	on footpath-300x160x60, pothole. (Pot Hole)	Junction to Angusfield Avenue.	.RD 14 Day	Job Closed	05/07/2016	06/07/2016	Act. RD01/23819
706648	repair damaged visi rail 2 panel and 1 post - Britain in Bloom request	at kepplestone manor as attached photo	.RD 14 Day	Contractor Completed	08/07/2016	08/07/2016	Act. RD01/23853
707209	Remove depressed and broken triangular slab causing trip hazard and replace with bitmac. (Rocking Slab)	On footway outside Albyn School opposite number 20.	.RD 7 Day	Job Closed	27/07/2016	27/07/2016	Act. RD01/24067
707243	Remove 6 slabs and replace with bitmac	opp 80-82 around tree pit	.RD 7 Day	Job Closed	28/07/2016	28/07/2016	Act. RD01/24079
707555	Remove raised slab causing trip hazard and replace with bitmac. (Rocking Slab)	Adjacent to tree pit opposite number 80.	.RD 7 Day	Job Closed	05/08/2016	06/08/2016	Act. RD01/24195

Effective: 11/05/2014 to 06/02/2017

Contract: Roads Contract (General Maint) (RD01)

Site: QUEEN'S ROAD (7600044)

Service: Footways

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,047.00		Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen South	
710421	Remove damaged and broken concrete causing trip hazard and replace with bitmac, approx' 1 square metre. (Sunken Footway)	At exit from ALBYN SCHOOL.	.RD 7 Day	Contractor Completed	06/12/2016	08/12/2016	Act. RD01/25397
710422	Remove 3 uneven slabs causing trip hazards due to tree root disturbance and replace with bitmac. (Sunken Footway)	On footway at entrance GORE VEGA (opposite number 46).	.RD 7 Day	Contractor Completed	06/12/2016	08/12/2016	Act. RD01/25397
710424	Remove 3 uneven slabs causing trip hazards and replace with bitmac. Tree root disturbance. (Sunken Footway)	On footway outside entrance to TBP (opposite number 50) against wall.	.RD 7 Day	Contractor Completed	06/12/2016	08/12/2016	Act. RD01/25397
Asset: 100,001.00		Asset - Locn.: 9051042911 - QUEENS ROAD, AB15 4ZT		Feature Type: W - Domestic Waste Property		Area: Aberdeen South	
10022500	Dry Recyclate - DELIVER 2X BLACK BOXES, 2X NETS AND 2X ROLLS OF KITCHEN CADDY LINERS. IGNORE QUEEN'S ROAD, AND DELIVER TO WOODEND AVENUE. (Enquiry 329677)	WOODEND AVENUE, ABERDEEN, AB15 6YL.	.Routine Maintenance	Job Cancelled	09/12/2013		
Asset: 100,220.00		Asset - Locn.: 9051031260 - QUEENS ROAD, AB15 4YG		Feature Type: W - Domestic Waste Property		Area: Aberdeen South	
124207	Missed Bin - PLEASE SEND OUT BROWN BIN + CALENDAR _ BLACK WHEELI BIN WAS MISSED YESTERDAY - WHOLE OF STREET MISSED (Enquiry 113308)	QUEENS ROAD	.Routine Maintenance	Job Cancelled	27/05/2010		
Asset: 100,308.00		Asset - Locn.: 9051031811 - KEPPLESTONE HOUSE, QUEENS ROAD,		Feature Type: W - Domestic Waste Property		Area: Aberdeen South	
10048135	Waste Other - TWO NETS REQUIRED AND A WHITE BAG PLEASE. (Enquiry 619639)	KEPPLESTONE HOUSE QUEEN'S ROAD	WM: 7 Day	Job Raised	16/01/2015	23/01/2015	Est.

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Site: QUEEN'S ROAD (7600044)

Locality: ABERDEEN, ABERDEEN CITY

Area: Aberdeen South

Customer Services

Enquiry No.: 679426 Logged by: Contact Centre on: 09/11/2016 11:38
 Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:
 Desc.: Reference No: DRAINAGE15816. Site (Street/Park/etc): Queens Road, eastbound. Location: Just before Anderson Drive roundabout. Locational Details: In front of house. First Type of Fault: Ponding/Flooding. First Fault Details: Water not draining and flooding at junction causing vehicle, cycle and pedestrian hazard. Name: [REDACTED] Telephone Number: [REDACTED] Email Address: [REDACTED]
 Location: QUEENS ROAD - DRAINAGE15816 - [REDACTED] Contact: [REDACTED]

Enquiry No.: 675484 Logged by: Contact Centre on: 03/10/2016 12:30
 Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:
 Desc.: ROADS28683 Hotel end mostly
 Locational Details : In front of house
 First Type of Fault : Poor Road Surface
 First Fault Details : Pothole
 Additional Information : The road surface has started to badly deteriorate recently. [REDACTED]
 Location: ROYAL COURT QUEEN'S ROAD Contact: [REDACTED]

Plot Number: 1,000.00 Feature Id - Location: S/25/1928 - QUEENS ROAD (22) Feature Type: RDS Road Section
 Job Number: 709043

Enquiry No.: 672165 Logged by: Contact Centre on: 02/09/2016 14:53
 Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:
 Desc.: Reference No: ROADS28627. Site (Street/Park/etc): 286 Queens Road, Aberdeen AB15 8DR. Location: Road going eastward before Hazlehead Roundabout, beside the old Tramway road. Locational Details: Opposite side of road. First Type of Fault: Rocking/Noisy/Low Manhole Cover
 Name: [REDACTED] Address Line 1: [REDACTED] Address Line 3: [REDACTED] Postcode: [REDACTED] Telephone Number: [REDACTED] Email Address: [REDACTED]
 Location: 286 QUEENS ROAD - ROADS28627 - [REDACTED] Contact: [REDACTED]

Enquiry No.: 671542 Logged by: Contact Centre on: 29/08/2016 11:44
 Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:
 Desc.: ROAD TRAFFIC SIGNS
 B9119 AT QUEENS CROSS WESTBOUND - THE REAR OF THE 20MPH SCHOOL SIGN AT ST. JOSEPHS FROM WHERE THE 30MPH SIGN HANGS IS COMPLETELY COVERED BY VEGETATION. IT REQUIRES PRUNING URGENTLY.
 MR TRAY
 Location: B9119 QUEENS CROSS WESTBOUND - [REDACTED] Contact: [REDACTED]

Enquiry No.: 668303 Logged by: Contact Centre on: 28/07/2016 09:03
 Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:
 Desc.: Caller would like to report there is a pot hole at this location. Could someone go out and repair this please [REDACTED]
 Location: QUEEN'S ROAD - just before the roundabout with North Anderson drive as you drive away from the city centre. Beside a roadside gully Contact: [REDACTED]

Plot Number: 1,000.00 Feature Id - Location: S/25/1928 - QUEENS ROAD (22) Feature Type: RDS Road Section
 Job Number: 707244

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Customer Services

Enquiry No.: 668172	Logged by: Contact Centre	on: 27/07/2016 00:02	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: FAO : ACC Roads Response service,			
Reference No : DRAINAGE15704 Site (Street/Park/etc) : Queens road Location : All road gullies from junction with Hazledene road and Hazlehead avenue Locational Details : Opposite side of road First Type of Fault : Blocked Gully First Fault Details : All road gullies between Hazledene road junction and Hazlehead avenue completely blocked with sand type material Additional Information : All road gullies completely blocked causing water to flood Hazledene Road- this is an ongoing problem- these gullies have previously been blocked			
Name : [REDACTED] Telephone Number : [REDACTED] Email Address : [REDACTED]			
Location: QUEEN's ROAD	Contact: [REDACTED]		
Plot Number: 1,000.00	Feature Id - Location: S/25/1928 - QUEENS ROAD (22)	Feature Type: RDS Road Section	
Job Number: 707197			
Enquiry No.: 666707	Logged by: Contact Centre	on: 08/07/2016 13:57	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Pothole on road			
Location: 223 Queen's Road - ST	Contact: Anon		
Plot Number: 1,000.00	Feature Id - Location: S/25/1928 - QUEENS ROAD (22)	Feature Type: RDS Road Section	
Job Number: 706660			
Defect Number: 459479			
Enquiry No.: 666305	Logged by: Contact Centre	on: 04/07/2016 16:05	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: THERE ARE A COUPLD OF LARGE HOLES ON THE PAVEMENT AT THE JUNCTION WITH QUEENS ROAD AND ANGUSFIELD AVENUE, [REDACTED] IS WORRIED SOMEONE WILL TRIP AND HAVE A REALLY NASTY ACCIDENT, COULD SOMEONE LOOK AT5 THIS ASAP PLEASE			
Location: ANGUSFIELD AVENUE AT JUNCTION WITH QUEENS ROAD - SH	Contact: [REDACTED]		
Plot Number: 1,047.00	Feature Id - Location: 1 - Footway	Feature Type: RDS Footway	
Job Number: 706549			
Defect Number: 459420			
Enquiry No.: 665193	Logged by: Contact Centre	on: 21/06/2016 10:11	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No: ROADS28418. Site (Street/Park/etc): Queens Road Westwards. Location: After Provost Graham Avenue. First Type of Fault: Rocking/Noisy/Low Manhole Cover. Second Type of Fault: Rocking/Noisy/Low Manhole Cover. Additional Information: The drains are damaged with lumps of bitumen visible Given previous report it would be worth visually checking the section Hazelhead roundabout to Smithfield Farm, as driving past I can't look at each one closely.			
Name: [REDACTED] Address Line 1: [REDACTED] Address Line 2: [REDACTED] Address Line 3: [REDACTED] Postcode: [REDACTED] Telephone Number: [REDACTED] Email Address: [REDACTED]			
Location: QUEENS ROAD - ROADS28418 - AB	Contact: [REDACTED]		
Enquiry No.: 663435	Logged by: Contact Centre	on: 27/05/2016 10:29	Enquiry Ref:
Service: Roads	Subject: Claims - Roads	Classification: Defect Report	
Desc.: tenant called in today for the first time asking about a claim for tripping on pavement on uneven surface on 3rd December 2015 she has photos etc she has been off work since this date			
Location: queen's road - cy	Contact: [REDACTED]		

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Customer Services

Enquiry No.: 663304 **Logged by:** Contact Centre **on:** 25/05/2016 11:43
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Caller would like to report that he has had a collision with the short wall running up this street after his tyre burst. A few of the stones have been dislodged. Could someone look into this please? If you need to contact him he can be reached on [REDACTED] - [REDACTED]
Location: QUEEN'S ROAD - outside Denseat Court **Contact:** [REDACTED]

Enquiry No.: 663285 **Logged by:** Contact Centre **on:** 25/05/2016 10:33
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No: ROADS28354. Site (Street/Park/etc): Queens Road. Location: Near to bus terminus at Hazlehaed on Queens Road. First Type of Fault: Pothole. First Fault Details: Large deep hole which has been repaired previously. Name: [REDACTED]. Address Line 1: [REDACTED] Email Address: [REDACTED]
Location: QUEENS ROAD - ROADS28354 - [REDACTED] **Contact:** [REDACTED]

Plot Number: 1,000.00 **Feature Id - Location:** S/25/1928 - QUEENS ROAD (22) **Feature Type:** RDS Road Section
Job Number: 704766

Enquiry No.: 662931 **Logged by:** Contact Centre **on:** 20/05/2016 11:34
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Pedestrian reporting blocked kerbside gully by bus shelter just west of Queens Den junction.
Location: QUEENS ROAD - AB **Contact:** Anon

Plot Number: 1,000.00 **Feature Id - Location:** S/25/1928 - QUEENS ROAD (22) **Feature Type:** RDS Road Section
Job Number: 705255 **Defect Number:** 458628

Enquiry No.: 662887 **Logged by:** Contact Centre **on:** 19/05/2016 16:00
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No: ROADS28327. Site (Street/Park/etc): Main Abedeen to Kingswells Road (Hazelhead). Location: Beside Bus Turning Layby/opposite turn in to Woodend hospital. First Type of Fault: Pothole
 First Fault Details: Sizable sunken area. Second Type of Fault: Poor Road Surface. Additional Information: Near the western exit of the Hazelhead bus turning there is a large area of sunken road surface on the main road that is getting worse and causing traffic to slow to 15>20mph to avoid suspension damage. It has been like this for 3 weeks and is getting worse.
 Name: [REDACTED] Address Line 1: [REDACTED] Address Line 2: [REDACTED] Address Line 3: [REDACTED] Postcode: [REDACTED] Email Address: [REDACTED]
Location: SKENE ROAD - ROADS28327 - [REDACTED] **Contact:** [REDACTED]

Plot Number: 1,000.00 **Feature Id - Location:** S/25/1928 - QUEENS ROAD (22) **Feature Type:** RDS Road Section
Job Number: 704766

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Customer Services

Enquiry No.: 662777

Logged by: Contact Centre

on: 18/05/2016 13:34

Service: Roads

Subject: General Enquiry

Classification: Defect Report

Enquiry Ref:

Desc.: -----Original Message-----

From:

Sent: 18 May 2016 13:20

To: RepairFinder

Subject: Notice of a Defect in the Carriageway (Cycling UK Hazard #129710)

To: Aberdeen City Council

[NOTE: If replying by email, please reply to the exact address this message was sent from

[REDACTED] has had the following hazard reported to it via the FillThatHole.org.uk website, and we believe that you may be the responsible highway authority.

Please use the web link below to update the status of this hazard in the FillThatHole.org.uk database directly:

<http://www.fillthathole.org.uk/hazard/129710?key=3764377a59>

OUR REFERENCE: #129710

The hazard is located at:

OS GRID REFERENCE: NJ 90785 05469

LOCATION DESCRIPTION:

219-225 Queen's Rd, Aberdeen, Aberdeen City AB15 8DJ

LOCATION MAP:

<http://www.fillthathole.org.uk/hazard/129710/map>

Hazard information:

HAZARD TYPE: Pothole

APPROX. SIZE: 30.0 cm

APPROX. DEPTH: 8.0 cm

APPROX. DISTANCE FROM KERB: 100.0 cm

DATE ENCOUNTERED: 2016-05-18

DEFECT DESCRIPTION:

Deep pothole on cycle lane.

FURTHER INFORMATION:

<http://www.fillthathole.org.uk/hazard/129710>

Change History:

-- 18 May 2016, 12:38pm -- Added to Database -- Reporter

Update our records:

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Customer Services

add comments to the hazard record, record the reference number you have assigned to the hazard, and/or mark the hazard as ¿Fixed¿ or ¿Rejected¿ using the following URL:

<http://www.fillthathole.org.uk/hazard/129710?key=3764377a59>

Location: QUEEN'S ROAD - AB

Contact: CTC - [REDACTED]

Plot Number: 1,000.00

Feature Id - Location: S/25/1928 - QUEENS ROAD (22)

Feature Type: RDS Road Section

Job Number: 704766

Enquiry No.: 662469

Logged by: Contact Centre

on: 15/05/2016 00:17

Service: Roads

Subject: Pot Hole - Road

Classification: Service Requested

Enquiry Ref:

Desc.: Reference No : ROADS28304

Site (Street/Park/etc) : Queens Road

Location : Hazlehead Gardens

First Type of Fault : Pothole

First Fault Details : pothole spans the western route of Queens road next to the hazlehead gardens opening. it is almost imposs ble to avoid and is soon going to start damaging vehicles

Name [REDACTED]

Address Line 1 : [REDACTED]

Postcode : [REDACTED]

Email Address [REDACTED]

Location: QUEEN'S ROAD

Contact: [REDACTED]

Plot Number: 1,000.00

Feature Id - Location: S/25/1928 - QUEENS ROAD (22)

Feature Type: RDS Road Section

Job Number: 704766

Enquiry No.: 660136

Logged by: Contact Centre

on: 17/04/2016 01:57

Service: Roads

Subject: General Enquiry

Classification: Defect Report

Enquiry Ref:

Desc.: DRAINAGE15576

Site (Street/Park/etc) : Queens Road Aberdeen.

Location : On road outside 171 Queens Road

Locational Details : In front of house

First Type of Fault : Blocked Gully

Additional Information : It has not been cleaned since the last time I reported it, the one on the oppisite side of the road at the bus stop is also chocked. Have you guys never heard of preventive maintainance. The pavement from Viewfield Road to 169 Queens Road needs resurfacing it is a disgrace,I have seen people falling after tripping on the surface.

Location: Queens Road Aberdeen. On road outside 171 Queens Road

Contact: [REDACTED]

Plot Number: 1,000.00

Feature Id - Location: S/25/1928 - QUEENS ROAD (22)

Feature Type: RDS Road Section

Job Number: 703773

Enquiry No.: 659005

Logged by: Contact Centre

on: 04/04/2016 16:27

Service: Roads

Subject: General Enquiry

Classification: Defect Report

Enquiry Ref:

Desc.: Police report a large oil spill at this location, going across both carriageways after a road traffic collision. Passed to Roads by phone [REDACTED]

Location: QUEEN'S ROAD - junction with Queen's Den

Contact: POLICE SCOTLAND

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Customer Services

Enquiry No.: 658857	Logged by: Contact Centre	on: 02/04/2016 22:55	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: FAO : ACC Roads Response service,			
Reference No : ROADS28065 Site (Street/Park/etc) : Road Location : Queen's Road junction with Hazelhead Gardens First Type of Fault : Poor Road Surface First Fault Details : Very poor, damaged strip running across Queens Road West bound Additional Information : There is a very rough, damaged strip running across the whole of the westbound side of Queens Road. Cars are regularly swerving to the opposite side of the road to avoid this section of damage.			
Name : [REDACTED] Address Line 1 : [REDACTED] Address Line 2 : [REDACTED] Postcode : [REDACTED] Email Address : [REDACTED]			
Location: Queen's Road	Contact: [REDACTED]		
Enquiry No.: 658744	Logged by: Contact Centre	on: 01/04/2016 09:27	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No: ROADS28058. Site (Street/Park/etc): QUEENS ROAD HEADING TOWARDS SKENE ROAD. Location: JUST BEYOND BUS STOP/TURNING AREA AT WOODEND. First Type of Fault: Poor Road Surface. First Fault Details: POSSIBLE PUBLIC UTILITY REINSTATEMENT? Name: [REDACTED] Address Line 1: [REDACTED] Address Line 2: [REDACTED] Postcode: AB15 5NZ. Email Address: [REDACTED]			
Location: QUEENS ROAD - ROADS28058 - [REDACTED]	Contact: [REDACTED]		
Enquiry No.: 658098	Logged by: Contact Centre	on: 24/03/2016 11:35	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: MR [REDACTED] WOULD LIKE SOMEONE IN THE ROADS TEAM TO CONTACT THE RESIDENTS IN [REDACTED] QUEEN'S ROAD AND GET THEM TO CUT BACK THE OVER HANGING VEGETATION FROM THEIR GARDEN, IT OVER HANGS THE PUBLIC FOOTPATH AND IT IS A NUISANCE AS HE SOMETIMES GETS WET FROM IT.			
Location: [REDACTED] QUEEN'S ROAD - SH	Contact: [REDACTED]		
Enquiry No.: 657044	Logged by: Contact Centre	on: 14/03/2016 05:43	Enquiry Ref:
Service: Roads	Subject: Pot Hole - Road	Classification: Service Requested	
Desc.: Reference No : ROADS27946 Site (Street/Park/etc) : B119 Queens Road, after Kings Gate Round toward the Crematorium Location : Pothole between 297 and 299 Queens Road Locational Details : In front of house First Type of Fault : Pothole First Fault Details : Pothole near to middle of the road			
Location: B119 Queens Road,	Contact: [REDACTED]		

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Customer Services

Enquiry No.: 655896	Logged by: Contact Centre	on: 29/02/2016 21:03	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No : ROADS27836 Site (Street/Park/etc) : road Location : left turn lane at Queens Road\Kings gate roundabout (coming from Westhill) First Type of Fault : Pothole First Fault Details : big pothole developing right at give way line if turning left onto Kings Gate Name : [REDACTED]			
Location: QUEEN'S ROAD	Contact: [REDACTED]		
Plot Number: 1,000.00	Feature Id - Location: S/25/1928 - QUEENS ROAD (22)	Feature Type: RDS Road Section	
Job Number: 702027	Defect Number: 456132		
Enquiry No.: 655740	Logged by: Contact Centre	on: 28/02/2016 17:49	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Hole in pavement "diameter and approx. 18" deep - could catch a heel in it and fall - passed to standby JW			
Location: Pavement outside 265 Queens Road	Contact: [REDACTED]		
Enquiry No.: 655096	Logged by: Contact Centre	on: 19/02/2016 14:28	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No: ROADS27760. Site (Street/Park/etc): Hazelhead Road. Location: Roundabout. First Type of Fault: Poor/Lack of Road Markings. Additional Information: When approaching the Hazelhead roundabout from Westhill direction there is no lane arrow markings in either lane for guidance. Name [REDACTED] Address Line 1: [REDACTED] Telephone Number: [REDACTED] Email Address [REDACTED]			
Location: QUEENS ROAD at HAZLEHEAD ROUNDABOUT - ROADS27760 - [REDACTED]	Contact: [REDACTED]		
Enquiry No.: 653724	Logged by: Contact Centre	on: 07/02/2016 22:56	Enquiry Ref:
Service: Roads	Subject: Claims - Roads	Classification: Claim	
Desc.: ROADS27553 Site (Street/Park/etc) : Queens Road, Aberdeen Location : 270 - 272 Queens Road Locational Details : Opposite side of road First Type of Fault : Rocking/Noisy/Low Manhole Cover First Fault Details : Low manhole cover, Westbound on Queens Road			
Location: Queens Road, Aberdeen	Contact: [REDACTED]		
Enquiry No.: 651470	Logged by: Contact Centre	on: 18/01/2016 15:29	Enquiry Ref:
Service: Roads	Subject: Claims - Roads	Classification: Claim	
Desc.: Reference No: WINTER14138. Site (Street/Park/etc): Queens Road. Location: Queens Road. Locational Details: Opposite side of road. First Type of Concern: Damage Due to Gritting. First Concern Details: Damage to new car caused by gritter. Additional Information: I purchased a new car on 12 January 2016. It was in immaculate condition. Unfortunately on the same day, around 7.45pm, I was driving the car home along Queens Road when a gritter passed on the opposite side of the road. The gritter sprayed the driver side of the car and has caused the paintwork to chip in a few places. This will require to be fixed to avoid rusting. I would be grateful if someone could call or email me as soon as possible to discuss this further as I will be looking to have the costs of the repair to the paintwork paid for in this instance and would like to understand how this will work. Kind regards [REDACTED]. Name: [REDACTED] Telephone Number: [REDACTED] Email Address: [REDACTED]			
Location: QUEENS ROAD - WINTER14138 - [REDACTED]	Contact: [REDACTED]		

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Customer Services

Enquiry No.: 651361 **Logged by:** Contact Centre **on:** 16/01/2016 23:43
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Site (Street/Park/etc) : B9119 queens road at Hazeldead
 Location : On main road at opening to old access to wood end hospital
 Locational Details : Opposite side of road
 First Type of Fault : Pothole
 First Fault Details : Pothole getting larger
 Second Type of Fault : Pothole
 Additional Information : Pothole on main B9119 queens road from west heading into city centre - just at entrance to wood end hospital at opposite bus terminus at Hazelhead

Name : [REDACTED]

Address Line 1 : [REDACTED]

Address Line 3 : [REDACTED]

Postcode : [REDACTED]

Email Address : [REDACTED]

Location: BLOOMFIELD COURT**Contact:** [REDACTED]**Plot Number:** 1,000.00 **Feature Id - Location:** S/25/1928 - QUEENS ROAD (22) **Feature Type:** RDS Road Section**Job Number:** 199606

Enquiry No.: 650710 **Logged by:** Contact Centre **on:** 12/01/2016 14:28
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Pothole at junction with Queen's Parade.
Location: Queen's Road - ST **Contact:** [REDACTED]

Plot Number: 1,000.00 **Feature Id - Location:** S/25/1928 - QUEENS ROAD (22) **Feature Type:** RDS Road Section**Job Number:** 199965

Enquiry No.: 650115 **Logged by:** Contact Centre **on:** 08/01/2016 10:59
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: ROADS27170 Just beside the junction of Skene Road with Hazlehead Gardens (where bus turns out) large pothole in the very middle of the road heading towards Kingswells. I have photos. My husband hit this pothole on Wednesday 6 Jan night. [REDACTED]
Location: B9119 Skene Road beside junction of Halzlehead Gardens **Contact:** [REDACTED]

Plot Number: 1,000.00 **Feature Id - Location:** S/25/1928 - QUEENS ROAD (22) **Feature Type:** RDS Road Section**Job Number:** 199606

Enquiry No.: 650016 **Logged by:** Contact Centre **on:** 07/01/2016 11:50
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No : ROADS27162

Site (Street/Park/etc) : Queens Road at Hazelhaed at Woodend bus terminus

Location : At the bus terminus on Queens Road going out of town side at Woodend

Locational Details : Opposite side of road

First Type of Fault : Pothole

First Fault Details : large pothole on the road

Name : [REDACTED]

Address Line 1 : [REDACTED]

Email Address : [REDACTED]

njc

Location: ROADS27162 - Queens Road**Contact:** [REDACTED]**Plot Number:** 1,000.00 **Feature Id - Location:** S/25/1928 - QUEENS ROAD (22) **Feature Type:** RDS Road Section**Job Number:** 199606

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Customer Services

Enquiry No.: 648832	Logged by: Contact Centre	on: 18/12/2015 12:24	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Pothole in the road in the box junction.			
Location: 110 QUEENS ROAD - [REDACTED]	Contact: [REDACTED]		
Plot Number: 1,000.00	Feature Id - Location: S/25/1928 - QUEENS ROAD (22)	Feature Type: RDS Road Section	
Job Number: 199358			
Enquiry No.: 645217	Logged by: Contact Centre	on: 10/11/2015 22:38	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: FAO : ACC Roads Response service,			
<p>Reference No : PATHS17047 Site (Street/Park/etc) : Queens Road Location : Start of the cycle lane on the east bound lane, after Viewfield Road. Locational Details : In footpath or lane First Type of Fault : Other First Fault Details : Information sign Additional Information : The in formation sign indicating the start of the cycle lane, is constantly turned towards the houses, just after the newsagents. Suspect its by the occupants how then illegally park their vehicles in the designated cycle lane. The parking matter will be highlighted to Police Service of Scotland, but, with partnership working being what it is nowadays, it would assist if the broken white lines indicating the segregation of the carriageway and the cycle lane was changed to a solid white line from this point up to the Springfield Road junction.</p>			
<p>Name : [REDACTED] Telephone Number : [REDACTED] Email Address [REDACTED]</p>			
Location: Queen's Road	Contact: [REDACTED]		
Plot Number: 1,047.00	Feature Id - Location: 1 - Footway	Feature Type: RDS Footway	
Job Number: 198372			
Enquiry No.: 644956	Logged by: Contact Centre	on: 09/11/2015 02:28	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: DRAINAGE15353			
<p>Site (Street/Park/etc) : Queens Road at junction of Hazledene Road Location : On corner of Queens Road/Hazledene Road junction towards Roundabout at Hazlehead First Type of Fault : Blocked Gully First Fault Details : Water flowing down Queens Road runs over blocked Gully and forms a large pool of flood water on Hazledene road Additional Information : This is a on-going problem where the road gully cannot take water flowing down Queens Road and it then flows in Hazledene Road causing flooding at the side of the road.</p>			
Location: Queens Road at junction of Hazledene Road	Contact: [REDACTED]		
Plot Number: 1,000.00	Feature Id - Location: S/25/1928 - QUEENS ROAD (22)	Feature Type: RDS Road Section	
Job Number: 198167			
Enquiry No.: 644945	Logged by: Contact Centre	on: 08/11/2015 16:56	Enquiry Ref:
Service: Roads	Subject: Roads OOH Emergency	Classification: Service Requested	
Desc.: LOCATED AT QUEEN'S ROAD BETWEEN FORREST ROAD AND FOUNTAIN HILL ROAD. ROAD WORKS PLASTIC CONES, ETC LOOSE AND CAUSING DISTURBANCE TO ROAD USERS; NEEDS SECURING. PASSED TO STANDBY			
PC. NO: 1206, NO INCIDENT NUMBER WAS PROVIDED			
Location: QUEEN'S ROAD	Contact: Police Scotland		

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Customer Services

Enquiry No.: 643951	Logged by: Contact Centre	on: 27/10/2015 13:05	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No: DRAINAGE15344. Site (Street/Park/etc): Queens Road. Location: Aberdeen. Locational Details: In front of house. First Type of Fault: Blocked Gully. First Fault Details: Drain blocked. Additional Information: Outside 169/171 Quens Road Aberdeen AB15 8BS. Name: [REDACTED] Telephone Number [REDACTED] Email Address: [REDACTED]			
Location: 169 QUEENS ROAD - DRAINAGE15344 - [REDACTED]	Contact: [REDACTED]		
Plot Number: 1,000.00	Feature Id - Location: S/25/1928 - QUEENS ROAD (22)	Feature Type: RDS Road Section	
Job Number: 197832			
Enquiry No.: 642432	Logged by: Contact Centre	on: 12/10/2015 09:33	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: POLICE CALLED REGARDING 5 ROAD SIGNS WERE MOVED ONTO THE ROAD LAST NIGHT.THE POLICE HAVE MOVED THEM TO THE PAVEMENT. INC NO 12 [REDACTED]			
Location: QUEEN'S ROAD	Contact: Police Scotland		
Enquiry No.: 639570	Logged by: Contact Centre	on: 07/09/2015 15:34	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: BLOCKED GULLY: Reference No: CLEAN17194. Site (Street/Park/etc): queen's road. Location: In front of bus shelter opposite viewfield road. Locational Details: In front of house. First Type of Concern: Other. First Concern Details: drain in street gutter badly needs cleaning as smell from it is apalling. Name: [REDACTED] Email Address [REDACTED]			
Location: 138 QUEENS ROAD - CLEAN17194 - [REDACTED]	Contact: [REDACTED]		
Plot Number: 1,000.00	Feature Id - Location: S/25/1928 - QUEENS ROAD (22)	Feature Type: RDS Road Section	
Job Number: 195680			
Enquiry No.: 639382	Logged by: Contact Centre	on: 04/09/2015 14:06	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No: ROADS26856. Site (Street/Park/etc): Queens Road. Location: Junction with Springfield Road. First Type of Fault: Poor Road Surface. Additional Information: Travelling into town. In the line for straight on into town on inside/passenger side/gutter side. 10m before stop line to stop line the surface is very uneven. Name: [REDACTED] Address Line 1: [REDACTED] Postcode: [REDACTED] Telephone Number: [REDACTED]. Email Address: [REDACTED]			
Location: QUEENS ROAD - ROADS26856 - [REDACTED]	Contact: [REDACTED]		
Enquiry No.: 637252	Logged by: Contact Centre	on: 12/08/2015 15:49	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No : ROADS26792 Site (Street/Park/etc) : Street Location : Queens Road Westbound - junction with Hazelhead Gardens First Type of Fault : Pothole First Fault Details : Very poor surface/potholes, cyclists often seen swerving into traffic to avoid it			
Location: Queens Road - Junction with Hazlehead Gardens	Contact: [REDACTED]		
Enquiry No.: 632275	Logged by: Contact Centre	on: 18/06/2015 14:01	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No: ROADS26609. Site (Street/Park/etc): Queen's Road. Location: Just east of crossing between Queen's Road and Groats Road. Locational Details: In footpath or lane. First Type of Fault: Pothole. First Fault Details: Pothole in middle of road. Second Type of Fault: Poor Road Surface. Second Fault Details: Road surface condition generally bad Additional Information: Map location: https://www.google.co.uk/maps/place/57%C2%B008&apos;42.0%C2%22N+2%C2%B010&apos;39.7%C2%22W/@57.145,-2.177682,19z/data=!3m1!4b1!4m2!3m1!1s0x0:0x0?hl=en . Name: [REDACTED] [REDACTED] Address Line 1: [REDACTED] Email Address: [REDACTED]			
Location: QUEENS ROAD - ROADS26609 - [REDACTED]	Contact: [REDACTED]		

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Customer Services

Enquiry No.: 631765	Logged by: Contact Centre	on: 11/06/2015 15:39	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Drain on opposite side of road backing up and over flowing.			
Location: 348 Queen's Road - [REDACTED]	Contact: [REDACTED]		
Plot Number: 1,000.00	Feature Id - Location: S/25/1928 - QUEENS ROAD (22)	Feature Type: RDS Road Section	
Job Number: 193379			
Enquiry No.: 628725	Logged by: Contact Centre	on: 04/05/2015 10:01	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No: ROADS26440. Site (Street/Park/etc): 270 - 272 Queens Road. Location: 270 / 272 Queens Road. Locational Details: Opposite side of road. First Type of Fault: Rocking/Noisy/Low Manhole Cover. First Fault Details: Noisy and Low manhole cover. Name [REDACTED] Address Line 1: [REDACTED] Address Line 2: [REDACTED] Postcode: [REDACTED] Email [REDACTED]			
Location: 270-272 QUEENS ROAD - ROADS26440 - [REDACTED]	Contact: [REDACTED]		
Enquiry No.: 625938	Logged by: Contact Centre	on: 29/03/2015 00:02	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No : ROADS26303 Site (Street/Park/etc) : Queens road Location : Man hole cover near junction with Hazelhead Gardens Locational Details : Opposite side of road First Type of Fault : Rocking/Noisy/Low Manhole Cover Additional Information : When cars drive over the manhole cover it makes a noise			
Location: QUEENS ROAD	Contact: [REDACTED]		
Enquiry No.: 624586	Logged by: Contact Centre	on: 10/03/2015 12:00	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Drain cover rocking/noisy - [REDACTED]			
Location: Queens Road - approx 20 meters east of Woodend Hospital entrance	Contact: [REDACTED]		
Enquiry No.: 623424	Logged by: Contact Centre	on: 24/02/2015 10:47	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Road broken up around manhole - [REDACTED]			
Location: Queens Road - section between 210-222, eastbound	Contact: Contact Centre		
Enquiry No.: 619252	Logged by: Contact Centre	on: 13/01/2015 10:28	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Reference No: DRAINAGE14933. Site (Street/Park/etc): Queen's Road, Aberdeen. Location: The stanks on S. side between Rubislaw Park Road and Viewfield Rd. Locational Details: In front of house. First Type of Fault: Blocked Gully. Name [REDACTED] Telephone Number [REDACTED] Email Address: [REDACTED]			
Location: QUEENS ROAD - DRAINAGE14933 - [REDACTED]	Contact: [REDACTED]		
Enquiry No.: 617691	Logged by: Contact Centre	on: 17/12/2014 18:11	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: Oil spillage on Queen's Road, at the junction with roundabout at North Anderson Drive, approximately 100m down Queen's Road towards Hazlehead direction. Police Incident number 288, [REDACTED] Passed to standby.			
Location: Queen's Road	Contact: Police Scotland		

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Customer Services

Enquiry No.: 617565

Logged by: Contact Centre

on: 16/12/2014 23:26

Service: Roads

Subject: General Enquiry

Classification: Defect Report

Enquiry Ref:

Desc.: FAO : ACC Roads Response service,

Reference No : PATHS16573

Site (Street/Park/etc) : Cycle lane on queens road past crematorium and nature reserve to westhill

Location : Cycle lane on queens road past crematorium and nature reserve to westhill

Locational Details : In footpath or lane

First Type of Fault : Poor Surface

First Fault Details : Black ice not being gritted very dangerous

Second Type of Fault : Poor Surface

Second Fault Details : Non gritted black ice

Additional Information : These cycle paths are not being gritted for those cycling to and from westhill for work in the mornings and evening, numerous cyclists are falling and it can't be long before there's a serious injury! Ridiculously dangerous.

Name [REDACTED]

Telephone Number : [REDACTED]

Email Address : [REDACTED]

Fault Reporting System

Location: [REDACTED] Cycle lane on queens road past crematorium and nature reserve to westhill

Contact [REDACTED]

Enquiry No.: 616698

Logged by: Contact Centre

on: 08/12/2014 11:12

Service: Roads

Subject: General Enquiry

Classification: Defect Report

Enquiry Ref:

Desc.: ROADS LORRY HAD FEUL CAP OFF AND SPILLED FEUL ON THE ROAD. PHONED THROUGH TO ROADS DEPT.

Location: COMING OFF NORTH ANDERSON DRIVE ALL THE WAY ALONG QUEENS ROAD TO HAZLEHEAD

Contact: [REDACTED]

Enquiry No.: 616531

Logged by: Contact Centre

on: 05/12/2014 09:01

Service: Roads

Subject: General Enquiry

Classification: Defect Report

Enquiry Ref:

Desc.: BLOCKED GULLIES: Reference No: DRAINAGE14912. Site (Street/Park/etc): Queens road. Location: Rubislaw park road to springfield road. First Type of Fault: Blocked Gully. First Fault Details: all gullies except 1 blocked west bound between Rubislaw park road and springfield road. Name: [REDACTED] Email Address [REDACTED]

Location: QUEENS ROAD - DRAINAGE14912 - [REDACTED]

Contact: [REDACTED]

Plot Number: 1,000.00

Feature Id - Location: S/25/1928 - QUEENS ROAD (22)

Feature Type: RDS Road Section

Job Number: 189058

Effective: 11/05/2014 to 06/02/2017

Display Action Officer: No

Service: Roads

Site: QUEEN'S ROAD (7600044)

Customer Services

Enquiry No.: 614695	Logged by: Contact Centre	on: 15/11/2014 22:33	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: FAO : ACC Roads Response service,			
Reference No : ROADS25770			
Site (Street/Park/etc) : queens road			
Location : westbound approaching hazelhead roundabout			
First Type of Fault : Rocking/Noisy/Low Manhole Cover			
First Fault Details : 2 manholes have sunk			
Name : [REDACTED]			
Address Line 1 : [REDACTED]			
Telephone Number : [REDACTED]			
Email Address : [REDACTED]			
Location: Queen's Road	Contact: [REDACTED]		
Enquiry No.: 611311	Logged by: Contact Centre	on: 08/10/2014 17:02	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: overhanging hedges on same side of queen's road as queen's den -			
Location: QUEEN'S ROAD - between Queen's den and hospital driveway - [REDACTED]	Contact: [REDACTED]		
Enquiry No.: 609373	Logged by: Contact Centre	on: 15/09/2014 10:13	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: DRAINS - drain in front of the house, on the main road - is smelling very badly -			
Location: 140 QUEEN'S ROAD - [REDACTED]	Contact: [REDACTED]		
Plot Number: 1,000.00	Feature Id - Location: S/25/1928 - QUEENS ROAD (22)	Feature Type: RDS Road Section	
Job Number: 187158			
Enquiry No.: 608449	Logged by: Contact Centre	on: 01/09/2014 16:38	Enquiry Ref:
Service: Roads	Subject: General Enquiry	Classification: Defect Report	
Desc.: PAVEMENT IS REALLY UNEVEN AND SLABS ARE STICKING UP, SOME HAVE SUNK AND A PEDESTRIAN HAS FALLEN AND BANGED HER HEAD, AN AMBULANCE WAS CALLED AT 4:20 AND SHE WAS TAKEN TO HOSPITAL, SHE WAS WEARING SUN GLASSES AND DID NOT NOTICE THE SUNKEN HOLE IN PAVEMENT.			
Location: 30 QUEENS ROAD - [REDACTED]	Contact: [REDACTED]		
Plot Number: 1,000.00	Feature Id - Location: S/25/1928 - QUEENS ROAD (22)	Feature Type: RDS Road Section	
Job Number: 186911			
Enquiry No.: 604810	Logged by: Contact Centre	on: 23/07/2014 09:46	Enquiry Ref:
Service: Roads	Subject: Pot Hole - Road	Classification: Enquiry	
Desc.: ¿moray.saville has left comment: Poor road surface turning left from kings gate onto queens road immediately before the hazlehead roundabout, there cracks in the road 2 small potholes which hold water (where kerb of the street meets the road) FORWARDED FROM NEW SITE- STREET REPAIRS.CO.UK			
Location: 282 QUEENS ROAD	Contact: [REDACTED]		