

**From:** [Grant Webster](#) on behalf of [Foi Enquiries](#)  
**To:** [REDACTED]  
**Subject:** EIR-17-0241 - Inspection - Kingswells  
**Date:** 08 March 2017 15:52:24  
**Attachments:** [Further Information - Right to Review & Appeal.pdf](#)  
[EIR-17-0241 - Skene Road History 1.pdf](#)  
[EIR-17-0241 - Skene Road History 2.pdf](#)  
[EIR-17-0241 - Skene Road History 3.pdf](#)  
[EIR-17-0241 - Skene Road History 4.pdf](#)

---

Dear [REDACTED],

Thank you for your information request of 16 February 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

**1) Please provide me with inspection reports for Aberdeen Kingswells roundabout exit to Aberdeen (A944) on 26 December 2016 and for the six months prior to this date.**

Please see attached 'Skene Road History 1' (Please note that inspections are logged for the whole of the road with more exact location information given against each defect logged, therefore we cannot provide records relating to one specific location, but rather the whole road as this is how the system logs them.)

**2) Maintenance reports for road works undertaken on 26 December 2016 and for the six months prior to this date.**

Please see attached 'Skene Road History 2'

**3) Inspection reports for Aberdeen Kingswells roundabout exit to Aberdeen (A944) after the 26 December 2016 till today's date.**

Please see attached 'Skene Road History 3'

**4) Maintenance reports for road works undertaken in that area after the 26 December 2016 till today's date.**

Please see attached 'Skene Road History 4'

**5) Information on frequency of inspection for that area**

Skene Road/ A944 is subject to a monthly inspection frequency in accordance with guidelines set out by 'Well Maintained Highways 2005'. Further information on this can be found on pages 5 and 6 of the 'Road Safety Inspection Manual' linked below.

[http://www.aberdeencity.gov.uk/web/files/Roads/road\\_safety\\_inspection\\_manual.pdf](http://www.aberdeencity.gov.uk/web/files/Roads/road_safety_inspection_manual.pdf)

**6) Details of type of inspections undertaken including any written process the Aberdeen city council imposes for such inspection.**

Please see link below, pages 7 and 8 for types of inspections and the bottom of page 11 for written processes. Details of inspections are not written down, they are recorded electronically which feeds into our master system, from which we can draw reports of inspections, repairs and enquiries, such as the type of reports provided in this request.

[http://www.aberdeencity.gov.uk/web/files/Roads/road\\_safety\\_inspection\\_manual.pdf](http://www.aberdeencity.gov.uk/web/files/Roads/road_safety_inspection_manual.pdf)

**7) Any contact from occupants, citizens, drivers or users of the A944 road, to Aberdeen City**

**council to advise ACC of defects on the A944 over the last 6 months and the relevant responses or actions from the Aberdeen city council to rectify such defects?**

There are no formal complaints logged regarding the Kingswells Roundabout/A944 for the last 6 months.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Head of Service level have been redacted (blackened out) from the attached Site History Report. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with 11(3)(a)(i) – Personal Information - of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, and the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as ACC considers that disclosure of this information would be a breach of the first Data Protection Principle (that personal information must be processed fairly and lawfully). Third parties and ACC Officers who are below Head of Service level named within the attached document would not expect ACC to release this information about them into the public domain under the EIRs (or the Freedom of Information (Scotland) Act 2002 (FOISA)).

We hope this helps with your request.

Yours sincerely,

Grant Webster  
Information Compliance Officer

**INFORMATION ABOUT THE HANDLING OF YOUR REQUEST**

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team  
Communications and Promotion  
Office of Chief Executive  
Aberdeen City Council  
3rd Floor North

Business Hub 17  
Marischal College  
Broad Street  
ABERDEEN AB10 1AQ

[foienquiries@aberdeencity.gov.uk](mailto:foienquiries@aberdeencity.gov.uk)

01224 523827/523602

Tel 03000 200 292

\*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.

Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

[www.aberdeencity.gov.uk](http://www.aberdeencity.gov.uk)

Effective: 26/06/2016 to 26/12/2016  
Site: SKENE ROAD (7600505)

Display Action Officer: No

Site: SKENE ROAD (7600505)

Locality: ABERDEEN, ABERDEEN CITY

Area: Aberdeen South

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b> 1,001.00	<b>Asset - Locn.:</b> S/22/2108 - SKENE ROAD (22)			<b>Feature Type:</b> RDS Road Section			<b>Area:</b> Aberdeen South	
<b>Batch:</b> 522056 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 15/12/2016
461809	Repair approx 3 square metres of damaged carriageway surface.	15/12/2016	On Westbound carriageway opposite lampost number 18.	Pot Hole	Internal		Committed	710620
<b>Batch:</b> 521323 - Inspection Batch	No actionable defects found			<b>Route:</b> Week: 34 - Area: 22				<b>Date:</b> 06/12/2016
<b>Batch:</b> 520875 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 28/11/2016
461560	Repair pothole approx' 400 x 100 x 60.	28/11/2016	Adjacent to lampost number 8.	Pot Hole	Internal		Archived	710212
<b>Batch:</b> 519892 - Inspection Batch				<b>Route:</b> Week: 30 - Area: 22				<b>Date:</b> 14/11/2016
461373	Repair 4 areas of damaged carriageway surface, total area approx' 4 square metres.	14/11/2016	3 x at nearside edge of Westbound carriageway between AWPR access point and SIXMILE HOUSE and 1 x on Eastbound carriageway at entrance to vets hospital.	Pot Hole	Internal		Archived	709938
<b>Batch:</b> 517040 - Inspection Batch	No actionable defects found			<b>Route:</b> Week: 26 - Area: 22				<b>Date:</b> 11/10/2016
<b>Batch:</b> 515561 - Inspection Batch				<b>Route:</b> Week: 22 - Area: 22				<b>Date:</b> 26/09/2016
460714	Clean and jet 6 gullies.	26/09/2016	On Westbound carriageway between AWPR access and entrance to Sixmile House.	Blocked Gully	Internal		Committed	708779
<b>Batch:</b> 510769 - Inspection Batch	No actionable defects found			<b>Route:</b> Week: 18 - Area: 22				<b>Date:</b> 17/08/2016
<b>Batch:</b> 506040 - Inspection Batch	No actionable defects found			<b>Route:</b> Week: 14 - Area: 22				<b>Date:</b> 19/07/2016
<b>Asset:</b> 1,002.00	<b>Asset - Locn.:</b> 1 - Grass verge			<b>Feature Type:</b> RDS Verge			<b>Area:</b> Aberdeen South	
<b>Batch:</b> 521324 - Inspection Batch	No actionable defects found			<b>Route:</b> Week: 34 - Area: 22				<b>Date:</b> 06/12/2016
<b>Batch:</b> 519905 - Inspection Batch	No actionable defects found			<b>Route:</b> Week: 30 - Area: 22				<b>Date:</b> 14/11/2016
<b>Batch:</b> 517041 - Inspection Batch	No actionable defects found			<b>Route:</b> Week: 26 - Area: 22				<b>Date:</b> 11/10/2016
<b>Batch:</b> 515581 - Inspection Batch	No actionable defects found			<b>Route:</b> Week: 22 - Area: 22				<b>Date:</b> 26/09/2016
<b>Batch:</b> 510768 - Inspection Batch	No actionable defects found			<b>Route:</b> Week: 18 - Area: 22				<b>Date:</b> 17/08/2016
<b>Batch:</b> 506039 - Inspection Batch	No actionable defects found			<b>Route:</b> Week: 14 - Area: 22				<b>Date:</b> 19/07/2016

Effective: 26/06/2016 to 26/12/2016  
 Site: SKENE ROAD (7600505)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	1,012.00	<b>Asset - Locn.:</b>	1 - Footway	<b>Feature Type:</b>	RDS Footway		<b>Area:</b>	Aberdeen North
<b>Batch:</b>	521325 - Inspection Batch			<b>Route:</b>	Week: 34 - Area: 22			<b>Date:</b> 06/12/2016
	No actionable defects found							
<b>Batch:</b>	519906 - Inspection Batch			<b>Route:</b>	Week: 30 - Area: 22			<b>Date:</b> 14/11/2016
	No actionable defects found							
<b>Batch:</b>	517042 - Inspection Batch			<b>Route:</b>	Week: 26 - Area: 22			<b>Date:</b> 11/10/2016
	No actionable defects found							
<b>Batch:</b>	515582 - Inspection Batch			<b>Route:</b>	Week: 22 - Area: 22			<b>Date:</b> 26/09/2016
	No actionable defects found							
<b>Batch:</b>	510767 - Inspection Batch			<b>Route:</b>	Week: 18 - Area: 22			<b>Date:</b> 17/08/2016
	No actionable defects found							
<b>Batch:</b>	506038 - Inspection Batch			<b>Route:</b>	Week: 14 - Area: 22			<b>Date:</b> 19/07/2016
	No actionable defects found							
<b>Asset:</b>	1,014.00	<b>Asset - Locn.:</b>	1 - splitter island	<b>Feature Type:</b>	RDS Hard Landscaping		<b>Area:</b>	Aberdeen North
<b>Batch:</b>	521326 - Inspection Batch			<b>Route:</b>	Week: 34 - Area: 22			<b>Date:</b> 06/12/2016
	No actionable defects found							
<b>Batch:</b>	519907 - Inspection Batch			<b>Route:</b>	Week: 30 - Area: 22			<b>Date:</b> 14/11/2016
	No actionable defects found							
<b>Batch:</b>	517043 - Inspection Batch			<b>Route:</b>	Week: 26 - Area: 22			<b>Date:</b> 11/10/2016
	No actionable defects found							
<b>Batch:</b>	515583 - Inspection Batch			<b>Route:</b>	Week: 22 - Area: 22			<b>Date:</b> 26/09/2016
	No actionable defects found							
<b>Batch:</b>	510766 - Inspection Batch			<b>Route:</b>	Week: 18 - Area: 22			<b>Date:</b> 17/08/2016
	No actionable defects found							
<b>Batch:</b>	506037 - Inspection Batch			<b>Route:</b>	Week: 14 - Area: 22			<b>Date:</b> 19/07/2016
	No actionable defects found							

Effective: 26/06/2016 to 26/12/2016

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: SKENE ROAD (7600505)

Site: SKENE ROAD (7600505)

Locality: ABERDEEN, ABERDEEN CITY

Area: Aberdeen South

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Asset:</b>	1,000.00	<b>Asset - Locn.:</b> S/21/2106 - SKENE ROAD (21)		<b>Feature Type:</b> RDS Road Section		<b>Area:</b> Aberdeen North	
59492	1xpothole at gully (see photograph ) (Pot Hole)	across from junction with Brodiach	.RD 2 Day	Job Closed	26/03/2009		
<b>Asset:</b>	1,001.00	<b>Asset - Locn.:</b> S/22/2108 - SKENE ROAD (22)		<b>Feature Type:</b> RDS Road Section		<b>Area:</b> Aberdeen South	
706774	repair two potholes 300 x 300 x 50	On Eastbound c/way at l/post 28 and at pedestrian crossing jctn with Groats Road	.RD 2 Day	Job Closed	13/07/2016	13/07/2016	Act. RD01/23889
707263	repair depression(void) 600 x 600 x 60	ON CYCLE PATH e/bound c/way near l/p 148	.RD 2 Day	Job Closed	28/07/2016	28/07/2016	Act. RD01/24083
708779	Clean and jet 6 gullies. (Blocked Gully)	On Westbound carriageway between AWPR access and entrance to Sixmile House.	.RD 14 Day	Order Printed	26/09/2016	10/10/2016	Est. RD01/24615
709918	repair pothole 600 x 200 x 55	about 50m west of entrance to crem on w/b carriageway	.RD 2 Day	Job Closed	14/11/2016	14/11/2016	Act. RD01/25143
709938	Repair 4 areas of damaged carriageway surface, total area approx' 4 square metres. (Pot Hole)	3 x at nearside edge of Westbound carriageway between AWPR access point and SIXMILE HOUSE and 1 x on Eastbound carriageway at entrance to vets hospital.	.RD 7 Day	Job Closed	14/11/2016	14/11/2016	Act. RD01/25160
710212	Repair pothole approx' 400 x 100 x 60. (Pot Hole)	Adjacent to lamppost number 8.	.RD 7 Day	Job Closed	28/11/2016	28/11/2016	Act. RD01/25316
710620	Repair approx 3 square metres of damaged carriageway surface. (Pot Hole)	On Westbound carriageway opposite lamppost number 18.	.RD 7 Day	Contractor Completed	15/12/2016	16/12/2016	Act. RD01/25528
<b>Asset:</b>	1,004.00	<b>Asset - Locn.:</b> 1 - Queens Road - Greenhedges-carriageway		<b>Feature Type:</b> RDS Carriageway		<b>Area:</b> Aberdeen South	
192034	Clean and jet 12 blocked gullies. (Blocked Gully)	Both sides of carriageway between GROATS ROAD and MAIDENCRAIG ROUNDABOUT.	.RD 14 Day	Job Closed	08/04/2015	02/07/2016	Act.
<b>Asset:</b>	1,009.00	<b>Asset - Locn.:</b> 2 - N side, Green Hedges - A944-verge		<b>Feature Type:</b> RDS Verge		<b>Area:</b> Aberdeen North	
13405	Pot Hole (Pot Hole)	0	Standard	Job Closed	17/10/2007		
13406	Pot Hole (Pot Hole)	0	Standard	Job Closed	17/10/2007		
<b>Asset:</b>	1,012.00	<b>Asset - Locn.:</b> 1 - Footway		<b>Feature Type:</b> RDS Footway		<b>Area:</b> Aberdeen North	
13403	Pot Hole (Pot Hole)	0	Standard	Job Closed	17/10/2007		
705861	repaint giveway lines and stop lines on CYCLE PATH as per [REDACTED]	as attached plan	.RD 28 Day	Contractor Completed	13/06/2016	20/07/2016	Act. RD01/23560
<b>Asset:</b>	1,013.00	<b>Asset - Locn.:</b> 2 - N side, Green Hedges - A944-footway		<b>Feature Type:</b> RDS Footway		<b>Area:</b> Aberdeen North	
13402	General Condition (General Condition)	0	Standard	Job Closed	17/10/2007		
<b>Asset:</b>	1,014.00	<b>Asset - Locn.:</b> 1 - splitter island		<b>Feature Type:</b> RDS Hard Landscaping		<b>Area:</b> Aberdeen North	
57160	Sunken Carriageway (Sunken Carriageway)	0	Standard	Job Closed	12/01/2009		

Effective: 26/06/2016 to 26/12/2016

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: SKENE ROAD (7600505)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,014.00		Asset - Locn.: 1 - splitter island		Feature Type: RDS Hard Landscaping		Area: Aberdeen North	
57161	Pot Hole (Pot Hole)	0	Standard	Job Closed	12/01/2009		
57162	Sunken Carriageway (Sunken Carriageway)	0	Standard	Job Closed	12/01/2009		
57163	Sunken Carriageway (Sunken Carriageway)	0	Standard	Job Closed	12/01/2009		
57164	Speed Cushions (Speed Cushions)	0	Standard	Job Closed	12/01/2009		
57165	Speed Cushions (Speed Cushions)	0	Standard	Job Closed	12/01/2009		
57166	Speed Cushions (Speed Cushions)	0	Standard	Job Closed	12/01/2009		

Effective: 26/12/2016 to 16/02/2017  
Site: SKENE ROAD (7600505)

Display Action Officer: No

Site: SKENE ROAD (7600505)

Locality: ABERDEEN, ABERDEEN CITY

Area: Aberdeen South

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	1,001.00	<b>Asset - Locn.:</b>	S/22/2108 - SKENE ROAD (22)	<b>Feature Type:</b>	RDS Road Section		<b>Area:</b>	Aberdeen South
<b>Batch:</b>	525979 - Inspection Batch		<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	16/02/2017
462868	Pothole, sunken carraigeway, 600x1000x60 approx.	16/02/2017	Skene rd,Heading west appox 100yds before roundabout, as you pass six,ile cottage, at safety barriers sunken carraigeway	Pot Hole	Internal		Committed	712464
<b>Batch:</b>	525530 - Inspection Batch		<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	10/02/2017
462678	clean and jet gully.	10/02/2017	Across from lamppost 194. (Near Langstracht/Cults r/about).	Blocked Gully	Internal		Committed	712224
<b>Batch:</b>	525196 - Inspection Batch		<b>Route:</b>	Week: 42 - Area: 22			<b>Date:</b>	07/02/2017
462567	Repair pothole approx' 450 x 100 x 60.	07/02/2017	Around gully on Eastbound carriageway between Kingswells roundabout and first bus stop.	Pot Hole	Internal		Committed	712085
<b>Batch:</b>	524382 - Inspection Batch		<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	24/01/2017
462293	Repair pothole approx' 150 x 450 x 55.	24/01/2017	Around gully on Westbound carriageway opposite lamppost number 3.	Pot Hole	Internal		Committed	711532
<b>Batch:</b>	523801 - Inspection Batch		<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	16/01/2017
462164	Repair pothole approx' 450 x 450 x 60.	16/01/2017	At West end of JESSIEFIELD LOOP at junction with main carriageway.	Pot Hole	Internal		Committed	711286
<b>Batch:</b>	523607 - Inspection Batch		<b>Route:</b>	Week: 38 - Area: 22			<b>Date:</b>	12/01/2017
462126	Repair pothole approx' 450 x 450 x 50.	12/01/2017	On Eastbound carriageway approx' 50 metres East of Vet hospital.	Pot Hole	Internal		Committed	711217
<b>Batch:</b>	523077 - Inspection Batch		<b>Route:</b>	Adhoc Inspection			<b>Date:</b>	05/01/2017
462031	at gully 490x140x72, pothole (CONE IN PLACE).	05/01/2017	50yds from r/about across from lamppost No194. C89C/Cults r/about.	Pot Hole	Internal		Committed	710922
<b>Asset:</b>	1,002.00	<b>Asset - Locn.:</b>	1 - Grass verge	<b>Feature Type:</b>	RDS Verge		<b>Area:</b>	Aberdeen South
<b>Batch:</b>	525201 - Inspection Batch		<b>Route:</b>	Week: 42 - Area: 22			<b>Date:</b>	07/02/2017
	No actionable defects found							
<b>Batch:</b>	523609 - Inspection Batch		<b>Route:</b>	Week: 38 - Area: 22			<b>Date:</b>	12/01/2017
	No actionable defects found							
<b>Asset:</b>	1,012.00	<b>Asset - Locn.:</b>	1 - Footway	<b>Feature Type:</b>	RDS Footway		<b>Area:</b>	Aberdeen North
<b>Batch:</b>	525202 - Inspection Batch		<b>Route:</b>	Week: 42 - Area: 22			<b>Date:</b>	07/02/2017
	No actionable defects found							
<b>Batch:</b>	523608 - Inspection Batch		<b>Route:</b>	Week: 38 - Area: 22			<b>Date:</b>	12/01/2017
	No actionable defects found							
<b>Asset:</b>	1,014.00	<b>Asset - Locn.:</b>	1 - splitter island	<b>Feature Type:</b>	RDS Hard Landscaping		<b>Area:</b>	Aberdeen North
<b>Batch:</b>	525203 - Inspection Batch		<b>Route:</b>	Week: 42 - Area: 22			<b>Date:</b>	07/02/2017
	No actionable defects found							



Effective: 26/12/2016 to 16/02/2017

Display Action Officer: No

Site: SKENE ROAD (7600505)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,014.00	Asset - Locn.:	1 - splitter island	Feature Type:	RDS Hard Landscaping	Area:	Aberdeen North	
Batch:	523610 - Inspection Batch			Route:	Week: 38 - Area: 22			Date: 12/01/2017
	No actionable defects found							

Effective: 26/12/2016 to 16/02/2017  
Site: SKENE ROAD (7600505)

Display Action Officer: No

Site: SKENE ROAD (7600505)

Locality: ABERDEEN, ABERDEEN CITY

Area: Aberdeen South

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Asset:</b> 1,000.00		<b>Asset - Locn.:</b> S/21/2106 - SKENE ROAD (21)		<b>Feature Type:</b> RDS Road Section		<b>Area:</b> Aberdeen North	
59492	1xpothole at gully (see photograph ) (Pot Hole)	across from junction with Brodiach	.RD 2 Day	Job Closed	26/03/2009		
<b>Asset:</b> 1,001.00		<b>Asset - Locn.:</b> S/22/2108 - SKENE ROAD (22)		<b>Feature Type:</b> RDS Road Section		<b>Area:</b> Aberdeen South	
710922	at gully 490x140x72, pothole (CONE IN PLACE). (Pot Hole)	50yds from r/about across from lamppost No194. C89C/Cults r/about.	.RD 2 Day	Contractor Completed	05/01/2017	05/01/2017	Act. RD01/25603
711091	clean and jet 15 gullies	from crematorium to r/about	.Routine Maintenance	Contractor Completed	10/01/2017	25/12/2016	Act.
711217	Repair pothole approx' 450 x 450 x 50. (Pot Hole)	On Eastbound carriageway approx' 50 metres East of Vet hospital.	.RD 2 Day	Contractor Completed	12/01/2017	12/01/2017	Act. RD01/25694
711286	Repair pothole approx' 450 x 450 x 60. (Pot Hole)	At West end of JESSIEFIELD LOOP at junction with main carriageway.	.RD 7 Day	Contractor Completed	16/01/2017	16/01/2017	Act. RD01/25726
711532	Repair pothole approx' 150 x 450 x 55. (Pot Hole)	Around gulley on Westbound carriageway opposite lamppost number 3.	.RD 7 Day	Contractor Completed	24/01/2017	24/01/2017	Act. RD01/25835
711991	Find and Fix 5 potholes filled by [REDACTED]	from cattle pens to ice alert station	.Routine Maintenance	Contractor Completed	06/02/2017	02/02/2017	Act.
712042	Find and Fix 3 potholes filled by [REDACTED]	unknown	.Routine Maintenance	Contractor Completed	06/02/2017	04/02/2017	Act.
712048	Find and Fix 6 potholes filled by [REDACTED]	l/p 5, l/p 27, l/p 34	.Routine Maintenance	Contractor Completed	06/02/2017	05/02/2017	Act.
712085	Repair pothole approx' 450 x 100 x 60. (Pot Hole)	Around gulley on Eastbound carriageway between Kingswells roundabout and first bus stop.	.RD 2 Day	Contractor Completed	07/02/2017	07/02/2017	Act. RD01/26033
712105	Repair pothole 300 x 400 x 50	opp l/p 18 on westbound c/way	.RD 2 Day	Contractor Completed	07/02/2017	07/02/2017	Act. RD01/26035
712221	Find and Fix 7 potholes filled by [REDACTED] - 600 x 600 x 50, 200 x 200 x 50	six mile house area	.Routine Maintenance	Contractor Completed	10/02/2017	09/02/2017	Act.
712224	clean and jet gully. (Blocked Gully)	Across from lamppost 194. (Near Langstracht/Cults r/about).	.RD 14 Day	Contractor Completed	10/02/2017	14/02/2017	Act. RD01/26111
712464	Pothole, sunken carraigeway, 600x1000x60 approx. (Pot Hole)	Skene rd,Heading west appox 100yds before roundabout, as you pass six Mile cottage, at safety barriers sunken carraigeway	.RD Emergency	Order Printed	16/02/2017	17/02/2017	Est. RD01/26153
<b>Asset:</b> 1,009.00		<b>Asset - Locn.:</b> 2 - N side, Green Hedges - A944-verge		<b>Feature Type:</b> RDS Verge		<b>Area:</b> Aberdeen North	
13405	Pot Hole (Pot Hole)	0	Standard	Job Closed	17/10/2007		
13406	Pot Hole (Pot Hole)	0	Standard	Job Closed	17/10/2007		
<b>Asset:</b> 1,012.00		<b>Asset - Locn.:</b> 1 - Footway		<b>Feature Type:</b> RDS Footway		<b>Area:</b> Aberdeen North	
13403	Pot Hole (Pot Hole)	0	Standard	Job Closed	17/10/2007		
711407	lift sign to top of poles as per [REDACTED]	ON CYCLE PATH	.RD 28 Day	Order Printed	19/01/2017	16/02/2017	Est. RD01/25786

Effective: 26/12/2016 to 16/02/2017  
 Site: SKENE ROAD (7600505)

Display Action Officer: No

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Asset:</b> 1,013.00		<b>Asset - Locn.:</b> 2 - N side, Green Hedges - A944-footway		<b>Feature Type:</b> RDS Footway		<b>Area:</b> Aberdeen North	
13402	General Condition (General Condition)	0	Standard	Job Closed	17/10/2007		
<b>Asset:</b> 1,014.00		<b>Asset - Locn.:</b> 1 - splitter island		<b>Feature Type:</b> RDS Hard Landscaping		<b>Area:</b> Aberdeen North	
57160	Sunken Carriageway (Sunken Carriageway)	0	Standard	Job Closed	12/01/2009		
57161	Pot Hole (Pot Hole)	0	Standard	Job Closed	12/01/2009		
57162	Sunken Carriageway (Sunken Carriageway)	0	Standard	Job Closed	12/01/2009		
57163	Sunken Carriageway (Sunken Carriageway)	0	Standard	Job Closed	12/01/2009		
57164	Speed Cushions (Speed Cushions)	0	Standard	Job Closed	12/01/2009		
57165	Speed Cushions (Speed Cushions)	0	Standard	Job Closed	12/01/2009		
57166	Speed Cushions (Speed Cushions)	0	Standard	Job Closed	12/01/2009		
<b>Asset:</b> 10,007.00		<b>Asset - Locn.:</b> 8 - 7TH W OF GROATS RD		<b>Feature Type:</b> SL - Street Lamp		<b>Area:</b> Aberdeen South	
535384	Light Out - Streetlight #8 - Lamp Out Reported via Android in the Street lighting category by [REDACTED] at 03:10 today Sent to Aberdeen City Council 5 minutes later 1x Lamp out on streetlight number eight. Located on Skene Road. (Enquiry 688318)	SKENE ROAD - Streetlight #8	SL 07-Day	Order Printed	09/02/2017	16/02/2017 Est.	SL01/108225
<b>Asset:</b> 10,010.00		<b>Asset - Locn.:</b> 11 - 2ND E OF CREMATORIOUS RD		<b>Feature Type:</b> SL - Street Lamp		<b>Area:</b> Aberdeen South	
535172	Light Out - Street lamp id no.11 is out, also reports that the lights are going off at 6am. And that there is a disused light at the end of the lane next to the burn which he feels should be reinstated as it is hazardous for cyclists. (Enquiry 687283)	Path off Skene Road leading to the Crematorium	SL 07-Day	Order Printed	01/02/2017	08/02/2017 Est.	SL01/108018

Effective: 26/12/2016 to 16/02/2017  
 Site: SKENE ROAD (7600505)

Display Action Officer: No

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 10,013.00	<b>Asset - Locn.:</b> 14 - 1ST W OF CREAMATORIUM RD		<b>Feature Type:</b> SL - Street Lamp		<b>Area:</b> Aberdeen South	
535379	Light Out - 1x Lamp out on the Bend To The Left sign. Located on Skene Road. Near the junction for the crematorium. Located on streetlight number fourteen.  1x Lamp out on the 30 Zone sign. Located on Skene Road. Near Groats Road. (Enquiry 688228)	Skene Road - ST	SL 07-Day	Order Printed	09/02/2017	16/02/2017 Est.	SL01/108219
	<b>Asset:</b> 10,070.00	<b>Asset - Locn.:</b> 46 - 13TH WEST OF JESSIEFIELD ACCESS ROAD		<b>Feature Type:</b> SL - Street Lamp		<b>Area:</b> Aberdeen South	
534901	Light Out - Reference No : LIGHTS33552 Site (Street/Park/etc) : B9119 Skene Road Location : South side of road First Type of Fault : Lamp Out Additional Information : Column number 46 (Enquiry 686145)	B9119 Skene Road - ST	SL 07-Day	Order Printed	20/01/2017	27/01/2017 Est.	SL01/107745
	<b>Asset:</b> 100,005.00	<b>Asset - Locn.:</b> 9051312385 - DEN OF MAIDENCRAIG PARK, SKENE ROAD,		<b>Feature Type:</b> W - Commercial Waste Property		<b>Area:</b> Aberdeen South	
805476	Light Out - Road traffic signs 1x Lamp out on the 100 Yards - 30 Zone sign. Located on Skene Road. Location: Easting/Northing: 389164/806086 (57.145537, -2.180706) Nearest road to the pin placed on the map (automatically generated by Bing Maps): Skene Road, Aberdeen, AB15 8 Nearest postcode to the pin placed on the map (automatically generated): AB15 8BE (190m away) (Enquiry 688240)	Skene Road - (street light) just approaching Maiden Craig reserve - passed Denset Court - see email below:	SL 07-Day	Job Raised	09/02/2017	16/02/2017 Est.	
10096265	New Bin Request - O42218 Deliver: 2xrolls caddy liners, 1xkitchen caddy, 1xwhite recycling bag, 1xkerbside box and net, 1x240L brownb in (Enquiry 1040554)	ABERDEEN, AB14 0PS	Standard	Contractor Completed	04/01/2017	05/01/2017 Act.	WDRE/254442

---

**Effective:** 26/12/2016 to 16/02/2017  
**Site:** SKENE ROAD (7600505)

---

**Display Action Officer:** No