

From: [Grant Webster](#) on behalf of [Foi Enquiries](#)
To: [REDACTED]
Subject: EIR-17-0273 - Inspection - Little Belmont Street
Date: 08 March 2017 15:42:26
Attachments: [Further Information - Right to Review & Appeal.pdf](#)
[EIR-17-0273 - Inspection Reports.pdf](#)
[EIR-17-0273 - Maintenance Management Reports.pdf](#)
[EIR-17-0273 - Little Belmont.pdf](#)

Dear [REDACTED]

Thank you for your information request of 15 February 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

We would be grateful if you would provide us with the undernoted information relative to repair, maintenance and inspection of the pavement on Little Belmont Street, Aberdeen outside Poldiono's Restaurant & Pizzeria.

We cannot provide inspection or repair orders specifically for outside this location as the system does not record it this way, any reports given are for the whole road, with more specific locations given under each inspection/ repair order.

1) Please provide a copy of all inspection reports for this pavement between 28/10/2013 and the present.

Please see attached inspection records.

Please also confirm;

2) When was the last inspection prior to 28th October 2016?

25 October 2016.

3) What was noted?

No actionable defects found.

4) How was the inspection carried out?

By foot and by vehicle.

5) When was first inspection following 28th October 2016?

30 October 2016.

6) What was noted?

Loose and rocking slabs outside The Little Belmont Hut and outside the front of The Old School House.

7) How was the inspection carried out?

By foot and by vehicle.

8) Has the defect been repaired?

Yes.

9) When was the defect noted?

30 October 2016.

10) What category was the defect?

Category 2.

11) When was the repair instructed?

30 October 2016.

12) When was the defect repaired?

7 November 2016.

13) Please provide copies of all work records for the pavement between 28/10/2013 and the date of this correspondence.

Please see attached 'Maintenance Management Report'.

14) Please provide photocopies of any photographs which you may hold of the defect.

Please see photos attached of all defects noted 30/10/2016 on Little Belmont Street.

15) Please provide copies of any records of complaints made to the council by members of the general public regarding defects on this pavement between 28/10/2010 and the date of this correspondence.

There are no complaints logged regarding the pavement on Little Belmont Street or from Poldino's Pizzeria

It may be best to provide clarification on what is logged as a "complaint", as the FOI appears to refer to service requests:

A complaint is an expression of dissatisfaction regarding our actions, or lack of action, or the standard of service provided by us or on our behalf. There are some topics that cannot be considered as a "complaint", such as first time service requests, which include reporting potholes.

For more information, please visit

http://www.aberdeencity.gov.uk/council_government/feedback_complaints/crc_whatisacomplaint.asp

16) We specifically call upon you to provide us with any complaints that have been made by Poldinos Pizzeria.

There are no complaints logged regarding the pavement on Little Belmont Street or from Poldino's Pizzeria

We hope this helps with your request.

Yours sincerely,

Information Compliance Officer

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team
Communications and Promotion
Office of Chief Executive
Aberdeen City Council
3rd Floor North
Business Hub 17
Marischal College
Broad Street
ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk

01224 523827/523602

Tel 03000 200 292

*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.
Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Site: LITTLE BELMONT STREET (7601007)	Locality: ABERDEEN, ABERDEEN CITY	Area: Aberdeen Central
---------------------------------------	-----------------------------------	------------------------

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	N/13/1484 - LITTLE BELMONT STREET	Feature Type:	RDS Road Section		Area: Aberdeen Central	
Batch:	525592 - Inspection Batch			Route:	Week: 41 - Area: 18			Date: 12/02/2017
	No actionable defects found							
Batch:	524451 - Inspection Batch			Route:	Week: 39 - Area: 18			Date: 25/01/2017
	No actionable defects found							
Batch:	523892 - Inspection Batch			Route:	Week: 37 - Area: 18			Date: 17/01/2017
	No actionable defects found							
Batch:	522362 - Inspection Batch			Route:	Week: 35 - Area: 18			Date: 20/12/2016
	No actionable defects found							
Batch:	522266 - Inspection Batch			Route:	Week: 33 - Area: 18			Date: 16/12/2016
	No actionable defects found							
Batch:	520856 - Inspection Batch			Route:	Week: 31 - Area: 18			Date: 25/11/2016
	No actionable defects found							
Batch:	519659 - Inspection Batch			Route:	Week: 29 - Area: 18			Date: 11/11/2016
	No actionable defects found							
Batch:	518379 - Inspection Batch			Route:	Week: 27 - Area: 18			Date: 30/10/2016
	No actionable defects found							
Batch:	517973 - Inspection Batch			Route:	Week: 25 - Area: 18			Date: 25/10/2016
	No actionable defects found							
Batch:	515623 - Inspection Batch			Route:	Week: 23 - Area: 18			Date: 26/09/2016
	No actionable defects found							
Batch:	514857 - Inspection Batch			Route:	Week: 21 - Area: 18			Date: 16/09/2016
	No actionable defects found							
Batch:	513032 - Inspection Batch			Route:	Week: 19 - Area: 18			Date: 02/09/2016
	No actionable defects found							
Batch:	512308 - Inspection Batch			Route:	Week: 17 - Area: 18			Date: 30/08/2016
	No actionable defects found							
Batch:	508584 - Inspection Batch			Route:	Week: 15 - Area: 18			Date: 04/08/2016
	No actionable defects found							
Batch:	506496 - Inspection Batch			Route:	Week: 13 - Area: 18			Date: 22/07/2016
	No actionable defects found							
Batch:	505287 - Inspection Batch			Route:	Week: 11 - Area: 18			Date: 06/07/2016
	No actionable defects found							
Batch:	505261 - Inspection Batch			Route:	Week: 09 - Area: 18			Date: 06/07/2016
	No actionable defects found							

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: N/13/1484 - LITTLE BELMONT STREET		Feature Type: RDS Road Section		Area: Aberdeen Central		
Batch: 503643	- Inspection Batch			Route: Week: 07	- Area: 18			Date: 13/06/2016
	No actionable defects found							
Batch: 502098	- Inspection Batch			Route: Week: 05	- Area: 18			Date: 31/05/2016
	No actionable defects found							
Batch: 500331	- Inspection Batch			Route: Week: 03	- Area: 18			Date: 13/05/2016
	No actionable defects found							
Batch: 499047	- Inspection Batch			Route: Week: 01	- Area: 18			Date: 28/04/2016
	No actionable defects found							
Batch: 497860	- Inspection Batch			Route: Week: 47	- Area: 18			Date: 15/04/2016
	No actionable defects found							
Batch: 497102	- Inspection Batch			Route: Week: 45	- Area: 18			Date: 04/04/2016
	No actionable defects found							
Batch: 495634	- Inspection Batch			Route: Week: 43	- Area: 18			Date: 16/03/2016
	No actionable defects found							
Batch: 495379	- Inspection Batch			Route: Week: 41	- Area: 18			Date: 11/03/2016
	No actionable defects found							
Batch: 493797	- Inspection Batch			Route: Week: 39	- Area: 18			Date: 19/02/2016
	No actionable defects found							
Batch: 492522	- Inspection Batch			Route: Week: 37	- Area: 18			Date: 05/02/2016
	No actionable defects found							
Batch: 491552	- Inspection Batch			Route: Week: 35	- Area: 18			Date: 22/01/2016
	No actionable defects found							
Batch: 490801	- Inspection Batch			Route: Week: 33	- Area: 18			Date: 13/01/2016
	No actionable defects found							
Batch: 489489	- Inspection Batch			Route: Week: 31	- Area: 18			Date: 22/12/2015
	No actionable defects found							
Batch: 488452	- Inspection Batch			Route: Week: 29	- Area: 18			Date: 10/12/2015
	No actionable defects found							
Batch: 487416	- Inspection Batch			Route: Week: 27	- Area: 18			Date: 27/11/2015
	No actionable defects found							
Batch: 486304	- Inspection Batch			Route: Week: 25	- Area: 18			Date: 13/11/2015
	No actionable defects found							
Batch: 485034	- Inspection Batch			Route: Week: 23	- Area: 18			Date: 30/10/2015
	No actionable defects found							
Batch: 485013	- Inspection Batch			Route: Week: 21	- Area: 18			Date: 30/10/2015
	No actionable defects found							

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: N/13/1484 - LITTLE BELMONT STREET		Feature Type: RDS Road Section		Area: Aberdeen Central		
Batch: 483592	- Inspection Batch No actionable defects found			Route: Week: 19 - Area: 18				Date: 02/10/2015
Batch: 482917	- Inspection Batch No actionable defects found			Route: Week: 17 - Area: 18				Date: 17/09/2015
Batch: 482108	- Inspection Batch No actionable defects found			Route: Week: 15 - Area: 18				Date: 04/09/2015
Batch: 480891	- Inspection Batch No actionable defects found			Route: Week: 13 - Area: 18				Date: 21/08/2015
Batch: 480314	- Inspection Batch No actionable defects found			Route: Week: 11 - Area: 18				Date: 19/08/2015
Batch: 476640	- Inspection Batch No actionable defects found			Route: Week: 09 - Area: 18				Date: 24/07/2015
Batch: 474085	- Inspection Batch No actionable defects found			Route: Week: 07 - Area: 18				Date: 13/07/2015
Batch: 472541	- Inspection Batch No actionable defects found			Route: Week: 05 - Area: 18				Date: 25/06/2015
Batch: 471446	- Inspection Batch No actionable defects found			Route: Week: 03 - Area: 18				Date: 12/06/2015
Batch: 470286	- Inspection Batch No actionable defects found			Route: Week: 01 - Area: 18				Date: 29/05/2015
Batch: 469301	- Inspection Batch No actionable defects found			Route: Week: 47 - Area: 18				Date: 15/05/2015
Batch: 468134	- Inspection Batch No actionable defects found			Route: Week: 45 - Area: 18				Date: 30/04/2015
Batch: 467041	- Inspection Batch No actionable defects found			Route: Week: 43 - Area: 18				Date: 16/04/2015
Batch: 465704	- Inspection Batch No actionable defects found			Route: Week: 41 - Area: 18				Date: 02/04/2015
Batch: 464310	- Inspection Batch No actionable defects found			Route: Week: 39 - Area: 18				Date: 23/03/2015
Batch: 461407	- Inspection Batch No actionable defects found			Route: Week: 37 - Area: 18				Date: 05/03/2015
Batch: 459869	- Inspection Batch No actionable defects found			Route: Week: 35 - Area: 18				Date: 20/02/2015
Batch: 456939	- Inspection Batch No actionable defects found			Route: Week: 33 - Area: 18				Date: 06/02/2015

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: N/13/1484 - LITTLE BELMONT STREET			Feature Type: RDS Road Section		Area: Aberdeen Central	
Batch: 454341 - Inspection Batch	No actionable defects found			Route: Week: 31 - Area: 18		Date: 23/01/2015		
Batch: 452923 - Inspection Batch	No actionable defects found			Route: Week: 29 - Area: 18		Date: 16/01/2015		
Batch: 450929 - Inspection Batch	No actionable defects found			Route: Week: 27 - Area: 18		Date: 07/01/2015		
Batch: 450802 - Inspection Batch	No actionable defects found			Route: Week: 25 - Area: 18		Date: 11/12/2014		
Batch: 450729 - Inspection Batch	No actionable defects found			Route: Week: 23 - Area: 18		Date: 27/11/2014		
Batch: 450642 - Inspection Batch	No actionable defects found			Route: Week: 21 - Area: 18		Date: 13/11/2014		
Batch: 450567 - Inspection Batch	No actionable defects found			Route: Week: 19 - Area: 18		Date: 03/11/2014		
Batch: 450520 - Inspection Batch	No actionable defects found			Route: Week: 17 - Area: 18		Date: 26/10/2014		
Batch: 450373 - Inspection Batch	No actionable defects found			Route: Week: 15 - Area: 18		Date: 02/10/2014		
Batch: 450152 - Inspection Batch	No actionable defects found			Route: Week: 13 - Area: 18		Date: 19/09/2014		
Batch: 450077 - Inspection Batch	No actionable defects found			Route: Week: 11 - Area: 18		Date: 04/09/2014		
Batch: 450039 - Inspection Batch	No actionable defects found			Route: Week: 09 - Area: 18		Date: 31/08/2014		
Batch: 39913 - Inspection Batch	No actionable defects found			Route: Week: 07 - Area: 18		Date: 08/08/2014		
Batch: 39813 - Inspection Batch	No actionable defects found			Route: Week: 05 - Area: 18		Date: 25/07/2014		
Batch: 39711 - Inspection Batch	No actionable defects found			Route: Week: 03 - Area: 18		Date: 10/07/2014		
Batch: 39593 - Inspection Batch	No actionable defects found			Route: Week: 01 - Area: 18		Date: 26/06/2014		
Batch: 39479 - Inspection Batch	No actionable defects found			Route: Week: 47 - Area: 18		Date: 12/06/2014		
Batch: 39360 - Inspection Batch	No actionable defects found			Route: Week: 45 - Area: 18		Date: 29/05/2014		

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: N/13/1484 - LITTLE BELMONT STREET		Feature Type: RDS Road Section		Area: Aberdeen Central		
Batch: 39264	- Inspection Batch			Route: Week: 43 - Area: 18				Date: 15/05/2014
	No actionable defects found							
Batch: 39216	- Inspection Batch			Route: Week: 41 - Area: 18				Date: 11/05/2014
	No actionable defects found							
Batch: 39215	- Inspection Batch			Route: Week: 43 - Area: 18				Date: 11/05/2014
	No actionable defects found							
Batch: 39029	- Inspection Batch			Route: Week: 39 - Area: 18				Date: 16/04/2014
	No actionable defects found							
Batch: 38906	- Inspection Batch			Route: Week: 37 - Area: 18				Date: 03/04/2014
	No actionable defects found							
Batch: 38822	- Inspection Batch			Route: Week: 35 - Area: 18				Date: 20/03/2014
	No actionable defects found							
Batch: 38669	- Inspection Batch			Route: Week: 33 - Area: 18				Date: 06/03/2014
	No actionable defects found							
Batch: 38553	- Inspection Batch			Route: Week: 31 - Area: 18				Date: 19/02/2014
	No actionable defects found							
Batch: 38425	- Inspection Batch			Route: Week: 29 - Area: 18				Date: 06/02/2014
	No actionable defects found							
Batch: 38313	- Inspection Batch			Route: Week: 27 - Area: 18				Date: 23/01/2014
	No actionable defects found							
Batch: 38185	- Inspection Batch			Route: Week: 25 - Area: 18				Date: 10/01/2014
	No actionable defects found							
Batch: 38184	- Inspection Batch			Route: Week: 23 - Area: 18				Date: 10/01/2014
	No actionable defects found							
Batch: 38041	- Inspection Batch			Route: Week: 21 - Area: 18				Date: 12/12/2013
	No actionable defects found							
Batch: 37948	- Inspection Batch			Route: Week: 19 - Area: 18				Date: 29/11/2013
	No actionable defects found							
Batch: 37823	- Inspection Batch			Route: Week: 17 - Area: 18				Date: 13/11/2013
	No actionable defects found							
Batch: 37704	- Inspection Batch			Route: Week: 15 - Area: 18				Date: 31/10/2013
	No actionable defects found							
Batch: 37703	- Inspection Batch			Route: Week: 13 - Area: 18				Date: 31/10/2013
	No actionable defects found							

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,001.00	Asset - Locn.: 1 - Footway			Feature Type: RDS Footway			Area: Aberdeen Central	
Batch: 525569 - Inspection Batch				Route: Week: 41 - Area: 18				Date: 12/02/2017
462695	Lift and relay loose and rocking Caithness slabs	10/02/2017	From side door of Ma Cameron's ro Belmont street along the front of the old school house and little Belmont hut at various locations (find and fix)	Rocking Slab	Internal		Committed	712245
Batch: 524452 - Inspection Batch	No actionable defects found			Route: Week: 39 - Area: 18				Date: 25/01/2017
Batch: 523893 - Inspection Batch	No actionable defects found			Route: Week: 37 - Area: 18				Date: 17/01/2017
Batch: 522363 - Inspection Batch	No actionable defects found			Route: Week: 35 - Area: 18				Date: 20/12/2016
Batch: 522267 - Inspection Batch	No actionable defects found			Route: Week: 33 - Area: 18				Date: 16/12/2016
Batch: 520685 - Inspection Batch				Route: Week: 31 - Area: 18				Date: 25/11/2016
461533	Lift and relay 3 x loose raised and rocking Caithness slabs	23/11/2016	Outside the old school house See photo	Rocking Slab	Internal		Archived	710166
Batch: 519660 - Inspection Batch	No actionable defects found			Route: Week: 29 - Area: 18				Date: 11/11/2016
Batch: 518378 - Inspection Batch				Route: Week: 27 - Area: 18				Date: 30/10/2016
461115	Lift and relay loose and rocking Caithness slabs	30/10/2016	Outside the little Belmont hut	Rocking Slab	Internal		Archived	709607
461116	Lift and relay loose and rocking Caithness slabs (Delivery Lorry damage)	30/10/2016	Along the front of the old school house bar See photos	Rocking Slab	Internal		Archived	709608
Batch: 517975 - Inspection Batch	No actionable defects found			Route: Week: 25 - Area: 18				Date: 25/10/2016
Batch: 515624 - Inspection Batch	No actionable defects found			Route: Week: 23 - Area: 18				Date: 26/09/2016
Batch: 514858 - Inspection Batch	No actionable defects found			Route: Week: 21 - Area: 18				Date: 16/09/2016
Batch: 513033 - Inspection Batch	No actionable defects found			Route: Week: 19 - Area: 18				Date: 02/09/2016
Batch: 512309 - Inspection Batch	No actionable defects found			Route: Week: 17 - Area: 18				Date: 30/08/2016
Batch: 512263 - Inspection Batch				Route: Adhoc Inspection				Date: 30/08/2016
460413	Lift and relay loose and rocking Caithness slab	30/08/2016	7 little belmont street	Rocking Slab	Internal		Archived	708164
Batch: 508585 - Inspection Batch	No actionable defects found			Route: Week: 15 - Area: 18				Date: 04/08/2016

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,001.00	Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen Central		
Batch: 506497	- Inspection Batch			Route: Week: 13	- Area: 18			Date: 22/07/2016
	No actionable defects found							
Batch: 505288	- Inspection Batch			Route: Week: 11	- Area: 18			Date: 06/07/2016
	No actionable defects found							
Batch: 505262	- Inspection Batch			Route: Week: 09	- Area: 18			Date: 06/07/2016
	No actionable defects found							
Batch: 503644	- Inspection Batch			Route: Week: 07	- Area: 18			Date: 13/06/2016
	No actionable defects found							
Batch: 502099	- Inspection Batch			Route: Week: 05	- Area: 18			Date: 31/05/2016
	No actionable defects found							
Batch: 500332	- Inspection Batch			Route: Week: 03	- Area: 18			Date: 13/05/2016
	No actionable defects found							
Batch: 499048	- Inspection Batch			Route: Week: 01	- Area: 18			Date: 28/04/2016
	No actionable defects found							
Batch: 497707	- Inspection Batch			Route: Week: 47	- Area: 18			Date: 15/04/2016
457363	Remove and replace broken and loose Caithness slab	13/04/2016	Outside the academy bar See photo	Broken Slab	Internal		Archived	703601
Batch: 497103	- Inspection Batch			Route: Week: 45	- Area: 18			Date: 04/04/2016
	No actionable defects found							
Batch: 495635	- Inspection Batch			Route: Week: 43	- Area: 18			Date: 16/03/2016
	No actionable defects found							
Batch: 495380	- Inspection Batch			Route: Week: 41	- Area: 18			Date: 11/03/2016
	No actionable defects found							
Batch: 493798	- Inspection Batch			Route: Week: 39	- Area: 18			Date: 19/02/2016
	No actionable defects found							
Batch: 492509	- Inspection Batch			Route: Week: 37	- Area: 18			Date: 05/02/2016
455312	Lift and relay loose and rocking slabs	05/02/2016	1 slab outside macbeans coffee/tea shop 2 outside ma Cameron's pub 2 outside the old schoolhouse pub 2 at corner of Belmont street	Rocking Slab	Internal		Archived	701100
Batch: 491553	- Inspection Batch			Route: Week: 35	- Area: 18			Date: 22/01/2016
	No actionable defects found							
Batch: 490802	- Inspection Batch			Route: Week: 33	- Area: 18			Date: 13/01/2016
	No actionable defects found							
Batch: 489490	- Inspection Batch			Route: Week: 31	- Area: 18			Date: 22/12/2015
	No actionable defects found							
Batch: 488538	- Inspection Batch			Route: Week: 29	- Area: 18			Date: 10/12/2015
	No actionable defects found							

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,001.00	Asset - Locn.: 1 - Footway			Feature Type: RDS Footway			Area: Aberdeen Central	
Batch: 487417 - Inspection Batch				Route: Week: 27 - Area: 18				Date: 27/11/2015
No actionable defects found								
Batch: 486305 - Inspection Batch				Route: Week: 25 - Area: 18				Date: 13/11/2015
No actionable defects found								
Batch: 485035 - Inspection Batch				Route: Week: 23 - Area: 18				Date: 30/10/2015
No actionable defects found								
Batch: 485001 - Inspection Batch				Route: Week: 21 - Area: 18				Date: 30/10/2015
452798 lift and relay 2 x loose and rocking Caithness slabs	30/10/2015	Outside the little Belmont hut See photo	Rocking Slab	Internal		Archived		197914
452799 lift and relay 1 x loose and rocking Caithness slab	30/10/2015	Outside the old schoolhouse pub See photo	Rocking Slab	Internal		Archived		197915
Batch: 483593 - Inspection Batch				Route: Week: 19 - Area: 18				Date: 02/10/2015
No actionable defects found								
Batch: 482918 - Inspection Batch				Route: Week: 17 - Area: 18				Date: 17/09/2015
No actionable defects found								
Batch: 482081 - Inspection Batch				Route: Week: 15 - Area: 18				Date: 04/09/2015
452028 lift and relay sunken Caithness slab	04/09/2015	Outside the old school house	Rocking Slab	Internal		Archived		196588
Batch: 480892 - Inspection Batch				Route: Week: 13 - Area: 18				Date: 21/08/2015
No actionable defects found								
Batch: 480315 - Inspection Batch				Route: Week: 11 - Area: 18				Date: 19/08/2015
No actionable defects found								
Batch: 476641 - Inspection Batch				Route: Week: 09 - Area: 18				Date: 24/07/2015
No actionable defects found								
Batch: 474086 - Inspection Batch				Route: Week: 07 - Area: 18				Date: 13/07/2015
No actionable defects found								
Batch: 472540 - Inspection Batch				Route: Week: 05 - Area: 18				Date: 25/06/2015
No actionable defects found								
Batch: 471447 - Inspection Batch				Route: Week: 03 - Area: 18				Date: 12/06/2015
No actionable defects found								
Batch: 470287 - Inspection Batch				Route: Week: 01 - Area: 18				Date: 29/05/2015
No actionable defects found								
Batch: 469302 - Inspection Batch				Route: Week: 47 - Area: 18				Date: 15/05/2015
No actionable defects found								
Batch: 468131 - Inspection Batch				Route: Week: 45 - Area: 18				Date: 30/04/2015
99668 lift and relay 2 x loose and rocking Caithness slabs	30/04/2015	Outside ma Cameron's pub	Rocking Slab	Internal		Archived		192849

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,001.00	Asset - Locn.:	1 - Footway	Feature Type:	RDS Footway	Area:	Aberdeen Central	
Batch:	468131 - Inspection Batch			Route:	Week: 45 - Area: 18			Date: 30/04/2015
99670	lift and relay all loose and rocking Caithness slabs in this area (find & fix)	30/04/2015	Outside the academy pub from the lane at ma Cameron's to the little Belmont hut See photos	Rocking Slab	Internal		Archived	192851
99671	remove broken Caithness slab and relay new slab	30/04/2015	Outside ma Cameron's pub	Broken Slab	Internal		Archived	192852
Batch:	467030 - Inspection Batch			Route:	Week: 43 - Area: 18			Date: 16/04/2015
99394	lift and relay 3 x loose and rocking Caithness slabs	16/04/2015	Between the old school house and the little Belmont hut	Rocking Slab	Internal		Archived	192323
Batch:	465705 - Inspection Batch No actionable defects found			Route:	Week: 41 - Area: 18			Date: 02/04/2015
Batch:	464311 - Inspection Batch No actionable defects found			Route:	Week: 39 - Area: 18			Date: 23/03/2015
Batch:	461408 - Inspection Batch No actionable defects found			Route:	Week: 37 - Area: 18			Date: 05/03/2015
Batch:	459870 - Inspection Batch No actionable defects found			Route:	Week: 35 - Area: 18			Date: 20/02/2015
Batch:	456941 - Inspection Batch No actionable defects found			Route:	Week: 33 - Area: 18			Date: 06/02/2015
Batch:	454342 - Inspection Batch No actionable defects found			Route:	Week: 31 - Area: 18			Date: 23/01/2015
Batch:	452924 - Inspection Batch No actionable defects found			Route:	Week: 29 - Area: 18			Date: 16/01/2015
Batch:	450930 - Inspection Batch No actionable defects found			Route:	Week: 27 - Area: 18			Date: 07/01/2015
Batch:	450802 - Inspection Batch No actionable defects found			Route:	Week: 25 - Area: 18			Date: 11/12/2014
Batch:	450729 - Inspection Batch No actionable defects found			Route:	Week: 23 - Area: 18			Date: 27/11/2014
Batch:	450642 - Inspection Batch No actionable defects found			Route:	Week: 21 - Area: 18			Date: 13/11/2014
Batch:	450567 - Inspection Batch No actionable defects found			Route:	Week: 19 - Area: 18			Date: 03/11/2014
Batch:	450520 - Inspection Batch No actionable defects found			Route:	Week: 17 - Area: 18			Date: 26/10/2014
Batch:	450373 - Inspection Batch No actionable defects found			Route:	Week: 15 - Area: 18			Date: 02/10/2014

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,001.00	Asset - Locn.:	1 - Footway	Feature Type:	RDS Footway		Area:	Aberdeen Central
Batch:	450152 - Inspection Batch			Route:	Week: 13 - Area: 18			Date: 19/09/2014
	No actionable defects found							
Batch:	450077 - Inspection Batch			Route:	Week: 11 - Area: 18			Date: 04/09/2014
	No actionable defects found							
Batch:	450039 - Inspection Batch			Route:	Week: 09 - Area: 18			Date: 31/08/2014
	No actionable defects found							
Batch:	39913 - Inspection Batch			Route:	Week: 07 - Area: 18			Date: 08/08/2014
	No actionable defects found							
Batch:	39813 - Inspection Batch			Route:	Week: 05 - Area: 18			Date: 25/07/2014
	No actionable defects found							
Batch:	39711 - Inspection Batch			Route:	Week: 03 - Area: 18			Date: 10/07/2014
	No actionable defects found							
Batch:	39593 - Inspection Batch			Route:	Week: 01 - Area: 18			Date: 26/06/2014
	No actionable defects found							
Batch:	39479 - Inspection Batch			Route:	Week: 47 - Area: 18			Date: 12/06/2014
	No actionable defects found							
Batch:	39360 - Inspection Batch			Route:	Week: 45 - Area: 18			Date: 29/05/2014
	No actionable defects found							
Batch:	39264 - Inspection Batch			Route:	Week: 43 - Area: 18			Date: 15/05/2014
	No actionable defects found							
Batch:	39216 - Inspection Batch			Route:	Week: 41 - Area: 18			Date: 11/05/2014
	No actionable defects found							
Batch:	39215 - Inspection Batch			Route:	Week: 43 - Area: 18			Date: 11/05/2014
	No actionable defects found							
Batch:	39029 - Inspection Batch			Route:	Week: 39 - Area: 18			Date: 16/04/2014
	No actionable defects found							
Batch:	38906 - Inspection Batch			Route:	Week: 37 - Area: 18			Date: 03/04/2014
	No actionable defects found							
Batch:	38822 - Inspection Batch			Route:	Week: 35 - Area: 18			Date: 20/03/2014
	No actionable defects found							
Batch:	38669 - Inspection Batch			Route:	Week: 33 - Area: 18			Date: 06/03/2014
	No actionable defects found							
Batch:	38553 - Inspection Batch			Route:	Week: 31 - Area: 18			Date: 19/02/2014
	No actionable defects found							
Batch:	38425 - Inspection Batch			Route:	Week: 29 - Area: 18			Date: 06/02/2014
	No actionable defects found							

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,001.00	Asset - Locn.:	1 - Footway	Feature Type:	RDS Footway		Area:	Aberdeen Central
Batch:	38313 - Inspection Batch			Route:	Week: 27 - Area: 18			Date: 23/01/2014
	No actionable defects found							
Batch:	38185 - Inspection Batch			Route:	Week: 25 - Area: 18			Date: 10/01/2014
	No actionable defects found							
Batch:	38184 - Inspection Batch			Route:	Week: 23 - Area: 18			Date: 10/01/2014
	No actionable defects found							
Batch:	38041 - Inspection Batch			Route:	Week: 21 - Area: 18			Date: 12/12/2013
	No actionable defects found							
Batch:	37948 - Inspection Batch			Route:	Week: 19 - Area: 18			Date: 29/11/2013
	No actionable defects found							
Batch:	37823 - Inspection Batch			Route:	Week: 17 - Area: 18			Date: 13/11/2013
	No actionable defects found							
Batch:	37704 - Inspection Batch			Route:	Week: 15 - Area: 18			Date: 31/10/2013
	No actionable defects found							
Batch:	37703 - Inspection Batch			Route:	Week: 13 - Area: 18			Date: 31/10/2013
	No actionable defects found							
Asset:	1,002.00	Asset - Locn.:	4 - Old Town School to Belmont Street-Footway	Feature Type:	RDS Footway		Area:	Aberdeen Central
Batch:	452925 - Inspection Batch			Route:	Week: 29 - Area: 18			Date: 16/01/2015
	No actionable defects found							
Batch:	450931 - Inspection Batch			Route:	Week: 27 - Area: 18			Date: 07/01/2015
	No actionable defects found							
Batch:	450802 - Inspection Batch			Route:	Week: 25 - Area: 18			Date: 11/12/2014
	No actionable defects found							
Batch:	450729 - Inspection Batch			Route:	Week: 23 - Area: 18			Date: 27/11/2014
	No actionable defects found							
Batch:	450642 - Inspection Batch			Route:	Week: 21 - Area: 18			Date: 13/11/2014
	No actionable defects found							
Batch:	450567 - Inspection Batch			Route:	Week: 19 - Area: 18			Date: 03/11/2014
	No actionable defects found							
Batch:	450520 - Inspection Batch			Route:	Week: 17 - Area: 18			Date: 26/10/2014
	No actionable defects found							
Batch:	450373 - Inspection Batch			Route:	Week: 15 - Area: 18			Date: 02/10/2014
	No actionable defects found							
Batch:	450152 - Inspection Batch			Route:	Week: 13 - Area: 18			Date: 19/09/2014
	No actionable defects found							
Batch:	450077 - Inspection Batch			Route:	Week: 11 - Area: 18			Date: 04/09/2014
	No actionable defects found							

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,002.00	Asset - Locn.: 4 - Old Town School to Belmont Street-Footway			Feature Type: RDS Footway			Area: Aberdeen Central	
Batch: 450039 - Inspection Batch	No actionable defects found			Route: Week: 09 - Area: 18				Date: 31/08/2014
Batch: 39913 - Inspection Batch	No actionable defects found			Route: Week: 07 - Area: 18				Date: 08/08/2014
Batch: 39813 - Inspection Batch	No actionable defects found			Route: Week: 05 - Area: 18				Date: 25/07/2014
Batch: 39711 - Inspection Batch	No actionable defects found			Route: Week: 03 - Area: 18				Date: 10/07/2014
Batch: 39593 - Inspection Batch	No actionable defects found			Route: Week: 01 - Area: 18				Date: 26/06/2014
Batch: 39479 - Inspection Batch	No actionable defects found			Route: Week: 47 - Area: 18				Date: 12/06/2014
Batch: 39360 - Inspection Batch				Route: Week: 45 - Area: 18				Date: 29/05/2014
95444 lift and relay loose rocking and raised 600 x 600 caithness slab	29/05/2014	between little belmont hut and the old school house	Rocking Slab	Internal		Archived		184301
Batch: 39264 - Inspection Batch	No actionable defects found			Route: Week: 43 - Area: 18				Date: 15/05/2014
Batch: 39216 - Inspection Batch	No actionable defects found			Route: Week: 41 - Area: 18				Date: 11/05/2014
Batch: 39215 - Inspection Batch	No actionable defects found			Route: Week: 43 - Area: 18				Date: 11/05/2014
Batch: 39029 - Inspection Batch	No actionable defects found			Route: Week: 39 - Area: 18				Date: 16/04/2014
Batch: 38906 - Inspection Batch	No actionable defects found			Route: Week: 37 - Area: 18				Date: 03/04/2014
Batch: 38822 - Inspection Batch	No actionable defects found			Route: Week: 35 - Area: 18				Date: 20/03/2014
Batch: 38669 - Inspection Batch	No actionable defects found			Route: Week: 33 - Area: 18				Date: 06/03/2014
Batch: 38553 - Inspection Batch	No actionable defects found			Route: Week: 31 - Area: 18				Date: 19/02/2014
Batch: 38425 - Inspection Batch	No actionable defects found			Route: Week: 29 - Area: 18				Date: 06/02/2014
Batch: 38313 - Inspection Batch	No actionable defects found			Route: Week: 27 - Area: 18				Date: 23/01/2014
Batch: 38185 - Inspection Batch	No actionable defects found			Route: Week: 25 - Area: 18				Date: 10/01/2014

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,002.00	Asset - Locn.: 4 - Old Town School to Belmont Street-Footway		Feature Type: RDS Footway		Area: Aberdeen Central		
Batch: 38184 - Inspection Batch	No actionable defects found		Route: Week: 23 - Area: 18		Date: 10/01/2014			
Batch: 38041 - Inspection Batch	No actionable defects found		Route: Week: 21 - Area: 18		Date: 12/12/2013			
Batch: 37948 - Inspection Batch			Route: Week: 19 - Area: 18		Date: 29/11/2013			
93775 lift and relay loose and rocking caithness slab	29/11/2013	outside the old. school house pub at second pillar up from entrance	Rocking Slab	Internal	Archived	179209		
93776 lift and reset raised and loose granite caithness kerb (vehicle overriding see photo)	29/11/2013	between ma camerons and old school house	Broken Kerb	Internal	Archived	179201		
Batch: 37823 - Inspection Batch	No actionable defects found		Route: Week: 17 - Area: 18		Date: 13/11/2013			
Batch: 37704 - Inspection Batch	No actionable defects found		Route: Week: 15 - Area: 18		Date: 31/10/2013			
Batch: 37703 - Inspection Batch	No actionable defects found		Route: Week: 13 - Area: 18		Date: 31/10/2013			
Asset:	1,003.00	Asset - Locn.: 1 - Back Wynd to Belmont Street-Carriageway		Feature Type: RDS Carriageway		Area: Aberdeen Central		
Batch: 452926 - Inspection Batch	No actionable defects found		Route: Week: 29 - Area: 18		Date: 16/01/2015			
Batch: 450932 - Inspection Batch	No actionable defects found		Route: Week: 27 - Area: 18		Date: 07/01/2015			
Batch: 450802 - Inspection Batch	No actionable defects found		Route: Week: 25 - Area: 18		Date: 11/12/2014			
Batch: 450729 - Inspection Batch	No actionable defects found		Route: Week: 23 - Area: 18		Date: 27/11/2014			
Batch: 450642 - Inspection Batch	No actionable defects found		Route: Week: 21 - Area: 18		Date: 13/11/2014			
Batch: 450567 - Inspection Batch	No actionable defects found		Route: Week: 19 - Area: 18		Date: 03/11/2014			
Batch: 450520 - Inspection Batch	No actionable defects found		Route: Week: 17 - Area: 18		Date: 26/10/2014			
Batch: 450373 - Inspection Batch	No actionable defects found		Route: Week: 15 - Area: 18		Date: 02/10/2014			
Batch: 450152 - Inspection Batch	No actionable defects found		Route: Week: 13 - Area: 18		Date: 19/09/2014			
Batch: 450077 - Inspection Batch	No actionable defects found		Route: Week: 11 - Area: 18		Date: 04/09/2014			

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,003.00	Asset - Locn.: 1 - Back Wynd to Belmont Street-Carriageway		Feature Type: RDS Carriageway		Area: Aberdeen Central		
Batch: 450039	- Inspection Batch			Route: Week: 09	- Area: 18			Date: 31/08/2014
	No actionable defects found							
Batch: 39913	- Inspection Batch			Route: Week: 07	- Area: 18			Date: 08/08/2014
	No actionable defects found							
Batch: 39813	- Inspection Batch			Route: Week: 05	- Area: 18			Date: 25/07/2014
	No actionable defects found							
Batch: 39711	- Inspection Batch			Route: Week: 03	- Area: 18			Date: 10/07/2014
	No actionable defects found							
Batch: 39593	- Inspection Batch			Route: Week: 01	- Area: 18			Date: 26/06/2014
	No actionable defects found							
Batch: 39479	- Inspection Batch			Route: Week: 47	- Area: 18			Date: 12/06/2014
	No actionable defects found							
Batch: 39360	- Inspection Batch			Route: Week: 45	- Area: 18			Date: 29/05/2014
	No actionable defects found							
Batch: 39264	- Inspection Batch			Route: Week: 43	- Area: 18			Date: 15/05/2014
	No actionable defects found							
Batch: 39216	- Inspection Batch			Route: Week: 41	- Area: 18			Date: 11/05/2014
	No actionable defects found							
Batch: 39215	- Inspection Batch			Route: Week: 43	- Area: 18			Date: 11/05/2014
	No actionable defects found							
Batch: 39029	- Inspection Batch			Route: Week: 39	- Area: 18			Date: 16/04/2014
	No actionable defects found							
Batch: 38906	- Inspection Batch			Route: Week: 37	- Area: 18			Date: 03/04/2014
	No actionable defects found							
Batch: 38822	- Inspection Batch			Route: Week: 35	- Area: 18			Date: 20/03/2014
	No actionable defects found							
Batch: 38669	- Inspection Batch			Route: Week: 33	- Area: 18			Date: 06/03/2014
	No actionable defects found							
Batch: 38553	- Inspection Batch			Route: Week: 31	- Area: 18			Date: 19/02/2014
	No actionable defects found							
Batch: 38425	- Inspection Batch			Route: Week: 29	- Area: 18			Date: 06/02/2014
	No actionable defects found							
Batch: 38313	- Inspection Batch			Route: Week: 27	- Area: 18			Date: 23/01/2014
	No actionable defects found							
Batch: 38185	- Inspection Batch			Route: Week: 25	- Area: 18			Date: 10/01/2014
	No actionable defects found							

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,003.00	Asset - Locn.: 1 - Back Wynd to Belmont Street-Carriageway		Feature Type: RDS Carriageway		Area: Aberdeen Central			
Batch: 38184 - Inspection Batch	No actionable defects found		Route: Week: 23 - Area: 18		Date: 10/01/2014			
Batch: 38041 - Inspection Batch	No actionable defects found		Route: Week: 21 - Area: 18		Date: 12/12/2013			
Batch: 37948 - Inspection Batch	No actionable defects found		Route: Week: 19 - Area: 18		Date: 29/11/2013			
Batch: 37823 - Inspection Batch	No actionable defects found		Route: Week: 17 - Area: 18		Date: 13/11/2013			
Batch: 37704 - Inspection Batch	No actionable defects found		Route: Week: 15 - Area: 18		Date: 31/10/2013			
Batch: 37703 - Inspection Batch	No actionable defects found		Route: Week: 13 - Area: 18		Date: 31/10/2013			
Batch: 37662 - Inspection Batch			Route: Adhoc Inspection		Date: 28/10/2013			
93474	Gully blocked	28/10/2013	Little Belmont Street, directly outside number 2, MacBeans	Blocked Gully	Internal		Archived	178451
Asset: 1,004.00	Asset - Locn.: 3 - No 2 to No 6-10-Footway		Feature Type: RDS Footway		Area: Aberdeen Central			
Batch: 452927 - Inspection Batch	No actionable defects found		Route: Week: 29 - Area: 18		Date: 16/01/2015			
Batch: 450933 - Inspection Batch	No actionable defects found		Route: Week: 27 - Area: 18		Date: 07/01/2015			
Batch: 450802 - Inspection Batch	No actionable defects found		Route: Week: 25 - Area: 18		Date: 11/12/2014			
Batch: 450729 - Inspection Batch	No actionable defects found		Route: Week: 23 - Area: 18		Date: 27/11/2014			
Batch: 450642 - Inspection Batch	No actionable defects found		Route: Week: 21 - Area: 18		Date: 13/11/2014			
Batch: 450567 - Inspection Batch	No actionable defects found		Route: Week: 19 - Area: 18		Date: 03/11/2014			
Batch: 450520 - Inspection Batch	No actionable defects found		Route: Week: 17 - Area: 18		Date: 26/10/2014			
Batch: 450373 - Inspection Batch	No actionable defects found		Route: Week: 15 - Area: 18		Date: 02/10/2014			
Batch: 450152 - Inspection Batch	No actionable defects found		Route: Week: 13 - Area: 18		Date: 19/09/2014			
Batch: 450077 - Inspection Batch	No actionable defects found		Route: Week: 11 - Area: 18		Date: 04/09/2014			

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,004.00	Asset - Locn.:	3 - No 2 to No 6-10-Footway	Feature Type:	RDS Footway		Area:	Aberdeen Central
Batch:	450039 - Inspection Batch			Route:	Week: 09 - Area: 18			Date: 31/08/2014
	No actionable defects found							
Batch:	39913 - Inspection Batch			Route:	Week: 07 - Area: 18			Date: 08/08/2014
	No actionable defects found							
Batch:	39813 - Inspection Batch			Route:	Week: 05 - Area: 18			Date: 25/07/2014
	No actionable defects found							
Batch:	39711 - Inspection Batch			Route:	Week: 03 - Area: 18			Date: 10/07/2014
	No actionable defects found							
Batch:	39593 - Inspection Batch			Route:	Week: 01 - Area: 18			Date: 26/06/2014
	No actionable defects found							
Batch:	39479 - Inspection Batch			Route:	Week: 47 - Area: 18			Date: 12/06/2014
	No actionable defects found							
Batch:	39368 - Inspection Batch			Route:	Adhoc Inspection			Date: 30/05/2014
95483	lift and relay loose and rocking caithness slab	30/05/2014	outside entrance to the old school house	Rocking Slab	Internal		Archived	184350
Batch:	39360 - Inspection Batch			Route:	Week: 45 - Area: 18			Date: 29/05/2014
	No actionable defects found							
Batch:	39264 - Inspection Batch			Route:	Week: 43 - Area: 18			Date: 15/05/2014
	No actionable defects found							
Batch:	39216 - Inspection Batch			Route:	Week: 41 - Area: 18			Date: 11/05/2014
	No actionable defects found							
Batch:	39215 - Inspection Batch			Route:	Week: 43 - Area: 18			Date: 11/05/2014
	No actionable defects found							
Batch:	39029 - Inspection Batch			Route:	Week: 39 - Area: 18			Date: 16/04/2014
	No actionable defects found							
Batch:	38906 - Inspection Batch			Route:	Week: 37 - Area: 18			Date: 03/04/2014
	No actionable defects found							
Batch:	38822 - Inspection Batch			Route:	Week: 35 - Area: 18			Date: 20/03/2014
	No actionable defects found							
Batch:	38669 - Inspection Batch			Route:	Week: 33 - Area: 18			Date: 06/03/2014
	No actionable defects found							
Batch:	38553 - Inspection Batch			Route:	Week: 31 - Area: 18			Date: 19/02/2014
	No actionable defects found							
Batch:	38425 - Inspection Batch			Route:	Week: 29 - Area: 18			Date: 06/02/2014
	No actionable defects found							
Batch:	38313 - Inspection Batch			Route:	Week: 27 - Area: 18			Date: 23/01/2014
	No actionable defects found							

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,004.00	Asset - Locn.:	3 - No 2 to No 6-10-Footway	Feature Type:	RDS Footway		Area:	Aberdeen Central
Batch:	38185 - Inspection Batch			Route:	Week: 25 - Area: 18			Date: 10/01/2014
	No actionable defects found							
Batch:	38184 - Inspection Batch			Route:	Week: 23 - Area: 18			Date: 10/01/2014
	No actionable defects found							
Batch:	38041 - Inspection Batch			Route:	Week: 21 - Area: 18			Date: 12/12/2013
	No actionable defects found							
Batch:	37948 - Inspection Batch			Route:	Week: 19 - Area: 18			Date: 29/11/2013
	No actionable defects found							
Batch:	37823 - Inspection Batch			Route:	Week: 17 - Area: 18			Date: 13/11/2013
	No actionable defects found							
Batch:	37704 - Inspection Batch			Route:	Week: 15 - Area: 18			Date: 31/10/2013
	No actionable defects found							
Batch:	37703 - Inspection Batch			Route:	Week: 13 - Area: 18			Date: 31/10/2013
	No actionable defects found							
Asset:	1,005.00	Asset - Locn.:	2 - Back Wynd to Belmont Street-Footway	Feature Type:	RDS Footway		Area:	Aberdeen Central
Batch:	452928 - Inspection Batch			Route:	Week: 29 - Area: 18			Date: 16/01/2015
	No actionable defects found							
Batch:	450934 - Inspection Batch			Route:	Week: 27 - Area: 18			Date: 07/01/2015
	No actionable defects found							
Batch:	450802 - Inspection Batch			Route:	Week: 25 - Area: 18			Date: 11/12/2014
	No actionable defects found							
Batch:	450729 - Inspection Batch			Route:	Week: 23 - Area: 18			Date: 27/11/2014
	No actionable defects found							
Batch:	450642 - Inspection Batch			Route:	Week: 21 - Area: 18			Date: 13/11/2014
	No actionable defects found							
Batch:	450567 - Inspection Batch			Route:	Week: 19 - Area: 18			Date: 03/11/2014
	No actionable defects found							
Batch:	450520 - Inspection Batch			Route:	Week: 17 - Area: 18			Date: 26/10/2014
	No actionable defects found							
Batch:	450373 - Inspection Batch			Route:	Week: 15 - Area: 18			Date: 02/10/2014
	No actionable defects found							
Batch:	450152 - Inspection Batch			Route:	Week: 13 - Area: 18			Date: 19/09/2014
	No actionable defects found							
Batch:	450077 - Inspection Batch			Route:	Week: 11 - Area: 18			Date: 04/09/2014
	No actionable defects found							
Batch:	450039 - Inspection Batch			Route:	Week: 09 - Area: 18			Date: 31/08/2014
	No actionable defects found							

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,005.00	Asset - Locn.:	2 - Back Wynd to Belmont Street-Footway	Feature Type:	RDS Footway		Area:	Aberdeen Central
Batch:	39913 - Inspection Batch			Route:	Week: 07 - Area: 18			Date: 08/08/2014
	No actionable defects found							
Batch:	39813 - Inspection Batch			Route:	Week: 05 - Area: 18			Date: 25/07/2014
	No actionable defects found							
Batch:	39711 - Inspection Batch			Route:	Week: 03 - Area: 18			Date: 10/07/2014
	No actionable defects found							
Batch:	39593 - Inspection Batch			Route:	Week: 01 - Area: 18			Date: 26/06/2014
	No actionable defects found							
Batch:	39479 - Inspection Batch			Route:	Week: 47 - Area: 18			Date: 12/06/2014
	No actionable defects found							
Batch:	39360 - Inspection Batch			Route:	Week: 45 - Area: 18			Date: 29/05/2014
	No actionable defects found							
Batch:	39264 - Inspection Batch			Route:	Week: 43 - Area: 18			Date: 15/05/2014
	No actionable defects found							
Batch:	39216 - Inspection Batch			Route:	Week: 41 - Area: 18			Date: 11/05/2014
	No actionable defects found							
Batch:	39215 - Inspection Batch			Route:	Week: 43 - Area: 18			Date: 11/05/2014
	No actionable defects found							
Batch:	39029 - Inspection Batch			Route:	Week: 39 - Area: 18			Date: 16/04/2014
	No actionable defects found							
Batch:	38906 - Inspection Batch			Route:	Week: 37 - Area: 18			Date: 03/04/2014
	No actionable defects found							
Batch:	38822 - Inspection Batch			Route:	Week: 35 - Area: 18			Date: 20/03/2014
	No actionable defects found							
Batch:	38669 - Inspection Batch			Route:	Week: 33 - Area: 18			Date: 06/03/2014
	No actionable defects found							
Batch:	38553 - Inspection Batch			Route:	Week: 31 - Area: 18			Date: 19/02/2014
	No actionable defects found							
Batch:	38425 - Inspection Batch			Route:	Week: 29 - Area: 18			Date: 06/02/2014
	No actionable defects found							
Batch:	38313 - Inspection Batch			Route:	Week: 27 - Area: 18			Date: 23/01/2014
	No actionable defects found							
Batch:	38185 - Inspection Batch			Route:	Week: 25 - Area: 18			Date: 10/01/2014
	No actionable defects found							
Batch:	38184 - Inspection Batch			Route:	Week: 23 - Area: 18			Date: 10/01/2014
	No actionable defects found							

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,005.00	Asset - Locn.:	2 - Back Wynd to Belmont Street-Footway	Feature Type:	RDS Footway		Area:	Aberdeen Central
Batch:	38041 - Inspection Batch			Route:	Week: 21 - Area: 18			Date: 12/12/2013
	No actionable defects found							
Batch:	37948 - Inspection Batch			Route:	Week: 19 - Area: 18			Date: 29/11/2013
	No actionable defects found							
Batch:	37823 - Inspection Batch			Route:	Week: 17 - Area: 18			Date: 13/11/2013
	No actionable defects found							
Batch:	37704 - Inspection Batch			Route:	Week: 15 - Area: 18			Date: 31/10/2013
	No actionable defects found							
Batch:	37703 - Inspection Batch			Route:	Week: 13 - Area: 18			Date: 31/10/2013
	No actionable defects found							
Asset:	2,001.00	Asset - Locn.:	7601007/J/00004 - Little Belmont Street 4	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	507788 - Inspection Batch			Route:	Adhoc Inspection			Date: 29/07/2016
	No actionable defects found							
Asset:	2,002.00	Asset - Locn.:	7601007/J/00003 - Little Belmont Street 3	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	507789 - Inspection Batch			Route:	Adhoc Inspection			Date: 29/07/2016
	No actionable defects found							
Asset:	2,003.00	Asset - Locn.:	7601007/J/00002 - Little Belmont Street 2	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	507790 - Inspection Batch			Route:	Adhoc Inspection			Date: 29/07/2016
	No actionable defects found							
Asset:	2,004.00	Asset - Locn.:	7601007/J/00001 - Little Belmont Street 1	Feature Type:	RDS Gully		Area:	Aberdeen Central
Batch:	507791 - Inspection Batch			Route:	Adhoc Inspection			Date: 29/07/2016
	No actionable defects found							

Effective: 28/10/2013 to 16/02/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: LITTLE BELMONT STREET (7601007)

Site: LITTLE BELMONT STREET (7601007)

Locality: ABERDEEN, ABERDEEN CITY

Area: Aberdeen Central

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		Asset - Locn.: N/13/1484 - LITTLE BELMONT STREET		Feature Type: RDS Road Section		Area: Aberdeen Central	
178146	clean and jet gully	o/s 2 macbeans coffee	.RD 7 Day	Job Closed	04/10/2013	28/10/2013	Act. RD01/6808
704182	lift and relay riased and loose caithness dimple slabs	on crossing point at junction with belmont street	.RD 7 Day	Job Closed	27/04/2016	02/05/2016	Act. RD01/23029
Asset: 1,001.00		Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen Central	
192323	lift and relay 3 x loose and rocking Caithness slabs (Rocking Slab)	Between the old school house and the little Belmont hut	.RD 7 Day	Job Closed	16/04/2015	16/04/2015	Act. RD01/9816
192849	lift and relay 2 x loose and rocking Caithness slabs (Rocking Slab)	Outside ma Cameron's pub	.RD 7 Day	Job Closed	30/04/2015	03/05/2015	Act. RD01/9929
192851	lift and relay all loose and rocking Caithness slabs in this area (find & fix) (Rocking Slab)	Outside the academy pub from the lane at ma Cameron's to the little Belmont hut See photos	.RD 7 Day	Job Closed	30/04/2015	03/05/2015	Act. RD01/9929
192852	remove broken Caithness slab and relay new slab (Broken Slab)	Outside ma Cameron's pub	.RD 7 Day	Job Closed	30/04/2015	20/05/2015	Act. RD01/9929
196588	lift and relay sunken Caithness slab (Rocking Slab)	Outside the old school house	.RD 7 Day	Job Closed	04/09/2015	05/09/2015	Act. RD01/20770
197914	lift and relay 2 x loose and rocking Caithness slabs (Rocking Slab)	Outside the little Belmont hut See photo	.RD 7 Day	Job Closed	30/10/2015	01/11/2015	Act. RD01/21252
197915	lift and relay 1 x loose and rocking Caithness slab (Rocking Slab)	Outside the old schoolhouse pub See photo	.RD 7 Day	Job Closed	30/10/2015	01/11/2015	Act. RD01/21252
701100	Lift and relay loose and rocking Caithness slabs (Rocking Slab)	1 slab outside macbeans coffee/tea shop 2 outside ma Cameron's pub 2 outside the old schoolhouse put 2 at corner of Belmont street	.RD 7 Day	Job Closed	05/02/2016	22/02/2016	Act. RD01/22103
703601	Remove and replace broken and loose Caithness slab (Broken Slab)	Outside the academy bar See photo	.RD 7 Day	Job Closed	13/04/2016	20/04/2016	Act. RD01/22800
708164	Lift and relay loose and rocking Caithness slab (Rocking Slab)	7 little belmont street	.RD 7 Day	Job Closed	30/08/2016	31/08/2016	Act. RD01/24353
709607	Lift and relay loose and rocking Caithness slabs (Rocking Slab)	Outside the little Belmont hut	.RD 7 Day	Job Closed	30/10/2016	07/11/2016	Act. RD01/25006
709608	Lift and relay loose and rocking Caithness slabs (Delivery Lorry damage) (Rocking Slab)	Along the front of the old school house bar See photos	.RD 7 Day	Job Closed	30/10/2016	07/11/2016	Act. RD01/25006
710166	Lift and relay 3 x loose raised and rocking Caithness slabs (Rocking Slab)	Outside the old school house See photo	.RD 7 Day	Job Closed	23/11/2016	28/11/2016	Act. RD01/25288

Effective: 28/10/2013 to 16/02/2017

Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)

Site: LITTLE BELMONT STREET (7601007)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,001.00		Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen Central	
712245	Lift and relay loose and rocking Caithness slabs (Rocking Slab)	From side door of Ma Cameron's ro Belmont street along the front of the old school house and little Belmont hut at various locations (find and fix)	.RD 7 Day	Contractor Completed	10/02/2017	13/02/2017	Act. RD01/26113
Asset: 1,002.00		Asset - Locn.: 4 - Old Town School to Belmont Street-Footway		Feature Type: RDS Footway		Area: Aberdeen Central	
179201	lift and reset raised and loose granite caithness kerb (vehicle overriding see photo) (Broken Kerb)	between ma camérons and old school house	.RD 7 Day	Job Closed	02/12/2013	09/12/2013	Act. RD01/7076
179209	lift and relay loose and rocking caithness slab (Rocking Slab)	outside the old. school house pub at second pillar up from entrance	.RD 7 Day	Job Closed	02/12/2013	09/12/2013	Act. RD01/7076
184301	lift and relay loose rocking and raised 600 x 600 caithness slab (Rocking Slab)	between little belmont hut and the old school house	.RD 7 Day	Job Closed	29/05/2014	29/05/2014	Act. RD01/8051
Asset: 1,003.00		Asset - Locn.: 1 - Back Wynd to Belmont Street-Carriageway		Feature Type: RDS Carriageway		Area: Aberdeen Central	
178451	Gully blocked (Blocked Gully)	Little Belmont Street, directly outside number 2, MacBeans	.RD 7 Day	Job Closed	29/10/2013	28/10/2013	Act.
Asset: 1,004.00		Asset - Locn.: 3 - No 2 to No 6-10-Footway		Feature Type: RDS Footway		Area: Aberdeen Central	
184350	lift and relay loose and rocking caithness slab (Rocking Slab)	outside entrance to the old school house	.RD 7 Day	Job Closed	30/05/2014	11/02/2016	Act. RD01/8063



little Belmont street



little Belmont street



little Belmont street



little Belmont street



little Belmont street