

From: [Foi Enquiries](#)
To: [REDACTED]
Subject: EIR-17-0419 - Inspection - Station Road
Date: 29 March 2017 11:48:41
Attachments: [Further Information - Right to Review & Appeal.pdf](#)
[EIR-17-0419 - Station Road Site History.pdf](#)

Dear [REDACTED],

Thank you for your information request of 14 March 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

In reference to EIR-17-0299:

Accident: 13/01/17

We refer to the above and our previous request regarding the pavement on Station Road, Aberdeen. We would be grateful if you would now provide us with the undernoted information relative to the repair, maintenance and inspection of the road on the East side of Station Road, Bucksburn, Aberdeen between the junction with Mugiemooss Road and the junction with Old Meldrum Road, Aberdeen.

Is this road adopted by the council in terms of the Roads (Scotland) Act 1984?

This carriageway is adopted by Aberdeen City Council Roads Department.

What inspection interval the council has identified as being appropriate for this road? What factors were used in assessing the inspection interval?

It is subject to a 6 monthly inspection frequency.

Please provide a copy of all inspection reports for this road between 13 January 2015 and the present (10 March 2017)

Please see inspection reports attached.

When was the last inspection prior to 13 January 2017?

1 November 2016

- **What was noted?**

3 potholes of various sizes outside number 9 and 2 potholes of various sizes along kerbside across from staging post under jobs 709701 and 709702.

- **How was the inspection carried out?**

By foot and by vehicle.

When was the first inspection following 13 January 2017?

As this road is on a 6 monthly inspection frequency, there has not yet been another inspection carried out since 1 November 2016.

- **What was noted?**

- **How was the inspection carried out?**

Not applicable.

Has the defect been repaired?

- **When was the defect noted?**
- **What category was the defect (either category 1 or category 2 as set out at 9.4.11 of the Code of Practice)?**
- **When was the repair instructed?**
- **When was the defect repaired?**

Not applicable, please see above.

Please provide copies of all work records for the road between 13 January 2015 and 10 March 2017?

Please see attached maintenance management report.

Please provide photocopies of any photographs which you may hold of the defect?

We do not hold any photographs of any defects on this road between 16/05/2016 and 15/03/2017.

Please provide copies of any records of complaints made to the council regarding defects on the road between 13 February 2015 and 10 March 2017?

Please see attached Customer services report, we have no official complaints regarding this road in the requested timescale.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Head of Service level have been redacted from the attached report. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with 11(3)(a)(i) of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, and the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as ACC considers that disclosure of this information would be a breach of the first Data Protection Principle (that personal information must be processed fairly and lawfully). Third parties and ACC Officers who are below Head of Service level named within the attached documents would not expect ACC to release this information about them into the public domain under the EIRs (or the Freedom of Information (Scotland) Act 2002 (FOISA)).

We hope this helps with your request.

Yours sincerely,

Information Compliance Team

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team
Communications and Promotion
Office of Chief Executive
Aberdeen City Council
3rd Floor North
Business Hub 17
Marischal College
Broad Street
ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk

01224 523827/523602

Tel 03000 200 292

*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.

Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

Effective: 13/01/2015 to 15/03/2017
Site: STATION ROAD (7600022)

Display Action Officer: No

Site: STATION ROAD (7600022)

Locality: BUCKSBURN, ABERDEEN, ABERDEEN CITY

Area: Aberdeen North

Condition Survey

| Defect No: Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|--|---------------------------------------|--|--------------------------------|----------|--------------|----------------------|------------------|
| Asset: 1,000 00 | Asset - Locn.: N02/2213 - | STATION ROAD (BUCKSBURN) | Feature Type: RDS Road Section | | | Area: Aberdeen North | |
| Batch: 518829 - Inspection Batch | | | Route: Week: 28 - Area: 01 | | | | Date: 01/11/2016 |
| No actionable defects found | | | | | | | |
| Batch: 500481 - Inspection Batch | | | Route: Week: 04 - Area: 01 | | | | Date: 16/05/2016 |
| 458394 3x520x430x52, 2x460x400x50, + 6xpotholes of various sizes. | 16/05/2016 | From No5 to bridge. | Pot Hole | Internal | | Archived | 704894 |
| 458393 3xpotholes of various sizes. | 16/05/2016 | Outside Staging Post. | Pot Hole | Internal | | Archived | 704895 |
| Batch: 496511 - Inspection Batch | | | Route: Adhoc Inspection | | | | Date: 14/03/2016 |
| 456533 540x320x52, 500x300x52, + 6xpotholes of various sizes. | 14/03/2016 | From No5 round to lampost No8 | Pot Hole | Internal | | Archived | 702510 |
| Batch: 493601 - Inspection Batch | | | Route: Adhoc Inspection | | | | Date: 18/02/2016 |
| 455808 refresh 2xFADED GIVEWAY LINES. | 18/02/2016 | At Muglemoss Road and Oldmeldrum Road. | Road Marking | Internal | | Archived | 701637 |
| Batch: 487242 - Inspection Batch | | | Route: Week: 28 - Area: 01 | | | | Date: 25/11/2015 |
| No actionable defects found | | | | | | | |
| Batch: 471683 - Inspection Batch | | | Route: Week: 04 - Area: 01 | | | | Date: 16/06/2015 |
| No actionable defects found | | | | | | | |
| Batch: 470308 - Inspection Batch | | | Route: Adhoc Inspection | | | | Date: 01/06/2015 |
| 450360 510x340x50, pothole. | 01/06/2015 | Between lamposts 3 & 4. | Pot Hole | Internal | | Archived | 193922 |
| Batch: 470307 - Inspection Batch | | | Route: Adhoc Inspection | | | | Date: 01/06/2015 |
| 450359 At front of house & side of house-280x260x50, 370x200x51, potholes. | 01/06/2015 | At No9 | Pot Hole | Internal | | Archived | 193921 |
| Batch: 464927 - Inspection Batch | | | Route: Adhoc Inspection | | | | Date: 27/03/2015 |
| 98982 580x400x56, 600x390x52, (at BT cover)2x540x320x50), + 8xpotholes of various sizes. | 27/03/2015 | From Muglemoss Road to Bridge. | Pot Hole | Internal | | Archived | 191761 |
| Asset: 1,003 00 | Asset - Locn.: 1 - Old Meldrum Road - | Muglemoss Road-carriageway | Feature Type: RDS Carriageway | | | Area: Aberdeen North | |
| Batch: 518827 - Inspection Batch | | | Route: Week: 28 - Area: 01 | | | | Date: 01/11/2016 |
| 461188 3xpotholes of various sizes. | 01/11/2016 | No9, (house at corner). | Pot Hole | Internal | | Archived | 709701 |
| 461187 along kerbside-360x340x53, + 2xpotholes of various sizes. | 01/11/2016 | Across from Staging Post. | Pot Hole | Internal | | Archived | 709702 |
| Batch: 500479 - Inspection Batch | | | Route: Week: 04 - Area: 01 | | | | Date: 16/05/2016 |
| No actionable defects found | | | | | | | |
| Batch: 487241 - Inspection Batch | | | Route: Week: 28 - Area: 01 | | | | Date: 25/11/2015 |
| 453589 12xpotholes of various sizes. | 25/11/2015 | From Alex Geddes to lampost No8. | Pot Hole | Internal | | Archived | 198811 |
| 453590 Clean and jet gully. | 25/11/2015 | Under Rail Bridge. | Blocked Gully | Internal | | Archived | 198810 |
| Batch: 471428 - Inspection Batch | | | Route: Week: 04 - Area: 01 | | | | Date: 12/06/2015 |
| No actionable defects found | | | | | | | |

15/03/2017

Site History Report

Page 2 of 3

Effective: 13/01/2015 to 15/03/2017
 Site: STATION ROAD (7600022)

Display Action Officer: No

Condition Survey

| Defect No: Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|--|--|--|------------------------------------|----------|--------------|----------------------|------------------|
| Asset: 1,005.00 | Asset - Locn.: 1 - Hard Landscaping | | Feature Type: RDS Hard Landscaping | | | Area: Aberdeen North | Date: 01/11/2016 |
| Batch: 518826 - Inspection Batch | No actionable defects found | | Route: Week: 28 - Area: 01 | | | | |
| Batch: 500478 - Inspection Batch | No actionable defects found | | Route: Week: 04 - Area: 01 | | | | Date: 16/05/2016 |
| Batch: 487240 - Inspection Batch | No actionable defects found | | Route: Week: 28 - Area: 01 | | | | Date: 25/11/2015 |
| Batch: 471427 - Inspection Batch | No actionable defects found | | Route: Week: 04 - Area: 01 | | | | Date: 12/06/2015 |
| Asset: 1,006.00 | Asset - Locn.: 1 - Footway | | Feature Type: RDS Footway | | | Area: Aberdeen North | |
| Batch: 518825 - Inspection Batch | No actionable defects found | | Route: Week: 28 - Area: 01 | | | | Date: 01/11/2016 |
| Batch: 500480 - Inspection Batch | No actionable defects found | | Route: Week: 04 - Area: 01 | | | | Date: 16/05/2016 |
| 458392 on footpath- around concrete cover, 30,40, 16/05/2016 | Culside Staging Post. | | Sunken Footway | Internal | | Archived | 704893 |
| Batch: 487239 - Inspection Batch | No actionable defects found | | Route: Week: 28 - Area: 01 | | | | Date: 25/11/2015 |
| Batch: 471426 - Inspection Batch | No actionable defects found | | Route: Week: 04 - Area: 01 | | | | Date: 12/06/2015 |
| Asset: 1,011.00 | Asset - Locn.: 1 - Grass Verges | | Feature Type: RDS Verges | | | Area: Aberdeen North | |
| Batch: 518823 - Inspection Batch | No actionable defects found | | Route: Week: 28 - Area: 01 | | | | Date: 01/11/2016 |
| Batch: 500464 - Inspection Batch | No actionable defects found | | Route: Week: 04 - Area: 01 | | | | Date: 16/05/2016 |
| Batch: 487238 - Inspection Batch | No actionable defects found | | Route: Week: 28 - Area: 01 | | | | Date: 25/11/2015 |
| Batch: 471425 - Inspection Batch | No actionable defects found | | Route: Week: 04 - Area: 01 | | | | Date: 12/06/2015 |
| Asset: 1,012.00 | Asset - Locn.: 6 - City Council Car Park | | Feature Type: RDS Car Park | | | Area: Aberdeen North | |
| Batch: 518828 - Inspection Batch | | | Route: Week: 28 - Area: 01 | | | | Date: 01/11/2016 |
| 461189 400x380x52, 390x360x50. Potholes. | 01/11/2016 | Within carpark (adjacent to Funeral sign). | Pol Hole | Internal | | Archived | 709703 |
| Batch: 500477 - Inspection Batch | No actionable defects found | | Route: Week: 04 - Area: 01 | | | | Date: 16/05/2016 |
| Batch: 487237 - Inspection Batch | No actionable defects found | | Route: Week: 28 - Area: 01 | | | | Date: 25/11/2015 |
| Batch: 485346 - Inspection Batch | No actionable defects found | | Route: Adhoc Inspection | | | | Date: 04/11/2015 |
| 452914 800x710x80, pothole | 04/11/2015 | In middle of carpark. | Pol Hole | Internal | | Archived | 198037 |

Effective: 13/01/2015 to 15/03/2017
Site: STATION ROAD (7600022)

Display Action Officer: No

Condition Survey

| Defect No: Description | Log Date | Location | Defect Type | Feature Type: RDS Car Park | Class. | Organisation | Status | Job No. |
|------------------------------------|------------|---|----------------------------|----------------------------|----------|--------------|----------------------|------------------|
| Asset: 1.012.00 | | Asset - Locn: 6 - City Council Car Park | | | | | | |
| Batch: 474113 - Inspection Batch | | | Route: Adhoc Inspection | Feature Type: RDS Car Park | | | Area: Aberdeen North | Date: 13/07/2015 |
| 451110 900x800x66, pothole. | 13/07/2015 | In middle of car park. | Pol Hole | | Internal | | Archived | 195067 |
| Batch: 474112 - Inspection Batch | | | Route: Adhoc Inspection | | | | | Date: 13/07/2015 |
| 451109 clean and jet blocked gully | 13/07/2015 | In car park.(map and photo supplied) | Blocked Gully | | Internal | | Archived | 195066 |
| Batch: 471424 - Inspection Batch | | | Route: Week: 04 - Area: 01 | | | | | Date: 12/06/2015 |
| No actionable defects found | | | | | | | | |

15/03/2017

Site History Report

Page 1 of 2

Effective: 13/01/2015 to 15/03/2017
Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)
Site: STATION ROAD (7600022)

Site: STATION ROAD (7600022)

Locality: BUCKSBURN, ABERDEEN, ABERDEEN CITY

Area: Aberdeen North

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|---------|---|--|--|--------------------------------|----------------------|----------------------|-----------------|
| Asset: | | Asset - Locn.: 1,000 00 | Asset - Locn.: 1 - Old Meltrum Road - Mugiemoss Road-carriageway | Feature Type: RDS Road Section | Area: Aberdeen North | Area: Aberdeen North | |
| 191761 | 560x400x56, 600x390x52, (at BT cover)2x540x320x50), + 8xpotholes of various sizes. (Pol Hole) | From Mugiemoss Road to Btdge. | .RD 7 Day | Job Closed | 27/03/2015 | 29/03/2015 | Act. RD01/9711 |
| 193921 | At front of house & side of house-280x260x50, 370x200x51, potholes. (Pol Hole) | At No9 | .RD 7 Day | Job Closed | 01/06/2015 | 02/06/2015 | Act. RD01/20140 |
| 193922 | 510x340x50, pothole. (Pol Hole) | Between lampposts. 3 & 4. | .RD 7 Day | Job Closed | 01/06/2015 | 02/06/2015 | Act. RD01/20140 |
| 701637 | refresh 2xFADED GIVEWAY LINES. (Road Marking) | At Mugiemoss Road and Oldmeltrum Road. | .RD 28 Day | Job Closed | 18/02/2016 | 26/02/2016 | Act. RD01/22236 |
| 702510 | 540x320x52, 500x300x52, + 6xpotholes of various sizes. (Pol Hole) | From No5 round to lamppost No8 | .RD 7 Day | Job Closed | 14/03/2016 | 16/03/2016 | Act. RD01/22467 |
| 704694 | 3x520x430x52, 2x460x400x50, + 6xpotholes of various sizes. (Pol Hole) | From No5 to bridge. | .RD 7 Day | Job Closed | 16/05/2016 | 16/05/2016 | Act. RD01/23217 |
| 704695 | 3xpotholes of various sizes. (Pol Hole) | Outside Staging Post. | .RD 7 Day | Job Closed | 16/05/2016 | 16/05/2016 | Act. RD01/23217 |
| Asset: | | Asset - Locn.: 1 - Old Meltrum Road - Mugiemoss Road-carriageway | Feature Type: RDS Carriageway | Area: Aberdeen North | | | |
| 198610 | Clean and jet gully. (Blocked Gully) | Under Rail Bridge. | .RD 14 Day | Job Closed | 25/11/2015 | 03/02/2016 | Act. RD01/21520 |
| 198611 | 12xpotholes of various sizes. (Pol Hole) | From Alex Geddes to lamppost No6. | .RD 7 Day | Job Closed | 25/11/2015 | 25/11/2015 | Act. RD01/21500 |
| 709701 | 3xpotholes of various sizes. (Pol Hole) | No9. (house at corner). | .RD 7 Day | Job Closed | 01/11/2016 | 03/11/2016 | Act. RD01/25036 |
| 709702 | along kerbside-360x340x53, + 2xpotholes of various sizes. (Pol Hole) | Across from Staging Post. | .RD 7 Day | Job Closed | 01/11/2016 | 05/11/2016 | Act. RD01/25036 |
| Asset: | | Asset - Locn.: 1 - Footway | Feature Type: RDS Footway | Area: Aberdeen North | | | |
| 704893 | on footpath- around concrete cover, 30.40, 50mm trips. (Sunken Footway) | Outside Staging Post. | .RD 7 Day | Job Closed | 16/05/2016 | 16/05/2016 | Act. RD01/23218 |
| Asset: | | Asset - Locn.: 6 - City Council Car Park | Feature Type: RDS Car Park | Area: Aberdeen North | | | |
| 195066 | clean and jet blocked gully. (Blocked Gully) | In car park.(map and photo supplied) | .RD 7 Day | Job Closed | 13/07/2015 | 19/07/2015 | Act. RD01/20459 |
| 195067 | 900x800x66, pothole. (Pol Hole) | In middle of car park. | .RD 7 Day | Job Closed | 13/07/2015 | 15/07/2015 | Act. RD01/20448 |
| 198037 | 800x710x80, pothole (Pol Hole) | In middle of carpark. | .RD 7 Day | Job Closed | 04/11/2015 | 04/11/2015 | Act. RD01/21304 |
| 709703 | 400x380x52, 390x360x50. Potholes. (Pol Hole) | Within carpark (adjacent to Funeral sign). | .RD 7 Day | Job Closed | 01/11/2016 | 05/11/2016 | Act. RD01/25041 |

15/03/2017

Site History Report

Page 2 of 2

Effective: 13/01/2015 to 15/03/2017
Display Action Officer: No

Contract: Roads Contract (General Maint) (RD01)
Site: STATION ROAD (7600022)

Effective: 13/01/2015 to 15/03/2017
Display Action Officer: No

Service: Roads
Site: STATION ROAD (7600022)

Site: STATION ROAD (7600022)

Locality: BUCKSBURN, ABERDEEN, ABERDEEN CITY

Area: Aberdeen North

Customer Services

Enquiry No.: 634324 Logged by: Contact Centre
Service: Roads Subject: General Enquiry on: 11/07/2015 22:22
Desc.: FAO : ACC Roads Response service, Classification: Defect Report Enquiry Ref:

Reference No : DRAINAGE15152
Site (Street/Part/etc) : Public car park, off Station Road
Location : Station Road, Bucksburn
First Type of Fault : Ponding/Flooding
First Fault Details : In the bottom left hand corner of the car park there is a blocked drain which is making a big pool of stagnant water in the car park
Additional Information : There is also plants growing in the pool of water and when it rains heavily the water runs down into Ferguson Court car parking area.

Name :
Telephone Number :
Email Address :

Location: Station Road

Contact:

Plot Number: 1,012,00 Feature Id - Location: 6 - City Council Car Park Feature Type: RDS Car Park
Job Number: 195066 Defect Number: 451109

Enquiry No.: 634323 Logged by: Contact Centre on: 11/07/2015 22:19
Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:
Desc.: FAO : ACC Roads Response service,

Reference No : DRAINAGE15151
Site (Street/Part/etc) : Car Park
Location : Ferguson Court
First Type of Fault : Ponding/Flooding
First Fault Details : After any heavy rain at least three car parking spaces are lost due to flooding
Additional Information : As you enter Ferguson Court it is the first car park on you left and it is in the right diagonal corner of the car park.
Location: Ferguson Court Contact:

Plot Number: 1,012,00 Feature Id - Location: 6 - City Council Car Park Feature Type: RDS Car Park
Job Number: 195066

Enquiry No.: 621608 Logged by: Contact Centre on: 03/02/2015 10:42
Service: Roads Subject: General Enquiry Classification: Defect Report Enquiry Ref:
Desc.: The length of Station Road in Bucksburn is in dire need of resurfacing. It is littered in potholes all the way along. While it may not be a main road, it should still be useable.
Location: STATION ROAD Contact: