From: Foi Enquiries

Subject: EIR-17-0494 - Inspections - Park Street

Date: 12 April 2017 14:37:09

Attachments: Further Information - Right to Review & Appeal.pdf

EIR-17-0494 - Park Street Condition Survey.pdf

EIR-17-0494 - Park Street Maintenance Management Redacted.pdf



To:

Thank you for your information request of 24 March 2017. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

We would be grateful if you would provide us with the undernoted information relative to the repair, maintenance and inspection of the east-side pavement on Park Street, Aberdeen.

Is this pavement adopted by the council in terms of the Roads (Scotland) Act 1984? This footway is adopted by Aberdeen City Council.

What inspection interval has the council identified as being appropriate for this pavement? 2 monthly.

What factors were used in the assessing the inspection interval?

The inspection frequency was attributed in conjunction with guidelines set out in 'Well Maintained Highways 2005' Please see link below pages 5 and 6.

http://www.aberdeencitv.gov.uk/web/files/Roads/road_safety_inspection_manual.pdf

Please provide a copy of all inspection reports for this pavement between 30th October 2014 and the present.

Please see attached report under 'Condition Survey'.

Please also confirm when was the last inspection prior to 30th October 2016?

08/10/2016 Routine and 26/10/2016. Adhoc inspection of railings following a road traffic collision.

What was noted?

No actionable safety defects found.

How was the inspection carried out?

By foot and by vehicle.

When was the first inspection following 30th October 2016?

16/11/2016

What was noted?

No actionable safety defects found.

How was the inspection carried out?

By foot and by vehicle.

Has the defect been repaired?

N/A as no actionable safety defects present.

When was the defect noted?

N/A

What category was the defect (either category 1 or category 2 as set out at 9.4.11 of the Code of Practice)?

N/A

When was the repair instructed?

N/A

When was the defect repaired?

N/A

Please provide a copy of the job sheet for this repair.

N/A

Please provide copies of all work records for the pavement between 30th October 2014 and the date of this correspondence.

Please see attached report under 'Maintenance Management'.

Please provide copies of any photographs which you may hold of the defect.

N/A

Please provide copies of any records of complaints made to the council regarding defects on this pavement between 30th October 2014 and the date of this correspondence.

No complaints made.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Head of Service level have been redacted (blacked out) from the attached reports. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with 11(3)(a)(i) of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, and the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as ACC considers that disclosure of this information would be a breach of the first Data Protection Principle (that personal information must be processed fairly and lawfully). Third parties and ACC Officers who are below Head of Service level named within the attached documents would not expect ACC to release this

information about them into the public domain under the EIRs (or the Freedom of Information (Scotland) Act 2002 (FOISA)).

We hope this helps with your request.

Yours sincerely,

Information Compliance Team

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team
Communications and Promotion
Office of Chief Executive
Aberdeen City Council
3rd Floor North
Business Hub 17
Marischal College
Broad Street
ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk 01224 523827/523602

Tel 03000 200 292

*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.

Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

Display Action Officer: No

Site: PARK STREET (7600024)

Site: PARK STREET (7600024) Locality: ABERDEEN, ABERDEEN CITY Area: Aberdeen Central

ondition Survey						
efect No: Description	Log Date	Location	Defect Type	Class. (Organisation Status	Job No.
Asset: 1,000.00 Asset - Locn.:	: N/15/1814 - P	ARK STREET	Feature Type: RDS Ro	ad Section	Area: Aberdeer	n Central
Batch: 527012 - Inspection Batch		Route: Week:	46 - Area: 14			Date: 06/03/2017
463198 Pothole 300 x 200 to fill	06/03/2017	Near end of building for Eagle may take away	Pot Hole	Internal	Committed	713083
463200 16 gullies to clear and jet	06/03/2017	All gullies on Park street	Blocked Gully	Internal	Committed	713085
463201 Pothole 500 x 400 to fill	06/03/2017		Pot Hole	Internal	Committed	713081
463199 3 potholes 300 x 300 to fill		At both sides of junction Princes street and along junction	Pot Hole	Internal	Committed	713084
463197 Pothole exposing ironwork to fill	06/03/2017	1st gully after constitution street heading to roundabout before bus shelter	Pot Hole	Internal	Committed	713082
Batch: 523401 - Inspection Batch		Route: Week:	38 - Area: 14			Date: 10/01/2017
No actionable defects found						
Batch: 520182 - Inspection Batch		Route: Week:	30 - Area: 14			Date: 16/11/2016
No actionable defects found						
Batch: 516853 - Inspection Batch		Route: Week:	22 - Area: 14			Date: 08/10/2016
No actionable defects found						
Batch: 507215 - Inspection Batch		Route: Week:	14 - Area: 14			Date: 27/07/2016
No actionable defects found						
Batch: 504510 - Inspection Batch		Route: Adhoo	Inspection			Date: 21/06/2016
459225 Blocked gully to clear and jet	21/06/2016	Just coming of roundabout before Frederick street	Blocked Gully	Internal	Archived	706214
Batch: 504509 - Inspection Batch		Route: Adhoo	Inspection			Date: 21/06/2016
459224 Damaged pedestrian rail, replace 2 sections and 2 posts one is an end post	21/06/2016	Near roundabout and Frederick street	Damaged Pedestrian Railing	Internal	Archived	706213
Batch: 504340 - Inspection Batch		Route: Adhoo	Inspection			Date: 20/06/2016
459192 Pothole 500 x 300 to fill	20/06/2016	At corner of junction with Constitution street	Pot Hole	Internal	Archived	706106
Batch: 502071 - Inspection Batch		Route: Week:	06 - Area: 14			Date: 31/05/2016
No actionable defects found						
Batch: 497225 - Inspection Batch		Route: Adhoo	Inspection			Date: 05/04/2016
457140 Blocked gully to clear and jet	05/04/2016	PARK STREET - Opposite Jasmine Terrace junction near lighting column 10	Blocked Gully	Internal	Archived	703340
Batch: 497118 - Inspection Batch		Route: Week:	46 - Area: 14			Date: 04/04/2016
457060 Blocked gully to clear and jet	04/04/2016	At corner of Princes street	Blocked Gully	Internal	Archived	703257
Batch: 493367 - Inspection Batch	2 2 20 . 0	Route: Week:			,	Date: 15/02/2016
455654 Pothole exposing ironwork to fill	15/02/2016	At gully corner of Princes Street	Pot Hole	Internal	Archived	701473
Batch: 488895 - Inspection Batch	. 5, 52, 25 10	Route: Week:			,	Date: 15/12/2015

No actionable defects found

Display Action Officer: No

Condition Survey

Defect No: Description	Log Date	Location	Defect Type	Class. Organisat	ion Status	Job No.
Asset: 1,000.00 Asset - Loc	n.: N/15/1814 - P	ARK STREET	Feature Type:	RDS Road Section	Area: Aberdee	en Central
Batch: 484224 - Inspection Batch		Route: Week:	22 - Area: 14			Date: 19/10/2015
452590 Blocked gully to clear and jet	19/10/2015	At corner of Princes street	Blocked Gully	Internal	Archived	197612
452591 Blocked gully to clear and jet	19/10/2015	At corner of Summerfield Terrace at shop	Blocked Gully	Internal	Archived	197613
452588 2 x blocked gullies to clear and jet	19/10/2015	At corner of Roslin place	Blocked Gully	Internal	Archived	197610
452592 Blocked gully to clear and jet	19/10/2015	Outside flats 181-211	Blocked Gully	Internal	Archived	197614
452589 2 x blocked gullies to clear and jet		At lighting column 5 and opposite near corner if Constitution Street	Blocked Gully	Internal	Archived	197611
452593 Pothole at manhole approx 500 x 200 to	to fill 19/10/2015	Just over railway bridge after lighting column 13	Pot Hole	Internal	Archived	197609
Batch: 481462 - Inspection Batch		Route: Week:	14 - Area: 14			Date: 27/08/2015
No actionable defects found						
Batch: 474776 - Inspection Batch		Route: Adhoc	Inspection			Date: 15/07/2015
451199 Area between ironworks has broken up exposing ironwork,remove any loose material and fill pothole approx 500 x 5		PARK STREET - ROADS26694 - AB	Pot Hole	Internal	Archived	195177
Batch: 472846 - Inspection Batch		Route: Week:	06 - Area: 14			Date: 30/06/201
No actionable defects found						
Batch: 468633 - Inspection Batch		Route: Week:	46 - Area: 14			Date: 07/05/201
No actionable defects found						
Batch: 462767 - Inspection Batch		Route: Week:	38 - Area: 14			Date: 12/03/201
98587 Pothole 500 x 250 x 50mm to fill ,other forming along junction if possible fill at time and report		At corner of junction with Constitution Street	Pot Hole	Internal	Archived	191225
Batch: 453967 - Inspection Batch		Route: Week:	30 - Area: 14			Date: 20/01/201
No actionable defects found						
Batch: 450657 - Inspection Batch		Route: Week:	22 - Area: 14			Date: 14/11/2014
No actionable defects found						
Asset: 1,001.00 Asset - Loc	:n.: 1 - Hard lands	scaping	Feature Type:	RDS Hard Landscaping	Area: Aberdee	en Central
Batch: 527013 - Inspection Batch		Route: Week:	46 - Area: 14			Date: 06/03/2017
No actionable defects found						
Batch: 523402 - Inspection Batch		Route: Week:	38 - Area: 14			Date: 10/01/201
No actionable defects found						
Batch: 520183 - Inspection Batch		Route: Week:	30 - Area: 14			Date: 16/11/2010
No actionable defects found						
Batch: 516857 - Inspection Batch		Route: Week:	22 - Area: 14			Date: 08/10/201
No actionable defects found						
			44 4			D 4 07/07/004
Batch: 507216 - Inspection Batch		Route: Week:	14 - Area: 14			Date: 27/07/2016

Condition Survey

fect No: Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,001.00	Asset - Locn.: 1 - Hard lands	scaping	Feature Type: RDS Ha	ard Landscap	ping	Area: Aberdee	n Central
Batch: 502072 - Inspection I	Batch	Route: W	eek: 06 - Area: 14				Date: 31/05/2016
No actionable defects for	ound						
Batch: 497121 - Inspection I	Batch	Route: W	'eek: 46 - Area: 14				Date: 04/04/2016
No actionable defects for	ound						
Batch: 493368 - Inspection I	Batch	Route: W	'eek: 38 - Area: 14				Date: 15/02/2016
No actionable defects for	ound						
Batch: 488896 - Inspection I	Batch	Route: W	'eek: 30 - Area: 14				Date: 15/12/2015
No actionable defects for	ound						
Batch: 484229 - Inspection I	Batch	Route: W	'eek: 22 - Area: 14				Date: 19/10/2015
No actionable defects for	ound						
Batch: 481463 - Inspection I	Batch	Route: W	'eek: 14 - Area: 14				Date: 27/08/2015
No actionable defects for	ound						
Batch: 472847 - Inspection I	Batch	Route: W	'eek: 06 - Area: 14				Date: 30/06/2015
No actionable defects for	ound						
Batch: 468634 - Inspection I	Batch	Route: W	'eek: 46 - Area: 14				Date: 07/05/2015
No actionable defects for	ound						
Batch: 462768 - Inspection I	Batch	Route: W	'eek: 38 - Area: 14				Date: 12/03/2015
No actionable defects for	ound						
Batch: 453968 - Inspection I	Batch	Route: W	'eek: 30 - Area: 14				Date: 20/01/2015
No actionable defects for	ound						
Batch: 450657 - Inspection I	Batch	Route: W	'eek: 22 - Area: 14				Date: 14/11/2014
No actionable defects for	ound						
Asset: 1,002.00	Asset - Locn.: 1 - Footway		Feature Type: RDS Fo	otway		Area: Aberdee	n Central
Batch: 527014 - Inspection I	Batch	Route: W	eek: 46 - Area: 14				Date: 06/03/2017
No actionable defects for	ound						
Batch: 523403 - Inspection I	Batch	Route: W	eek: 38 - Area: 14				Date: 10/01/2017
No actionable defects for	ound						
Batch: 520184 - Inspection I	Batch	Route: W	eek: 30 - Area: 14				Date: 16/11/2016
No actionable defects for	ound						
Batch: 518085 - Inspection I	Batch	Route: A	dhoc Inspection				Date: 26/10/2016
461078 Replace 2 damaged see	ctions and 1 post 26/10/2016	Near corner with Frederick Street	Damaged Pedestrian Railing	Internal		Committed	709548
Batch: 516856 - Inspection I	Batch	Route: W	eek: 22 - Area: 14				Date: 08/10/2016
No actionable defects for	ound						
Batch: 507217 - Inspection I	Batch	Route: W	eek: 14 - Area: 14				Date: 27/07/2016
No actionable defects for	ound						
Batch: 502073 - Inspection I	Batch	Route: W	eek: 06 - Area: 14				Date: 31/05/2016
No actionable defects for	and the second						

Display Action Officer: No

Condition Survey

Defect No: Des	cription		Log Date	Location	Defect Type	Class.		Status	Job No.
Asset:	1,002.00	Asset - Locn.: '	I - Footway		Featu	re Type: RDS Footway	Ar	rea: Aberdeen	Central
Batch: 4	97122 - Inspection	Batch			Route: Week: 46 - Area: 14				Date: 04/04/2016
No a	actionable defects	found							
Batch: 4	95492 - Inspection	Batch			Route: Adhoc Inspection				Date: 14/03/2016
sect	lace damaged ped ion ,1 end post and ooted slab	estrian barrier, 1 d 1 other post ,reset	14/03/2016	Near junction with Frede	rick street Damaged Ped	destrian Railing Interna	al	Archived	702498
Batch: 4	93369 - Inspection	Batch			Route: Week: 38 - Area: 14				Date: 15/02/2016
No a	actionable defects	found							
Batch: 4	88897 - Inspection	Batch			Route: Week: 30 - Area: 14				Date: 15/12/2015
No a	actionable defects	found							
Batch: 4	84230 - Inspection	Batch			Route: Week: 22 - Area: 14				Date: 19/10/2015
No a	actionable defects	found							
Batch: 4	84029 - Inspection	Batch			Route: Adhoc Inspection				Date: 14/10/2015
452514 Upro	ooted bollard not d	amaged to reset	14/10/2015	Outside 133-147	Damaged Bol	lard Interna	al	Archived	197531
Batch: 4	81465 - Inspection	Batch			Route: Week: 14 - Area: 14				Date: 27/08/2015
No a	actionable defects	found							
Batch: 4	72848 - Inspection	Batch			Route: Week: 06 - Area: 14				Date: 30/06/2015
No a	actionable defects	found							
Batch: 4	68635 - Inspection	Batch			Route: Week: 46 - Area: 14				Date: 07/05/2015
No a	actionable defects	found							
Batch: 4	62769 - Inspection	Batch			Route: Week: 38 - Area: 14				Date: 12/03/2015
No a	actionable defects	found							
Batch: 4	53969 - Inspection	Batch			Route: Week: 30 - Area: 14				Date: 20/01/2015
No a	actionable defects	found							
Batch: 4	50657 - Inspection	Batch			Route: Week: 22 - Area: 14				Date: 14/11/2014
No a	actionable defects	found							
Asset:	1,003.00	Asset - Locn.: 8	3 - Park Road	to Duff Street-Footway	Featu	re Type: RDS Footway	Ar	rea: Aberdeen	Central
Batch: 4	53970 - Inspection	Batch			Route: Week: 30 - Area: 14				Date: 20/01/2015
No a	actionable defects	found							
Batch: 4	50657 - Inspection	Batch			Route: Week: 22 - Area: 14				Date: 14/11/2014
No a	actionable defects	found							
Asset:	1,004.00	Asset - Locn.: '	l - Grass verg	je	Featu	re Type: RDS Verge	Ar	rea: Aberdeen	Central
Batch: 5	27015 - Inspection	Batch			Route: Week: 46 - Area: 14				Date: 06/03/2017
No a	actionable defects	found							
Batch: 5	23404 - Inspection	Batch			Route: Week: 38 - Area: 14				Date: 10/01/2017
No a	actionable defects	found							

Condition	Survey
-----------	--------

ect No: Description	Log Date Location	Defect Type		Organisation	Status	Job No.
Asset: 1,004.00	Asset - Locn.: 1 - Grass verge	Feature Type:	: RDS Verge		Area: Aberde	en Central
Batch: 520185 - Inspection Ba	tch	Route: Week: 30 - Area: 14				Date: 16/11/2016
No actionable defects four	nd					
Batch: 516858 - Inspection Ba	tch	Route: Week: 22 - Area: 14				Date: 08/10/2016
No actionable defects four	nd					
Batch: 507218 - Inspection Ba	tch	Route: Week: 14 - Area: 14				Date: 27/07/2016
No actionable defects four	nd					
Batch: 502074 - Inspection Ba	tch	Route: Week: 06 - Area: 14				Date: 31/05/2016
No actionable defects four	nd					
Batch: 497123 - Inspection Ba	tch	Route: Week: 46 - Area: 14				Date: 04/04/2016
No actionable defects four	nd					
Batch: 493370 - Inspection Ba	tch	Route: Week: 38 - Area: 14				Date: 15/02/2016
No actionable defects four	nd					
Batch: 488898 - Inspection Ba	tch	Route: Week: 30 - Area: 14				Date: 15/12/2015
No actionable defects four	nd					
Batch: 484231 - Inspection Ba	tch	Route: Week: 22 - Area: 14				Date: 19/10/2015
No actionable defects four	nd					
Batch: 481464 - Inspection Ba	tch	Route: Week: 14 - Area: 14				Date: 27/08/2015
No actionable defects four	nd					
Batch: 472849 - Inspection Ba	tch	Route: Week: 06 - Area: 14				Date: 30/06/2015
No actionable defects four	nd					
Batch: 468636 - Inspection Ba	tch	Route: Week: 46 - Area: 14				Date: 07/05/2015
No actionable defects four	nd					
Batch: 462771 - Inspection Ba	tch	Route: Week: 38 - Area: 14				Date: 12/03/2015
No actionable defects four	nd					
Batch: 453971 - Inspection Ba	tch	Route: Week: 30 - Area: 14				Date: 20/01/2015
No actionable defects four	nd					
Batch: 450657 - Inspection Ba	tch	Route: Week: 22 - Area: 14				Date: 14/11/2014
No actionable defects four	nd					
Asset: 1,005.00	Asset - Locn.: 2 - Princes Street to Frederick Street-Foo	otway Feature Type:	: RDS Footway		Area: Aberde	en Central
Batch: 453972 - Inspection Ba	tch	Route: Week: 30 - Area: 14				Date: 20/01/2015
No actionable defects four	nd					
Batch: 450657 - Inspection Ba	tch	Route: Week: 22 - Area: 14				Date: 14/11/2014
No actionable defects four						
Asset: 1,006.00	Asset - Locn.: 9 - Lemon Street to Duff Street-Footway	Feature Type:	: RDS Footway		Area: Aberde	en Central
Batch: 453973 - Inspection Ba	tch	Route: Week: 30 - Area: 14				Date: 20/01/2015
No actionable defects four	nd					

Condition Survey

ect No: Description	1	Log Date Location	Defe	ct Type	Class.	Organisation	Status	Job No.
Asset: 1,00	6.00 Asse	et - Locn.: 9 - Lemon Street to Duff Street-Footwa	ıy	Feature Type: RI	OS Footway		Area: Aberdee	n Central
Batch: 450657 -	Inspection Batch		Route: Week: 22 - A	rea: 14				Date: 14/11/2014
No actionab	le defects found							
Asset: 1,00	7.00 Asse	et - Locn.: 3 - Princes Street to Summerfield Terra	ace-Footway	Feature Type: RI	OS Footway		Area: Aberdee	n Central
Batch: 453974 -	Inspection Batch		Route: Week: 30 - A	rea: 14				Date: 20/01/2015
No actionab	le defects found							
Batch: 450657 -	Inspection Batch		Route: Week: 22 - A	rea: 14				Date: 14/11/2014
No actionab	le defects found							
Asset: 1,00	8.00 Ass	et - Locn.: 10 - Lemon Street to Constitution Stree	et-Footway	Feature Type: RI	OS Footway		Area: Aberdee	n Central
Batch: 453975 -	Inspection Batch		Route: Week: 30 - A	rea: 14				Date: 20/01/2015
No actionab	le defects found							
Batch: 450657 -	Inspection Batch		Route: Week: 22 - A	rea: 14				Date: 14/11/2014
No actionab	le defects found							
Asset: 1,00	9.00 Asse	et - Locn.: 4 - 101 to Summerfield Terrace-Footwa	ay	Feature Type: RI	OS Footway	ı	Area: Aberdee	n Central
Batch: 453976 -	Inspection Batch		Route: Week: 30 - A	rea: 14				Date: 20/01/2015
No actionab	le defects found							
Batch: 450657 -	Inspection Batch		Route: Week: 22 - A	rea: 14				Date: 14/11/2014
	le defects found							
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		et - Locn.: 11 - Justice Port to Constitution Street-	Footway	Feature Type: RI	OS Footway		Area: Aberdee	n Central
Batch: 453977 -	Inspection Batch		Route: Week: 30 - A	rea: 14				Date: 20/01/2015
	le defects found							
Batch: 450657 -	Inspection Batch		Route: Week: 22 - A	rea: 14				Date: 14/11/2014
	le defects found							
,-		et - Locn.: 5 - 101 to Jasmine Terrace-Footway		Feature Type: RI	OS Footway		Area: Aberdee	n Central
Batch: 453978 -	Inspection Batch		Route: Week: 30 - A	rea: 14				Date: 20/01/2015
	le defects found							
	Inspection Batch		Route: Week: 22 - A	rea: 14				Date: 14/11/2014
	le defects found							
		et - Locn.: 12 - Justice Port-Footway		Feature Type: RI	JS Footway		Area: Aberdee	
	Inspection Batch		Route: Week: 30 - A	rea: 14				Date: 20/01/2015
	ole defects found		-					-
	Inspection Batch		Route: Week: 22 - A	rea: 14				Date: 14/11/2014
	ele defects found	-1 Lan 0 404 to leaving Towns 5		Footoma Em. Di	20 5		A Ab!	. 0 1 1
, , , , , , , , , , , , , , , , , , , ,		et - Locn.: 6 - 181 to Jasmine Terrace-Footway	B . W	Feature Type: RI	JS Footway		Area: Aberdee	
	Inspection Batch		Route: Week: 30 - A	rea: 14				Date: 20/01/2015
No actionab	le defects found							

Condition	Survey
-----------	--------

ect No: Description	Log Date Location	Defect Type		Organisation	Status	Job No.
Asset: 1,013.00	Asset - Locn.: 6 - 181 to Jasmine Terrace-Footway	Feature Type	Feature Type: RDS Footway			n Central
Batch: 450657 - Insp	pection Batch	Route: Week: 22 - Area: 14				Date: 14/11/2014
No actionable d						
Asset: 1,014.00	Asset - Locn.: 1 - East North Street to Park Road-Carr	iageway Feature Type	: RDS Carriageway		Area: Aberdee	n Central
Batch: 453981 - Insp	pection Batch	Route: Week: 30 - Area: 14				Date: 20/01/2015
No actionable d	efects found					
Batch: 450657 - Insp	pection Batch	Route: Week: 22 - Area: 14				Date: 14/11/2014
No actionable d						
Asset: 1,015.00	Asset - Locn.: 7 - 181 to Roslin Terrace-Footway	Feature Type	: RDS Footway		Area: Aberdee	n Central
Batch: 453982 - Insp	pection Batch	Route: Week: 30 - Area: 14				Date: 20/01/2015
No actionable d	efects found					
Batch: 450657 - Insp	pection Batch	Route: Week: 22 - Area: 14				Date: 14/11/2014
No actionable d						
Asset: 2,001.00		Feature Type	: RDS Gully		Area: Aberdee	n Central
Batch: 510491 - Insp	pection Batch	Route: Adhoc Inspection				Date: 16/08/2016
No actionable d						
Asset: 2,002.00		Feature Type	: RDS Gully		Area: Aberdee	n Central
Batch: 510492 - Insp	pection Batch	Route: Adhoc Inspection				Date: 16/08/2016
No actionable d						
Asset: 2,003.00		top Feature Type	: RDS Gully		Area: Aberdee	n Central
Batch: 510493 - Insp		Route: Adhoc Inspection				Date: 16/08/2016
No actionable d						
Asset: 2,004.00	3	Feature Type	: RDS Gully		Area: Aberdee	n Central
Batch: 510494 - Insp	pection Batch	Route: Adhoc Inspection				Date: 16/08/2016
No actionable d						
Asset: 2,005.00		Feature Type	: RDS Gully		Area: Aberdee	
Batch: 510495 - Insp		Route: Adhoc Inspection				Date: 16/08/2016
No actionable d						
Asset: 2,006.00			: RDS Gully		Area: Aberdee	
Batch: 510496 - Insp		Route: Adhoc Inspection				Date: 16/08/2016
No actionable d						
Asset: 2,007.00		Feature Type	: RDS Gully		Area: Aberdee	
Batch: 510497 - Insp		Route: Adhoc Inspection				Date: 16/08/2016
No actionable d						
Asset: 2,008.00		Feature Type	: RDS Gully		Area: Aberdee	
Batch: 510498 - Insp	nection Batch	Route: Adhoc Inspection				Date: 16/08/2016

Display Action Officer: No

Condition	Survey
-----------	--------

ct No: Description	Log Date Location	Defect Type Cla	ass. Organisation Status Job No.
Asset: 2,009.00	Asset - Locn.: 7600024/J/00010 - Flat #104-110	Feature Type: RDS Gully	Area: Aberdeen Central
Batch: 510499 - Inspe	ection Batch	Route: Adhoc Inspection	Date : 16/08/2016
No actionable de	fects found		
Asset: 2,010.00	Asset - Locn.: 7600024/J/00009 - Bins opp 104-110	Feature Type: RDS Gully	Area: Aberdeen Central
Batch: 510500 - Inspe	ection Batch	Route: Adhoc Inspection	Date: 16/08/2016
No actionable de	fects found		
Asset: 2,011.00	Asset - Locn.: 7600024/J/00012 - Gate to car park	Feature Type: RDS Gully	Area: Aberdeen Central
Batch: 510501 - Inspe	ection Batch	Route: Adhoc Inspection	Date: 16/08/2016
No actionable de	fects found		
Asset: 2,012.00	Asset - Locn.: 7600024/J/00011 - Parking area	Feature Type: RDS Gully	Area: Aberdeen Central
Batch: 510502 - Inspe	ection Batch	Route: Adhoc Inspection	Date: 16/08/2016
No actionable de	fects found		
Asset: 2,013.00	Asset - Locn.: 7600024/J/00014 - Flat #124-134	Feature Type: RDS Gully	Area: Aberdeen Central
Batch: 510503 - Inspe	ection Batch	Route: Adhoc Inspection	Date: 16/08/2016
No actionable de	fects found		
Asset: 2,014.00	Asset - Locn.: 7600024/J/00013 - Jasmine terrace june	ction Feature Type: RDS Gully	Area: Aberdeen Central
Batch: 510504 - Inspe	ection Batch	Route: Adhoc Inspection	Date: 16/08/2016
No actionable de	fects found		
Asset: 2,015.00	Asset - Locn.: 7600024/J/00016 - At LP10	Feature Type: RDS Gully	Area: Aberdeen Central
Batch: 510505 - Inspe	ection Batch	Route: Adhoc Inspection	Date: 16/08/2016
No actionable de	fects found		
Asset: 2,016.00	Asset - Locn.: 7600024/J/00015 - Opp Duff Street	Feature Type: RDS Gully	Area: Aberdeen Central
Batch: 510506 - Inspe	ection Batch	Route: Adhoc Inspection	Date: 16/08/2016
No actionable de	fects found		
Asset: 2,017.00	Asset - Locn.: 7600024/J/00018 - Opp car park	Feature Type: RDS Gully	Area: Aberdeen Central
Batch: 510507 - Inspe	ection Batch	Route: Adhoc Inspection	Date: 16/08/2016
No actionable de	fects found		
Asset: 2,018.00	Asset - Locn.: 7600024/J/00017 - Opp LP 12	Feature Type: RDS Gully	Area: Aberdeen Central
Batch: 510508 - Inspe	ection Batch	Route: Adhoc Inspection	Date: 16/08/2016

No actionable defects found

Effective: 30/10/2014 to 03/04/2017 Display Action Officer: No	04/2017	Co	Site: PARK STREET (7600024)	it) (MDOT)		
Site: PARK STREET (7600024)	Locality: A	Locality: ABERDEEN, ABERDEEN CITY	ווי	Area:	Area: Aberdeen Central	ral
Maintenance Management						
Job No. Description	Location	Priority	Job Status	Entered C	Completion	Works Order
Asset: 1,000.00	Asset - Locn.: N/15/1814 - PARK STREET		Feature Type: RDS Road Section	Ar	Area: Aberdeen Central	entral
s to clear and je	at following locations just past	RD 14 Day	Job Closed	29/10/2014 03	02/11/2014 Act. RD01/8881	RD01/8881
(Discount Chily)	opposite Constitution Street junction at fact of Park Place					
188128 reset bollard and surrounding	outside flats 104 - 110	.RD 14 Day	Job Closed	29/10/2014 30	30/10/2014 Act.	RD01/8874
188129 blocked gully to clear and jet	outside Restore at comer	.RD 14 Day	Job Closed	29/10/2014 03	02/11/2014 Act.	RD01/8881
188484 blocked gully to clear and jet	opposite Princes Street junction	.RD 14 Day	Job Closed	14/11/2014 24	24/11/2014 Act.	RD01/8989
188485 blocked gully to clear and jet	opposite Frederick Street iunction last gully before	.RD 14 Day	Job Closed	14/11/2014 2	24/11/2014 Act.	RD01/8989
188486 blocked gully to clear and let	roundabout junction at comer at Princes Street	.RD 14 Day	Job Closed	14/11/2014 24	24/11/2014 Act.	RD01/8989
188487 blocked gully to clear and jet	junction opposite sub station near Duff	.RD 14 Day	Job Closed	14/11/2014 2	24/11/2014 Act.	RD01/8989
188488 blocked gully to clear and jet	opposite Jasmine Terrace	RD 14 Day	Job Closed	14/11/2014 2	24/11/2014 Act.	RD01/8989
188489 pothole to fill at gully	opposite Princes street junction between lighting columns 4 and	.RD 7 Day	Job Closed	14/11/2014 1	15/11/2014 Act.	RD01/8986
188490 pothole to fill at manhole	opposite sub station near Duff	.RD 7 Day	Job Closed	14/11/2014 1	15/11/2014 Act.	RD01/8986
188491 pothols to fill at manhole	near Summerfield Terrace	.RD 7 Day	Job Closed	14/11/2014 1	15/11/2014 Act.	RD01/8986
191225 Pothole 500 x 250 x 50mm to fill others forming along junction if possible fill at time and report	At comer of junction with Constitution Street	.RD 7 Day	Job Closed	12/03/2015 1:	12/03/2015 Act.	RD01/9584
192707 blocked gully to clear and jet	just of raundabout just before junction Frederick Street	.RD 14 Day	Job Closed		20/09/2015 Act.	
195177 Area between ironworks has broken up exposing ironwork, remove any loose material and fill pothole approx	PARK STREET - ROADS26694 - AB	.RD 7 Day	Jab Clased	15/07/2015 1:	17/07/2015 Act.	RD01/20456
×		.RD 7 Day	Job Closed			
197610 2 x blocked gullies to clear and jet (Blocked Gully)	At corner of Roslin place	.RD 14 Day	Job Closed	19/10/2015 1	15/11/2015 Act.	RD01/21131
jet (Blocked Gully) 197612 Blocked gully to clear and jet (Blocked Gully)	near comer if Constitution Street At comer of Princes street	.RD 14 Day	Jab Clased	19/10/2015 2:	23/10/2015 Act. RD01/21131	RD01/21131

Contract: Roads Contract (General Maint) (RD01) Site: PARK STREET (7600024)	Effective: 30/10/2014 to 03/04/2017 Display Action Officer: No

192693 damaged pedestrian rail , replace just before 2 sections and 2 posts junction 192706 damaged pedestrian rail , replace just before 2 sections and 2 posts junction	Asset: 1,002.00 Asset-Loc	jet	oles 300 x 300 to fill (Pot	713083 Pothole 300 x 200 to fill (Pot Near end of bui	le expasing ironwork to filt tale)	713081 Pothole 500 x 400 to fill (Pot Opposite C	710387 Find and Fix 12 potholes filled by urquhart road junction	Fix 1 potholes filled by	surface ,on failed 2no 500x400x50.	gully to clear and jet I Gully)	ged pedestrian rail, replace ions and 2 posts one is an ost (Damaged Pedestrian o)	706106 Pathole 500 x 300 to fill (Pat At corner of junctic Hole)	(Blocked Gully) (Blocked Gully) (Blocked Gully) (Blocked Gully) (Blocked Gully)	clear and jet	702568 Find and Fix 9 potholes filled by various locations	(posing ironwork to fill	700282 Find and Fix 3 patholes filled by unknown	(Blocked Gully) 197614 Blocked gully to clear and jet Outside fl	clear and jet	1,000.00	Job No. Description Location	Maintenance Management
e Frederick Street		All guilles on Park street	At both sides of junction Princes street and along junction	Near end of building for Eagle may lake away	1st gully after constitution street heading to roundabout before bus shalter	Opposite Constitution street at	road junction	o/s key store around manhole	as you leave roundabout heading north as you pass chinese eagle may takeaway.	Just coming of roundabout before Frederick street	Near roundabout and Frederick street	At comer of junction with Constitution street	PARK STREET - Opposite Jasmine Terrace junction near lighting column 10	At comer of Princes street	cations	At gully comer of Princes Street		Outside flats 181-211	At comer of Summerfield Terrace	Asset - Locn.: N/15/1814 - PARK STREET		
.RD 14 Day		,RD 14 Day	.RD 7 Day	.RD 7 Day	.RD 7 Day	.RD 7 Day	.Routine Maintenance	.Routine Maintenance	.RD 7 Day	.RD 14 Day	.RD 14 Day	.RD 7 Day	.RD 14 Day	.RD 14 Day	.Routine Maintenance	.RD 7 Day	.Routine Maintenance	.RD 14 Day	RD 14 Day	Feature	Priority	
Job Cancelled	Feature Type: RDS Footway	Order Printed	Contractor Completed	Contractor Completed	Contractor Completed	Contractor Completed	Contractor Completed	Contractor Completed	Job Closed	Job Closed	Job Closed	Job Closed	Job Closed	Job Closed	Job Closed	Job Closed	Job Clased	Job Closed	Job Closed	Feature Type: RDS Road Section	Job Status	
27/04/2015	37/04/2015	06/03/2017	06/03/2017	06/03/2017	06/03/2017	06/03/2017	05/12/2016	20/10/2016	29/09/2016	21/06/2016	21/06/2016	20/06/2016	05/04/2016	04/04/2016	16/03/2016	15/02/2016	19/01/2016	19/10/2015	19/10/2015		Entered	
27/04/2015 27/04/2015 Act.	Area: Aberdeen Central	UB/U3/2017 Z0/U3/2017 ESt. ND01/z0370	06/03/2017 06/03/2017 Act. RD01/26366	06/03/2017 06/03/2017 Act. RD01/26366	06/03/2017 06/03/2017 Act. RD01/26366	06/03/2017 Act. RD01/26366	03/12/2016 Act.	16/10/2016 Act.			21/06/2016 21/06/2016 ACL KD01/23669	20/06/2016 Act. RD01/23672		04/04/2016 09/04/2016 Act. RD01/22742	16/03/2016 13/03/2016 Act	21/02/2016 Act RD01/22199	18/11/2015 Act.	04/11/2015 Act. RD01/21131	23/10/2015 Act. RD01/21131	Area: Aberdeen Central	Completion Works Order	

Maintenance Management Job No. Effective: 30/10/2014 to 03/04/2017 Display Action Officer: No 709162 blocked gully,clean. 702498 Replace damaged pedestrian Near jubarrier, 1 section, 1 end post and street 1 other post reset uproofed slab 709548 Replace 2 damaged sections and Near comer with Frederick Street 709163 repoint service lid, remove old 197531 Uprooted bollard not damaged to Outside 133-147 195506 damaged pedestrian rail, replace just before. Frederick Street Description reset (Damaged Bollard) 1 sections and 1 post (Damaged Pedestrian Railing) Asset: 1,002.00 Asset - Locn.: 1 - Footway Near junction with Frederick outside newsagent at comer of summerfield terr. at corner shop newsagent summerfield terr Location unction .RD 14 Day .RD 14 Day .RD 14 Day Priority .RD 7 Day .RD 7 Day .RD 14 Day Contract: Roads Contract (General Maint) (RD01) Site: PARK STREET (7600024) Feature Type: RDS Footway Contractor Completed Job Closed Job Status Job Closed Job Closed Job Closed Job Closed 26/10/2016 26/10/2016 Act. RD01/24972 10/10/2016 10/10/2016 Act. 14/03/2016 14/03/2016 Act. RD01/22461 14/10/2015 14/10/2015 Act. RD01/21058 24/07/2015 24/07/2015 Act. RD01/20513 Entered 10/10/2016 12/10/2016 Act. RD01/24848 Area: Aberdeen Central Completion RD01/24832 Works Order

1 post (Damaged Pedestrian