

From: [Foi Enquiries](#)
To: [REDACTED]
Subject: EIR-17-0556 - Inspection Report - Kirk Brae
Date: 20 April 2017 12:01:06
Attachments: [EIR-17-0556 - Kirk Brae Reports.pdf](#)
[Further Information - Right to Review & Appeal.pdf](#)

Dear [REDACTED]

Please provide inspection reports for Kirk Brae from 15/01/2017 to present and repair orders for the same timescale.

Please see attached reports.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Head of Service level have been redacted (blacked out) from the attached reports. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with 11(3)(a)(i) of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, and the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as ACC considers that disclosure of this information would be a breach of the first Data Protection Principle (that personal information must be processed fairly and lawfully). Third parties and ACC Officers who are below Head of Service level named within the attached documents would not expect ACC to release this information about them into the public domain under the EIRs (or the Freedom of Information (Scotland) Act 2002 (FOISA)).

We hope this helps with your request.

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Yours sincerely,

Information Compliance Team
Communications and Promotion
Office of Chief Executive
Aberdeen City Council
3rd Floor North

Business Hub 17
Marischal College
Broad Street
ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk

01224 523827/523602

Tel 03000 200 292

*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.
Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

Effective: 15/01/2017 to 06/04/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: KIRK BRAE (7600214)

Site: KIRK BRAE (7600214)		Locality: CULTS, ABERDEEN, ABERDEEN CITY				Area: Aberdeen South		
Condition Survey								
Defect No: Description		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: S/22/1404 - KIRKBRAE		Feature Type: RDS Road Section		Area: Aberdeen South		
Batch: 528025 - Inspection Batch				Route: Adhoc Inspection				Date: 20/03/2017
463563	Repair pothole approx' 400 x 400 x 55.	20/03/2017	Adjacent to lamppost number 27.	Pot Hole	Internal		Committed	713654
Batch: 527445 - Inspection Batch				Route: Week: 47 - Area: 22				Date: 13/03/2017
No actionable defects found								
Batch: 525815 - Inspection Batch				Route: Adhoc Inspection				Date: 14/02/2017
462798	Repair pothole approx' 600 x 200 x 65.	14/02/2017	At edge of carriageway outside 91 - 95.	Pot Hole	Internal		Committed	712368
Batch: 525814 - Inspection Batch				Route: Adhoc Inspection				Date: 14/02/2017
462797	Repair pothole approx' 300 x 300 x 60.	14/02/2017	At junction with KIRKBRAE AVENUE.	Pot Hole	Internal		Committed	712367
Batch: 525809 - Inspection Batch				Route: Adhoc Inspection				Date: 14/02/2017
462792	Repair pothole approx' 300 x 300 x 60.	14/02/2017	On Southbound carriageway approx' 40 metres South of junction with LADYHILL ROAD.	Pot Hole	Internal		Committed	712362
Batch: 525808 - Inspection Batch				Route: Adhoc Inspection				Date: 14/02/2017
462791	Repair pothole approx' 600 x 200 x 50.	14/02/2017	At edge of Northbound carriageway approx' 50 metres North of junction with LADYHILL ROAD.	Pot Hole	Internal		Committed	712361
Batch: 525803 - Inspection Batch				Route: Adhoc Inspection				Date: 14/02/2017
462790	Repair pothole approx' 300 x 200 x 60.	14/02/2017	On Northbound carriageway approx' 40 metres South of entrance to COUNTESSWELLS HOUSE.	Pot Hole	Internal		Committed	712360
Batch: 525600 - Inspection Batch				Route: Adhoc Inspection				Date: 13/02/2017
462717	Repair 2 potholes, both approx' 450 x 300 x 55.	13/02/2017	Outside number 83	Pot Hole	Internal		Committed	712276
Batch: 524822 - Inspection Batch				Route: Adhoc Inspection				Date: 01/02/2017
462418	Repair pothole 700'x 600 x 60.	01/02/2017	Adjacent to gully on Southbound carriageway outside house called WOODLEY.	Pot Hole	Internal		Committed	711879
Batch: 523788 - Inspection Batch				Route: Week: 39 - Area: 22				Date: 16/01/2017
No actionable defects found								
Asset:	1,002.00	Asset - Locn.: 1 - Grass verge		Feature Type: RDS Verge		Area: Aberdeen South		
Batch: 527452 - Inspection Batch				Route: Week: 47 - Area: 22				Date: 13/03/2017
No actionable defects found								
Batch: 523789 - Inspection Batch				Route: Week: 39 - Area: 22				Date: 16/01/2017
No actionable defects found								
Asset:	1,009.00	Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen South		
Batch: 527453 - Inspection Batch				Route: Week: 47 - Area: 22				Date: 13/03/2017
No actionable defects found								

Effective: 15/01/2017 to 06/04/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: KIRK BRAE (7600214)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,009.00	Asset - Locn.: 1 - Footway		Feature Type: RDS Footway			Area: Aberdeen South	
Batch:	523790 - Inspection Batch			Route: Week: 39 - Area: 22				Date: 16/01/2017
No actionable defects found								

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1,000.00	Asset - Locn.: S/22/1404 - KIRKBRAE		Feature Type: RDS Road Section			Area: Aberdeen South
64488	loose gully frame (Iron Works)	opposite junction with friarsfield road	.RD 28 Day	Job Cancelled	26/10/2009		
710962	Repair approx' 10 square metres of damaged carriageway surface.	Between junctions with Countesswells Road and Friarsfield Road.	.RD 14 Day	Order Printed	09/01/2017	23/01/2017	Est. RD01/25651
711879	Repair pothole 700'x 600 x 60. (Pot Hole)	Adjacent to gully on Southbound carriageway outside house called WOODLEY.	.RD 2 Day	Contractor Completed	01/02/2017	01/02/2017	Act. RD01/25947
712125	Call-Out 7/2/17 - 18.45 - repaired pothole done by [REDACTED]	100m north of ladyhill	.RD Emergency	Contractor Completed	08/02/2017	07/02/2017	Act.
712256	Find andn Fix 4 potholes repaired by [REDACTED]	o/s 74 , opp ladyhill road jctn, north of 30/40 speed limit signs	.Routine Maintenance	Contractor Completed	10/02/2017	10/02/2017	Act.
712276	Repair 2 potholes, both approx' 450 x 300 x 55. (Pot Hole)	Outside number 83	.RD 2 Day	Contractor Completed	13/02/2017	13/02/2017	Act. RD01/26122
712360	Repair pothole approx' 300 x 200 x 60. (Pot Hole)	On Northbound carriageway approx' 40 metres South of entrance to COUNTESSWELLS HOUSE.	.RD 2 Day	Contractor Completed	14/02/2017	14/02/2017	Act. RD01/26126
712361	Repair pothole approx' 600 x 200 x 50. (Pot Hole)	At edge of Northbound carriageway approx' 50 metres North of junction with LADYHILL ROAD.	.RD 2 Day	Contractor Completed	14/02/2017	14/02/2017	Act. RD01/26126
712362	Repair pothole approx' 300 x 300 x 60. (Pot Hole)	On Southbound carriageway approx' 40 metres South of junction with LADYHILL ROAD.	.RD 2 Day	Contractor Completed	14/02/2017	14/02/2017	Act. RD01/26126
712367	Repair pothole approx' 300 x 300 x 60. (Pot Hole)	At junction with KIRKBRAE AVENUE.	.RD 2 Day	Contractor Completed	14/02/2017	14/02/2017	Act. RD01/26126
712368	Repair pothole approx' 600 x 200 x 65. (Pot Hole)	At edge of carriageway outside 91 - 95.	.RD 2 Day	Contractor Completed	14/02/2017	14/02/2017	Act. RD01/26126
712774	refresh double yellow lines as per [REDACTED]	between 44 and 46 as attached plan	.RD 28 Day	Contractor Completed	23/02/2017	28/02/2017	Act. RD01/26250
713103	Find and Fix 1 pothole filled by [REDACTED]	near jctn with Kirk Place	.Routine Maintenance	Contractor Completed	07/03/2017	06/03/2017	Act.
713270	Repair pothole 1500 x 500 x 60	l/p 26	.RD 2 Day	Contractor Completed	13/03/2017	13/03/2017	Act. RD01/26441
713271	Repair 4 potholes	between Kirk Brae Avenue and Countesswells Road	.RD 2 Day	Contractor Completed	13/03/2017	13/03/2017	Act. RD01/26440
713298	Clean and jet 4 gullies.	Between junction with KIRK PLACE and LADYHILL ROAD.	.RD 28 Day	Contractor Completed	13/03/2017	16/03/2017	Act. RD01/26470
713654	Repair pothole approx' 400 x 400 x 55. (Pot Hole)	Adjacent to lamppost number 27.	.RD 2 Day	Contractor Completed	20/03/2017	20/03/2017	Act. RD01/26622

Effective: 15/01/2017 to 06/04/2017

Contract: Roads Contract (General Maint) (RD01)

Display Action Officer: No

Site: KIRK BRAE (7600214)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		Asset - Locn.: S/22/1404 - KIRKBRAE		Feature Type: RDS Road Section		Area: Aberdeen South	
713855	Find and Fix 1 pothole 1m x 300 x 50 repaired by [REDACTED]	around gully at jctn Friarsfield Road	.Routine Maintenance	Contractor Completed	24/03/2017	23/03/2017	Act.
713972	Find and Fix 8 potholes filled by [REDACTED]	beside ladyhill road	.Routine Maintenance	Contractor Completed	28/03/2017	26/03/2017	Act.
Asset: 1,009.00		Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen South	
64791	area of subsidence approx' 0.25 cubic metres (Pot Hole)	outside number 48 on footway	.RD 7 Day	Job Closed	04/11/2009		

(712125)



ABERDEEN
CITY COUNCIL

Roads Operations
Enterprise, Planning and Infrastructure
Aberdeen City Council
Tulloch Roads Depot
Craigshaw Drive
Aberdeen
AB12 3AL

Incident Report

Date.....7-2-17.....	Location of Incident
Arrived on site...1845.....	KIRKBRIDE @ 100m NORTH OF LADY MILL
Left site.....1900.....	
Incident type	Originator of Callout Message & time received
POTHOLE	RCC 1815
Vehicles / Plant used	Plant Type.....LOKKY..... Plant Number.....4702.....
Material used & quantity (eg sand, Vialix, absorbent granules)	VIALIX X 7 BAGS
Cones / Signs / Barriers used & quantity	N/A
Action Taken & any further action required	FILLED HOLE!
Any other information (eg Vehicle registration number or Police Office number)	N/A

NAME..



SIGNATURE..

