From:	Foi Enquiries
To:	[redacted]
Subject:	EIR-16-0883 - Maintenance Records - Crombie and Sinclair Road
Date:	18 July 2016 10:35:30
Attachments:	Further Information - Right to Review & Appeal.pdf EIR-16-0883 - Crombie Place.pdf EIR-16-0883 - Sinclair Place_Redacted.pdf

---

Dear [redacted],

Thank you for your information request of 6 July 2016. Aberdeen City Council (ACC) has completed the necessary search for the information requested.

Pursuant to the Freedom of Information (Scotland) Act 2002, we make the following request:

- for all maintenance records (including repair and repainting records) covering Sinclair Road and Crombie Place (AB11 9PJ) between 24th November 2014 to 24th May 2016. This is to include all records, logbooks and photographs which are held.

Please see attached site history reports for both roads, as they are recorded as separate inspection locations on our system. We do not hold any photographs of either location during the specified time scale, we also do not keep log books, any information regarding each road is listed under condition survey and maintenance management in the site history reports.

ACC is unable to provide you with information on **logbooks and photographs** as it is not held by the Council. In order to comply with its obligations under the terms of Regulation 10(4)(a) - Information Not Held - of the EIRs, ACC hereby gives notice that this information is not held by it. ACC is required by Regulation 10(1)(b) of the EIRs to inform you as to why in all the circumstances of the case, the public interest in maintaining this exception outweighs the public interest in disclosing this information to you. ACC is satisfied that it does not hold this information and considers that, as there is no information held, the public interest lies with the exception.

Please note that third party names and personal details, as well as the names of ACC Officers who are below Head of Service level have been redacted (blacked out) from the attached Site History Report. This is because ACC considers that this information is excepted from disclosure. In order to comply with its obligations under the terms of Regulation 13 of the EIRs, ACC hereby give notice that we are refusing your request under the terms of Regulation 11(2) in conjunction with INSERT REGULATION of the EIRs.

In making this decision ACC considered the following points:

ACC is of the opinion that Regulation 11(2) applies to the information specified above as the information in question is personal information relating to living individuals, and the applicant is not the data subject.

ACC is of the opinion that Regulation 11(3)(a)(i) applies, as ACC considers that disclosure of this information would be a breach of the first Data Protection Principle (that personal information must be processed fairly and lawfully) and second Data Protection Principle (personal information must only be processed for a specific and lawful purpose).

Third parties named within the attached documents and ACC Officers below Head of Service level would not expect ACC to release this information about them into the public domain under the EIRs (or the Freedom of Information (Scotland) Act 2002 (FOISA)).

We hope this helps with your request.

Yours sincerely,

Grant Webster
Information Compliance Officer

INFORMATION ABOUT THE HANDLING OF YOUR REQUEST

As the information which you requested is environmental information, as defined under Regulation 2(1) of the Environmental Information (Scotland) Regulations 2004 (the EIRs), ACC considered that it was exempt from release through FOISA, and must therefore give you notice that we are refusing your request under Section 39(2) of FOISA (Freedom of Information (Scotland) Act 2002). However, you have a separate right to access the information which you have requested under Regulation 5 of the EIRs, under which ACC has handled your request. Please refer to the attached PDF for more information about your rights under the EIRs.

Information Compliance Team
Communications and Promotion
Office of Chief Executive
Aberdeen City Council
Room 1-24
Town House
Broad Street
ABERDEEN AB10 1AQ

foienquiries@aberdeencity.gov.uk
01224 523827/523602

Tel 03000 200 292

*03000 numbers are free to call if you have 'free minutes' included in your mobile call plan.
Calls from BT landlines will be charged at the local call rate of 10.24p per minute (the same as 01224s).

www.aberdeencity.gov.uk

Effective: 24/11/2014 to 24/05/2016
Site: CROMBIE PLACE (7600194)

Display Action Officer: No

Site: CROMBIE PLACE (7600194) **Locality:** TORRY, ABERDEEN, ABERDEEN CITY **Area:** Aberdeen South

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,000.00	**Asset - Locn.:** S/34/0699 - CROMBIE PLACE			**Feature Type:** RDS Road Section			**Area:** Aberdeen South	
Batch: 501045 - Inspection Batch				**Route:** Week: 04 - Area: 27				**Date:** 23/05/2016
No actionable defects found								
Batch: 494622 - Inspection Batch				**Route:** Week: 40 - Area: 27				**Date:** 03/03/2016
No actionable defects found								
Batch: 487949 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 04/12/2015
No actionable defects found								
Batch: 482886 - Inspection Batch				**Route:** Week: 16 - Area: 27				**Date:** 16/09/2015
No actionable defects found								
Batch: 472447 - Inspection Batch				**Route:** Week: 04 - Area: 27				**Date:** 23/06/2015
No actionable defects found								
Batch: 465454 - Inspection Batch				**Route:** Week: 40 - Area: 27				**Date:** 31/03/2015
No actionable defects found								
Batch: 461520 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 06/03/2015
98459	Pothole500x300x60,3no	06/03/2015	At jct of sinclair rd,at harbour side	Pot Hole	Internal		Archived	191007
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 05/01/2015
No actionable defects found								
Asset: 1,001.00	**Asset - Locn.:** 1 - Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 501047 - Inspection Batch				**Route:** Week: 04 - Area: 27				**Date:** 23/05/2016
No actionable defects found								
Batch: 494623 - Inspection Batch				**Route:** Week: 40 - Area: 27				**Date:** 03/03/2016
No actionable defects found								
Batch: 487950 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 04/12/2015
No actionable defects found								
Batch: 482886 - Inspection Batch				**Route:** Week: 16 - Area: 27				**Date:** 16/09/2015
No actionable defects found								
Batch: 472446 - Inspection Batch				**Route:** Week: 04 - Area: 27				**Date:** 23/06/2015
No actionable defects found								
Batch: 465453 - Inspection Batch				**Route:** Week: 40 - Area: 27				**Date:** 31/03/2015
No actionable defects found								
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 05/01/2015
No actionable defects found								
Asset: 2,001.00	**Asset - Locn.:** Opp LP 4			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455264 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 30/01/2015
No actionable defects found								

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: CROMBIE PLACE (7600194)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,002.00	**Asset - Locn.:** Corner of crombie place & Sinclair road		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch:	455265 - Inspection Batch			**Route:** Adhoc Inspection			**Date:** 30/01/2015	
	No actionable defects found							
Asset:	2,003.00	**Asset - Locn.:** Corner of crombie place & Sinclair road		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch:	455266 - Inspection Batch			**Route:** Adhoc Inspection			**Date:** 30/01/2015	
	No actionable defects found							
Asset:	2,004.00	**Asset - Locn.:** At LP 1		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch:	455267 - Inspection Batch			**Route:** Adhoc Inspection			**Date:** 30/01/2015	
	No actionable defects found							
Asset:	2,005.00	**Asset - Locn.:** Opp LP 1		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch:	455268 - Inspection Batch			**Route:** Adhoc Inspection			**Date:** 30/01/2015	
	No actionable defects found							
Asset:	2,006.00	**Asset - Locn.:** Torry marine base entrance		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch:	455269 - Inspection Batch			**Route:** Adhoc Inspection			**Date:** 30/01/2015	
	No actionable defects found							

Customer Services

Enquiry No.: 655183 **Logged by:** Contact Centre **on:** 22/02/2016 10:08
Service: Street Care & Cleansing **Subject:** Dog Fouling - Priority **Classification:** Enquiry **Enquiry Ref:**
Desc.: would like mess cleared up - ongoing problem with dog fouling in the area of Crombie place and Sinclair place would it be possible to have dog bins can you call on to advise what action we can take he has spoken to environmental health previously
Location: crombie place **Contact:**

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: CROMBIE PLACE (7600194)

Customer Services

Enquiry No.: 647869 **Logged by:** Contact Centre **on:** 09/12/2015 10:06
Service: Street Care & Cleansing **Subject:** Dog Fouling - Priority **Classification:** Enquiry **Enquiry Ref:**
Desc.: PASSED TO BY PHONE
From:
Sent: 08 December 2015 15:13
To: Response
Subject: Dog Fowling

Good Afternoon,

I would like to report the mess on Crombie Place, Torry left by thoughtless dog owners. The pavement is disgusting, I have reported it to the dog warden and they suggested I contact the cleansing dept. I tried to find it on the city council website but got nowhere.
I hope you can do something about the mess.

Kindest Regards,

Please view our website at
Location: CROMBIE PLACE, TORRY - **Contact:**

Enquiry No.: 647294 **Logged by:** Contact Centre **on:** 02/12/2015 14:31
Service: Street Care & Cleansing **Subject:** Dog Fouling - Priority **Classification:** Enquiry **Enquiry Ref:**
Desc.: dog fouling on pavement outside cordiners
Location: 5 crombie place - cy **Contact:**

Enquiry No.: 627590 **Logged by:** Contact Centre **on:** 17/04/2015 09:56
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No: ROADS26388. Site (Street/Park/etc): Crombie Place Torry. Location: junction with Sinclair Road. Locational Details: Opposite side of road. First Type of Fault: Poor Road Surface. First Fault Details: heavy traffic and previous poor repair mean the surface is in extremely poor condition. Name: Address Line 1: Address Line 2: Address Line 3: Postcode: Telephone Number: Email Address:
Location: CROMBIE PLACE, TORRY - ROADS26388 - **Contact:**

Enquiry No.: 625653 **Logged by:** Contact Centre **on:** 24/03/2015 16:16
Service: Street Care & Cleansing **Subject:** Other - Priority Cleansing **Classification:** Enquiry **Enquiry Ref:**
Desc.: can an urgent clean up please be done for crombie place and sinclair road of all rubbish and dog mess- mr advises he has a royal visitor on 25th march and area in a mess can mr please be emailed on and advised asap please or phoned
Location: crombie place-kl **Contact:**

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	**Asset - Locn.:** S/34/0699 - CROMBIE PLACE		**Feature Type:** RDS Road Section		**Area:** Aberdeen South	
157876	Pothole in trench approx 1500x400x55	Near access into Aberdeen Harbour	.Routine Maintenance	Job Cancelled	25/04/2011		
183147	jetpatch,series of ruits and potholes .	at jct with sinclair rd. as you head up from south esp east	.RD 28 Day	Job Cancelled	16/04/2014	17/04/2015 Act.	RD01/7854

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Site: SINCLAIR ROAD (7600814) **Locality:** TORRY, ABERDEEN, ABERDEEN CITY **Area:** Aberdeen South

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,000.00	**Asset - Locn.:** S/34/2101 - SINCLAIR ROAD			**Feature Type:** RDS Road Section			**Area:** Aberdeen South	
Batch: 501082 - Inspection Batch			**Route:** Week: 04 - Area: 27					**Date:** 23/05/2016
No actionable defects found								
Batch: 494673 - Inspection Batch			**Route:** Week: 40 - Area: 27					**Date:** 03/03/2016
No actionable defects found								
Batch: 493119 - Inspection Batch			**Route:** Adhoc Inspection					**Date:** 11/02/2016
455573 2no blocked gullys clean.		11/02/2016	2no blocked gullys, ponding issues.at lampost no 3 to bt green box unit., one on footpath at yellow marked cassie, and gully on road next to green bt box., re opps huttons,	Blocked Gully	Internal		Committed	701386
Batch: 491990 - Inspection Batch			**Route:** Adhoc Inspection					**Date:** 27/01/2016
454981 Blocked gully, clean.		27/01/2016	At lampost 14. 10mtrs west.Old side door ent totrojan crates.	Blocked Gully	Internal		Committed	700659
Batch: 491883 - Inspection Batch			**Route:** Adhoc Inspection					**Date:** 26/01/2016
454957 Blocked gully,clean.		26/01/2016	At lampost no 10, no unit 66.	Blocked Gully	Internal		Committed	700630
Batch: 491390 - Inspection Batch			**Route:** Adhoc Inspection					**Date:** 19/01/2016
454717 Blocked gully on footpath.		19/01/2016	10 mtrs from jct of victoria rd, on footpath outside harbour barbers	Blocked Gully	Internal		Committed	700273
Batch: 487934 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 03/12/2015
No actionable defects found								
Batch: 482886 - Inspection Batch			**Route:** Week: 16 - Area: 27					**Date:** 16/09/2015
No actionable defects found								
Batch: 472677 - Inspection Batch			**Route:** Week: 04 - Area: 27					**Date:** 26/06/2015
No actionable defects found								
Batch: 466018 - Inspection Batch			**Route:** Adhoc Inspection					**Date:** 07/04/2015
99165 Pothole, 600x200x50' filled by inspector		07/04/2015	At trojan crates	Pot Hole	Internal		Committed	192000
Batch: 465414 - Inspection Batch			**Route:** Week: 40 - Area: 27					**Date:** 31/03/2015
No actionable defects found								
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,001.00	**Asset - Locn.:** 1 - Victoria Road-Greyhope Road-Carriageway			**Feature Type:** RDS Carriageway			**Area:** Aberdeen South	
Batch: 501083 - Inspection Batch			**Route:** Week: 04 - Area: 27					**Date:** 23/05/2016
No actionable defects found								
Batch: 494674 - Inspection Batch			**Route:** Week: 40 - Area: 27					**Date:** 03/03/2016
No actionable defects found								
Batch: 487933 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 03/12/2015
No actionable defects found								

Effective: 24/11/2014 to 24/05/2016 Display Action Officer: No
Site: SINCLAIR ROAD (7600814)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,001.00	Asset - Locn.: 1 - Victoria Road-Greyhope Road-Carriageway			Feature Type: RDS Carriageway			Area: Aberdeen South	
Batch: 482886 - Inspection Batch			Route: Week: 16 - Area: 27					Date: 16/09/2015
No actionable defects found								
Batch: 472678 - Inspection Batch			Route: Week: 04 - Area: 27					Date: 26/06/2015
No actionable defects found								
Batch: 465413 - Inspection Batch			Route: Week: 40 - Area: 27					Date: 31/03/2015
No actionable defects found								
Batch: 450893 - Inspection Batch			Route: Week: 28 - Area: 27					Date: 06/01/2015
No actionable defects found								
Asset: 1,002.00	Asset - Locn.: 1 - Victoria Road-27 Sinclair Road-Footway			Feature Type: RDS Footway			Area: Aberdeen South	
Batch: 501084 - Inspection Batch			Route: Week: 04 - Area: 27					Date: 23/05/2016
No actionable defects found								
Batch: 494676 - Inspection Batch			Route: Week: 40 - Area: 27					Date: 03/03/2016
No actionable defects found								
Batch: 487932 - Inspection Batch			Route: Week: 28 - Area: 27					Date: 03/12/2015
No actionable defects found								
Batch: 482886 - Inspection Batch			Route: Week: 16 - Area: 27					Date: 16/09/2015
No actionable defects found								
Batch: 472679 - Inspection Batch			Route: Week: 04 - Area: 27					Date: 26/06/2015
No actionable defects found								
Batch: 465412 - Inspection Batch			Route: Week: 40 - Area: 27					Date: 31/03/2015
No actionable defects found								
Batch: 450893 - Inspection Batch			Route: Week: 28 - Area: 27					Date: 06/01/2015
No actionable defects found								
Asset: 1,003.00	Asset - Locn.: 2 - 37-39 Sinclair Road-Footway			Feature Type: RDS Footway			Area: Aberdeen South	
Batch: 450893 - Inspection Batch			Route: Week: 28 - Area: 27					Date: 06/01/2015
No actionable defects found								
Asset: 1,004.00	Asset - Locn.: 3 - 41 Sinclair Road-Footway			Feature Type: RDS Footway			Area: Aberdeen South	
Batch: 450893 - Inspection Batch			Route: Week: 28 - Area: 27					Date: 06/01/2015
No actionable defects found								
Asset: 1,005.00	Asset - Locn.: 4 - 41 Sinclair Road-Footway			Feature Type: RDS Footway			Area: Aberdeen South	
Batch: 450893 - Inspection Batch			Route: Week: 28 - Area: 27					Date: 06/01/2015
No actionable defects found								
Asset: 1,006.00	Asset - Locn.: 38 - Mansefield Road-Footway			Feature Type: RDS Footway			Area: Aberdeen South	
Batch: 450893 - Inspection Batch			Route: Week: 28 - Area: 27					Date: 06/01/2015
No actionable defects found								

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,007.00	**Asset - Locn.:** 5 - 41 Sinclair Road-Footway		**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch:	450893 - Inspection Batch			**Route:** Week: 28 - Area: 27			**Date:** 06/01/2015	
	No actionable defects found							
Asset:	1,008.00	**Asset - Locn.:** 39 - Mansefield Road-Footway		**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch:	450893 - Inspection Batch			**Route:** Week: 28 - Area: 27			**Date:** 06/01/2015	
	No actionable defects found							
Asset:	1,009.00	**Asset - Locn.:** 6 - Crombie Place, 30 metres West of junction-Footway		**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch:	450893 - Inspection Batch			**Route:** Week: 28 - Area: 27			**Date:** 06/01/2015	
	No actionable defects found							
Asset:	1,010.00	**Asset - Locn.:** 40 - Mansefield Road-Footway		**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch:	450893 - Inspection Batch			**Route:** Week: 28 - Area: 27			**Date:** 06/01/2015	
	No actionable defects found							
Asset:	1,011.00	**Asset - Locn.:** 7 - South Esplanade East/Crombie Place-Footway		**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch:	450893 - Inspection Batch			**Route:** Week: 28 - Area: 27			**Date:** 06/01/2015	
	No actionable defects found							
Asset:	1,012.00	**Asset - Locn.:** 41 - Mansefield Road-Footway		**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch:	450893 - Inspection Batch			**Route:** Week: 28 - Area: 27			**Date:** 06/01/2015	
	No actionable defects found							
Asset:	1,013.00	**Asset - Locn.:** 8 - South Esplanade East/Crombie Place-Footway		**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch:	450893 - Inspection Batch			**Route:** Week: 28 - Area: 27			**Date:** 06/01/2015	
	No actionable defects found							
Asset:	1,014.00	**Asset - Locn.:** 42 - Mansefield Road-Footway		**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch:	450893 - Inspection Batch			**Route:** Week: 28 - Area: 27			**Date:** 06/01/2015	
	No actionable defects found							
Asset:	1,015.00	**Asset - Locn.:** 9 - 72 Sinclair Road, opposite-Mansefield Road, opposite-Footw		**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch:	450893 - Inspection Batch			**Route:** Week: 28 - Area: 27			**Date:** 06/01/2015	
	No actionable defects found							
Asset:	1,016.00	**Asset - Locn.:** 10 - Mansefield Road, opposite-Torry Dock, access-Footway		**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch:	450893 - Inspection Batch			**Route:** Week: 28 - Area: 27			**Date:** 06/01/2015	
	No actionable defects found							
Asset:	1,017.00	**Asset - Locn.:** 11 - Torry Dock, access-Footway		**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch:	459269 - Inspection Batch			**Route:** Adhoc Inspection			**Date:** 18/02/2015	
98134	Pothole 400x400x50, filled by inspector,	18/02/2015	At jct of sinclair pl.	Pot Hole	Internal		Uncommitt	190496
Batch:	450893 - Inspection Batch			**Route:** Week: 28 - Area: 27			**Date:** 06/01/2015	
	No actionable defects found							

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,018.00	**Asset - Locn.:** 12 - Victoria Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,019.00	**Asset - Locn.:** 13 - 10 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,020.00	**Asset - Locn.:** 14 - 27 Sinclair Road, opposite-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,021.00	**Asset - Locn.:** 15 - Timber Yard-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,022.00	**Asset - Locn.:** 16 - Timber Yard-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,023.00	**Asset - Locn.:** 17 - 41 Sinclair Road, opposite-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,024.00	**Asset - Locn.:** 18 - Crombie Place, 25 metres West of junction-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,025.00	**Asset - Locn.:** 19 - Crombie Place-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,026.00	**Asset - Locn.:** 20 - Crombie Place-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,027.00	**Asset - Locn.:** 21 - 66 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,028.00	**Asset - Locn.:** 22 - 68-72 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,029.00	**Asset - Locn.:** 23 - 74 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,030.00	**Asset - Locn.:** 24 - 78-80 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 06/01/2015
No actionable defects found								
Asset: 1,031.00	**Asset - Locn.:** 25 - 78-80 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 06/01/2015
No actionable defects found								
Asset: 1,032.00	**Asset - Locn.:** 26 - 78-80 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 06/01/2015
No actionable defects found								
Asset: 1,033.00	**Asset - Locn.:** 27 - 86-88 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 06/01/2015
No actionable defects found								
Asset: 1,034.00	**Asset - Locn.:** 28 - 88 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 06/01/2015
No actionable defects found								
Asset: 1,035.00	**Asset - Locn.:** 29 - 98 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 06/01/2015
No actionable defects found								
Asset: 1,036.00	**Asset - Locn.:** 30 - 100 Sinclair Road-Mansefield Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 06/01/2015
No actionable defects found								
Asset: 1,037.00	**Asset - Locn.:** 31 - Mansefield Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 06/01/2015
No actionable defects found								
Asset: 1,038.00	**Asset - Locn.:** 32 - 136-140 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 06/01/2015
No actionable defects found								
Asset: 1,039.00	**Asset - Locn.:** 33 - 136-140 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 06/01/2015
No actionable defects found								
Asset: 1,040.00	**Asset - Locn.:** 34 - 136-140 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 06/01/2015
No actionable defects found								
Asset: 1,041.00	**Asset - Locn.:** 35 - 136-140 Sinclair Road-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch				**Route:** Week: 28 - Area: 27				**Date:** 06/01/2015
No actionable defects found								

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,042.00	**Asset - Locn.:** 36 - Mansefield Road, 85 metres East of junction-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 1,043.00	**Asset - Locn.:** 37 - Mansefield Road, 100 metres East of junction-Footway			**Feature Type:** RDS Footway			**Area:** Aberdeen South	
Batch: 450893 - Inspection Batch			**Route:** Week: 28 - Area: 27					**Date:** 06/01/2015
No actionable defects found								
Asset: 2,001.00	**Asset - Locn.:** Outside no. 170			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000709 - Inspection Batch			**Route:** Adhoc Inspection Route					**Date:** 27/01/2015
No actionable defects found								
Asset: 2,002.00	**Asset - Locn.:** Opp no. 170			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000710 - Inspection Batch			**Route:** Adhoc Inspection Route					**Date:** 27/01/2015
No actionable defects found								
Asset: 2,003.00	**Asset - Locn.:** Near LP 24			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000711 - Inspection Batch			**Route:** Adhoc Inspection Route					**Date:** 27/01/2015
No actionable defects found								
Asset: 2,004.00	**Asset - Locn.:** Opp LP 24			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000712 - Inspection Batch			**Route:** Adhoc Inspection Route					**Date:** 27/01/2015
No actionable defects found								
Asset: 2,005.00	**Asset - Locn.:** Opp LP 24			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000713 - Inspection Batch			**Route:** Adhoc Inspection Route					**Date:** 27/01/2015
No actionable defects found								
Asset: 2,006.00	**Asset - Locn.:** Near LP 24			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000714 - Inspection Batch			**Route:** Adhoc Inspection Route					**Date:** 27/01/2015
No actionable defects found								
Asset: 2,007.00	**Asset - Locn.:** Opp LP 23			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000742 - Inspection Batch			**Route:** Adhoc Inspection Route					**Date:** 27/01/2015
No actionable defects found								
Asset: 2,008.00	**Asset - Locn.:** Opp LP 23			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000743 - Inspection Batch			**Route:** Adhoc Inspection Route					**Date:** 27/01/2015
No actionable defects found								
Asset: 2,009.00	**Asset - Locn.:** Opp LP 23			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000744 - Inspection Batch			**Route:** Adhoc Inspection Route					**Date:** 27/01/2015
No actionable defects found								
Asset: 2,010.00	**Asset - Locn.:**			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000745 - Inspection Batch			**Route:** Adhoc Inspection Route					**Date:** 27/01/2015
No actionable defects found								

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 2,011.00	**Asset - Locn.:**			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000746 - Inspection Batch				**Route:** Adhoc Inspection Route			**Date:** 27/01/2015	
No actionable defects found								
Asset: 2,012.00	**Asset - Locn.:** Opp Briggs yard			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000747 - Inspection Batch				**Route:** Adhoc Inspection Route			**Date:** 27/01/2015	
No actionable defects found								
Asset: 2,013.00	**Asset - Locn.:** Opp Churchill drilling tools car park			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000748 - Inspection Batch				**Route:** Adhoc Inspection Route			**Date:** 27/01/2015	
No actionable defects found								
Asset: 2,014.00	**Asset - Locn.:** Opp Churchill drilling tools car park			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000749 - Inspection Batch				**Route:** Adhoc Inspection Route			**Date:** 27/01/2015	
No actionable defects found								
Asset: 2,015.00	**Asset - Locn.:** Opp lighthouse			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000750 - Inspection Batch				**Route:** Adhoc Inspection Route			**Date:** 27/01/2015	
No actionable defects found								
Asset: 2,016.00	**Asset - Locn.:** Opp Briggs pollution response base			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000751 - Inspection Batch				**Route:** Adhoc Inspection Route			**Date:** 27/01/2015	
No actionable defects found								
Asset: 2,017.00	**Asset - Locn.:** Opp G. B. England garage services			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000752 - Inspection Batch				**Route:** Adhoc Inspection Route			**Date:** 27/01/2015	
No actionable defects found								
Asset: 2,018.00	**Asset - Locn.:** Opp G. B. England garage services			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000753 - Inspection Batch				**Route:** Adhoc Inspection Route			**Date:** 27/01/2015	
No actionable defects found								
Asset: 2,019.00	**Asset - Locn.:** At corner of Sinclair Rd & Mansefield Rd			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 3000754 - Inspection Batch				**Route:** Adhoc Inspection Route			**Date:** 27/01/2015	
No actionable defects found								
Asset: 2,020.00	**Asset - Locn.:** Opp LP 15			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455307 - Inspection Batch				**Route:** Adhoc Inspection			**Date:** 02/02/2015	
No actionable defects found								
Asset: 2,021.00	**Asset - Locn.:** At LP 15			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455308 - Inspection Batch				**Route:** Adhoc Inspection			**Date:** 02/02/2015	
No actionable defects found								
Asset: 2,022.00	**Asset - Locn.:** Opp LP 15			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455309 - Inspection Batch				**Route:** Adhoc Inspection			**Date:** 02/02/2015	
No actionable defects found								

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,023.00	**Asset - Locn.:** Opp LP 15		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455310 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset:	2,024.00	**Asset - Locn.:** Near LP 15		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455313 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset:	2,025.00	**Asset - Locn.:** Opp LP 14		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455320 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset:	2,026.00	**Asset - Locn.:** At LP 14		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455321 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset:	2,027.00	**Asset - Locn.:** Near LP 14		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455322 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset:	2,028.00	**Asset - Locn.:** Outside no. 92-98		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455324 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset:	2,029.00	**Asset - Locn.:** Opp no. 92-98		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455325 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset:	2,030.00	**Asset - Locn.:** At LP 13		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455326 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset:	2,031.00	**Asset - Locn.:** Opp LP 13		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455328 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset:	2,032.00	**Asset - Locn.:** Outside no. 88		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455329 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset:	2,033.00	**Asset - Locn.:** Opp no. 88		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455330 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset:	2,034.00	**Asset - Locn.:** Opp no. 86		**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455331 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								

Effective: 24/11/2014 to 24/05/2016 Display Action Officer: No
Site: SINCLAIR ROAD (7600814)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,035.00	Asset - Locn.: Near LP 12		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455343 - Inspection Batch			Route: Adhoc Inspection				Date: 02/02/2015
	No actionable defects found							
Asset:	2,036.00	Asset - Locn.: At LP 12		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455355 - Inspection Batch			Route: Adhoc Inspection				Date: 02/02/2015
	No actionable defects found							
Asset:	2,037.00	Asset - Locn.: Opp LP 12		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455360 - Inspection Batch			Route: Adhoc Inspection				Date: 02/02/2015
	No actionable defects found							
Asset:	2,038.00	Asset - Locn.: Opp John Ross Jr.		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455361 - Inspection Batch			Route: Adhoc Inspection				Date: 02/02/2015
	No actionable defects found							
Asset:	2,039.00	Asset - Locn.: Outside john Ross jr		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455362 - Inspection Batch			Route: Adhoc Inspection				Date: 02/02/2015
	No actionable defects found							
Asset:	2,040.00	Asset - Locn.: Outside John Ross Jr		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455363 - Inspection Batch			Route: Adhoc Inspection				Date: 02/02/2015
	No actionable defects found							
Asset:	2,041.00	Asset - Locn.: At LP 11		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455364 - Inspection Batch			Route: Adhoc Inspection				Date: 02/02/2015
	No actionable defects found							
Asset:	2,042.00	Asset - Locn.: Opp LP 11		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455365 - Inspection Batch			Route: Adhoc Inspection				Date: 02/02/2015
	No actionable defects found							
Asset:	2,043.00	Asset - Locn.: Opp LP 11		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455366 - Inspection Batch			Route: Adhoc Inspection				Date: 02/02/2015
	No actionable defects found							
Asset:	2,044.00	Asset - Locn.: At LP 11		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455367 - Inspection Batch			Route: Adhoc Inspection				Date: 02/02/2015
	No actionable defects found							
Asset:	2,045.00	Asset - Locn.: Outside no. 74		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455368 - Inspection Batch			Route: Adhoc Inspection				Date: 02/02/2015
	No actionable defects found							
Asset:	2,046.00	Asset - Locn.: Opp no. 74		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455369 - Inspection Batch			Route: Adhoc Inspection				Date: 02/02/2015
	No actionable defects found							

Effective: 24/11/2014 to 24/05/2016 Display Action Officer: No
Site: SINCLAIR ROAD (7600814)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,047.00	Asset - Locn.: Outside no. 72		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455370 - Inspection Batch			Route: Adhoc Inspection			Date: 02/02/2015	
	No actionable defects found							
Asset:	2,048.00	Asset - Locn.: Opp no. 72		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455371 - Inspection Batch			Route: Adhoc Inspection			Date: 02/02/2015	
	No actionable defects found							
Asset:	2,049.00	Asset - Locn.: Opp LP 10		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455372 - Inspection Batch			Route: Adhoc Inspection			Date: 02/02/2015	
	No actionable defects found							
Asset:	2,050.00	Asset - Locn.: Opp no. 99		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455373 - Inspection Batch			Route: Adhoc Inspection			Date: 02/02/2015	
	No actionable defects found							
Asset:	2,051.00	Asset - Locn.: At LP 9		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455375 - Inspection Batch			Route: Adhoc Inspection			Date: 02/02/2015	
	No actionable defects found							
Asset:	2,052.00	Asset - Locn.: Opp LP 9		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455379 - Inspection Batch			Route: Adhoc Inspection			Date: 02/02/2015	
	No actionable defects found							
Asset:	2,053.00	Asset - Locn.: Opp cordiners		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455423 - Inspection Batch			Route: Adhoc Inspection			Date: 02/02/2015	
	No actionable defects found							
Asset:	2,054.00	Asset - Locn.: Outside cordiners		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455424 - Inspection Batch			Route: Adhoc Inspection			Date: 02/02/2015	
	No actionable defects found							
Asset:	2,055.00	Asset - Locn.: Opp LP 8		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455426 - Inspection Batch			Route: Adhoc Inspection			Date: 02/02/2015	
	No actionable defects found							
Asset:	2,056.00	Asset - Locn.: At LP 8		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455434 - Inspection Batch			Route: Adhoc Inspection			Date: 02/02/2015	
	No actionable defects found							
Asset:	2,057.00	Asset - Locn.: Outside cordiners		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455435 - Inspection Batch			Route: Adhoc Inspection			Date: 02/02/2015	
	No actionable defects found							
Asset:	2,058.00	Asset - Locn.: Near LP 8		Feature Type: RDS Gully			Area: Aberdeen South	
Batch:	455436 - Inspection Batch			Route: Adhoc Inspection			Date: 02/02/2015	
	No actionable defects found							

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 2,059.00	**Asset - Locn.:** Outside Joseph Robertson			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455437 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,060.00	**Asset - Locn.:** Opp LP 7			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455438 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,061.00	**Asset - Locn.:** At LP 7			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455439 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,062.00	**Asset - Locn.:** Opp LP 7			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455440 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,063.00	**Asset - Locn.:** At LP 7			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455443 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,064.00	**Asset - Locn.:** Opp James cordiner			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455458 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,065.00	**Asset - Locn.:** Opp LP 6			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455459 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,066.00	**Asset - Locn.:** Opp LP 6			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455460 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,067.00	**Asset - Locn.:** Opp cordiners wood mill			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455461 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,068.00	**Asset - Locn.:** Opp cordiners wood mill			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455462 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,069.00	**Asset - Locn.:** Opp cordiners wood mill			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455463 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,070.00	**Asset - Locn.:** At LP 5			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455464 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 2,071.00	**Asset - Locn.:** At LP 5			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455465 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,072.00	**Asset - Locn.:** Outside no. 31			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455466 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,073.00	**Asset - Locn.:** Opp LP 4			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455467 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,074.00	**Asset - Locn.:** At LP 3			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455471 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,075.00	**Asset - Locn.:** Opp Hutton's			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455486 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,076.00	**Asset - Locn.:** Opp LP 2			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455489 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,077.00	**Asset - Locn.:** Opp LP 2			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455490 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,078.00	**Asset - Locn.:** Opp LP 2			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455491 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,079.00	**Asset - Locn.:** At LP 1			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455492 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,080.00	**Asset - Locn.:** At LP 1			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455493 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,081.00	**Asset - Locn.:** Opp Taylor's			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455494 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								
Asset: 2,082.00	**Asset - Locn.:** Opp LP 1			**Feature Type:** RDS Gully			**Area:** Aberdeen South	
Batch: 455495 - Inspection Batch				**Route:** Adhoc Inspection				**Date:** 02/02/2015
No actionable defects found								

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.

Asset: 2,083.00 **Asset - Locn.:** Opp gents cut & go **Feature Type:** RDS Gully **Area:** Aberdeen South
Batch: 455496 - Inspection Batch **Route:** Adhoc Inspection **Date:** 02/02/2015
No actionable defects found

Asset: 2,084.00 **Asset - Locn.:** At LP 2 **Feature Type:** RDS Gully **Area:** Aberdeen South
Batch: 455497 - Inspection Batch **Route:** Adhoc Inspection **Date:** 02/02/2015
No actionable defects found

Asset: 2,085.00 **Asset - Locn.:** Outside no. 1 **Feature Type:** RDS Gully **Area:** Aberdeen South
Batch: 455502 - Inspection Batch **Route:** Adhoc Inspection **Date:** 02/02/2015
No actionable defects found

Customer Services

Enquiry No.: 1025874 **Logged by:** **on:** 25/04/2016 15:20
Service: Waste Collection **Subject:** Flytipping **Classification:** Enquiry
Desc.: uplift: old furniture
Location: Sinclair Road, Torry **Contact:** WasteAndRecycling FLY1
Plot Number: 100,011.00 **Feature Id - Location:** 9051081270 - 6 SINCLAIR ROAD, TORRY, **Feature Type:** W - Domestic Waste Property
Job Number: 10079871

Enquiry No.: 1023682 **Logged by:** **on:** 21/03/2016 16:13
Service: Waste Collection **Subject:** Flytipping - Housing White Goo **Classification:** Enquiry
Desc.: UPLIFT: OLD FRIDGE AT BIN AREA
Location: Sinclair Road Torry **Contact:** ACC
Plot Number: 100,009.00 **Feature Id - Location:** 9051119979 SINCLAIR ROAD, TORRY, AB11 9PN **Feature Type:** W - Domestic Waste Property
Job Number: 10077425

Enquiry No.: 1022692 **Logged by:** **on:** 07/03/2016 12:58
Service: Waste Collection **Subject:** Flytipping **Classification:** Enquiry
Desc.: uplift: SOFA AT NO 6 ON PAVEMENT
Location: SINCLAIR ROAD **Contact:** WasteAndRecycling FLY1
Plot Number: 100,011.00 **Feature Id - Location:** 9051081270 - SINCLAIR ROAD, TORRY, **Feature Type:** W - Domestic Waste Property
Job Number: 10076344

Enquiry No.: 1022620 **Logged by:** Marian Blanco **on:** 04/03/2016 15:32
Service: Waste Collection **Subject:** Fw:Flytipping - White Goods **Classification:** Enquiry
Desc.: UPLIFT: 1X SMALL FRIDGE OUTSIDE 6
Location: SINCLAIR ROAD **Contact:** WasteAndRecycling FLY1
Plot Number: 100,011.00 **Feature Id - Location:** 9051081270 - SINCLAIR ROAD, TORRY, **Feature Type:** W - Domestic Waste Property
Job Number: 10076265

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Customer Services

Enquiry No.: 1013512 **Logged by:** **on:** 28/09/2015 12:58
Service: Waste Collection **Subject:** Flytipping **Classification:** Enquiry
Desc.: UPLIFT: 1X TV 1X CHAIR OPP HAIR CARE
Location: SINCLAIR ROAD OPP HAIR CARE **Contact:**
Plot Number: 100,028.00 **Feature Id - Location:** 9051081014 - 10 SINCLAIR ROAD, TORRY, AB11 9PN **Feature Type:** W - Commercial Waste Property
Job Number: 10066216

Enquiry No.: 1003018 **Logged by:** **on:** 08/04/2015 16:21
Service: Waste Collection **Subject:** Flytipping **Classification:** Enquiry
Desc.: uplift:TV BY BINS NEXT TO TAYLORS OFF LICENCE
Location: 1-170 SINCLAIR ROAD NEXT TO THE TAYLOR OFF LICENCE **Contact:** FLY1
Plot Number: 100,047.00 **Feature Id - Location:** 9051095410 - 82 - 84 SINCLAIR ROAD, TORRY, AB11 9PP **Feature Type:** W - Domestic Waste Property
Job Number: 10054959

Enquiry No.: 1002910 **Logged by:** **on:** 07/04/2015 14:55
Service: Waste Collection **Subject:** Flytipping **Classification:** Enquiry
Desc.: UPLIFT: TV BY HOUSEHOLD BIN AT TAYLORS
Location: 2-167 SINCLAIR ROAD AT TAYLORS **Contact:** FLY1
Plot Number: 100,047.00 **Feature Id - Location:** 9051095410 - 82 - 84 SINCLAIR ROAD, TORRY, AB11 9PP **Feature Type:** W - Domestic Waste Property
Job Number: 10054845

Enquiry No.: 1002691 **Logged by:** **on:** 02/04/2015 14:29
Service: Waste Collection **Subject:** Flytipping **Classification:** Enquiry
Desc.: Uplift: tv by No 8
Location: 8 Sinclair Road **Contact:** FLY1
Plot Number: 100,020.00 **Feature Id - Location:** 9051080945 - 8 SINCLAIR ROAD, TORRY, AB11 9PL **Feature Type:** W - Commercial Waste Property
Job Number: 10054607

Enquiry No.: 662974 **Logged by:** Contact Centre **on:** 20/05/2016 16:17
Service: Waste Collection **Subject:** Missed Bin **Classification:** Enquiry **Enquiry Ref:**
Desc.: "MISSED BIN COLLECTION" Premises will be open from 9.00-12.30 21/05
Location: **Contact:**

Enquiry No.: 662859 **Logged by:** Contact Centre **on:** 19/05/2016 11:47
Service: Street Care & Cleansing **Subject:** Dog Bins **Classification:** Enquiry **Enquiry Ref:**
Desc.: Caller would like a dog bin installed in the vicinity of their premises. They have a long running issue with dog fouling in the area. Could someone give them a call back on to discuss whether this will be possible - AD
Location: SINCLAIR ROAD **Contact:**

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Customer Services

Enquiry No.: 660993 **Logged by:** Contact Centre **on:** 26/04/2016 22:09
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: FAO : ACC Roads Response service,

Reference No : PATHS17310
Site (Street/Park/etc) : Sinclair Road
Location : gate leading to a car park for Crombie Court
Locational Details : At rear of house
First Type of Fault : Other
First Fault Details : cars duble parked
Second Type of Fault : Public Utility Reinstatement
Second Fault Details : cars parked very narrow at gate for car park Crombie Court
Additional Information : when getting out from the car park driver can't see oncoming vehicles, very dangerous for people with kids. if possible please add double yellow lines so no one can park there.

Name :
Telephone Number
Location: Sinclair Road **Contact:**

Enquiry No.: 660137 **Logged by:** Contact Centre **on:** 17/04/2016 02:01
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: PATHS17300
Site (Street/Park/etc) : Sinclair Road, Torry
Location : 5/7
Locational Details : In front of house
First Type of Fault : Other
First Fault Details : Blocked drain in pavement causing flooding
Location: Sinclair Road, Torry 5/7 **Contact:**

Enquiry No.: 659812 **Logged by:** Contact Centre **on:** 13/04/2016 09:30
Service: Graffiti **Subject:** Graffiti Request Private Work **Classification:** Enquiry **Enquiry Ref:**
Desc.: Reference No: GRAFFITI3059. Site (Street/Park/etc): Sinclair Road Torry. Location: 4/6. Locational Details: In front of house. First Type of Concern: Graffiti. First Concern Details: on green junction box. Name: . Email Address:
Location: SINCLAIR ROAD, TORRY - GRAFFITI3059 - **Contact:**

Enquiry No.: 657020 **Logged by:** Contact Centre **on:** 12/03/2016 23:31
Service: Street Lighting **Subject:** Light Out **Classification:** Enquiry **Enquiry Ref:**
Desc.: FAO : ACC Lighting service,

Reference No : LIGHTS31321
Site (Street/Park/etc) : Sinclair Road, Torry
Location : column 12
First Type of Fault : Lamp Out
Name :
Email Address :
Location: **Contact:**

Plot Number: 10,011.00 **Feature Id - Location:** 12 - AT 84 **Feature Type:** SL - Street Lamp
Job Number: 528190

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Customer Services

Enquiry No.: 656775 **Logged by:** Contact Centre **on:** 09/03/2016 16:21
Service: Waste Collection **Subject:** Missed Bin **Classification:** Enquiry **Enquiry Ref:**
Desc.: BULK BINS SUPPOSED TO BE EMMPTIED MONDAY/WEDNESDAY/FRIDAY BUT THERE HAS BEEN NO COLLECTION FOR OVER A WEEK. PLEASE GO AS SOON AS POSSIBLE. ANY PROBLEMS CONTACT
Location: SINCLAIR ROAD **Contact:**

Enquiry No.: 655827 **Logged by:** Contact Centre **on:** 29/02/2016 13:46
Service: Waste Collection **Subject:** Waste Other **Classification:** Enquiry **Enquiry Ref:**
Desc.: COMPANY REQUESTS COSTS FOR WEEKLY UPLIFT GLASS,GENERAL, FOOD WASTE ETC. RETURN CALL TO DISCUSS-- TEL
Location: SINCLAIR ROAD **Contact:**

Enquiry No.: 654407 **Logged by:** Contact Centre **on:** 12/02/2016 15:48
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.:
Location: Road splitting and part being washed away by high tide. **Contact:**

Enquiry No.: 652527 **Logged by:** Contact Centre **on:** 27/01/2016 12:04
Service: Street Lighting **Subject:** Light Out **Classification:** Enquiry **Enquiry Ref:**
Desc.: Reference No: LIGHTS30759. Site (Street/Park/etc): Sinclair Road, Torry. Location: column 12. First Type of Fault: Flickering Lamp. Name: . Email Address:
Location: Lamp No.12, SINCLAIR ROAD, TORRY - LIGHTS30759 - AB **Contact:**
Plot Number: 10,011.00 **Feature Id - Location:** 12 - AT 84 **Feature Type:** SL - Street Lamp
Job Number: 526526

Enquiry No.: 652518 **Logged by:** Contact Centre **on:** 27/01/2016 11:31
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No : DRAINAGE15497
Site (Street/Park/etc) : Sinclair Road, Torry
Location : junct with crombie place
First Type of Fault : Blocked Gully
Additional Information : in front of car park
Location: Sinclair Road - ST **Contact:**

Enquiry No.: 652462 **Logged by:** Contact Centre **on:** 27/01/2016 05:24
Service: Drainage **Subject:** Blocked Gully **Classification:** Service Requested **Enquiry Ref:**
Desc.: Reference No : DRAINAGE15493
Site (Street/Park/etc) : Sinclair Road, Torry
Location : adj to column 14
First Type of Fault : Blocked Gully
Location: Sinclair Road, Torry **Contact:**
Plot Number: 1,000.00 **Feature Id - Location:** S/34/2101 - SINCLAIR ROAD **Feature Type:** RDS Road Section
Job Number: 700659

Enquiry No.: 652375 **Logged by:** Contact Centre **on:** 26/01/2016 12:09
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: DRAINAGE15488 - BLOCKED GULLY IN FRONT OF FISH HOUSE - REF COLUMN 10. LK
Location: sinclair road **Contact:**
Plot Number: 1,000.00 **Feature Id - Location:** S/34/2101 - SINCLAIR ROAD **Feature Type:** RDS Road Section
Job Number: 700630

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Customer Services

Enquiry No.: 652306 **Logged by:** Contact Centre **on:** 26/01/2016 04:14
Service: Drainage **Subject:** Blocked Gully **Classification:** Service Requested **Enquiry Ref:**
Desc.: FAO : ACC Lighting service,

Reference No : LIGHTS30723
Site (Street/Park/etc) : Ashwood Road
Location : opposite number 20
Locational Details : Opposite side of road
First Type of Fault : Lamp Out
Second Type of Fault : Lamp Out
Additional Information : One lamp been out for a few weeks.

Name :
Telephone Number :
Email Address :

Location: **Contact:**

Enquiry No.: 652015 **Logged by:** Contact Centre **on:** 22/01/2016 11:18
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Caller reports that there is a blocked gully outside their business and the water level is raising to the point in which it is almost flooding them. Passed to Roads by phone - /
Location: SINCLAIR ROAD **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** S/34/2101 - SINCLAIR ROAD **Feature Type:** RDS Road Section
Job Number: 700273

Enquiry No.: 651377 **Logged by:** Contact Centre **on:** 18/01/2016 00:42
Service: Street Lighting **Subject:** Light Out **Classification:** Enquiry **Enquiry Ref:**
Desc.: Reference No : LIGHTS30587
Site (Street/Park/etc) : Sinclair Road, Torry
Location : column 12
First Type of Fault : Lamp Out
Name :
Email Address :
Location: sinclair road **Contact:**

Plot Number: 10,011.00 **Feature Id - Location:** 12 - AT 84 **Feature Type:** SL - Street Lamp
Job Number: 526526

Enquiry No.: 651091 **Logged by:** Contact Centre **on:** 14/01/2016 12:49
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: BLOCKED GULLY ON THE ROAD OUTSIDE THE PROPERTY . THANK YOU
Location: SINCLAIR ROAD - BLOCKED GULLY - **Contact:**

Enquiry No.: 649963 **Logged by:** Contact Centre **on:** 07/01/2016 09:23
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: THERE IS A LARGE PUDDLE ON THE ROAD AND THE PAVEMENT OUTSIDE THE HAIRDRESSERS ON SINCLAIR ROAD.
Location: SINCLAIR ROAD AT THE **Contact:**

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Customer Services

Enquiry No.: 645092 **Logged by:** Contact Centre **on:** 10/11/2015 08:12
Service: Waste Collection **Subject:** Contract Query - WC **Classification:** Enquiry **Enquiry Ref:**
Desc.: Mrs will be taking over r on 170 Sinclair Road approx. 1 12 2015.
She would like costings for collection of general waste, glass bottles and tins.
Her contact number is [redacted]
Can someone contact her to advise.

cheers

Location: sinclair road **Contact:**

Enquiry No.: 643416 **Logged by:** Contact Centre **on:** 21/10/2015 13:28
Service: Waste Collection **Subject:** Contract Query - WC **Classification:** Enquiry **Enquiry Ref:**
Desc.: Caller is taking over this business and would like the name in the waste collection contract changed to their own. Could someone give them a call back to help them with this on thanks -
Location: SINCLAIR ROAD **Contact:**

Enquiry No.: 639650 **Logged by:** Contact Centre **on:** 08/09/2015 11:42
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No: DRAINAGE15292. Site (Street/Park/etc): sinclair Road, Torry. Location: in front of entrance of Robertson factory. First Type of Fault: Blocked Gully. Name: . Email Address:
Location: SINCLAIR ROAD, TORRY - DRAINAGE15292 - **Contact:** David Fryer

Plot Number: 1,000.00 **Feature Id - Location:** S/34/2101 - SINCLAIR ROAD **Feature Type:** RDS Road Section
Job Number: 190871

Enquiry No.: 639648 **Logged by:** Contact Centre **on:** 08/09/2015 11:41
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Reference No: DRAINAGE15291. Site (Street/Park/etc): sinclair Road, Torry. Location: junct with crombie place. First Type of Fault: Blocked Gully. Name: . Email Address:
Location: SINCLAIR ROAD, TORRY - DRAINAGE15291 - **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** S/34/2101 - SINCLAIR ROAD **Feature Type:** RDS Road Section
Job Number: 193660

Enquiry No.: 634695 **Logged by:** Contact Centre **on:** 17/07/2015 09:07
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Blocked gullies outside - water is coming down into shops.
Location: Sinclair Road - EG **Contact:**

Enquiry No.: 634565 **Logged by:** Contact Centre **on:** 15/07/2015 16:00
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: Blocked gully in yard has previously been cleared by council, would we clear but charge for work done? Please contact to arrange.
Location: Sinclair Road - **Contact:**

Enquiry No.: 633649 **Logged by:** Contact Centre **on:** 03/07/2015 11:17
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: BLOCKED GULLYS BOTH SIDES OF STREET - AT JUNCTION AND FURTHER ALONG THE STREET - THANKS
Location: SINCLAIR ROAD AT JUNCTION **Contact:**

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Customer Services

Enquiry No.: 632025 **Logged by:** Contact Centre **on:** 16/06/2015 09:12
Service: Street Care & Cleansing **Subject:** Discarded Needles **Classification:** Enquiry **Enquiry Ref:**
Desc.: A MEMBER OF THE PUBLIC HAS PICKED UP A BUNCH OF NEEDLES LEFT ON THE STREET ON SINCLAIR ROAD AND ASKED CORDINERS TIMBER IF THEY HAD A BOX THEY COULD BE PUT IN. SO THE NEEDLES ARE NOW IN A BOX AT CORDINERS TIMBER RECEPTION.TEL: COULD THEY BE PICKED UP AND DISPOSED OF PLEASE. ASK FOR OR = REQUIRED.

CHEERS

Location: SINCLAIR ROAD TORRY. **Contact:** ANON JUN 10 ANON JUN 10

Enquiry No.: 629132 **Logged by:** Contact Centre **on:** 07/05/2015 18:00
Service: Roads **Subject:** General Enquiry **Classification:** Defect Report **Enquiry Ref:**
Desc.: - incident : of – advised that people have moved the cones and signage and are using the closed road - road closed for resurfacing -- email also sent to roads -
Location: SINCLAIR ROAD - closed section - **Contact:**

Enquiry No.: 618976 **Logged by:** Contact Centre **on:** 09/01/2015 11:37
Service: Waste Collection **Subject:** Contract Query - WC **Classification:** Enquiry **Enquiry Ref:**
Desc.: DCA PLEASE RING ON AABOUT INCREASING THIER BIN UPLIFT. THEY CURRENTLY HAVE ONE BIN AND REQUEST THEY HAVE TWO.
Location: SINCLAIR ROAD **Contact:**

Enquiry No.: 349160 **Logged by:** **on:** 23/02/2015 15:34
Service: Waste Collection **Subject:** Fw:Flytipping - White Goods **Classification:** Enquiry
Desc.: UPLIFT: 1X FREDGE
Location: 1 SINCLAIR ROAD AT BIN AREA **Contact:** FLY1
Plot Number: 100,057.00 **Feature Id - Location:** 9051123169 - 110 SINCLAIR ROAD, TORRY, AB11 9PR **Feature Type:** W - Domestic Waste Property
Job Number: 10050957

Enquiry No.: 349159 **Logged by:** **on:** 23/02/2015 15:31
Service: Waste Collection **Subject:** Flytipping **Classification:** Enquiry
Desc.: uplift: sofa bed bed side table carpets chairs by waste bins outside 107
Location: SINCLAIR ROAD **Contact:** FLY1
Plot Number: 100,057.00 **Feature Id - Location:** 9051123169 - 110 SINCLAIR ROAD, TORRY, AB11 9PR **Feature Type:** W - Domestic Waste Property
Job Number: 10050956

Enquiry No.: 347857 **Logged by:** **on:** 02/02/2015 12:24
Service: Waste Collection **Subject:** Flytipping **Classification:** Enquiry
Desc.: UPLIFT: mattress outside 41
Location: .. SINCLAIR ROAD **Contact:** FLY1
Plot Number: 100,035.00 **Feature Id - Location:** 9051121572 - 41 SINCLAIR ROAD, TORRY, AB11 9PL **Feature Type:** W - Commercial Waste Property
Job Number: 10049580

Enquiry No.: 347856 **Logged by:** **on:** 02/02/2015 12:23
Service: Waste Collection **Subject:** Flytipping **Classification:** Enquiry
Desc.: UPLIFT: mattress by bins outside 89
Location: SINCLAIR ROAD **Contact:** FLY1
Plot Number: 100,049.00 **Feature Id - Location:** 9051095202 SINCLAIR ROAD, TORRY, AB11 9PP **Feature Type:** W - Domestic Waste Property
Job Number: 10049579

Effective: 24/11/2014 to 24/05/2016 **Display Action Officer:** No
Site: SINCLAIR ROAD (7600814)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,000.00		**Asset - Locn.:** S/34/2101 - SINCLAIR ROAD		**Feature Type:** RDS Road Section		**Area:** Aberdeen South	
69012	Pothole,300 x 300 x 60 (Pot Hole)	Crombie place	.RD 14 Day	Job Closed	19/04/2010		
188643	blocked gully, clean, full to the brim of debris.	lpno 5.at larder sandwiches and robertsons buildings.	.RD 7 Day	Job Closed	20/11/2014	23/11/2014 Act.	RD01/9019
190871	clean and jet all gullies	from jctn with Victoria Road to its jctn with Greyhope Road	.RD 14 Day	Contractor Completed	27/02/2015	22/03/2015 Act.	RD01/9520
192000	Pothole, 600x200x50' filled by inspector (Pot Hole)	At trojan crates	.RD 2 Day	Contractor Completed	07/04/2015	07/04/2015 Act.	RD01/9766
193660	blocked gullys, clean.4no.	south side premier fixings 10yds east of lp 10, north side lp no 3 next to green box, opps lp 6 ,opps lp 18	.RD 14 Day	Order Printed	22/05/2015	05/06/2015 Est.	RD01/20086
197750	Find and fix 2 potholes by L Basnell and S Hadden	unknown	.Routine Maintenance	Contractor Completed	27/10/2015	03/10/2015 Act.	
700273	Blocked gully on footpath. (Blocked Gully)	10 mtrs from jct of victoria rd, on footpath outside harbour barbers	.RD 7 Day	Contractor Completed	19/01/2016	23/01/2016 Act.	RD01/21964
700630	Blocked gully,clean. (Blocked Gully)	At lampost no 10, no unit 66.	.RD 7 Day	Contractor Completed	26/01/2016	12/03/2016 Act.	RD01/22438
700659	Blocked gully, clean. (Blocked Gully)	At lampost 14. 10mtrs west.Old side door ent totrojan crates.	.RD 7 Day	Contractor Completed	27/01/2016	16/02/2016 Act.	RD01/22038
701386	2no blocked gullys clean. (Blocked Gully)	2no blocked gullys, ponding issues.at lampost no 3 to bt green box unit., one on footpath at yellow marked cassie, and gully on road next to green bt box., re opps huttons,	.RD 7 Day	Contractor Completed	11/02/2016	22/02/2016 Act.	RD01/22172
Asset: 1,001.00		**Asset - Locn.:** 1 - Victoria Road-Greyhope Road-Carriageway		**Feature Type:** RDS Carriageway		**Area:** Aberdeen South	
68998	Pot Hole		Standard	Job Closed	19/04/2010		
69000	Pothole.300 x 300 x 60 (Pot Hole)	Crombie place	.RD 14 Day	Job Closed	19/04/2010		
Asset: 1,002.00		**Asset - Locn.:** 1 - Victoria Road-27 Sinclair Road-Footway		**Feature Type:** RDS Footway		**Area:** Aberdeen South	
196647	clean and jet F/P gully	O/S Hairdresser	.RD 14 Day	Contractor Completed	07/09/2015	04/09/2015 Act.	
Asset: 1,017.00		**Asset - Locn.:** 11 - Torry Dock, access-Footway		**Feature Type:** RDS Footway		**Area:** Aberdeen South	
190496	Pothole 400x400x50, filled by inspector, (Pot Hole)	At jct of sinclair pl.	.RD 2 Day	Contractor Completed	18/02/2015	18/02/2015 Act.	

Effective: 24/11/2014 to 24/05/2016 Display Action Officer: No
Site: SINCLAIR ROAD (7600814)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 10,011.00	**Asset - Locn.:** 12 - AT 84		**Feature Type:** SL - Street Lamp		**Area:** Aberdeen South	
526526	Light Out - Reference No : LIGHTS30587 Site (Street/Park/etc) : Sinclair Road, Torry Location : column 12 First Type of Fault : Lamp Out Name : Email Address : (Enquiry 651377)	sinclair road	SL 07-Day	Contractor Completed	18/01/2016	23/01/2016 Act.	SL01/99441
528190	Light Out - FAO : ACC Lighting service, Reference No : LIGHTS31321 Site (Street/Park/etc) : Sinclair Road, Torry Location : column 12 First Type of Fault : Lamp Out Name : Email Address : (Enquiry 657020)		SL 07-Day	Contractor Completed	14/03/2016	17/03/2016 Act.	SL01/101092
	Asset: 100,009.00	**Asset - Locn.:** 9051119979 - 4 SINCLAIR ROAD, TORRY, AB11 9PN		**Feature Type:** W - Domestic Waste Property		**Area:** Aberdeen South	
10077425	Flytipping - Housing White Goo - UPLIFT: OLD FRIDGE AT BIN AREA (Enquiry 1023682)	4-6 Sinclair Road Torry	WM: 7 Day	Contractor Completed	21/03/2016	22/03/2016 Act.	DW2008/164705
	Asset: 100,011.00	**Asset - Locn.:** 9051081270 - 6 SINCLAIR ROAD, TORRY,		**Feature Type:** W - Domestic Waste Property		**Area:** Aberdeen South	
396018	Bulky Uplift WhiteG (Paid) - UPLIFT FRIDGE (Enquiry 316705)	6 SINCLAIR ROAD	WM: 7 Day	Job Cancelled - Waste	20/12/2012	19/12/2014 Act.	DW2008/133282
10076265	Fw:Flytipping - White Goods - UPLIFT: 1X SMALL FRIDGE OUTSIDE 6 (Enquiry 1022620)	6 SINCLAIR ROAD	WM: 7 Day	Works Committed	04/03/2016	11/03/2016 Est.	DW2008/164331
10076344	Flytipping - uplift: SOFA AT NO 6 ON PAVEMENT (Enquiry 1022692)	6 SINCLAIR ROAD	WM: 7 Day	Contractor Completed	07/03/2016	09/03/2016 Act.	DW2008/164369
10079871	Flytipping - uplift: old furniture (Enquiry 1025874)	6 Sinclair Road, Torry	WM: 7 Day	Contractor Completed	25/04/2016	27/04/2016 Act.	DW2008/165443
	Asset: 100,020.00	**Asset - Locn.:** 9051080945 - 8 SINCLAIR ROAD, TORRY, AB11 9PL		**Feature Type:** W - Commercial Waste Property		**Area:** Aberdeen South	
10054607	Flytipping - Uplift: tv by No 8 (Enquiry 1002691)	8 Sinclair Road	WM: 7 Day	Contractor Completed	02/04/2015	07/04/2015 Act.	DW2008/156026